

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Bulli Public School (1411)
Region : Illawarra and South East
State Electorate : Keira
Local Government Area : Wollongong

Initial Survey : Noel Arnold & Associates : 30 - Mar - 2008
Reviewed By : Grencap-NAA : 01 - Aug - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - General Learning - 1923 - Timber (Timber)						
Exterior						
Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Packing to Floor Joists	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	38m2	Throughout, Upper portion, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1411/B00A/Eaves Linings/S1					Chrysotile (white asbestos)
Interior						
B00A - R0001 - Duplicating Workroom						
No Asbestos						
B00A - R0002 - General Storeroom						
No Asbestos						
B00A - R0004 - Home Base						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	47.98m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1411/B00A/R0004/Floor Coverings Res/Textile/S24					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive	47.98m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1411/B00A/R0004/Floor Coverings Res/Textile/S25					Chrysotile (white asbestos)
B00A - R0005 - Home Base						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	47.97m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1411/B00A/R0004/Floor Coverings Res/Textile/S24					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive	47.97m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1411/B00A/R0004/Floor Coverings Res/Textile/S25					Chrysotile (white asbestos)
B00A - R0006 - Withdrawal Space - 1hb						
Wall Linings Internal	Flat AC Sheeting	2m2	South, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	1411/B00A/R0007/Wall Linings Internal/S3					Chrysotile (white asbestos)
Electrical Backing Board	Resinous Board	0.5m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	1411/B00A/R0006/Electrical Backing Board/S26					Chrysotile (white asbestos)
B00A - R0007 - General Storeroom						
Wall Linings Internal	Flat AC Sheeting	2m2	North, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	1411/B00A/R0007/Wall Linings Internal/S3					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	8.11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1411/B00A/R0008/Floor Coverings Res/Textile/S2					Chrysotile (white asbestos)
B00A - R0008 - Staff Toilet						
Floor Coverings Res/Textile	Vinyl Tiles	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1411/B00A/R0008/Floor Coverings Res/Textile/S2					Chrysotile (white asbestos)
B00A - R0009 - Movement						
Wall Linings Internal	Lower infill panel	15m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	1411/B00A/R0009/Wall Linings Internal/S23					Chrysotile (white asbestos) , Amosite (brown asbestos)
B00A - R0010 - Movement						
Lower infill panel	Flat AC Sheeting	3m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	1411/B00A/R0009/Wall Linings Internal/S23					Chrysotile (white asbestos) , Amosite (brown asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 1952 - Timber (Timber)**Exterior**

Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Packing to Floor Joists	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	24m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1411/B00B/R0001/Ceiling Structures/Linings/S4					Chrysotile (white asbestos)

Interior**B00B - R0001 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	38m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1411/B00B/R0001/Ceiling Structures/Linings/S4					Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	1m2	East, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1411/B00B/R0001/Ceiling Structures/Linings/S4					Chrysotile (white asbestos)

B00B - R0002 - Home Base

Ceiling Structures/Linings	Flat AC Sheeting	53m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1411/B00B/R0001/Ceiling Structures/Linings/S4					Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	26m2	Throughout, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1411/B00B/R0001/Ceiling Structures/Linings/S4					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					No Asbestos Detected
	1411/B00B/R0005/Floor Coverings Res/Textile/S5					

B00B - R0003 - Home Base

Ceiling Structures/Linings	Flat AC Sheeting	53m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1411/B00B/R0001/Ceiling Structures/Linings/S4					Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	26m2	Throughout, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1411/B00B/R0001/Ceiling Structures/Linings/S4					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					No Asbestos Detected
	1411/B00B/R0005/Floor Coverings Res/Textile/S5					

B00B - R0004 - Staff Room Annexe

No Asbestos

B00B - R0005 - Home Base Store

Floor Coverings Res/Textile	Vinyl Tiles					No Asbestos Detected
	1411/B00B/R0005/Floor Coverings Res/Textile/S5					

B00B - R0006 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1411/B00B/R0001/Ceiling Structures/Linings/S4					Chrysotile (white asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning/Administration - 1969 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
Ceiling Voids - Flat Roof	No Asbestos Found					
Gable Verge Lining	Flat AC Sheeting 1411/B00C/Gable Verge Lining/S22	10m2	North & South	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
In-fill-panel	Flat AC Sheeting 1411/B00C/In-fill-panel/S10	21m2	East	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Wall Cladding	Flat AC Sheeting 1411/B00C/Wall Cladding/S19					No Asbestos Detected
Eaves Linings	Corrugated AC Sheeting 1411/B00C/R0021/Ceiling Structures/Linings/S21	60m2	East	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)

Interior**B00C - R0001 - Toilets - Boys/Girls**

No Asbestos

B00C - R0002 - Home Base Store

Floor Coverings Res/Textile	Vinyl Tiles 1411/B00C/R0002/Floor Coverings Res/Textile/S12					No Asbestos Detected
-----------------------------	--	--	--	--	--	-----------------------------

B00C - R0003 - Personal Effects Storage

Floor Coverings Res/Textile	Vinyl Tiles 1411/B00C/R0002/Floor Coverings Res/Textile/S12					No Asbestos Detected
-----------------------------	--	--	--	--	--	-----------------------------

B00C - R0004 - Home Base

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 1411/B00C/R0002/Floor Coverings Res/Textile/S12					No Asbestos Detected
-----------------------------	--	--	--	--	--	-----------------------------

B00C - R0005 - Home Base

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 1411/B00C/R0002/Floor Coverings Res/Textile/S12					No Asbestos Detected
-----------------------------	--	--	--	--	--	-----------------------------

B00C - R0006 - Home Base Store

Floor Coverings Res/Textile	Vinyl Tiles 1411/B00C/R0002/Floor Coverings Res/Textile/S12					No Asbestos Detected
-----------------------------	--	--	--	--	--	-----------------------------

B00C - R0007 - Personal Effects Storage

Floor Coverings Res/Textile	Vinyl Tiles 1411/B00C/R0002/Floor Coverings Res/Textile/S12					No Asbestos Detected
-----------------------------	--	--	--	--	--	-----------------------------

B00C - R0008 - Main Switch Board

Floor Coverings Res/Textile	Vinyl Tiles 1411/B00C/R0002/Floor Coverings Res/Textile/S12					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting 1411/B00C/R0008/Wall Linings Internal/S13	4m2	North, South, East	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting 1411/B00C/R0008/Wall Linings Internal/S13	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

B00C - R0009 - Home Base Store

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles					
	1411/B00C/R0002/Floor Coverings Res/Textile/S12					No Asbestos Detected
B00C - R0010 - Home Base						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	1411/B00C/R0002/Floor Coverings Res/Textile/S12					No Asbestos Detected
B00C - R0011 - Principal						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	1411/B00C/R0002/Floor Coverings Res/Textile/S12					No Asbestos Detected
B00C - R0014 - Staff Toilet						
Wall Linings Internal	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1411/B00C/R0014/Wall Linings Internal/S20					Chrysotile (white asbestos)
B00C - R0015 - Staff Toilet						
Wall Linings Internal	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1411/B00C/R0014/Wall Linings Internal/S20					Chrysotile (white asbestos)
B00C - R0016 - Movement						
No Asbestos						
B00C - R0019 - Staff Room						
In-fill-panel	Flat AC Sheeting	4m	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1411/B00C/In-fill-panel/S10					Chrysotile (white asbestos)
B00C - R0021 - Movement						
Wall Linings Internal	Flat AC Sheeting					
	1411/B00C/R0021/Wall Linings Internal/S11					No Asbestos Detected
In-fill-panel	Flat AC Sheeting	19m	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	1411/B00C/In-fill-panel/S10					Chrysotile (white asbestos)
Ceiling Structures/Linings	Corrugated AC Sheeting	75.97m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1411/B00C/R0021/Ceiling Structures/Linings/S21					Chrysotile (white asbestos) , Amosite (brown asbestos)
B00C - R0022 - Sick Bay						
Wall Linings Internal	Flat AC Sheeting					
	1411/B00C/R0021/Wall Linings Internal/S11					No Asbestos Detected
In-fill-panel	Flat AC Sheeting	2m	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	1411/B00C/In-fill-panel/S10					Chrysotile (white asbestos)
B00C - R0023 - Entry Vestibule						
No Asbestos						
B00C - R0024 - Clerical Office						
No Asbestos						
B00C - R0025 - Security Store						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Library - 1958 - Timber (Timber)**Exterior**

Underfloor Voids - Packing to Floor Joists	No Asbestos Found					
Ceiling Voids - Flat Roof	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1411/B00D/Eaves Linings/S6					Chrysotile (white asbestos)

Interior**B00D - R0001 - Reading Area**

Wall Linings Internal	Flat AC Sheeting	2m2	Behind Heater	Good Condition (1)	Low (1)	Low Priority (2-3)
	1411/B00D/R0001/Wall Linings Internal/S8					Chrysotile (white asbestos)

B00D - R0002 - Reading Area

Wall Linings Internal	Flat AC Sheeting	2m2	Behind Heater	Good Condition (1)	Low (1)	Low Priority (2-3)
	1411/B00D/R0001/Wall Linings Internal/S8					Chrysotile (white asbestos)

B00D - R0003 - K.L.A. Store

No Asbestos

B00D - R0004 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1411/B00D/Eaves Linings/S6					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1411/B00D/R0005/Floor Coverings Res/Textile/S9					Chrysotile (white asbestos)

B00D - R0005 - Library Office/Workroom

Ceiling Structures/Linings	Flat AC Sheeting	32m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1411/B00D/Eaves Linings/S6					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles	32m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1411/B00D/R0005/Floor Coverings Res/Textile/S9					Chrysotile (white asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Special Purpose/General Learning - 1958 - Timber (Timber)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible
Ceiling Voids - Raked Ceiling	Non Accessible Area - Area inaccessible

Interior

B00E - R0001 - General Storeroom

Floor Coverings Res/Textile	Vinyl Tiles	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1411/B00E/R0003/Floor Coverings Res/Textile/S15					Chrysotile (white asbestos)	

B00E - R0002 - Special Programs Room

Floor Coverings Res/Textile	Vinyl Tiles	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1411/B00E/R0003/Floor Coverings Res/Textile/S15					Chrysotile (white asbestos)	

B00E - R0003 - Withdrawal Space - 1hb

Floor Coverings Res/Textile	Vinyl Tiles	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1411/B00E/R0003/Floor Coverings Res/Textile/S15					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00F - Pupil Facilities/Building Services - 1969 - Brick/Block (Brick/Block)						
Exterior						
Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
Eaves Linings	Flat AC Sheeting	10m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	1411/B00F/Eaves Linings/S18				Chrysotile (white asbestos)	
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1411/B00C/Gable Verge Lining/S22				Chrysotile (white asbestos)	
Interior						
B00F - R0001 - Cleaning Supplies						
Ceiling Structures/Linings	Flat AC Sheeting	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1411/B00F/R0001/Ceiling Structures/Linings/S16				Chrysotile (white asbestos)	
B00F - R0002 - Toilets - Boys						
Partition Walls (Cubicles)	Compressed AC Sheet 1411/B00F/R0002/Partition Walls (Cubicles)/S17					
	No Asbestos Detected					
Ceiling Structures/Linings	Flat AC Sheeting	28m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1411/B00F/Eaves Linings/S18				Chrysotile (white asbestos)	
B00F - R0003 - Cleaning Supplies						
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1411/B00F/Eaves Linings/S18				Chrysotile (white asbestos)	
B00F - R0004 - Toilets - Girls						
Partition Walls (Cubicles)	Compressed AC Sheet 1411/B00F/R0002/Partition Walls (Cubicles)/S17					
	No Asbestos Detected					
Ceiling Structures/Linings	Flat AC Sheeting	29m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1411/B00F/Eaves Linings/S18				Chrysotile (white asbestos)	
B00F - R0005 - Toilets - Girls						
Partition Walls (Cubicles)	Compressed AC Sheet 1411/B00F/R0002/Partition Walls (Cubicles)/S17					
	No Asbestos Detected					
Ceiling Structures/Linings	Flat AC Sheeting	31m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1411/B00F/Eaves Linings/S18				Chrysotile (white asbestos)	
B00F - R0006 - Staff Toilet						
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1411/B00F/Eaves Linings/S18				Chrysotile (white asbestos)	
B00F - R0007 - Toilets - Boys						
Partition Walls (Cubicles)	Compressed AC Sheet 1411/B00F/R0002/Partition Walls (Cubicles)/S17					
	No Asbestos Detected					
Ceiling Structures/Linings	Flat AC Sheeting	27m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1411/B00F/Eaves Linings/S18				Chrysotile (white asbestos)	
B00F - R0008 - Staff Toilet						
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1411/B00F/Eaves Linings/S18				Chrysotile (white asbestos)	
B00F - R0009 - Garden Store						
Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1411/B00F/R0001/Ceiling Structures/Linings/S16				Chrysotile (white asbestos)	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - R0010 - General Assistant/Bulk Store

Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1411/B00F/R0001/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - Other-Community Use - 1984 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab on Ground Non Accessible Area

- Area inaccessible

Ceiling Voids - Flat Roof No Asbestos Found

Interior**B00I - R0001 - Dental Clinic**

No Asbestos

B00I - R0002 - Movement

No Asbestos

B00I - R0003 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
-----------------------	------------------	------	------------	--------------------	---------	--------------------

1411/B00I/R0005/Wall Linings Internal/S27

Chrysotile (white asbestos)

B00I - R0004 - Clerical Office

No Asbestos

B00I - R0005 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
-----------------------	------------------	------	------------	--------------------	---------	--------------------

1411/B00I/R0005/Wall Linings Internal/S27

Chrysotile (white asbestos)

B00I - R0006 - Staff Room

No Asbestos

B00I - R0007 - Dental Clinic

No Asbestos

B00I - R0008 - Dental Clinic

No Asbestos

B00I - R0009 - Dental Clinic

No Asbestos

B00I - R0010 - Cleaning Distributed Store

Wall Linings Internal	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
-----------------------	------------------	------	------------	--------------------	---------	--------------------

1411/B00I/R0005/Wall Linings Internal/S27

Chrysotile (white asbestos)

B00I - R0011 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - Other - 2006 - Steel (Steel)

Exterior

Underfloor Voids - Packing to Floor Joists	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00J - R0001 - Special Programs Room

No Asbestos

B00J - R0002 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Library - 2007 - Steel (Steel)

Exterior

Underfloor Voids - Packing to Floor Joists No Asbestos Found

Ceiling Voids No Asbestos Found

Interior

B00K - R0001 - Reading Area

No Asbestos

B00K - R0002 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Pupil Facilities/Multi Purpose Facilities - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground Non Accessible Area

- Area inaccessible

Ceiling Voids No Asbestos Found

Interior

B00L - R0001 - Communal Space

No Asbestos

B00L - R0002 - Raised Platform

No Asbestos

B00L - R0003 - Chair Storeroom

No Asbestos

B00L - R0004 - Communal/Performance Store

No Asbestos

B00L - R0005 - P.E. Store

No Asbestos

B00L - R0006 - Toilet - Lobby

No Asbestos

B00L - R0007 - No Access

No Asbestos

B00L - R0008 - Sound Cupboard

No Asbestos

B00L - R0009 - Toilet - Lobby

No Asbestos

B00L - R0010 - Toilets - Boys

No Asbestos

B00L - R0011 - Cleaning Distributed Store

No Asbestos

B00L - R0012 - Other

No Asbestos

B00L - R0013 - Main Switch Board

No Asbestos

B00L - R0014 - Access Shower/Toilet/Change

No Asbestos

B00L - R0015 - Covered Outdoor Learning Area

No Asbestos

B00L - R0016 - Movement

No Asbestos

B00L - R0017 - Ramp

No Asbestos

B00L - R0018 - Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 810 - D13517 - FSU/Shelter/Stores : Placement Date - 30/06/1995

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos		1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos		1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos		25.92 m2

Interior

R1 - Canteen

End wall panel	Flat AC Sheet	Assumed Asbestos		18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		28 m2

R2 - Covered Area

End wall panel	Flat AC Sheet	Assumed Asbestos		18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		109 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos		4 m2
---------	---------------	------------------	--	------

R4 - Sports Store

Ceiling	Flat AC Sheet	Assumed Asbestos		10 m2
---------	---------------	------------------	--	-------

R5 - Garden Store

Ceiling	Flat AC Sheet	Assumed Asbestos		8 m2
---------	---------------	------------------	--	------

R6 - Change Room

Ceiling	Flat AC Sheet	Assumed Asbestos		3 m2
---------	---------------	------------------	--	------

R7 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos		2 m2
---------	---------------	------------------	--	------

OS 602 - D13668 - Learning Unit - Standard With P.A.A. : Placement Date - 24/02/2012

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D15494 - Learning Unit - Standard With P.A.A. : Placement Date - 8/03/2007

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos		1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos		1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos		11.52 m2

Interior

R1 - Learning space/withdrawal/entry

Ceiling	Flat AC Sheet	Assumed Asbestos		70 m2
---------	---------------	------------------	--	-------

R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos		18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		3 m2

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

Available Asbestos Related Electronic Files

1411_ASB_150514_AMP.pdf

* Note : Refer to AMS for details of the attachment(s).

2017