

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Bungendore Public School (1421)
Region : Illawarra and South East
State Electorate : Monaro
Local Government Area : Palerang

Initial Survey : Noel Arnold & Associates : 08 - Jul - 2016
Reviewed By : Greencap-NAA : 08 - Jul - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/Staff Facilities - 1878 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
Eaves Linings	Flat AC Sheeting 1421/B00B/Eaves Linings/S9	12m2	East	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Ceiling void	Non Accessible Area - Height Restriction - 4m					
Window	Putty 1421/B00A/Window/S12					No Asbestos Detected

Interior**B00A - R0014 - Movement**

No Asbestos

B00A - R0015 - Staff Room Annexe

No Asbestos

B00A - R0016 - Staff Room

No Asbestos

B00A - R0017 - Movement

No Asbestos

B00A - R0018 - Deputy Principal

No Asbestos

B00A - R0020 - Distribution Board

No Asbestos

Note: No inspection of live electrical installation.

B00A - R0023 - External Movement

No Asbestos

B00A - R0024 - Staff KitchenFloor Coverings Res/Textile
No Asbestos Found**B00A - R0025 - Staff Toilet**

Wall Linings Internal	Flat AC Sheeting 1421/B00A/R0030/Wall Linings Internal/S15					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting 1421/B00A/R0030/Wall Linings Internal/S15					No Asbestos Detected

B00A - R0026 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting 1421/B00A/R0030/Wall Linings Internal/S15					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting 1421/B00A/R0030/Wall Linings Internal/S15					No Asbestos Detected

B00A - R0027 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting 1421/B00A/R0030/Wall Linings Internal/S15					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting 1421/B00A/R0030/Wall Linings Internal/S15					No Asbestos Detected

B00A - R0028 - Toilet - Lobby

Wall Linings Internal	Flat AC Sheeting 1421/B00A/R0030/Wall Linings Internal/S15					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting 1421/B00A/R0030/Wall Linings Internal/S15					No Asbestos Detected

B00A - R0029 - Toilet - Lobby

Ceiling Structures/Linings	Flat AC Sheeting 1421/B00A/R0030/Wall Linings Internal/S15					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Wall Linings Internal	Flat AC Sheeting					
	1421/B00A/R0030/Wall Linings Internal/S15					No Asbestos Detected
B00A - R0030 - Toilet - Lobby						
Wall Linings Internal	Flat AC Sheeting					
	1421/B00A/R0030/Wall Linings Internal/S15					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting					
	1421/B00A/R0030/Wall Linings Internal/S15					No Asbestos Detected
B00A - R0031 - Other						
Floor Coverings Res/Textile	Vinyl sheet under carpet					
	1421/B00A/R0031/Floor Coverings Res/Textile/S13					No Asbestos Detected
Floor Coverings Res/Textile	Adhesive					
	1421/B00A/R0031/Floor Coverings Res/Textile/S14					No Asbestos Detected
B00A - R0032 - General Storeroom						
Floor Coverings Res/Textile	Vinyl Sheet					
	1421/B00A/R0031/Floor Coverings Res/Textile/S13					No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 1968 - Brick/Veneer (Brick/Veneer)**Exterior**

In-fill-panel	Flat AC Sheeting	6m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	1421/B00B/In-fill-panel/S8					Chrysotile (white asbestos)
Eaves Linings	Flat AC Sheeting	14m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	1421/B00B/Eaves Linings/S9					Chrysotile (white asbestos)
Uderfloor void	AC Fragments/Debris	0.1m2	Variable positions	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
	1421/B00B/Uderfloor void/S11					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Ceiling void	No Asbestos Found					

Interior**B00B - R0004 - Home Base**

Floor Coverings Res/Textile No Asbestos Found

B00B - R0005 - Home Base Store

Floor Coverings Res/Textile Vinyl Sheet
1421/B00A/R0031/Floor Coverings Res/Textile/S13 **No Asbestos Detected**

B00B - R0008 - Home Base

No Asbestos

B00B - R0009 - Practical Activities - 1hb

Floor Coverings Res/Textile No Asbestos Found

B00B - R0010 - External Movement

Wall Linings Internal	Flat AC Sheeting	8m2	Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1421/B00B/In-fill-panel/S8					Chrysotile (white asbestos)

B00B - R0011 - Home Base Store

Floor Coverings Res/Textile No Asbestos Found

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning - 1980 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Raked Ceiling	Non Accessible Area - Area inaccessible
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

Interior

B00E - R0001 - Practical Activities - 1hb

Floor Coverings Res/Textile	No Asbestos Found
-----------------------------	-------------------

B00E - R0002 - Kiln Room

No Asbestos

B00E - R0003 - Movement

No Asbestos

B00E - R0004 - Home Base

No Asbestos

B00E - R0005 - Home Base Store

No Asbestos

B00E - R0006 - Movement

No Asbestos

B00E - R0007 - Staff Study

No Asbestos

B00E - R0008 - Home Base

No Asbestos

B00E - R0009 - Home Base Store

No Asbestos

B00E - R0010 - Movement

No Asbestos

B00E - R0011 - Home Base

No Asbestos

B00E - R0012 - Home Base Store

No Asbestos

B00E - R0013 - Withdrawal Space - 1hb

No Asbestos

B00E - R0014 - Home Base

No Asbestos

B00E - R0015 - Home Base Store

No Asbestos

B00E - R0016 - Movement

No Asbestos

B00E - R0017 - Cleaning Distributed Store

No Asbestos

B00E - R0018 - Distribution Board

Note: No inspection of live electrical installation.

Electrical Backing Board	Resinous Board 1421/B00E/R0018/Electrical Backing Board/S18
--------------------------	--

No Asbestos Detected

B00E - R0019 - Personal Effects Storage

Floor Coverings Res/Textile	Vinyl Tiles	2m2	North, East	Good Condition (1)	Low (1)	Low Priority (2-3)
1421/B00E/R0019/Floor Coverings Res/Textile/S3						Chrysotile (white asbestos)

B00E - R0020 - Practical Activities - 1hb

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No						Test Result
Floor Coverings Res/Textile	No Asbestos Found					
B00E - R0021 - Communications Room						
Floor Coverings Res/Textile	No Asbestos Found					
B00E - R0022 - General Storeroom						
Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1421/B00E/R0019/Floor Coverings Res/Textile/S3					Chrysotile (white asbestos)
B00E - R0023 - Practical Activities - 1hb						
Floor Coverings Res/Textile	No Asbestos Found					
B00E - R0024 - Toilets - Girls						
No Asbestos						
B00E - R0025 - Toilets - Boys						
No Asbestos						
B00E - R0026 - Movement						
No Asbestos						
B00E - R0027 - Movement						
No Asbestos						
B00E - R0028 - Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Administration - 1878 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
Eaves Linings	Flat AC Sheeting 1421/B00A/R0022/Ceiling Structures/Linings/S7					No Asbestos Detected
Ceiling void	No Asbestos Found					

Interior**B00G - R0005 - Clerical Office/Workroom**

No Asbestos

B00G - R0007 - Principal

No Asbestos

B00G - R0011 - Sick Bay

Floor Coverings Res/Textile No Asbestos Found

B00G - R0014 - Duplicating Workroom

Floor Coverings Res/Textile No Asbestos Found

B00G - R0015 - Movement

No Asbestos

B00G - R0016 - Cleaning Distributed Store

Floor Coverings Res/Textile	Vinyl Sheet 1421/B00A/R0031/Floor Coverings Res/Textile/S13					No Asbestos Detected
-----------------------------	--	--	--	--	--	-----------------------------

B00G - R0017 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting 1421/B00A/R0022/Wall Linings Internal/S6					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting 1421/B00A/R0022/Ceiling Structures/Linings/S7					No Asbestos Detected

B00G - R0018 - Clerical Office

No Asbestos

B00G - R0019 - Movement

No Asbestos

B00G - R0020 - Entry Vestibule

No Asbestos

B00G - R0021 - Movement

No Asbestos

B00G - R0022 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - General Learning/Pupil Facilities - 1999 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible
Ceiling void	No Asbestos Found

Interior**B00I - R0001 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting 1421/B00I/R0001/Ceiling Structures/Linings/S16	No Asbestos Detected
----------------------------	--	----------------------

B00I - R0002 - Kiln Room

Ceiling Structures/Linings	Flat AC Sheeting 1421/B00I/R0005/Ceiling Structures/Linings/S10	No Asbestos Detected
----------------------------	--	----------------------

B00I - R0003 - Cleaning Distributed Store

Ceiling Structures/Linings	Flat AC Sheeting 1421/B00I/R0005/Ceiling Structures/Linings/S10	No Asbestos Detected
----------------------------	--	----------------------

B00I - R0004 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting 1421/B00I/R0005/Ceiling Structures/Linings/S10	No Asbestos Detected
----------------------------	--	----------------------

B00I - R0005 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting 1421/B00I/R0005/Ceiling Structures/Linings/S10	No Asbestos Detected
----------------------------	--	----------------------

B00I - R0006 - Home Base Store

Floor Coverings Res/Textile	Vinyl Sheet 1421/B00A/R0031/Floor Coverings Res/Textile/S13	No Asbestos Detected
-----------------------------	--	----------------------

B00I - R0007 - Practical Activities - 1hb

Floor Coverings Res/Textile	Vinyl Sheet 1421/B00A/R0031/Floor Coverings Res/Textile/S13	No Asbestos Detected
-----------------------------	--	----------------------

B00I - R0008 - Home Base

No Asbestos

B00I - R0009 - Withdrawal Space - 1hb

No Asbestos

B00I - R0010 - Home Base

No Asbestos

B00I - R0011 - Practical Activities - 1hb

Floor Coverings Res/Textile	Vinyl Sheet 1421/B00A/R0031/Floor Coverings Res/Textile/S13	No Asbestos Detected
-----------------------------	--	----------------------

B00I - R0012 - Home Base Store

Floor Coverings Res/Textile	Vinyl Sheet 1421/B00A/R0031/Floor Coverings Res/Textile/S13	No Asbestos Detected
-----------------------------	--	----------------------

B00I - R0013 - Personal Effects Storage

Ceiling Structures/Linings	Flat AC Sheeting 1421/B00I/R0005/Ceiling Structures/Linings/S10	No Asbestos Detected
----------------------------	--	----------------------

B00I - R0014 - Personal Effects Storage

Ceiling Structures/Linings	Flat AC Sheeting 1421/B00I/R0005/Ceiling Structures/Linings/S10	No Asbestos Detected
----------------------------	--	----------------------

B00I - R0015 - Distribution Board

No Asbestos

Note: No inspection of live electrical installation.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - General Learning - 1999 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
In-fill-panel	Flat AC Sheeting		1421/B001/R0005/Ceiling Structures/Linings/S10			No Asbestos Detected
Ceiling Voids	No Asbestos Found					

Interior

B00J - R0001 - Movement

Ceiling Structures/Linings	Flat AC Sheeting		1421/B001/R0005/Ceiling Structures/Linings/S10			No Asbestos Detected
----------------------------	------------------	--	--	--	--	----------------------

B00J - R0002 - Practical Activities - 1hb

Floor Coverings Res/Textile	Vinyl Sheet		1421/B00A/R0031/Floor Coverings Res/Textile/S13			No Asbestos Detected
-----------------------------	-------------	--	---	--	--	----------------------

B00J - R0003 - Home Base Store

Floor Coverings Res/Textile	Vinyl Sheet		1421/B00A/R0031/Floor Coverings Res/Textile/S13			No Asbestos Detected
-----------------------------	-------------	--	---	--	--	----------------------

B00J - R0004 - Movement

Ceiling Structures/Linings	Flat AC Sheeting		1421/B001/R0005/Ceiling Structures/Linings/S10			No Asbestos Detected
----------------------------	------------------	--	--	--	--	----------------------

B00J - R0005 - Home Base

No Asbestos

B00J - R0006 - Withdrawal Space - 1hb

No Asbestos

B00J - R0007 - Home Base

No Asbestos

B00J - R0008 - Practical Activities - 1hb

Floor Coverings Res/Textile	Vinyl Sheet		1421/B00A/R0031/Floor Coverings Res/Textile/S13			No Asbestos Detected
-----------------------------	-------------	--	---	--	--	----------------------

B00J - R0009 - Home Base Store

Floor Coverings Res/Textile	Vinyl Sheet		1421/B00A/R0031/Floor Coverings Res/Textile/S13			No Asbestos Detected
-----------------------------	-------------	--	---	--	--	----------------------

B00J - R0010 - Personal Effects Storage

Ceiling Structures/Linings	Flat AC Sheeting		1421/B001/R0005/Ceiling Structures/Linings/S10			No Asbestos Detected
----------------------------	------------------	--	--	--	--	----------------------

B00J - R0011 - Personal Effects Storage

Ceiling Structures/Linings	Flat AC Sheeting		1421/B001/R0005/Ceiling Structures/Linings/S10			No Asbestos Detected
----------------------------	------------------	--	--	--	--	----------------------

B00J - R0012 - Withdrawal Space - 1hb

No Asbestos

B00J - R0013 - Home Base

No Asbestos

B00J - R0014 - Practical Activities - 1hb

Floor Coverings Res/Textile	Vinyl Sheet		1421/B00A/R0031/Floor Coverings Res/Textile/S13			No Asbestos Detected
-----------------------------	-------------	--	---	--	--	----------------------

B00J - R0015 - Home Base Store

Floor Coverings Res/Textile	Vinyl Sheet		1421/B00A/R0031/Floor Coverings Res/Textile/S13			No Asbestos Detected
-----------------------------	-------------	--	---	--	--	----------------------

B00J - R0016 - Distribution Board

Note: No inspection of live electrical installation.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Library/Communal Facilities - 1999 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible
Ceiling Voids	No Asbestos Found

Interior**B00K - R0001 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting 1421/B00K/R0006/Wall Linings Internal/S5	No Asbestos Detected
----------------------------	--	----------------------

B00K - R0002 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 1421/B00K/R0006/Wall Linings Internal/S5	No Asbestos Detected
----------------------------	--	----------------------

B00K - R0003 - Reading Area

Ceiling Structures/Linings	Non Accessible Area - Height Restriction - 6m
----------------------------	--

B00K - R0004 - Library Office/Workroom

Ceiling Structures/Linings	Non Accessible Area - Height Restriction - 6m
----------------------------	--

B00K - R0005 - Communications Room

No Asbestos

B00K - R0006 - Toilets - Boys/Girls

Wall Linings Internal	Flat AC Sheeting 1421/B00K/R0006/Wall Linings Internal/S5	No Asbestos Detected
-----------------------	--	----------------------

Ceiling Structures/Linings	Flat AC Sheeting 1421/B00K/R0006/Wall Linings Internal/S5	No Asbestos Detected
----------------------------	--	----------------------

B00K - R0007 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00K - R0008 - Special Programs Room

No Asbestos

B00K - R0009 - General Storeroom

No Asbestos

B00K - R0010 - Cleaning Distributed Store

Floor Coverings Res/Textile	No Asbestos Found
-----------------------------	-------------------

B00K - R0011 - Canteen

Floor Coverings Res/Textile	No Asbestos Found
-----------------------------	-------------------

B00K - R0012 - Canteen Office/Store

Floor Coverings Res/Textile	No Asbestos Found
-----------------------------	-------------------

B00K - R0013 - Movement

No Asbestos

B00K - R0014 - Communal Space

No Asbestos

B00K - R0015 - P.E. Store

No Asbestos

B00K - R0016 - General Storeroom

No Asbestos

B00K - R0017 - Hall Chair Store

No Asbestos

B00K - R0018 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00K - R0019 - General Assistant/Bulk Store						
No Asbestos						
B00K - R0020 - General Storeroom						
Floor Coverings Res/Textile	No Asbestos Found					
B00K - R0021 - Cleaning Supplies						
No Asbestos						
B00K - R0022 - Garden Store						
No Asbestos						
B00K - R0023 - Cleaning Distributed Store						
Floor Coverings Res/Textile	No Asbestos Found					
B00K - R0024 - Toilets - Girls						
No Asbestos						
B00K - R0025 - Toilets - Boys/Girls						
No Asbestos						
B00K - R0026 - Movement						
Ceiling Structures/Linings	Non Accessible Area - Height Restriction - 4m					
B00K - R0027 - Lift						
No Asbestos						
B00K - R0028 - Raised Platform						
No Asbestos						
B00K - R0029 - General Storeroom						
Floor Coverings Res/Textile	No Asbestos Found					
B00K - R0030 - Movement						
Ceiling Structures/Linings	Non Accessible Area - Height Restriction					
B00K - R0031 - Toilets - Boys						
No Asbestos						
B00K - R0032 - Sports Store						
No Asbestos						
B00K - R0033 - Plant						
No Asbestos						
B00K - R0034 - Plant						
No Asbestos						
B00K - R0035 - Movement						
No Asbestos						
B00K - R0036 - Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - General Learning - 2006 - Fibre Cement Clad (Fibre Cement Clad)**Exterior**

Wall Cladding	Compressed AC Sheet 1421/B00L/Wall Cladding/S1					No Asbestos Detected
Entry Steps	Compressed AC Sheet 1421/B00L/Entry Steps/S2					No Asbestos Detected
Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible					
Underfloor void	No Asbestos Found					

Interior**B00L - R0001 - Movement**

Floor Coverings Res/Textile	Compressed AC Sheet 1421/B00L/Entry Steps/S2					No Asbestos Detected
Wall Linings Internal	Compressed AC Sheet 1421/B00K/R0006/Wall Linings Internal/S5					No Asbestos Detected

B00L - R0002 - Practical Activities - 1hb

Floor Coverings Res/Textile	No Asbestos Found					
--------------------------------	-------------------	--	--	--	--	--

B00L - R0003 - Home Base Store

No Asbestos

B00L - R0004 - Home Base

No Asbestos

B00L - R0005 - Withdrawal Space - 2hb

No Asbestos

B00L - R0006 - Home Base

No Asbestos

B00L - R0007 - Home Base Store

No Asbestos

B00L - R0008 - Practical Activities - 1hb

Floor Coverings Res/Textile	No Asbestos Found					
--------------------------------	-------------------	--	--	--	--	--

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - General Learning/Other - 2008 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found					
Underfloor void	Packing 1421/B00M/Underfloor void/S17					No Asbestos Detected
Eaves Linings	Flat AC Sheeting 1421/B00M/Eaves Linings/S19					No Asbestos Detected
Underfloor void	AC Fragments/Debris 1421/B00M/Underfloor void/S17					No Asbestos Detected

Interior

B00M - R0001 - Staff Kitchen

Floor Coverings Res/Textile No Asbestos Found

B00M - R0002 - Home Base Store

Floor Coverings Res/Textile No Asbestos Found

B00M - R0003 - Home Base Store

Floor Coverings Res/Textile No Asbestos Found

B00M - R0004 - Toilets-Unisex

Floor Coverings Res/Textile No Asbestos Found

B00M - R0005 - Other-After School Care

Floor Coverings Res/Textile No Asbestos Found

B00M - R0006 - Special Programs Room

No Asbestos

B00M - R0007 - External Movement

No Asbestos

B00M - R0008 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00N - General Learning - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible
Ceiling Voids	No Asbestos Found

Interior

B00N - R0001 - Practical Activities - 1hb

Floor Coverings Res/Textile	No Asbestos Found
-----------------------------	-------------------

B00N - R0002 - Home Base Store

No Asbestos

B00N - R0003 - Home Base

No Asbestos

B00N - R0004 - Withdrawal Space - 2hb

No Asbestos

B00N - R0005 - Home Base

No Asbestos

B00N - R0006 - Home Base Store

No Asbestos

B00N - R0007 - Practical Activities - 1hb

Floor Coverings Res/Textile	No Asbestos Found
-----------------------------	-------------------

B00N - R0008 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B000 - General Learning - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible
Ceiling Voids	No Asbestos Found

Interior

B000 - R0001 - Practical Activities - 1hb

Floor Coverings Res/Textile	No Asbestos Found
-----------------------------	-------------------

B000 - R0002 - Home Base Store

No Asbestos

B000 - R0003 - Home Base

No Asbestos

B000 - R0004 - Withdrawal Space - 2hb

No Asbestos

B000 - R0005 - Home Base

No Asbestos

B000 - R0006 - Home Base Store

No Asbestos

B000 - R0007 - Practical Activities - 1hb

Floor Coverings Res/Textile	No Asbestos Found
-----------------------------	-------------------

B000 - R0008 - Practical Activities - 1hb

Floor Coverings Res/Textile	No Asbestos Found
-----------------------------	-------------------

B000 - R0009 - Home Base Store

No Asbestos

B000 - R0010 - Home Base

No Asbestos

B000 - R0011 - Home Base

No Asbestos

B000 - R0012 - Home Base Store

No Asbestos

B000 - R0013 - Practical Activities - 1hb

Floor Coverings Res/Textile	No Asbestos Found
-----------------------------	-------------------

B000 - R0014 - Withdrawal Space - 2hb

No Asbestos

B000 - R0015 - External Movement

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D13297 - Learning Unit - Standard With P.A.A. : Placement Date - 12/04/2010

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D14263 - Learning Unit - Standard With P.A.A. : Placement Date - 20/01/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 603 - D18196 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 12/03/2009

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017