


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Burnside Public School (1433)
Region : Western Sydney
State Electorate : Parramatta
Local Government Area : The Hills

Initial Survey : Noel Arnold & Associates : 03 - Apr - 2008
Reviewed By : Parsons Brinckerhoff : 07 - Feb - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning/Administration - 1922 - Brick/Veneer (Brick/Veneer)

Exterior

In-fill-panel	Compressed AC Sheet 1433/B00A/In-fill-panel/S2					No Asbestos Detected
Ceiling lining	No Asbestos Found					
Underfloor void	AC Fragments/Debris 1433/B00A/Underfloor void/S5	1m2	Throughout	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5) Chrysotile (white asbestos)

Interior

B00A - R0001 - Security Store

Floor Coverings Res/Textile	Vinyl Tiles 1433/B00A/R0001/Floor Coverings Res/Textile/S3					No Asbestos Detected
--------------------------------	---	--	--	--	--	-----------------------------

B00A - R0002 - Movement

No Asbestos

B00A - R0003 - Home Base

No Asbestos

B00A - R0004 - Home Base

No Asbestos

B00A - R0005 - Principal

No Asbestos

B00A - R0006 - Clerical Office

No Asbestos

B00A - R0007 - Movement

No Asbestos

B00A - R0010 - General Storeroom

No Asbestos

B00A - R0011 - Movement

No Asbestos

B00A - R0013 - Staff Toilet

No Asbestos

B00A - R0015 - General Storeroom

No Asbestos

B00A - R0016 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 1433/B00A/R0016/Ceiling Structures/Linings/S6	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
----------------------------	---	-----	------------	--------------------	---------	---

B00A - R0017 - Movement

No Asbestos

B00A - R0018 - Home Base

No Asbestos

B00A - R0019 - Home Base

No Asbestos

B00A - R0020 - Withdrawal Space - 1hb

No Asbestos

B00A - R0021 - Duplicating Workroom

No Asbestos

B00A - R0022 - Stairs

No Asbestos

B00A - R0023 - Stairs

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
B00A - R0024 - Stairs						
No Asbestos						
B00A - R0025 - Stairs						
No Asbestos						
B00A - R0026 - Clerical Office						
Recently Modified Space Requires Inspection						
B00A - R0027 - Staff Room						
Recently Modified Space Requires Inspection						
B00A - R0028 - Staff Kitchen						
Recently Modified Space Requires Inspection						
B00A - R1001 - Home Base						
No Asbestos						
B00A - R1002 - Home Base						
No Asbestos						
B00A - R1003 - Staff Room						
No Asbestos						
B00A - R1004 - Home Base						
No Asbestos						
B00A - R1005 - Practical Activities - 1hb						
No Asbestos						
B00A - R1006 - Movement						
No Asbestos						
B00A - R1007 - Staff Toilet						
No Asbestos						
B00A - R1008 - General Storeroom						
No Asbestos						
B00A - R1009 - Home Base						
No Asbestos						
B00A - R1010 - Home Base						
No Asbestos						
B00A - R1011 - Cleaning Supplies						
Floor Coverings Res/Textile		Vinyl Tiles				
1433/B00A/R1011/Floor Coverings Res/Textile/S4					No Asbestos Detected	
B00A - R1012 - Stairs						
No Asbestos						
B00A - R1013 - Stairs						
No Asbestos						
B00A - R1014 - Stairs						
No Asbestos						
B00A - R9001 - Withdrawal Space - 1hb						
No Asbestos						
B00A - R9002 - Movement						
No Asbestos						
B00A - R9003 - Stairs						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning/Other-After School Care - 1912 - Timber (Timber)

Exterior

Ceiling voids	No Asbestos Found					
Underfloor void	AC Fragments/Debris 1433/B00B/Underfloor void/S8					No Asbestos Detected

Interior

B00B - R0001 - External Movement

No Asbestos

B00B - R0004 - Other-After School Care

No Asbestos

B00B - R0005 - Other-After School Care

No Asbestos

B00B - R0006 - Other-After School Care

No Asbestos

B00B - R0007 - Uniform Shop

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Building Services - 1922 - Brick/Block (Brick/Block)

Exterior

Ceiling lining	No Asbestos Found
Underfloor void	No Asbestos Found

Interior

B00C - R0001 - General Assistant/Bulk Store

No Asbestos

B00C - R0002 - P.E. Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Pupil Facilities/General Learning - 1922 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found
Underfloor void	No Asbestos Found

Interior

B00F - R0001 - Drinking Facilities

Ceiling Structures/Linings	Flat AC Sheeting 1433/B00F/R0001/Ceiling Structures/Linings/S7	No Asbestos Detected
----------------------------	---	-----------------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Communal Facilities/Pupil Facilities - 1922 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling void	Non Accessible Area - No access due to height
Underfloor void	No Asbestos Found

Interior**B00H - R0002 - Staff Kitchen**

No Asbestos

B00H - R0003 - Canteen Office/Store

No Asbestos

B00H - R0004 - Communal Space

No Asbestos

B00H - R0005 - Movement

No Asbestos

B00H - R0006 - Movement

No Asbestos

B00H - R0007 - General Storeroom

No Asbestos

B00H - R0008 - General Storeroom

No Asbestos

B00H - R0009 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B001 - Pupil Facilities/Building Services - 2009 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor void	No Asbestos Found

Interior

B001 - R0001 - Toilets - Girls

No Asbestos

B001 - R0002 - Disabled Toilet

No Asbestos

B001 - R0003 - Toilets - Boys

No Asbestos

B001 - R0004 - General Storeroom

No Asbestos

B001 - R0005 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - Library - 2010 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor void	No Asbestos Found

Interior

B00J - R0001 - Reading Area

No Asbestos

B00J - R0002 - Library Office/Workroom

No Asbestos

B00J - R0003 - Communications Room

No Asbestos

B00J - R0004 - Resource/Toy Space

No Asbestos

B00J - R0005 - Access Shower/Toilet/Change

No Asbestos

B00J - R0006 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - General Learning - 2010 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor void	No Asbestos Found

Interior

B00K - R0001 - Practical Activities

No Asbestos

B00K - R0002 - Practical Activities

No Asbestos

B00K - R0003 - Home Base Store

No Asbestos

B00K - R0004 - Withdrawal Space - 2hb

No Asbestos

B00K - R0005 - Home Base

No Asbestos

B00K - R0006 - Home Base

No Asbestos

B00K - R0007 - Home Base Store

No Asbestos

B00K - R0008 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017