

# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Burwood Public School (1455)  
**Region :** South Western Sydney  
**State Electorate :** Strathfield  
**Local Government Area :** Burwood

**Initial Survey :** Noel Arnold & Associates : 18 - Jan - 2008  
**Reviewed By :** Parsons Brinckerhoff : 28 - Feb - 2017



# 2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - Library/Administration - 1879 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Void	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00A - M0001 - Communications Room**

No Asbestos

**B00A - M0002 - Movement**

No Asbestos

**B00A - M0003 - Stairs**

No Asbestos

**B00A - M0004 - Stairs**

No Asbestos

**B00A - M0005 - Stairs**

No Asbestos

**B00A - R0001 - Sick Bay**

No Asbestos

**B00A - R0002 - Movement**

No Asbestos

**B00A - R0003 - Special Programs Room**

No Asbestos

**B00A - R0004 - Movement**

No Asbestos

**B00A - R0005 - Movement**

No Asbestos

**B00A - R0006 - Main Switch Board**

No Asbestos

**B00A - R0007 - Interview**

No Asbestos

**B00A - R0008 - Staff Toilet**

No Asbestos

**B00A - R0009 - Cleaning Distributed Store**

No Asbestos

**B00A - R0010 - Movement**

No Asbestos

**B00A - R0011 - Principal**

No Asbestos

**B00A - R0012 - Entry Vestibule**

No Asbestos

**B00A - R0013 - Movement**

No Asbestos

**B00A - R0014 - Clerical Office**

No Asbestos

**B00A - R0015 - Clerical Office/Workroom**

No Asbestos

**B00A - R0016 - Reading Area**

No Asbestos

**B00A - R0017 - Reading Area**

No Asbestos

**B00A - R0018 - Reading Area**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
	No Asbestos					
	<b>B00A - R0019 - General Storeroom</b>					
	No Asbestos					
	<b>B00A - R0020 - Library Office/Workroom</b>					
	No Asbestos					
	<b>B00A - R0023 - Movement</b>					
	No Asbestos					
	<b>B00A - R0024 - Reading Area</b>					
	No Asbestos					
	<b>B00A - R0025 - Stairs</b>					
	No Asbestos					
	<b>B00A - R0026 - Stairs</b>					
	No Asbestos					
	<b>B00A - R0027 - Stairs</b>					
	No Asbestos					
	<b>B00A - R0028 - Toilet - Lobby</b>					
	No Asbestos					
	<b>B00A - R0029 - Staff Toilet</b>					
	No Asbestos					
	<b>B00A - R0030 - Staff Toilet</b>					
	No Asbestos					
	<b>B00A - R0031 - Toilet - Lobby</b>					
	No Asbestos					
	<b>B00A - R1001 - Staff Kitchen</b>					
	No Asbestos					
	<b>B00A - R1002 - Staff Room</b>					
	No Asbestos					
	<b>B00A - R1003 - Movement</b>					
	No Asbestos					
	<b>B00A - R1004 - General Assistant/Bulk Store</b>					
	No Asbestos					
	<b>B00A - R1005 - General Storeroom</b>					
	No Asbestos					
	<b>B00A - R1006 - Movement</b>					
	No Asbestos					
	<b>B00A - R1007 - Cleaning Distributed Store</b>					
	No Asbestos					
	<b>B00A - R1010 - Movement</b>					
	No Asbestos					
	<b>B00A - R1011 - Staff Room Annexe</b>					
	No Asbestos					
	<b>B00A - R1012 - Interview</b>					
	No Asbestos					
	<b>B00A - R1013 - Duplicating Workroom</b>					
	No Asbestos					
	<b>B00A - R1014 - Distribution Board</b>					Note: No inspection of live electrical installation.
	No Asbestos					
	<b>B00A - R1015 - Stairs</b>					
	No Asbestos					
	<b>B00A - R1016 - Stairs</b>					
	No Asbestos					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00A - R1017 - Staff Toilet</b>						
No Asbestos						
<b>B00A - R1018 - Toilet - Lobby</b>						
No Asbestos						
<b>B00A - R1019 - Toilet - Lobby</b>						
No Asbestos						
<b>B00A - R1020 - Staff Toilet</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - General Learning/Support Unit - 1890 - Brick/Block (Brick/Block)****Exterior**

Underfloor Voids      Non Accessible Area  
- No manhole in Building

**Interior****B00B - R0001 - Cleaning Distributed Store**

No Asbestos

**B00B - R0002 - Movement**

No Asbestos

**B00B - R0003 - Movement**

No Asbestos

**B00B - R0004 - Home Base Store**

No Asbestos

**B00B - R0005 - Practical Activities - 1hb**

No Asbestos

**B00B - R0006 - General Storeroom**

No Asbestos

**B00B - R0007 - Movement**

No Asbestos

**B00B - R0008 - Movement**

No Asbestos

**B00B - R0009 - Home Base**

No Asbestos

**B00B - R0013 - Withdrawal - S**

No Asbestos

**B00B - R0014 - Toilets - Girls**

Partition Walls (Cubicles)	Compressed AC Sheet	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1455/B00B/R0042/Partition Walls (Cubicles)/S1						<b>Chrysotile (white asbestos)</b>

**B00B - R0015 - Uniform Shop**

No Asbestos

**B00B - R0016 - Personal Effects Storage**

No Asbestos

**B00B - R0017 - Movement**

No Asbestos

**B00B - R0018 - Toilets - Boys**

Partition Walls (Cubicles)	Compressed AC Sheet	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1455/B00B/R0042/Partition Walls (Cubicles)/S1						<b>Chrysotile (white asbestos)</b>

**B00B - R0019 - Movement**

No Asbestos

**B00B - R0020 - Practical Activities - 1hb**

No Asbestos

**B00B - R0021 - Home Base**

No Asbestos

**B00B - R0022 - Withdrawal Space - 1hb**

No Asbestos

**B00B - R0023 - Movement**

No Asbestos

**B00B - R0025 - Movement**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00B - R0026 - Security Store</b>						
No Asbestos						
<b>B00B - R0027 - Staff Toilet</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1455/B00B/R0027/Partition Walls (Cubicles)/S2					<b>Chrysotile (white asbestos)</b>	
<b>B00B - R0028 - Home Base</b>						
No Asbestos						
<b>B00B - R0029 - Withdrawal Space - 1hb</b>						
No Asbestos						
<b>B00B - R0030 - Movement</b>						
No Asbestos						
<b>B00B - R0031 - Movement</b>						
No Asbestos						
<b>B00B - R0032 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00B - R0033 - Movement</b>						
No Asbestos						
<b>B00B - R0034 - Movement</b>						
No Asbestos						
<b>B00B - R0035 - Cleaning Distributed Store</b>						
No Asbestos						
<b>B00B - R0036 - Home Base Store</b>						
No Asbestos						
<b>B00B - R0037 - Home Base</b>						
No Asbestos						
<b>B00B - R0038 - Withdrawal Space - 1hb</b>						
No Asbestos						
<b>B00B - R0039 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00B - R0040 - Distribution Board</b>					Note: No inspection of live electrical installation.	
No Asbestos						
<b>B00B - R0041 - Toilets - Boys</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1455/B00B/R0042/Partition Walls (Cubicles)/S1					<b>Chrysotile (white asbestos)</b>	
<b>B00B - R0042 - Toilets - Girls</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1455/B00B/R0042/Partition Walls (Cubicles)/S1					<b>Chrysotile (white asbestos)</b>	
<b>B00B - R0043 - Movement</b>						
No Asbestos						
<b>B00B - R0044 - Special Programs Room</b>						
No Asbestos						
<b>B00B - R0045 - Special Programs Room</b>						
No Asbestos						
<b>B00B - R0047 - Toilets - Boys/Girls</b>						
No Asbestos						
<b>B00B - R0049 - Movement</b>						
No Asbestos						
<b>B00B - R0050 - Movement</b>						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00B - R0051 - Movement</b>						
No Asbestos						
<b>B00B - R0052 - Home Base Store</b>						
No Asbestos						
<b>B00B - R0053 - Practical Activities - M - 1hb</b>						
No Asbestos						
<b>B00B - R0054 - Staff Room Annexe</b>						
No Asbestos						
<b>B00B - R0055 - Movement</b>						
No Asbestos						
<b>B00B - R0056 - Home Base</b>						
No Asbestos						
<b>B00B - R0057 - Movement</b>						
No Asbestos						
<b>B00B - R0058 - Stairs</b>						
No Asbestos						
<b>B00B - R0059 - Stairs</b>						
No Asbestos						
<b>B00B - R0060 - Stairs</b>						
No Asbestos						
<b>B00B - R0061 - Stairs</b>						
No Asbestos						
<b>B00B - R0062 - Raised Platform</b>						
No Asbestos						
<b>B00B - R0063 - Movement</b>						
No Asbestos						
<b>B00B - R0064 - Home Base</b>						
No Asbestos						
<b>B00B - R0065 - Home Base</b>						
No Asbestos						
<b>B00B - R1001 - Movement</b>						
No Asbestos						
<b>B00B - R1002 - Distribution Board</b>						
No Asbestos					Note: No inspection of live electrical installation.	
<b>B00B - R1003 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00B - R1004 - Movement</b>						
No Asbestos						
<b>B00B - R1005 - Home Base</b>						
No Asbestos						
<b>B00B - R1006 - Withdrawal Space - 1hb</b>						
No Asbestos						
<b>B00B - R1007 - Home Base Store</b>						
No Asbestos						
<b>B00B - R1008 - Home Base</b>						
No Asbestos						
<b>B00B - R1009 - General Storeroom</b>						
No Asbestos						
<b>B00B - R1010 - Movement</b>						
No Asbestos						
<b>B00B - R1012 - Home Base</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No						Test Result
No Asbestos						
<b>B00B - R1013 - Staff Room Annexe</b>						
No Asbestos						
<b>B00B - R1014 - Home Base Store</b>						
No Asbestos						
<b>B00B - R1016 - Movement</b>						
No Asbestos						
<b>B00B - R1017 - Security Store</b>						
No Asbestos						
<b>B00B - R1018 - Movement</b>						
No Asbestos						
<b>B00B - R1019 - Home Base</b>						
No Asbestos						
<b>B00B - R1020 - Withdrawal Space - 1hb</b>						
No Asbestos						
<b>B00B - R1021 - Home Base Store</b>						
No Asbestos						
<b>B00B - R1022 - Home Base</b>						
No Asbestos						
<b>B00B - R1023 - Deputy Principal</b>						
No Asbestos						
<b>B00B - R1024 - Toilets - Girls</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1455/B00B/R1029/Partition Walls (Cubicles)/S4						<b>Chrysotile (white asbestos)</b>
<b>B00B - R1025 - Cleaning Distributed Store</b>						
No Asbestos						
<b>B00B - R1026 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00B - R1027 - Distribution Board</b>						Note: No inspection of live electrical installation.
No Asbestos						
<b>B00B - R1028 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00B - R1029 - Toilets - Boys</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1455/B00B/R1029/Partition Walls (Cubicles)/S4						<b>Chrysotile (white asbestos)</b>
<b>B00B - R1030 - Withdrawal Space - 1hb</b>						
No Asbestos						
<b>B00B - R1031 - Personal Effects Storage</b>						
No Asbestos						
<b>B00B - R1032 - Home Base Store</b>						
No Asbestos						
<b>B00B - R1033 - Home Base</b>						
No Asbestos						
<b>B00B - R1034 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00B - R1036 - Stairs</b>						
No Asbestos						
<b>B00B - R1037 - Stairs</b>						
No Asbestos						
<b>B00B - R1038 - Stairs</b>						



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	<b>Sample No</b>					<b>Test Result</b>

No Asbestos

**B00B - R1039 - Stairs**

No Asbestos

**B00B - R1040 - Practical Activities/Movement - 1hb**

No Asbestos

**B00B - R1041 - Practical Activities/Movement - 1hb**

No Asbestos

**B00B - R1042 - Raised Platform**

No Asbestos

**B00B - R1043 - Home Base**

No Asbestos

**B00B - R1044 - Practical Activities - 1hb**

No Asbestos

**B00B - R1045 - Home Base**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

**B00C - General Learning - 1917 - Timber (Timber)****Exterior**

No Asbestos

**Interior****B00C - R0001 - General Storeroom**

Ceiling Structures/Linings	Flat AC Sheeting	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1455/B00C/R0005/Ceiling Structures/Linings/S7			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

Wall Linings Internal	Flat AC Sheeting	20m2	All surfaces, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1455/B00C/R0005/Wall Linings Internal/S6			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00C - R0002 - Home Base**

Ceiling Structures/Linings	Flat AC Sheeting	83m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1455/B00C/R0005/Ceiling Structures/Linings/S7			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

Wall Linings Internal	Flat AC Sheeting	60m2	All surfaces, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1455/B00C/R0005/Wall Linings Internal/S6			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00C - R0003 - Craft Store**

Wall Linings Internal	Flat AC Sheeting	20m2	All surfaces, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1455/B00C/R0005/Wall Linings Internal/S6			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

Ceiling Structures/Linings	Flat AC Sheeting	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1455/B00C/R0005/Ceiling Structures/Linings/S7			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

Floor Coverings Res/Textile	Vinyl Sheet					
	1455/B00C/R0005/Floor Coverings Res/Textile/S8			<b>No Asbestos Detected</b>		

**B00C - R0004 - General Storeroom**

Wall Linings Internal	Flat AC Sheeting	15m2	All surfaces, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1455/B00C/R0005/Wall Linings Internal/S6			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

Ceiling Structures/Linings	Flat AC Sheeting	13m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1455/B00C/R0005/Ceiling Structures/Linings/S7			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

Floor Coverings Res/Textile	Vinyl Sheet					
	1455/B00C/R0005/Floor Coverings Res/Textile/S8			<b>No Asbestos Detected</b>		

**B00C - R0005 - Sports Store**

Wall Linings Internal	Flat AC Sheeting	15m2	All surfaces, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1455/B00C/R0005/Wall Linings Internal/S6			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

Ceiling Structures/Linings	Flat AC Sheeting	17m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1455/B00C/R0005/Ceiling Structures/Linings/S7			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

Floor Coverings Res/Textile	Vinyl Sheet					
	1455/B00C/R0005/Floor Coverings Res/Textile/S8			<b>No Asbestos Detected</b>		

**B00C - R0006 - Movement**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1455/B00C/R0005/Ceiling Structures/Linings/S7				Chrysotile (white asbestos) , Amosite (brown asbestos)		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - Pupil Facilities - 1965 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids - Slab on Ground      No Asbestos Found

**Interior**

**B00D - R0001 - Toilets - Boys**

No Asbestos

**B00D - R0002 - Toilets - Girls**

No Asbestos

**B00D - R0003 - Toilets - Girls**

No Asbestos

**B00D - R0004 - Cleaning Distributed Store**

No Asbestos

**B00D - R0005 - Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - Pupil Facilities - 1955 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids - Raked Ceiling      No Asbestos Found

Underfloor Voids - Slab on Ground      No Asbestos Found

**Interior**

**B00F - R0001 - Drinking Facilities**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - General Learning - 2005 - Fibre Cement Clad (Fibre Cement Clad)**

**Exterior**

Ceiling Voids                      No Asbestos Found

**Interior**

**B00G - R0001 - Movement**

No Asbestos

**B00G - R0002 - Practical Activities - 1hb**

No Asbestos

**B00G - R0003 - Home Base Store**

Vinyl Tiles (Under Floor      No Asbestos Found  
Covering/Carpet)

**B00G - R0004 - Home Base**

Vinyl Tiles (Under Floor      No Asbestos Found  
Covering/Carpet)

**B00G - R0005 - Withdrawal Space - 2hb**

Vinyl Tiles (Under Floor      No Asbestos Found  
Covering/Carpet)

**B00G - R0006 - Home Base**

Vinyl Tiles (Under Floor      No Asbestos Found  
Covering/Carpet)

**B00G - R0007 - Home Base Store**

Vinyl Tiles (Under Floor      No Asbestos Found  
Covering/Carpet)

**B00G - R0008 - Practical Activities - 1hb**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00H - Communal Facilities - 2010 - Brick/Veneer (Brick/Veneer)****Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

**Interior****B00H - R0001 - Communal Space**

No Asbestos

**B00H - R0002 - Raised Platform**

No Asbestos

**B00H - R0003 - Toilet - Lobby**

No Asbestos

**B00H - R0004 - Toilets - Boys**

No Asbestos

**B00H - R0005 - P.E. Store**

No Asbestos

**B00H - R0006 - Movement**

No Asbestos

**B00H - R0007 - Communal/Performance Store**

No Asbestos

**B00H - R0008 - Ramp**

No Asbestos

**B00H - R0010 - Hall Chair Store**

No Asbestos

**B00H - R0011 - Movement**

No Asbestos

**B00H - R0012 - Cleaning Distributed Store**

No Asbestos

**B00H - R0013 - No Access**

No Asbestos

**B00H - R0014 - Toilet - Lobby**

No Asbestos

**B00H - R0015 - Toilets - Girls**

No Asbestos

**B00H - R0016 - Sound Cupboard**

No Asbestos

**B00H - R0017 - Access Shower/Toilet/Change**

No Asbestos

**B00H - R0018 - No Access**

No Asbestos

**B00H - R0019 - External Movement**

No Asbestos

**B00H - R0020 - Canteen Office/Store**

No Asbestos

**B00H - R0021 - Canteen**

No Asbestos

**B00H - R0022 - Movement**

No Asbestos

**B00H - R0023 - Movement**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

## Demountables

**Demountable details as per the AMS records as of 15 Feb 2017.**

**OS 601 - D10794 - Learning Unit - Standard/Withdrawal : Placement Date - 31/07/2007**

### Exterior

Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

### Interior

#### R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

#### R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

#### R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2
---------	---------------	------------------	-------

**OS 602 - D11079 - Learning Unit - Standard With P.A.A. : Placement Date - 24/12/2013**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

### Exterior

No Asbestos Found.

### Interior

#### R1 - Learning space/withdrawal/entry

No Asbestos Found.

#### R2 - Home Base Store

No Asbestos Found.

**OS 603 - D11615 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 9/11/2004**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

### Exterior

No Asbestos Found.

### Interior

#### R1 - Learning space/withdrawal/entry

No Asbestos Found.

#### R2 - Home Base Store

No Asbestos Found.

**OS 751 - D11929 - Learning Unit - ESL : Placement Date - 3/02/1999**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

### Exterior

No Asbestos Found.

### Interior

#### R1 - Esl

No Asbestos Found.

#### R2 - Esl

No Asbestos Found.

**OS 603 - D12763 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 24/10/2009**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

### Exterior



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 603 - D12764 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 24/10/2009**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 602 - D13871 - Learning Unit - Standard With P.A.A. : Placement Date - 3/12/2013**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 601 - D14700 - Learning Unit - Standard/Withdrawal : Placement Date - 11/09/2008**

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Entry**

No Asbestos Found.

**R2 - General Learning Space**

No Asbestos Found.

**R3 - Store**

No Asbestos Found.

**OS 601 - D14847 - Learning Unit - Standard/Withdrawal : Placement Date - 9/02/2004**

**Exterior**

Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>Interior</b>						
<b>R1 - Entry</b>						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
<b>R2 - General Learning Space</b>						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
<b>R3 - Store</b>						
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2
<b>OS 601 - D16249 - Learning Unit - Standard/Withdrawal : Placement Date - 27/03/2001</b>						
<b>Exterior</b>						
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
<b>Interior</b>						
<b>R1 - Entry</b>						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
<b>R2 - General Learning Space</b>						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
<b>R3 - Store</b>						
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Listing of Electronic Attachments as of 22/03/2017***

**Available Asbestos Related Electronic Files**

1455\_ASB\_010313\_AMP.pdf

\* Note : Refer to AMS for details of the attachment(s).

2017