


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Bonnells Bay Public School (2532)  
**Region :** Hunter/Central Coast  
**State Electorate :** Lake Macquarie  
**Local Government Area :** Lake Macquarie

**Initial Survey :** Noel Arnold & Associates : 22 - Apr - 2008  
**Reviewed By :** AECOM : 29 - Jun - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - Administration/Staff Facilities - 1994 - Brick/Veneer (Brick/Veneer)****Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible
Ceiling Voids	No Asbestos Found

**Interior****B00A - R0001 - External Movement**

No Asbestos

**B00A - R0002 - Clerical Office**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0003 - Principal**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0004 - Staff Room Annexe**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0005 - Cleaning Distributed Store**

No Asbestos

**B00A - R0006 - Staff Room Annexe**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0007 - Staff Room Annexe**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0008 - Staff Room**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0009 - Movement**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0010 - Staff Toilet**

No Asbestos

**B00A - R0011 - Staff Toilet**

No Asbestos

**B00A - R0012 - Staff Toilet**

No Asbestos

**B00A - R0013 - Security Store**

No Asbestos

**B00A - R0014 - Duplicating Workroom**

No Asbestos

**B00A - R0015 - Distribution Board**

No Asbestos

Note: No inspection of live electrical installation.

**B00A - R0016 - Sick Bay - Shower/Toilet**

No Asbestos

**B00A - R0017 - Sick Bay**

No Asbestos

**B00A - R0018 - Interview**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0019 - Entry Vestibule**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - R0020 - Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - Pupil Facilities - 1960 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
Eaves Linings	Flat AC Sheeting 2532/B00B/Eaves Linings/S1					<b>No Asbestos Detected</b>

**Interior**

**B00B - R0001 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting 2532/B00B/Eaves Linings/S1					<b>No Asbestos Detected</b>
----------------------------	--	--	--	--	--	-----------------------------

**B00B - R0002 - Canteen**

No Asbestos

**B00B - R0003 - Canteen**

No Asbestos

**B00B - R0004 - Staff Toilet**

No Asbestos

**B00B - R0005 - Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

### B00C - Communal Facilities/Building Services - 1994 - Brick/Block (Brick/Block)

#### Exterior

Underfloor Voids - Slab on Ground      Non Accessible Area  
- Area inaccessible

Ceiling Voids      No Asbestos Found

#### Interior

##### B00C - R0001 - Drinking Facilities

No Asbestos

##### B00C - R0002 - Disabled Toilet

No Asbestos

##### B00C - R0003 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

##### B00C - R0004 - Plant

No Asbestos

##### B00C - R0005 - Plant

No Asbestos

##### B00C - R0006 - Communal Space

No Asbestos

##### B00C - R0007 - General Storeroom

No Asbestos

##### B00C - R0008 - Cleaning Supplies

No Asbestos

##### B00C - R0009 - P.E. Store

No Asbestos

##### B00C - R0010 - Hall Chair Store

No Asbestos

##### B00C - R0011 - Raised Platform

No Asbestos

##### B00C - R0012 - Cleaning Distributed Store

No Asbestos

##### B00C - R0013 - Shower/Change

No Asbestos

##### B00C - R0014 - Toilets - Girls

No Asbestos

##### B00C - R0015 - Movement

No Asbestos

##### B00C - R0016 - Toilets - Boys

No Asbestos

##### B00C - R0017 - External Movement

No Asbestos

##### B00C - R9001 - Sports Store

No Asbestos

##### B00C - R9002 - Garden Store

No Asbestos

##### B00C - R9003 - General Assistant/Bulk Store

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - Library/Tiered Learning - 1994 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Packing to Floor Joists	No Asbestos Found
Ceiling Voids	No Asbestos Found

**Interior**

**B00D - R0001 - Movement**

No Asbestos

**B00D - R0002 - Plant**

No Asbestos

**B00D - R0003 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00D - R0004 - Special Programs Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00D - R0005 - Special Programs Room**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00D - R0006 - K.L.A. Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00D - R0007 - Library Office/Workroom**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00D - R0008 - Reading Area**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00D - R0009 - External Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - Pupil Facilities/Building Services - 1950 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids - Packing to Floor Joists	No Asbestos Found
Ceiling Voids - Raked Ceiling	Non Accessible Area - Area inaccessible no void entrance located

**Interior**

**B00E - R0001 - Toilets - Boys**

No Asbestos

**B00E - R0002 - Toilets - Girls**

No Asbestos

**B00E - R0003 - External Movement**

No Asbestos

**B00E - R0004 - Cleaning Distributed Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - General Learning - 1994 - Brick/Veneer (Brick/Veneer)****Exterior**

Underfloor Voids - Packing to Floor Joists      No Asbestos Found

Ceiling Voids      No Asbestos Found

**Interior****B00F - R0001 - External Movement**

No Asbestos

**B00F - R0002 - Practical Activities - 1hb**

No Asbestos

**B00F - R0003 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00F - R0004 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00F - R0005 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00F - R0006 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00F - R0007 - Practical Activities - 1hb**

No Asbestos

**B00F - R0008 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00F - R0009 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00F - R0010 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00F - R0011 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00F - R0012 - Practical Activities - 1hb**

No Asbestos

**B00F - R0013 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00F - R0014 - Cleaning Distributed Store**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - General Learning/Building Services - 1994 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Packing to Floor Joists	No Asbestos Found
Ceiling Voids	No Asbestos Found

**Interior**

**B00G - R0001 - Cleaning Distributed Store**

No Asbestos

**B00G - R0002 - External Movement**

No Asbestos

**B00G - R0003 - Practical Activities - 1hb**

No Asbestos

**B00G - R0004 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00G - R0005 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00G - R0006 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00G - R0007 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00G - R0008 - Practical Activities - 1hb**

No Asbestos

**B00G - R0009 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00G - R0010 - Distribution Board**

Note: No inspection of live electrical installation.

Non Accessible	Resinous Board	0.5m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------	----------------	-------	---------------	--------------------	---------	--------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - General Learning - 1994 - Brick/Veneer (Brick/Veneer)****Exterior**

Underfloor Voids - Packing to Floor Joists      No Asbestos Found

Ceiling Voids      No Asbestos Found

**Interior****B00H - R0001 - External Movement**

No Asbestos

**B00H - R0002 - Practical Activities - 1hb**

No Asbestos

**B00H - R0003 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00H - R0004 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00H - R0005 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00H - R0006 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00H - R0007 - Practical Activities - 1hb**

No Asbestos

**B00H - R0008 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00H - R0009 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00H - R0010 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00H - R0011 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00H - R0012 - Practical Activities - 1hb**

No Asbestos

**B00H - R0013 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00I - General Learning - 1994 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Packing to Floor Joists	No Asbestos Found
Ceiling Voids	No Asbestos Found

**Interior**

**B00I - R0001 - External Movement**

No Asbestos

**B00I - R0002 - Kiln Room**

No Asbestos

**B00I - R0003 - Practical Activities - 1hb**

No Asbestos

**B00I - R0004 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00I - R0005 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00I - R0006 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00I - R0007 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00I - R0008 - Practical Activities - 1hb**

No Asbestos

**B00I - R0009 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00I - R0010 - Main Switch Board**

Electrical Mounting Board	Resinous Board	2Unit	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
---------------------------	----------------	-------	------------	--------------------	---------	--------------------

**Assumed Asbestos - Electrical Hazard**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00J - Multi Purpose Facilities - 2007 - Steel (Steel)**

**Exterior**

Underfloor Voids - Packing to Floor Joists	No Asbestos Found
Ceiling Voids	No Asbestos Found

**Interior**

**B00J - R0001 - Special Programs Room**

No Asbestos

**B00J - R0002 - Special Programs Store**

No Asbestos

**B00J - R0003 - Special Programs Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00K - Shed - 1965 - Metal Shed (Metal Shed)**

**Exterior**

Ceiling Void	Requires Inspection
Underfloor Void	Requires Inspection

**Interior**

**B00K - R0001 - Garden Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00L - General Learning/Building Services - 2010 - Brick/Veneer (Brick/Veneer)****Exterior**

Underfloor Voids - Packing to Floor Joists      No Asbestos Found

Ceiling Voids      No Asbestos Found

**Interior****B00L - R0001 - Special Programs Room**

No Asbestos

**B00L - R0002 - Special Programs Store**

No Asbestos

**B00L - R0003 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00L - R0004 - Practical Activities - 1hb**

No Asbestos

**B00L - R0005 - Home Base Store**

No Asbestos

**B00L - R0006 - Home Base**

No Asbestos

**B00L - R0007 - Withdrawal Space - 2hb**

No Asbestos

**B00L - R0008 - Practical Activities - 1hb**

No Asbestos

**B00L - R0009 - Home Base**

No Asbestos

**B00L - R0010 - Home Base Store**

No Asbestos

**B00L - R0011 - Practical Activities - 1hb**

No Asbestos

**B00L - R0012 - Home Base Store**

No Asbestos

**B00L - R0013 - Home Base**

No Asbestos

**B00L - R0014 - Withdrawal Space - 2hb**

No Asbestos

**B00L - R0015 - Practical Activities - 1hb**

No Asbestos

**B00L - R0016 - Home Base**

No Asbestos

**B00L - R0017 - Home Base Store**

No Asbestos

**B00L - R0018 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00L - R0019 - Sports Store**

No Asbestos

**B00L - R0020 - General Assistant/Bulk Store**

No Asbestos

**B00L - R0021 - Garden Store**

No Asbestos

**B00L - R0022 - External Movement**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Demountables**

**Demountable details as per the AMS records as of 15 Feb 2017.**

**OS 603 - D10687 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 28/07/2015**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 602 - D11547 - Learning Unit - Standard With P.A.A. : Placement Date - 11/01/2016**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 602 - D14852 - Learning Unit - Standard With P.A.A. : Placement Date - 18/06/2013**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 603 - D15110 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 11/12/2014**

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017