

# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Bald Face Public School (3794)  
**Region :** Sydney  
**State Electorate :** Oatley  
**Local Government Area :** Kogarah

**Initial Survey :** Noel Arnold & Associates : 30 - Mar - 2008  
**Reviewed By :** Parsons Brinckerhoff : 01 - Nov - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - General Learning/Library - 1948 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting 3794/B00A/Eaves Linings/S7	40m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
Gable Verge Lining	Flat AC Sheeting 3794/B00A/Gable Verge Lining/S9	20m	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
Ceiling Void	No Asbestos Found					
Underfloor Void	No Asbestos Found					

**Interior**

**B00A - R0001 - External Movement**

No Asbestos

**B00A - R0002 - Toilets - Boys**

No Asbestos

**B00A - R0003 - Disabled Toilet**

Shelf	Flat AC Sheeting 3794/B00A/R0003/Shelf/S2					<b>No Asbestos Detected</b>
-------	--	--	--	--	--	-----------------------------

**B00A - R0004 - Toilets - Girls**

No Asbestos

**B00A - R0005 - Home Base**

No Asbestos

**B00A - R0006 - Home Base Store**

No Asbestos

**B00A - R0007 - Home Base Store**

No Asbestos

**B00A - R0008 - Movement**

No Asbestos

**B00A - R0010 - Home Base**

No Asbestos

**B00A - R0016 - External Movement**

No Asbestos

**B00A - R0017 - Reading Area**

No Asbestos

**B00A - R0018 - Communications Room**

No Asbestos

**B00A - R0019 - Library Office/Workroom**

No Asbestos

**B00A - R0020 - External Movement**

No Asbestos

**B00A - R0021 - Home Base**

No Asbestos

**B00A - R0022 - Practical Activities - 1hb**

No Asbestos

**B00A - R0023 - Home Base Store**

No Asbestos

**B00A - R0024 - Communications Room**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - Administration/General Learning - 1948 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting 3794/B00B/Eaves Linings/S8	50m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Gable Verge Lining	Flat AC Sheeting 3794/B00B/Gable Verge Lining/S10	20m	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Ceiling Void	No Asbestos Found					
Underfloor Void	No Asbestos Found					

**Interior**

**B00B - R0002 - Canteen**

No Asbestos

**B00B - R0003 - Staff Toilet**

No Asbestos

**B00B - R0004 - Security Store**

No Asbestos

**B00B - R0005 - Duplicating Workroom**

No Asbestos

**B00B - R0006 - Movement**

No Asbestos

**B00B - R0007 - Staff Room Annex**

No Asbestos

**B00B - R0008 - Home Base**

Wall Linings Internal	Flat AC Sheeting 3794/B00B/R0012/Wall Linings Internal/S3	2m2	West facing, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
				<b>Chrysotile (white asbestos)</b>		

**B00B - R0009 - Practical Activities - 1hb**

No Asbestos

**B00B - R0010 - Home Base Store**

No Asbestos

**B00B - R0011 - Personal Effects Storage**

No Asbestos

**B00B - R0012 - Home Base**

Wall Linings Internal	Flat AC Sheeting 3794/B00B/R0012/Wall Linings Internal/S3	2m2	East facing, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
				<b>Chrysotile (white asbestos)</b>		

**B00B - R0013 - Practical Activities - 1hb**

No Asbestos

**B00B - R0014 - Home Base Store**

No Asbestos

**B00B - R0015 - Cleaning Supplies**

No Asbestos

**B00B - R0016 - External Movement**

No Asbestos

**B00B - R0017 - Entry Vestibule**

No Asbestos

**B00B - R0018 - Movement**

Manhole in Ceiling	Flat AC Sheeting 3794/B00B/R0018/Manhole in Ceiling/S11					<b>No Asbestos Detected</b>
--------------------	--	--	--	--	--	-----------------------------

**B00B - R0019 - Clerical Office/Workroom**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

**B00B - R0020 - Sick Bay**

No Asbestos

**B00B - R0021 - Staff Shower/Change**

Wall Linings Internal	Flat AC Sheeting					
	3794/B00B/R0021/Wall Linings Internal/S6					<b>No Asbestos Detected</b>

Ceiling Structures/Linings	Flat AC Sheeting					
	3794/B00B/R0021/Wall Linings Internal/S6					<b>No Asbestos Detected</b>

**B00B - R0022 - Staff Toilet**

Wall Linings Internal	Flat AC Sheeting					
	3794/B00B/R0021/Wall Linings Internal/S6					<b>No Asbestos Detected</b>

Ceiling Structures/Linings	Flat AC Sheeting					
	3794/B00B/R0021/Wall Linings Internal/S6					<b>No Asbestos Detected</b>

**B00B - R0023 - Principal**

No Asbestos

**B00B - R0024 - Staff Room**

No Asbestos

**B00B - R0028 - External Movement**

No Asbestos

**B00B - R0029 - General Storeroom**

No Asbestos

**B00B - R0030 - External Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - Pupil Facilities - 1974 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Void	No Asbestos Found

**Interior**

**B00G - R0001 - Garden Store**

No Asbestos

**B00G - R0002 - Drinking Facilities**

No Asbestos

**B00G - R0003 - External Movement**

No Asbestos

**B00G - R0004 - Toilets - Boys**

No Asbestos

**B00G - R0005 - Toilets - Girls**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

### B00H - Communal Facilities/General Learning - 1997 - Brick/Block (Brick/Block)

#### Exterior

Underfloor Voids - Slab on Ground      No Asbestos Found

Ceiling Voids      No Asbestos Found

#### Interior

##### B00H - R0001 - External Movement

No Asbestos

##### B00H - R0002 - External Movement

No Asbestos

##### B00H - R0004 - Raised Platform

No Asbestos

##### B00H - R0005 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

##### B00H - R0006 - Plant

No Asbestos

##### B00H - R0007 - Hall Chair Store

No Asbestos

##### B00H - R0008 - Shower/Change

No Asbestos

##### B00H - R0009 - Toilets - Girls

No Asbestos

##### B00H - R0010 - External Movement

No Asbestos

##### B00H - R0011 - External Movement

No Asbestos

##### B00H - R0012 - Uniform Shop

No Asbestos

##### B00H - R0013 - Toilets - Boys

No Asbestos

##### B00H - R0014 - General Assistant/Bulk Store

No Asbestos

##### B00H - R0015 - Sports Store

No Asbestos

##### B00H - R0016 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

##### B00H - R0017 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

##### B00H - R0018 - Practical Activities - 1hb

No Asbestos

##### B00H - R0019 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

##### B00H - R0020 - Practical Activities - 1hb

No Asbestos

##### B00H - R0021 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

##### B00H - R0022 - Home Base Store

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00H - R0023 - Garden Store**

No Asbestos

**B00H - R0024 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00H - R0025 - Movement**

No Asbestos

**B00H - R0026 - Movement**

No Asbestos

**B00H - R0027 - Communal Space**

No Asbestos

**B00H - R0028 - Movement**

No Asbestos

**B00H - R0029 - Plant**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00I - General Learning - 2010 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00I - R0001 - Home Base**

No Asbestos

**B00I - R0002 - Home Base Store**

No Asbestos

**B00I - R0003 - Practical Activities - 1hb**

No Asbestos

**B00I - R0004 - Withdrawal Space - 2hb**

No Asbestos

**B00I - R0005 - Home Base**

No Asbestos

**B00I - R0006 - Home Base Store**

No Asbestos

**B00I - R0007 - Practical Activities - 1hb**

No Asbestos

**B00I - R0008 - External Movement**

No Asbestos

**B00I - R0009 - Home Base**

No Asbestos

**B00I - R0010 - Home Base Store**

No Asbestos

**B00I - R0011 - Practical Activities - 1hb**

No Asbestos

**B00I - R0012 - Withdrawal Space - 2hb**

No Asbestos

**B00I - R0013 - Home Base**

No Asbestos

**B00I - R0014 - Home Base Store**

No Asbestos

**B00I - R0015 - Practical Activities - 1hb**

No Asbestos

**B00I - R0016 - External Movement**

No Asbestos

**B00I - R0017 - External Movement**

No Asbestos





Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Demountables***

**There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017