

# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Blacktown West Public School (4116)  
**Region :** Western Sydney  
**State Electorate :** Blacktown  
**Local Government Area :** Blacktown

**Initial Survey :** Noel Arnold & Associates : 05 - Apr - 2008  
**Reviewed By :** Parsons Brinckerhoff : 01 - Nov - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - Library/Building Services - 1957 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Eaves Linings	Flat AC Sheeting	30m2	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4116/B00C/Eaves Linings/S27				<b>Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)</b>	
Panels Under Windows	Flat AC Sheeting	12Unit(s)	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4116/B00A/R0011/Panel below window/S2				<b>Chrysotile (white asbestos)</b>	
Ceiling Void	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior**

**B00A - R0001 - Staff Kitchen**

No Asbestos

**B00A - R0002 - Security Store**

No Asbestos

**B00A - R0003 - Library Office/Workroom**

No Asbestos

**B00A - R0004 - Reading Area**

No Asbestos

**B00A - R0005 - Reading Area**

No Asbestos

**B00A - R0006 - K.L.A. Store**

No Asbestos

**B00A - R0007 - K.L.A. Store**

No Asbestos

**B00A - R0008 - Library Office/Workroom**

No Asbestos

**B00A - R0009 - Movement**

No Asbestos

**B00A - R0010 - Reading Area**

No Asbestos

**B00A - R0011 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	55m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4116/B00A/R0011/Ceiling Structures/Linings/S1				<b>Chrysotile (white asbestos)</b>	
Panels Below Windows	Flat AC Sheeting	12Unit(s)	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4116/B00A/R0011/Panel below window/S2				<b>Chrysotile (white asbestos)</b>	

**B00A - R9001 - General Storeroom**

No Asbestos

**B00A - R9002 - Security Store**

No Asbestos

**B00A - R9003 - General Assistant/Bulk Store**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - General Learning - 1957 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Eaves Linings	Flat AC Sheeting	50m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4116/B00C/Eaves Linings/S27					<b>Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)</b>
Ceiling Void	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior**

**B00B - R0002 - Home Base Store**

No Asbestos

**B00B - R0003 - Home Base Store**

No Asbestos

**B00B - R0006 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	5m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4116/B00B/R0006/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>
Panels Above Door	Flat AC Sheeting	1m2	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4116/B00B/R0006/panels above door/S11					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00B - R0007 - Home Base**

No Asbestos

**B00B - R0008 - General Storeroom**

No Asbestos

**B00B - R0009 - Staff Room Annexe**

No Asbestos

**B00B - R0010 - Movement**

No Asbestos

**B00B - R0011 - Movement**

Panels Above Door	Flat AC Sheeting	1m2	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4116/B00B/R0006/panels above door/S11					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting	5m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4116/B00B/R0006/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>

**B00B - R0012 - Home Base**

No Asbestos

**B00B - R0013 - Home Base Store**

No Asbestos

**B00B - R0014 - Home Base Store**

No Asbestos

**B00B - R0015 - Personal Effects Storage**

No Asbestos

**B00B - R0016 - Movement**

No Asbestos

**B00B - R0017 - General Storeroom**

No Asbestos

**B00B - R0018 - Movement**

Panels Above Door	Flat AC Sheeting	1m2	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4116/B00B/R0006/panels above door/S11					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00B - R0019 - General Storeroom</b>						
No Asbestos						
<b>B00B - R0020 - Home Base</b>						
No Asbestos						
<b>B00B - R0021 - Movement</b>						
No Asbestos						
<b>B00B - R0022 - Special Programs Room</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - General Learning - 1957 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Eaves Linings	Flat AC Sheeting	50m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4116/B00C/Eaves Linings/S27					<b>Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)</b>
Ceiling Void	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior**

**B00C - R0001 - Home Base**

No Asbestos

**B00C - R0002 - General Storeroom**

No Asbestos

**B00C - R0003 - Movement**

Panels Above Door	Flat AC Sheeting	1m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4116/B00B/R0006/panels above door/S11					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00C - R0004 - General Storeroom**

No Asbestos

**B00C - R0005 - Movement**

No Asbestos

**B00C - R0006 - Personal Effects Storage**

No Asbestos

**B00C - R0007 - Home Base Store**

No Asbestos

**B00C - R0008 - Home Base Store**

No Asbestos

**B00C - R0009 - Home Base**

No Asbestos

**B00C - R0010 - Home Base**

No Asbestos

**B00C - R0011 - Home Base Store**

No Asbestos

**B00C - R0012 - General Storeroom**

No Asbestos

**B00C - R0013 - Personal Effects Storage**

No Asbestos

**B00C - R0014 - Movement**

No Asbestos

**B00C - R0015 - General Storeroom**

No Asbestos

**B00C - R0016 - Movement**

Panel above door	Flat AC Sheeting	1m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4116/B00C/R0016/Panel above door/S12					<b>Chrysotile (white asbestos)</b>

**B00C - R0017 - General Storeroom**

No Asbestos

**B00C - R0018 - Home Base**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - Administration/Staff Facilities - 1957 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Eaves Linings	Flat AC Sheeting	50m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4116/B00C/Eaves Linings/S27				<b>Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)</b>	
Ceiling Void	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior**

**B00D - R0001 - Clerical Office/Workroom**

No Asbestos

**B00D - R0002 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	2m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4116/B00B/R0006/Ceiling Structures/Linings/S3				<b>Chrysotile (white asbestos)</b>	
Panels above door	Flat AC Sheeting	1m2	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4116/B00B/R0006/panels above door/S11				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	

**B00D - R0004 - Movement**

Panel above door	Flat AC Sheeting	1m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4116/B00D/R0004/Panel above door/S4				<b>Chrysotile (white asbestos)</b>	
Ceiling Structures/Linings	Flat AC Sheeting	5m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4116/B00B/R0006/Ceiling Structures/Linings/S3				<b>Chrysotile (white asbestos)</b>	

**B00D - R0006 - Security Store**

No Asbestos

**B00D - R0007 - Principal**

No Asbestos

**B00D - R0008 - Plant**

No Asbestos

**B00D - R0009 - Deputy Principal**

No Asbestos

**B00D - R0010 - General Storeroom**

No Asbestos

**B00D - R0014 - Staff Room**

No Asbestos

**B00D - R0015 - Cleaning Distributed Store**

No Asbestos

**B00D - R0016 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	2m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4116/B00B/R0006/Ceiling Structures/Linings/S3				<b>Chrysotile (white asbestos)</b>	
Panels above door	Flat AC Sheeting	1m2	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4116/B00B/R0006/panels above door/S11				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	

**B00D - R0017 - Movement**

No Asbestos

**B00D - R0018 - Duplicating Workroom**

No Asbestos

**B00D - R0019 - General Storeroom**

No Asbestos

**B00D - R0020 - General Storeroom**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	<b>Sample No</b>					<b>Test Result</b>

No Asbestos

**B00D - R0021 - Staff Room Annexe**

No Asbestos

**B00D - R0022 - Movement**

No Asbestos

**B00D - R0023 - Movement**

No Asbestos

**B00D - R0024 - Staff Shower/Change**

No Asbestos

**B00D - R0025 - Staff Toilet**

No Asbestos

**B00D - R0026 - Movement**

No Asbestos

**B00D - R0027 - Staff Toilet**

No Asbestos

**B00D - R0028 - Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - Other-Commercial/General Learning - 1957 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Eaves Linings	Flat AC Sheeting	10m2	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4116/B00E/Eaves Linings/S5					<b>Chrysotile (white asbestos)</b>
Underfloor Voids	Flat AC Sheeting					<b>No Asbestos Detected</b>
	4116/B00E/Underfloor Voids/S29					
Ceiling Void	No Asbestos Found					
Eaves Linings	Flat AC Sheeting					<b>No Asbestos Detected</b>
	4116/B00E/Eaves Linings/S28					

**Interior**

**B00E - R0001 - Staff Toilet**

No Asbestos

**B00E - R0002 - Cleaning Distributed Store**

No Asbestos

**B00E - R0003 - Other-Community Use**

No Asbestos

**B00E - R0004 - Movement**

No Asbestos

**B00E - R0007 - Other-Commercial**

No Asbestos

**B00E - R0008 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting					<b>No Asbestos Detected</b>
	4116/B00E/R0008/Ceiling Structures/Linings/S6					

**B00E - R0009 - Movement**

No Asbestos

**B00E - R0010 - Community Clinic**

No Asbestos

**B00E - R0011 - Community Clinic**

No Asbestos

**B00E - R0012 - Home Base**

No Asbestos

**B00E - R0013 - Home Base**

No Asbestos

**B00E - R0014 - General Storeroom**

No Asbestos

**B00E - R0015 - Withdrawal Space - 2hb**

No Asbestos

**B00E - R0016 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting					<b>No Asbestos Detected</b>
	4116/B00E/R0016/Ceiling Structures/Linings/S35					

**B00E - R0017 - Home Base**

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - General Learning - 1957 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Eaves Linings	Flat AC Sheeting 4116/B00E/Eaves Linings/S28					<b>No Asbestos Detected</b>
Underfloor Voids	No Asbestos Found					
Ceiling Void	AC Fragments/Debris 4116/B00F/Ceiling Void/S32	1m	Adjacent Manhole	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5) <b>Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)</b>

**Interior**

**B00F - R0001 - Home Base**

No Asbestos

**B00F - R0002 - Home Base Store**

No Asbestos

**B00F - R0003 - Personal Effects Storage**

No Asbestos

**B00F - R0004 - Movement**

No Asbestos

**B00F - R0005 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	9m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
	4116/B00F/R0005/Ceiling Structures/Linings/S7					

**B00F - R0006 - Personal Effects Storage**

No Asbestos

**B00F - R0007 - Home Base Store**

No Asbestos

**B00F - R0008 - Home Base**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - Communal Facilities - 1957 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Eaves Linings	Flat AC Sheeting	20m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4116/B00C/Eaves Linings/S27					<b>Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)</b>
Ceiling Void	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior**

**B00G - R0001 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	5m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4116/B00G/R0001/Ceiling Structures/Linings/S9					<b>Chrysotile (white asbestos)</b>
Panel above door	Flat AC Sheeting	1m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4116/B00G/R0001/Panel above door/S10					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00G - R0002 - Movement**

No Asbestos

**B00G - R0003 - Communal Space**

No Asbestos

**B00G - R0004 - Uniform Shop**

Floor Coverings Res/Textile	Vinyl Tiles	22m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4116/B00G/R0004/Floor Coverings Res/Textile/S8					<b>Chrysotile (white asbestos)</b>

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - Pupil Facilities - 1957 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Void	No Asbestos Found

**Interior**

**B00H - R0001 - Toilets - Boys**

Partition Walls (Cubicles)	Compressed AC Sheet	4116/B00H/R0001/Partition Walls (Cubicles)/S13	<b>No Asbestos Detected</b>
----------------------------	---------------------	--	-----------------------------

**B00H - R0002 - Drinking Facilities**

No Asbestos

**B00H - R0003 - Garden Store**

No Asbestos

**B00H - R0004 - Drinking Facilities**

No Asbestos

**B00H - R0005 - Toilets - Girls**

No Asbestos

**B00H - R0006 - Sports Store**

Partition Walls (Cubicles)	Compressed AC Sheet	4116/B00H/R0001/Partition Walls (Cubicles)/S13	<b>No Asbestos Detected</b>
----------------------------	---------------------	--	-----------------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00I - General Learning - 1957 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Eaves Linings	Flat AC Sheeting	20m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4116/B00C/Eaves Linings/S27				<b>Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)</b>	
Ceiling Void	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior**

**B00I - R0001 - Home Base Store**

No Asbestos

**B00I - R0002 - Personal Effects Storage**

No Asbestos

**B00I - R0003 - Movement**

No Asbestos

**B00I - R0004 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	5m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4116/B00I/R0009/Ceiling Structures/Linings/S17				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	

**B00I - R0005 - Home Base**

No Asbestos

**B00I - R0006 - Home Base**

No Asbestos

**B00I - R0007 - Personal Effects Storage**

No Asbestos

**B00I - R0008 - Movement**

No Asbestos

**B00I - R0009 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	9m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4116/B00I/R0009/Ceiling Structures/Linings/S17				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	

**B00I - R0010 - Home Base**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00J - General Learning - 1957 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Eaves Linings	Flat AC Sheeting	40m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4116/B00C/Eaves Linings/S27				<b>Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)</b>	
Ceiling Void	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior**

**B00J - R0001 - Movement**

No Asbestos

**B00J - R0002 - Movement**

No Asbestos

**B00J - R0003 - Personal Effects Storage**

No Asbestos

**B00J - R0004 - Home Base Store**

No Asbestos

**B00J - R0005 - Home Base**

No Asbestos

**B00J - R0006 - Home Base**

No Asbestos

**B00J - R0007 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	9m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4116/B00J/R0007/Ceiling Structures/Linings/S18				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	

**B00J - R0008 - Movement**

No Asbestos

**B00J - R0009 - Personal Effects Storage**

No Asbestos

**B00J - R0010 - Home Base Store**

No Asbestos

**B00J - R0011 - Home Base Store**

No Asbestos

**B00J - R0012 - Home Base**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00K - General Learning - 1957 - Timber (Timber)**

**Exterior**

Underfloor Voids	No Asbestos Found
Ceiling Void	No Asbestos Found

**Interior**

**B00K - R0001 - Home Base Store**

No Asbestos

**B00K - R0002 - Home Base**

No Asbestos

**B00K - R0003 - Home Base**

No Asbestos

**B00K - R0004 - Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00L - General Learning - 1957 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Eaves Linings	Flat AC Sheeting 4116/B00E/Eaves Linings/S5	40m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Ceiling Void	No Asbestos Found					
Underfloor Voids	AC Fragments/Debris 4116/B00L/Underfloor Voids/S31	1m2	Variable positions	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5) <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**Interior**

**B00L - R0001 - Home Base**

No Asbestos

**B00L - R0002 - Home Base Store**

No Asbestos

**B00L - R0003 - Personal Effects Storage**

No Asbestos

**B00L - R0004 - Movement**

No Asbestos

**B00L - R0005 - General Storeroom**

No Asbestos

**B00L - R0006 - Home Base Store**

No Asbestos

**B00L - R0007 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting 4116/B00L/R0007/Ceiling Structures/Linings/S19					<b>No Asbestos Detected</b>
Panel above door	Flat AC Sheeting 4116/B00L/R0007/Panel above door/S21	1m2	East facing	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00L - R0008 - Personal Effects Storage**

No Asbestos

**B00L - R0009 - Home Base**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00M - Communal Facilities - 1957 - Timber (Timber)**

**Exterior**

Ceiling Void	Non Accessible Area - No Access - Manhole >5m in middle of room - Too high to access safely
Underfloor Voids	No Asbestos Found

**Interior**

**B00M - R0001 - Movement**

No Asbestos

**B00M - R0002 - Communal Space**

No Asbestos

**B00M - R0003 - Raised Platform**

No Asbestos

**B00M - R0004 - No Access**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00N - General Learning - 1957 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids	No Asbestos Found 4116/B00N/Exterior/Ceiling Void/S33				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
Ceiling Void	AC Fragments/Debris 4116/B00N/Exterior/Ceiling Void/S33	1m2	Variable positions	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5)
					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	

**Interior**

**B00N - R0001 - Staff Room Annexe**

No Asbestos

**B00N - R0002 - Staff Room Annexe**

No Asbestos

**B00N - R0003 - General Storeroom**

No Asbestos

**B00N - R0004 - Cleaning Distributed Store**

No Asbestos

**B00N - R0005 - Home Base Store**

No Asbestos

**B00N - R0006 - Movement**

No Asbestos

**B00N - R0007 - Personal Effects Storage**

No Asbestos

**B00N - R0008 - Home Base Store**

No Asbestos

**B00N - R0009 - Home Base**

No Asbestos

**B00N - R0010 - Home Base**

No Asbestos

**B00N - R0011 - Home Base Store**

No Asbestos

**B00N - R0012 - Personal Effects Storage**

No Asbestos

**B00N - R0013 - Movement**

No Asbestos

**B00N - R0014 - Toilets - Boys/Girls**

Wall Linings Internal	Flat AC Sheeting 4116/B00N/R0014/Wall Linings Internal/S16	10m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)
					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
Ceiling Structures/Linings	Flat AC Sheeting 4116/B00N/R0014/Ceiling Structures/Linings/S34	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	

**B00N - R0015 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting 4116/B00N/R0016/Ceiling Structures/Linings/S22	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	

**B00N - R0016 - Movement**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4116/B00N/R0016/Ceiling Structures/Linings/S22				Chrysotile (white asbestos) , Amosite (brown asbestos)		

**B00N - R0017 - Staff Toilet**

No Asbestos

**B00N - R9001 - Sports Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B000 - Pupil Facilities - 1957 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids - Flat Roof	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

**Interior**

**B000 - R0001 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting					
	4116/B000/R0001/Ceiling Structures/Linings/S26					<b>No Asbestos Detected</b>

**B000 - R0002 - Movement**

Wall Linings Internal	Flat AC Sheeting	11m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4116/B000/R0002/Wall Linings Internal/S25					<b>Chrysotile (white asbestos)</b>

Ceiling Structures/Linings	Flat AC Sheeting					
	4116/B000/R0001/Ceiling Structures/Linings/S26					<b>No Asbestos Detected</b>

**B000 - R0003 - Canteen**

Ceiling Structures/Linings	Flat AC Sheeting	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4116/B000/R0005/Ceiling Structures/Linings/S23					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

Floor Coverings Res/Textile	Vinyl Tiles					
	4116/B000/R0005/Floor Coverings Res/Textile/S24					<b>No Asbestos Detected</b>

**B000 - R0004 - Movement**

Floor Coverings Res/Textile	Vinyl Tiles					
	4116/B000/R0005/Floor Coverings Res/Textile/S24					<b>No Asbestos Detected</b>

**B000 - R0005 - Canteen Office/Store**

Ceiling Structures/Linings	Flat AC Sheeting	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4116/B000/R0005/Ceiling Structures/Linings/S23					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>


Floor Coverings Res/Textile	Vinyl Tiles					
	4116/B000/R0005/Floor Coverings Res/Textile/S24					<b>No Asbestos Detected</b>

**B000 - R0006 - Canteen Office/Store**

Ceiling Structures/Linings	Flat AC Sheeting	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4116/B000/R0005/Ceiling Structures/Linings/S23					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B000 - R0007 - Staff Toilet**

Ceiling Structures/Linings	Flat AC Sheeting	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4116/B000/R0005/Ceiling Structures/Linings/S23					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00P - Pupil Facilities - 1957 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Void	No Asbestos Found

**Interior**

**B00P - R0001 - Drinking Facilities**

No Asbestos

**B00P - R0002 - Drinking Facilities**

No Asbestos

**B00P - R0003 - Toilets - Girls**

No Asbestos

**B00P - R0004 - Toilets - Boys**

Partition Walls (Cubicles)	Compressed AC Sheet 4116/B00P/R0004/Partition Walls (Cubicles)/S14	<b>No Asbestos Detected</b>
Wall Linings Internal	Flat AC Sheeting 4116/B00P/R0004/Wall Linings Internal/S15	<b>No Asbestos Detected</b>

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00Q - Other - 2008 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Slab on Ground      No Asbestos Found

Ceiling Voids      No Asbestos Found

**Interior**

**B00Q - R0001 - General Storeroom**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00R - Pupil Facilities/Communal Facilities - 2010 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00R - R0001 - Communal Space**

No Asbestos

**B00R - R0002 - Raised Platform**

No Asbestos

**B00R - R0003 - Movement**

No Asbestos

**B00R - R0004 - Movement**

No Asbestos

**B00R - R0005 - Hall Chair Store**

No Asbestos

**B00R - R0006 - Movement**

No Asbestos

**B00R - R0007 - Cleaning Distributed Store**

No Asbestos

**B00R - R0008 - Plant**

No Asbestos

**B00R - R0009 - Main Switch Board**

No Asbestos

**B00R - R0010 - Toilet - Lobby**

No Asbestos

**B00R - R0011 - Toilets - Girls**

No Asbestos

**B00R - R0012 - Sound Cupboard**

No Asbestos

**B00R - R0013 - Toilet - P**

No Asbestos

**B00R - R0014 - Toilet - Lobby**

No Asbestos

**B00R - R0015 - Toilets - Boys**

No Asbestos

**B00R - R0016 - P.E. Store**

No Asbestos

**B00R - R0017 - Communal/Performance Store**

No Asbestos

**B00R - R0018 - External Movement**

No Asbestos

**B00R - R0019 - Canteen**

No Asbestos

**B00R - R0020 - Canteen Office/Store**

No Asbestos

**B00R - R0021 - Ramp**

No Asbestos

**B00R - R0022 - Covered Outdoor Learning Area**

No Asbestos

**B00R - R0023 - Movement**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Demountables***

**There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.**

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017