


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Berkeley West Public School (4180)  
**Region :** Illawarra and South East  
**State Electorate :** Wollongong  
**Local Government Area :** Wollongong

**Initial Survey :** Noel Arnold & Associates : 05 - Apr - 2008  
**Reviewed By :** AECOM : 18 - Jun - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - Library/Various - 1962 - Concrete Framed (Concrete Framed)**

**Exterior**

Eaves Linings	Flat AC Sheeting 4180/B00A/Eaves Linings/S8					No Asbestos Detected
Gable Verge Lining	Flat AC Sheeting 4180/B00A/Eaves Linings/S8					No Asbestos Detected
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Non Accessible Area - Height Restriction					

**Interior**

**B00A - R0001 - Home Base (67.78 m2)**

No Asbestos

**B00A - R0006 - External Movement (1.98 m2)**

No Asbestos

**B00A - R0012 - General Storeroom (3.84 m2)**

No Asbestos

**B00A - R0014 - Main Switch Board (0.28 m2)**

Electrical Mounting Board	Resinous Board	1Unit	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
---------------------------	----------------	-------	------------	--------------------	---------	--------------------

**Assumed Asbestos - Electrical Hazard**

**B00A - R0028 - External Movement (8.11 m2)**

No Asbestos

**B00A - R0029 - Staff Room Annexe (19.19 m2)**

No Asbestos

**B00A - R0030 - Entry Vestibule (21.11 m2)**

No Asbestos

**B00A - R0031 - Clerical Office (27.25 m2)**

No Asbestos

**B00A - R0032 - Clerical Office/Workroom (10.82 m2)**

No Asbestos

**B00A - R0033 - Principal (16 m2)**

No Asbestos

**B00A - R0034 - Cleaning Distributed Store (0.65 m2)**

No Asbestos

**B00A - R0035 - Cleaning Distributed Store (1.34 m2)**

No Asbestos

**B00A - R0036 - Movement (5.97 m2)**

No Asbestos

**B00A - R0037 - Movement (25.65 m2)**

No Asbestos

**B00A - R0038 - Staff Toilet (4.2 m2)**

No Asbestos

**B00A - R0039 - Staff Toilet (3.89 m2)**

No Asbestos

**B00A - R0040 - Staff Toilet (4.39 m2)**

No Asbestos

**B00A - R0041 - Deputy Principal - Type 1 (13.55 m2)**

No Asbestos

**B00A - R0042 - Security Store (13.55 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	<b>Sample No</b>					<b>Test Result</b>

No Asbestos

**B00A - R0043 - Sick Bay (13.59 m2)**

No Asbestos

**B00A - R0044 - Interview (13.55 m2)**

No Asbestos

**B00A - R0045 - Disabled Toilet (7.11 m2)**

No Asbestos

**B00A - R0046 - Staff Kitchen (10.26 m2)**

No Asbestos

**B00A - R0047 - Staff Room (37 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - General Learning - 1959 - Concrete Framed (Concrete Framed)**

**Exterior**

Eaves Linings	Flat AC Sheeting 4180/B00A/Eaves Linings/S8					No Asbestos Detected
Gable Verge Lining	Flat AC Sheeting 4180/B00A/Eaves Linings/S8					No Asbestos Detected
Underfloor Voids	Non Accessible Area - Height Restriction					
Ceiling Voids	No Asbestos Found					

**Interior**

**B00B - R0008 - External Movement (1.99 m2)**

No Asbestos

**B00B - R0009 - Reading Area (134.35 m2)**

No Asbestos

**B00B - R0010 - K.L.A. Store (8.34 m2)**

No Asbestos

**B00B - R0011 - K.L.A. Store (8.22 m2)**

No Asbestos

**B00B - R0012 - Library Office/Workroom (16.89 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

**B00C - General Learning/Pupil Facilities - 1962 - Concrete Framed (Concrete Framed)****Exterior**

Eaves Linings	Flat AC Sheeting	50m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4180/B00C/R0001/Ceiling Structures/Linings/S11			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Non Accessible Area - Height Restriction					

**Interior****B00C - R0001 - Movement (12.45 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4180/B00C/R0001/Ceiling Structures/Linings/S11			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00C - R0002 - Canteen Office/Store (1.07 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4180/B00C/R0002/Floor Coverings Res/Textile/S6			<b>Chrysotile (white asbestos)</b>		

**B00C - R0003 - Canteen Office/Store (4.92 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4180/B00C/R0001/Ceiling Structures/Linings/S11			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00C - R0004 - Staff Toilet (1.32 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4180/B00C/R0001/Ceiling Structures/Linings/S11			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00C - R0005 - General Storeroom (26.19 m2)**

No Asbestos

**B00C - R0006 - Home Base (58.22 m2)**

No Asbestos

**B00C - R0007 - Home Base Store (6.14 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4180/B00F/R0008/Floor Coverings Res/Textile/S1			<b>Chrysotile (white asbestos)</b>		

**B00C - R0008 - Personal Effects Storage (4.01 m2)**

No Asbestos

**B00C - R0009 - Cleaning Distributed Store (4.04 m2)**

No Asbestos

**B00C - R0010 - Movement (6.32 m2)**

No Asbestos

**B00C - R0011 - Home Base (58.69 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	59m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4180/B00F/R0008/Floor Coverings Res/Textile/S1			<b>Chrysotile (white asbestos)</b>		

**B00C - R0012 - General Storeroom (6.07 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4180/B00F/R0008/Floor Coverings Res/Textile/S1			<b>Chrysotile (white asbestos)</b>		

**B00C - R0013 - External Movement (1.55 m2)**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - General Learning - 1959 - Concrete Framed (Concrete Framed)**

**Exterior**

Ceiling Voids - Flat Roof	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

**Interior**

**B00D - R0001 - Movement (86.87 m2)**

No Asbestos

**B00D - R0002 - Movement (7.64 m2)**

No Asbestos

**B00D - R0003 - Cleaning Distributed Store (3.73 m2)**

No Asbestos

**B00D - R0004 - General Storeroom (12.04 m2)**

No Asbestos

**B00D - R0005 - Movement (1.77 m2)**

No Asbestos

**B00D - R0006 - Personal Effects Storage (6.54 m2)**

No Asbestos

**B00D - R0007 - Home Base Store (6.06 m2)**

No Asbestos

**B00D - R0008 - Home Base (56.24 m2)**

No Asbestos

**B00D - R0009 - Home Base (56.31 m2)**

No Asbestos

**B00D - R0010 - Home Base Store (6.06 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4180/B00E/R0016/Floor Coverings Res/Textile/S3					<b>Chrysotile (white asbestos)</b>	

**B00D - R0011 - Personal Effects Storage (14.64 m2)**

No Asbestos

**B00D - R0012 - Home Base (56.54 m2)**

No Asbestos

**B00D - R0013 - Home Base Store (6.11 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4180/B00E/R0016/Floor Coverings Res/Textile/S3					<b>Chrysotile (white asbestos)</b>	

**B00D - R0014 - Distribution Board (0.87 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B00D - R0015 - Cleaning Distributed Store (0.84 m2)**

No Asbestos

**B00D - R0016 - Entry Vestibule (7.19 m2)**

No Asbestos

**B00D - R0017 - Interview (16.44 m2)**

No Asbestos

**B00D - R0018 - General Storeroom (4.35 m2)**

Floor Coverings Res/Textile	Vinyl Tiles				
4180/B00D/R0018/Floor Coverings Res/Textile/S7					<b>No Asbestos Detected</b>

**B00D - R0019 - Staff Toilet (4.23 m2)**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00D - R0020 - Stairs (15.29 m2)</b>						
No Asbestos						
<b>B00D - R0021 - Stairs (4.75 m2)</b>						
No Asbestos						
<b>B00D - R1001 - Movement (85.87 m2)</b>						
No Asbestos						
<b>B00D - R1002 - General Storeroom (12.9 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	4180/B00D/R0018/Floor Coverings Res/Textile/S7					<b>No Asbestos Detected</b>
<b>B00D - R1003 - General Storeroom (4.28 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	4180/B00D/R0018/Floor Coverings Res/Textile/S7					<b>No Asbestos Detected</b>
<b>B00D - R1004 - Personal Effects Storage (6.62 m2)</b>						
No Asbestos						
<b>B00D - R1005 - Home Base Store (6.55 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	4180/B00D/R0018/Floor Coverings Res/Textile/S7					<b>No Asbestos Detected</b>
<b>B00D - R1006 - Home Base (58.02 m2)</b>						
No Asbestos						
<b>B00D - R1007 - Home Base (58.26 m2)</b>						
No Asbestos						
<b>B00D - R1008 - Home Base Store (6.46 m2)</b>						
No Asbestos						
<b>B00D - R1009 - Personal Effects Storage (14.68 m2)</b>						
No Asbestos						
<b>B00D - R1010 - Home Base (58.33 m2)</b>						
No Asbestos						
<b>B00D - R1011 - Home Base Store (6.46 m2)</b>						
No Asbestos						
<b>B00D - R1012 - Cleaning Distributed Store (0.96 m2)</b>						
No Asbestos						
<b>B00D - R1013 - Cleaning Distributed Store (0.87 m2)</b>						
No Asbestos						
<b>B00D - R1014 - Movement (5.97 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	4180/B00D/R0018/Floor Coverings Res/Textile/S7					<b>No Asbestos Detected</b>
<b>B00D - R1015 - Staff Toilet (4.66 m2)</b>						
No Asbestos						
<b>B00D - R1016 - Staff Toilet (4.63 m2)</b>						
No Asbestos						
<b>B00D - R1017 - Staff Room Annexe (19.32 m2)</b>						
No Asbestos						
<b>B00D - R1018 - Stairs (16.19 m2)</b>						
No Asbestos						
<b>B00D - R1019 - Stairs (16.01 m2)</b>						
No Asbestos						
<b>B00D - R9001 - General Storeroom (101.75 m2)</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

**B00D - R9002 - Sports Store (16.02 m2)**

No Asbestos

**B00D - R9003 - General Assistant/Bulk Store (15.83 m2)**

No Asbestos

**B00D - R9004 - Movement (100.67 m2)**

No Asbestos

**B00D - R9005 - P.E. Store (31.54 m2)**

No Asbestos

**B00D - R9006 - Movement (15.17 m2)**

No Asbestos

**B00D - R9007 - Cleaning Distributed Store (0.86 m2)**

No Asbestos

**B00D - R9008 - Stairs (11.36 m2)**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - General Learning - 1962 - Concrete Framed (Concrete Framed)**

**Exterior**

Eaves Linings	Flat AC Sheeting	50m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4180/B00E/Eaves Linings/S16					<b>Chrysotile (white asbestos)</b>
Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

**Interior**

**B00E - R0001 - General Storeroom (12.06 m2)**

Floor Coverings Res/Textile	Vinyl Tiles					
	4180/B00E/R0002/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>

**B00E - R0002 - Movement (23.1 m2)**

Floor Coverings Res/Textile	Vinyl Tiles					
	4180/B00E/R0002/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>

**B00E - R0003 - Toilets - Boys/Girls (2.88 m2)**

No Asbestos

**B00E - R0004 - Personal Effects Storage (11.67 m2)**

No Asbestos

**B00E - R0005 - Home Base (86.92 m2)**

Ceiling Structures/Linings	Vermiculite					
	4180/B00E/R0005/Ceiling Structures/Linings/S4					<b>Limited Samples Taken</b>
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00E - R0006 - Home Base (60.06 m2)**

Ceiling Structures/Linings	Vermiculite					
	4180/B00E/R0005/Ceiling Structures/Linings/S4					<b>Limited Samples Taken</b>
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00E - R0007 - Personal Effects Storage (9.3 m2)**

Ceiling Structures/Linings	Vermiculite					
	4180/B00E/R0005/Ceiling Structures/Linings/S4					<b>Limited Samples Taken</b>
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00E - R0008 - Movement (5.25 m2)**

Ceiling Structures/Linings	Vermiculite					
	4180/B00E/R0005/Ceiling Structures/Linings/S4					<b>Limited Samples Taken</b>
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00E - R0009 - Distribution Board (0.48 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B00E - R0010 - Cleaning Distributed Store (8.1 m2)**

No Asbestos

**B00E - R0011 - Movement (44.96 m2)**

No Asbestos

**B00E - R0012 - Home Base (58.63 m2)**

Ceiling Structures/Linings	Vermiculite					
	4180/B00E/R0005/Ceiling Structures/Linings/S4					<b>Limited Samples Taken</b>
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00E - R0013 - Home Base Store (4.62 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4180/B00E/R0016/Floor Coverings Res/Textile/S3					<b>Chrysotile (white asbestos)</b>

**B00E - R0014 - Personal Effects Storage (4.86 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4180/B00E/R0016/Floor Coverings Res/Textile/S3				<b>Chrysotile (white asbestos)</b>		
<b>B00E - R0015 - Distribution Board (0.35 m2)</b>				Note: No inspection of live electrical installation.		
Wall Linings Internal	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4180/B00E/R0015/Wall Linings Internal/S5				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4180/B00E/R0015/Wall Linings Internal/S5				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00E - R0016 - Movement (16.87 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4180/B00E/R0016/Floor Coverings Res/Textile/S3				<b>Chrysotile (white asbestos)</b>		
<b>B00E - R0017 - General Storeroom (14.39 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4180/B00E/R0016/Floor Coverings Res/Textile/S3				<b>Chrysotile (white asbestos)</b>		
<b>B00E - R0018 - Personal Effects Storage (4.77 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4180/B00E/R0016/Floor Coverings Res/Textile/S3				<b>Chrysotile (white asbestos)</b>		
<b>B00E - R0019 - Home Base (57.68 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
4180/B00E/R0005/Ceiling Structures/Linings/S4				<b>Limited Samples Taken</b>		
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						
<b>B00E - R0020 - Home Base Store (4.59 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4180/B00E/R0016/Floor Coverings Res/Textile/S3				<b>Chrysotile (white asbestos)</b>		
<b>B00E - R0021 - Stairs (1.3 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
4180/B00E/R0005/Ceiling Structures/Linings/S4				<b>Limited Samples Taken</b>		
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						
<b>B00E - R0022 - Stairs (4.03 m2)</b>						
No Asbestos						
<b>B00E - R1001 - Home Base (57.9 m2)</b>						
No Asbestos						
<b>B00E - R1002 - Personal Effects Storage (12.02 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
4180/B00E/R0002/Floor Coverings Res/Textile/S2				<b>No Asbestos Detected</b>		
<b>B00E - R1003 - Movement (8.61 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
4180/B00E/R0002/Floor Coverings Res/Textile/S2				<b>No Asbestos Detected</b>		
<b>B00E - R1004 - General Storeroom (11.25 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
4180/B00E/R0002/Floor Coverings Res/Textile/S2				<b>No Asbestos Detected</b>		
<b>B00E - R1005 - Staff Room Annexe (57.74 m2)</b>						
No Asbestos						
<b>B00E - R1006 - Home Base (58.93 m2)</b>						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00E - R1007 - Home Base Store (4.55 m2)</b>						
No Asbestos						
<b>B00E - R1008 - Personal Effects Storage (4.83 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4180/B00E/R0016/Floor Coverings Res/Textile/S3					<b>Chrysotile (white asbestos)</b>	
<b>B00E - R1009 - Movement (21.61 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4180/B00E/R0016/Floor Coverings Res/Textile/S3					<b>Chrysotile (white asbestos)</b>	
<b>B00E - R1010 - Personal Effects Storage (4.8 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4180/B00E/R0016/Floor Coverings Res/Textile/S3					<b>Chrysotile (white asbestos)</b>	
<b>B00E - R1011 - Home Base (58.06 m2)</b>						
No Asbestos						
<b>B00E - R1012 - Home Base Store (4.58 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4180/B00E/R0016/Floor Coverings Res/Textile/S3					<b>Chrysotile (white asbestos)</b>	
<b>B00E - R1013 - Stairs (12.02 m2)</b>						
No Asbestos						
<b>B00E - R1014 - Stairs (13.47 m2)</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

**B00F - Other-D.E.C. Admin/Communal Facilities - 1959 - Concrete Framed (Concrete Framed)**

**Exterior**

Eaves Linings	Flat AC Sheeting	60m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4180/B00F/R0029/Ceiling Structures/Linings/S12			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Gable Verge Lining	Flat AC Sheeting	15m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4180/B00F/R0029/Ceiling Structures/Linings/S12			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Non Accessible Area - Area inaccessible					

**Interior**

**B00F - R0001 - Other - Regional Use (6.2 m2)**

No Asbestos

**B00F - R0002 - Other - Regional Use (5.76 m2)**

No Asbestos

**B00F - R0003 - Other - Regional Use (18.7 m2)**

No Asbestos

**B00F - R0004 - Other - Regional Use (16.76 m2)**

No Asbestos

**B00F - R0005 - Entry Vestibule (11.64 m2)**

No Asbestos

**B00F - R0006 - External Movement (1.44 m2)**

No Asbestos

**B00F - R0008 - Music Store (6.62 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4180/B00F/R0008/Floor Coverings Res/Textile/S1			<b>Chrysotile (white asbestos)</b>		

**B00F - R0009 - Movement (6.43 m2)**

No Asbestos

**B00F - R0010 - Movement (12.2 m2)**

No Asbestos

**B00F - R0011 - Other - Regional Use (5.62 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4180/B00F/R0008/Floor Coverings Res/Textile/S1			<b>Chrysotile (white asbestos)</b>		

**B00F - R0012 - General Storeroom (3.46 m2)**

No Asbestos

**B00F - R0013 - Other - Regional Use (21.2 m2)**

No Asbestos

**B00F - R0014 - External Movement (1.56 m2)**

No Asbestos

**B00F - R0015 - Other - Regional Use (55.49 m2)**

No Asbestos

**B00F - R0016 - General Storeroom (6.45 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4180/B00F/R0008/Floor Coverings Res/Textile/S1			<b>Chrysotile (white asbestos)</b>		

**B00F - R0017 - Sports Store (3.61 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4180/B00F/R0008/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)	
<b>B00F - R0018 - Sports Store (3.63 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4180/B00F/R0008/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)	
<b>B00F - R0019 - Distribution Board (0.16 m2)</b>				Note: No inspection of live electrical installation.		
Wall Linings Internal	Flat AC Sheeting	4m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
4180/B00F/R0019/Wall Linings Internal/S13					Chrysotile (white asbestos)	
<b>B00F - R0020 - Movement (6.09 m2)</b>						
No Asbestos						
<b>B00F - R0021 - External Movement (1.58 m2)</b>						
No Asbestos						
<b>B00F - R0022 - Raised Platform (21.85 m2)</b>						
No Asbestos						
<b>B00F - R0023 - General Storeroom (6.54 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4180/B00F/R0008/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)	
<b>B00F - R0024 - Communal Space (111.01 m2)</b>						
No Asbestos						
<b>B00F - R0025 - General Storeroom (4.44 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4180/B00F/R0008/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)	
<b>B00F - R0026 - Toilets - Boys/Girls (1.82 m2)</b>						
No Asbestos						
<b>B00F - R0027 - Movement (6.06 m2)</b>						
No Asbestos						
<b>B00F - R0028 - General Storeroom (3.57 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4180/B00F/R0008/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)	
<b>B00F - R0029 - External Movement (1.6 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4180/B00F/R0029/Ceiling Structures/Linings/S12					Chrysotile (white asbestos) , Amosite (brown asbestos)	
<b>B00F - R0030 - Other-Commercial (14.55 m2)</b>						
No Asbestos						
<b>B00F - R0031 - Other-Commercial (42.96 m2)</b>						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - Pupil Facilities - 1959 - Concrete (Concrete)**

**Exterior**

Eaves Linings	Flat AC Sheeting	60m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4180/B00G/R0006/Ceiling Structures/Linings/S15				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
Gable Verge Lining	Flat AC Sheeting	8m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4180/B00G/R0006/Ceiling Structures/Linings/S15				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

**Interior**

**B00G - R0001 - Drinking Facilities (9.35 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4180/B00G/R0006/Ceiling Structures/Linings/S15				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	

**B00G - R0002 - Toilets - Girls (34.99 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	35m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4180/B00G/R0006/Ceiling Structures/Linings/S15				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	

**B00G - R0003 - General Storeroom (5.2 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4180/B00G/R0006/Ceiling Structures/Linings/S15				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	

**B00G - R0004 - Cleaning Distributed Store (5.28 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4180/B00G/R0006/Ceiling Structures/Linings/S15				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	

**B00G - R0006 - Drinking Facilities (9.24 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4180/B00G/R0006/Ceiling Structures/Linings/S15				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	

**B00G - R0007 - Toilets - Boys (38.09 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	39m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4180/B00G/R0006/Ceiling Structures/Linings/S15				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	

**B00G - R0008 - Staff Toilet (1.13 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4180/B00G/R0006/Ceiling Structures/Linings/S15				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	

**B00G - R0009 - External Movement (44.89 m2)**

No Asbestos

**B00G - R0010 - External Movement (9.08 m2)**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - Pupil Facilities - 1959 - Concrete (Concrete)**

**Exterior**

Eaves Linings	Flat AC Sheeting	20m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4180/B00H/Eaves Linings/S10					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids	No Asbestos Found					

**Interior**

**B00H - R0001 - Toilets - Girls (53.64 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4180/B00H/Eaves Linings/S10					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00H - R0002 - Cleaning Distributed Store (1.3 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4180/B00H/Eaves Linings/S10					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B001 - Pupil Facilities - 1959 - Concrete (Concrete)**

**Exterior**

Eaves Linings	Flat AC Sheeting	20m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4180/B001/R0001/Ceiling Structures/Linings/S9			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Gable Verge Lining	Flat AC Sheeting	8m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4180/B001/R0001/Ceiling Structures/Linings/S9			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids	No Asbestos Found					

**Interior**

**B001 - R0001 - Toilets - Boys (57.96 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	57m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4180/B001/R0001/Ceiling Structures/Linings/S9			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B001 - R0002 - Cleaning Distributed Store (1.3 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	1.5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4180/B001/R0001/Ceiling Structures/Linings/S9			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00J - Multi Purpose Facilities - 2010 - Brick/Veneer (Brick/Veneer)**

**Exterior**

No Asbestos

**Interior**

**B00J - R0001 - Communal Space (140.15 m2)**

No Asbestos

**B00J - R0002 - Raised Platform (63.21 m2)**

No Asbestos

**B00J - R0003 - Chair Storeroom (9.62 m2)**

No Asbestos

**B00J - R0004 - Communal/Performance Store (9.58 m2)**

No Asbestos

**B00J - R0005 - P.E. Store (13.08 m2)**

No Asbestos

**B00J - R0006 - Toilet - Lobby (2.4 m2)**

No Asbestos

**B00J - R0007 - Toilets - Girls (7.25 m2)**

No Asbestos

**B00J - R0008 - Sound Cupboard (2.04 m2)**

No Asbestos

**B00J - R0009 - Toilet - Lobby (3.43 m2)**

No Asbestos

**B00J - R0010 - Toilets - Boys (5.8 m2)**

No Asbestos

**B00J - R0011 - Cleaning Distributed Store (3.45 m2)**

No Asbestos

**B00J - R0012 - Plant (1.6 m2)**

No Asbestos

**B00J - R0013 - Access Shower/Toilet/Change (6.9 m2)**

No Asbestos

**B00J - R0014 - Main Switch Board (3.26 m2)**

No Asbestos

**B00J - R0015 - Covered Outdoor Learning Area (150.4 m2)**

No Asbestos

**B00J - R0016 - Movement (6.97 m2)**

No Asbestos

**B00J - R0017 - Movement (16.38 m2)**

No Asbestos

**B00J - R0018 - Canteen Office/Store (9.35 m2)**

No Asbestos

**B00J - R0019 - Ramp (10.52 m2)**

No Asbestos

**B00J - R0020 - Canteen (26.57 m2)**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Demountables***

**There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017