


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Budgewoi Public School (4183)
Region : Hunter/Central Coast
State Electorate : Swansea
Local Government Area : Wyong

Initial Survey : Noel Arnold & Associates : 14 - Mar - 2008
Reviewed By : Parsons Brinckerhoff : 17 - Jun - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning - 1961 - Timber (Timber)**Exterior**

Eaves Linings	Flat AC Sheeting	40m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4183/B00A/Eaves Linings/S8				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00A - R0001 - Movement (9.05 m2)**

Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	4183/B00A/R0010/Ceiling Structures/Linings/S12					

B00A - R0002 - Home Base (56.85 m2)

Wall Linings Internal	Flat AC Sheeting	2m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4183/B00A/R0006/Wall Linings Internal/S2 Chrysotile (white asbestos)					

B00A - R0003 - Personal Effects Storage (9.94 m2)

No Asbestos

B00A - R0004 - Personal Effects Storage (10.34 m2)

No Asbestos

B00A - R0005 - Movement (11.2 m2)

No Asbestos

B00A - R0006 - Staff Toilet (3.55 m2)

Wall Linings Internal	Flat AC Sheeting	8m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	4183/B00A/R0006/Wall Linings Internal/S2 Chrysotile (white asbestos)					

B00A - R0007 - Home Base (77.94 m2)

Wall Linings Internal	Flat AC Sheeting	2m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4183/B00A/R0006/Wall Linings Internal/S2 Chrysotile (white asbestos)					

B00A - R0008 - Home Base (56.84 m2)

Ceiling Structures/Linings	Compressed AC Sheet	2m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4183/B00A/R0008/Ceiling Structures/Linings/S1 Chrysotile (white asbestos) , Amosite (brown asbestos)					

B00A - R0009 - Personal Effects Storage (10.21 m2)

No Asbestos

B00A - R0010 - Movement (8.82 m2)

Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	4183/B00A/R0010/Ceiling Structures/Linings/S12					

B00A - R0011 - Movement (6.28 m2)

No Asbestos

B00A - R0012 - Distribution Board (0.86 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0013 - Special Programs Room (52.78 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 1988 - Brick/Veneer (Brick/Veneer)

Exterior

In-fill-panel	Compressed AC Sheet 4183/B00B/In-fill-panel/S18					No Asbestos Detected
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00B - R0001 - General Assistant/Bulk Store (13.69 m2)

No Asbestos

B00B - R0002 - Music Store (15.84 m2)

No Asbestos

B00B - R0003 - Cleaning Supplies (12.75 m2)

No Asbestos

B00B - R0004 - Sports Store (14.07 m2)

Ceiling Structures/Linings	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4183/B00B/R0004/Ceiling Structures/Linings/S13					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)

Wall Linings Internal	Flat AC Sheeting 4183/B00B/R0004/Wall Linings Internal/S3					No Asbestos Detected
-----------------------	--	--	--	--	--	----------------------

B00B - R0005 - Home Base (57.98 m2)

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

B00B - R0006 - Personal Effects Storage (10.44 m2)

No Asbestos

B00B - R0007 - Movement (7.17 m2)

Ceiling Structures/Linings	Flat AC Sheeting 4183/B00A/R0010/Ceiling Structures/Linings/S12					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

B00B - R0008 - Movement (5.95 m2)

No Asbestos

B00B - R0009 - Personal Effects Storage (10.43 m2)

No Asbestos

B00B - R0010 - Home Base (57.99 m2)

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

B00B - R0011 - Home Base (58.15 m2)

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

B00B - R0012 - Personal Effects Storage (10.62 m2)

No Asbestos

B00B - R0013 - Interview (23.92 m2)

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

B00B - R0014 - K.L.A. Store (3.52 m2)

No Asbestos

B00B - R0015 - Movement (5.9 m2)

No Asbestos

B00B - R0016 - Movement (7.97 m2)

Ceiling Structures/Linings	Flat AC Sheeting 4183/B00A/R0010/Ceiling Structures/Linings/S12					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning - 1988 - Brick/Block (Brick/Block)

Exterior

Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4183/B00C/Gable Verge Lining/S11					Chrysotile (white asbestos)
Eaves Linings	Flat AC Sheeting	80m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4183/B00C/Eaves Linings/S9					Chrysotile (white asbestos)
In-fill-panel	Compressed AC Sheet	50m2	North & South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4183/B00C/In-fill-panel/S17					Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00C - R0001 - General Storeroom (58.21 m2)

No Asbestos

B00C - R0002 - Kiln Room (4.2 m2)

No Asbestos

B00C - R0003 - Sports Store (14.53 m2)

No Asbestos

B00C - R0005 - Handwashing Facilities (16.56 m2)

No Asbestos

B00C - R0006 - Toilets - Boys (25.77 m2)

Partition Walls (Cubicles)	Compressed AC Sheet					
	4183/B00C/R0006/Partition Walls (Cubicles)/S4					No Asbestos Detected

B00C - R0007 - Handwashing Facilities (17.12 m2)

No Asbestos

B00C - R0008 - Toilets - Girls (27.71 m2)

Partition Walls (Cubicles)	Compressed AC Sheet					
	4183/B00C/R0006/Partition Walls (Cubicles)/S4					No Asbestos Detected

B00C - R0009 - Movement (41.08 m2)

No Asbestos

B00C - R0010 - Security Store (4.94 m2)

No Asbestos

B00C - R0011 - Movement (16.68 m2)

No Asbestos

B00C - R0012 - Main Switch Board (7.99 m2)

Ceiling Structures/Linings	Flat AC Sheeting					
	4183/B00C/R0012/Ceiling Structures/Linings/S14					No Asbestos Detected

B00C - R0013 - General Storeroom (23.1 m2)

No Asbestos

B00C - R0014 - Movement (22.89 m2)

No Asbestos

B00C - R0015 - Disabled Toilet (9.18 m2)

No Asbestos

B00C - R0016 - Stairs (4.92 m2)

No Asbestos

B00C - R1001 - Staff Toilet (3.82 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
B00C - R1002 - Staff Toilet (3.8 m2)						
No Asbestos						
B00C - R1003 - Movement (6.37 m2)						
No Asbestos						
B00C - R1004 - Cleaning Distributed Store (4.1 m2)						
No Asbestos						
B00C - R1005 - Staff Room Annexe (26.8 m2)						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00C - R1006 - Staff Room (51.37 m2)						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00C - R1007 - Staff Room Annexe (14.25 m2)						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00C - R1008 - Personal Effects Storage (7.51 m2)						
No Asbestos						
B00C - R1009 - Distribution Board (0.82 m2)						
				Note: No inspection of live electrical installation.		
Floor Coverings Res/Textile	Vinyl Tiles	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4183/B00C/R1009/Floor Coverings Res/Textile/S5				Chrysotile (white asbestos)		
B00C - R1010 - Home Base Store (4.67 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4183/B00C/R1009/Floor Coverings Res/Textile/S5				Chrysotile (white asbestos)		
B00C - R1011 - Home Base (56.13 m2)						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00C - R1012 - Home Base (56.93 m2)						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00C - R1013 - Home Base Store (4.6 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4183/B00C/R1009/Floor Coverings Res/Textile/S5				Chrysotile (white asbestos)		
B00C - R1014 - Personal Effects Storage (17.93 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4183/B00C/R1009/Floor Coverings Res/Textile/S5				Chrysotile (white asbestos)		
B00C - R1015 - Home Base Store (4.6 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4183/B00C/R1009/Floor Coverings Res/Textile/S5				Chrysotile (white asbestos)		
B00C - R1016 - Home Base (56.13 m2)						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00C - R1017 - Movement (92.32 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	93m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4183/B00H/R1006/Ceiling Structures/Linings/S15				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00C - R1018 - Stairs (11.1 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4183/B00H/R1006/Ceiling Structures/Linings/S15				Chrysotile (white asbestos) , Amosite (brown asbestos)		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Pupil Facilities - 1988 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00D - R0001 - Movement (66.69 m2)

No Asbestos

B00D - R0002 - Canteen (46.37 m2)

No Asbestos

B00D - R0003 - Uniform Shop (6.44 m2)

No Asbestos

B00D - R0004 - Canteen Office/Store (6.57 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Communal Facilities/Pupil Facilities - 1973 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00E - R0001 - Shower/Change (2.92 m2)

No Asbestos

B00E - R0002 - Toilets - Boys (18.8 m2)

No Asbestos

B00E - R0003 - Movement (23.09 m2)

No Asbestos

B00E - R0004 - Toilets - Girls (18.24 m2)

No Asbestos

B00E - R0005 - Shower/Change (2.92 m2)

No Asbestos

B00E - R0006 - Movement (1.04 m2)

No Asbestos

B00E - R0007 - Disabled Toilet (4.55 m2)

No Asbestos

B00E - R0008 - Movement (14.98 m2)

No Asbestos

B00E - R0009 - Cleaning Distributed Store (5.87 m2)

No Asbestos

B00E - R0010 - P.E. Store (14.15 m2)

No Asbestos

B00E - R0011 - Cleaning Distributed Store (12.03 m2)

No Asbestos

B00E - R0012 - Plant (4.68 m2)

No Asbestos

B00E - R0013 - Music Store (16.3 m2)

No Asbestos

B00E - R0014 - Communal/Performance Store (12.98 m2)

No Asbestos

B00E - R0015 - Garage/Carport (37.94 m2)

No Asbestos

B00E - R0016 - Plant (0.78 m2)

No Asbestos

B00E - R0017 - Plant (0.78 m2)

No Asbestos

B00E - R0018 - Raised Platform (51.4 m2)

No Asbestos

B00E - R0019 - Communal Space (199.09 m2)

No Asbestos

B00E - R0020 - Distribution Board (1.92 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00E - R0021 - Movement (3.96 m2)

No Asbestos

B00E - R0022 - Movement (6.69 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Library - 1988 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00F - R0001 - Distribution Board (1.5 m2) Note: No inspection of live electrical installation.

No Asbestos

B00F - R0002 - Cleaning Distributed Store (3.47 m2)

No Asbestos

B00F - R0003 - Movement (18.94 m2)

No Asbestos

B00F - R0004 - Plant (4.49 m2)

No Asbestos

B00F - R0005 - Special Programs Store (3.03 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0006 - Special Programs Room (42.83 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0007 - Entry Vestibule (20.03 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0008 - Reading Area (217.28 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0009 - Library Office/Workroom (26.78 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0010 - K.L.A. Store (17.79 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0011 - Movement (13.61 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Administration - 1988 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior**B00G - R0001 - Movement (8.75 m2)**

No Asbestos

B00G - R0002 - Entry Vestibule (14.77 m2)Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00G - R0003 - Clerical Office (13.82 m2)**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00G - R0004 - Sick Bay (9.33 m2)**

No Asbestos

B00G - R0005 - Staff Shower/Change (3.61 m2)

No Asbestos

B00G - R0006 - Staff Toilet (4.77 m2)

No Asbestos

B00G - R0007 - Staff Toilet (4.8 m2)

No Asbestos

B00G - R0008 - Principal (15.85 m2)Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00G - R0009 - Security Store (9.45 m2)**

No Asbestos

B00G - R0010 - Staff Room Annexe (13.72 m2)Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00G - R0011 - Movement (6.48 m2)**

No Asbestos

B00G - R0012 - Entry Vestibule (14.7 m2)Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00G - R0013 - Staff Room Annexe (13.8 m2)**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00G - R0014 - Cleaning Distributed Store (5.15 m2)**

No Asbestos

B00G - R0015 - Distribution Board (1.17 m2)

No Asbestos

Note: No inspection of live electrical installation.

B00G - R0016 - Security Store (14.64 m2)

No Asbestos

B00G - R0017 - Duplicating Workroom (34.35 m2)

No Asbestos

B00G - R0018 - Interview (14.07 m2)Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00G - R0019 - Movement (25.13 m2)**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - R0020 - Movement (5.51 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - General Learning - 1988 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	30m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	4183/B00C/Eaves Linings/S9					Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	10m2	North & South	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4183/B00C/Gable Verge Lining/S11					Chrysotile (white asbestos)

Interior

B00H - R0001 - Distribution Board (0.92 m2) Note: No inspection of live electrical installation.

No Asbestos

B00H - R0002 - Practical Activities - 1hb (10.28 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4183/B00H/R0002/Ceiling Structures/Linings/S6					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles					No Asbestos Detected
	4183/B00H/R0002/Floor Coverings Res/Textile/S7					

B00H - R0003 - Home Base (64.48 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4183/B00H/R0002/Ceiling Structures/Linings/S6					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00H - R0004 - Home Base (64.49 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4183/B00H/R0002/Ceiling Structures/Linings/S6					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00H - R0005 - Practical Activities - 1hb (10.28 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4183/B00H/R0002/Ceiling Structures/Linings/S6					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles					No Asbestos Detected
	4183/B00H/R0002/Floor Coverings Res/Textile/S7					

B00H - R0006 - Movement (39.57 m2)

No Asbestos

B00H - R1001 - Distribution Board (0.92 m2) Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
	4183/B00H/R1001/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)

B00H - R1002 - Practical Activities - 1hb (10.28 m2)

Floor Coverings Res/Textile	Vinyl Tiles	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4183/B00C/R1009/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)

B00H - R1003 - Home Base (64.48 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00H - R1004 - Home Base (64.49 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00H - R1005 - Practical Activities - 1hb (10.28 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4183/B00C/R1009/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)	
B00H - R1006 - Movement (39.57 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4183/B00H/R1006/Ceiling Structures/Linings/S15					Chrysotile (white asbestos) , Amosite (brown asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B001 - Communal Facilities - 1997 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					
Eaves Linings	Flat AC Sheeting 4183/B001/Eaves Linings/S10					No Asbestos Detected

Interior

B001 - R0001 - Other-Community Use (91.52 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B001 - R0002 - Canteen (13.11 m2)

No Asbestos

B001 - R0003 - Special Programs Store (4.7 m2)

No Asbestos

B001 - R0004 - Shower/Change (5.44 m2)

No Asbestos

B001 - R0005 - Movement (28.93 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - General Learning - 2002 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior**B00J - R0001 - Practical Activities - 1hb (19.75 m2)**

No Asbestos

B00J - R0002 - Home Base Store (6.02 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R0003 - Home Base (59.33 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R0004 - Withdrawal Space - 2hb (11.62 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R0005 - Home Base (59.96 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R0006 - Practical Activities - 1hb (19.19 m2)

No Asbestos

B00J - R0007 - Home Base Store (6.07 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R0008 - General Assistant/Bulk Store (26.16 m2)

No Asbestos

B00J - R0009 - Stairs (21.57 m2)

No Asbestos

B00J - R0010 - Movement (90.44 m2)

No Asbestos

B00J - R0011 - Stairs (10.63 m2)

No Asbestos

B00J - R0012 - Distribution Board (0.48 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00J - R1001 - Laundry - Type 2 (7.16 m2)

No Asbestos

B00J - R1002 - Access Shower/Toilet - Type 2 (20.27 m2)

No Asbestos

B00J - R1003 - Practical Activities - 1hb (19.04 m2)

No Asbestos

B00J - R1004 - Home Base Store (5.96 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R1005 - Home Base (59.75 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R1006 - Withdrawal Space - 2hb (11.69 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R1007 - Home Base (59.76 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R1008 - Practical Activities - 1hb (18.92 m2)

No Asbestos

B00J - R1009 - Home Base Store (5.96 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R1010 - Movement (52.26 m2)

No Asbestos

B00J - R1011 - Movement (77.17 m2)

No Asbestos

B00J - R1012 - Stairs (26.35 m2)

No Asbestos

B00J - R1013 - Stairs (5.25 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00K - General Learning/Pupil Facilities - 2010 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior**B00K - R0001 - Practical Activities - 1hb (17.06 m2)**

No Asbestos

B00K - R0002 - Personal Effects Storage (3.76 m2)

No Asbestos

B00K - R0003 - Withdrawal Space - 1hb (8.85 m2)

No Asbestos

B00K - R0004 - Home Base Store (6.02 m2)

No Asbestos

B00K - R0005 - Home Base (58.25 m2)

No Asbestos

B00K - R0006 - Toilets - Girls (22.81 m2)

No Asbestos

B00K - R0007 - Toilets - Boys (16.32 m2)

No Asbestos

B00K - R0008 - Disabled Shower/Toilet (5.89 m2)

No Asbestos

B00K - R0009 - Practical Activities - 1hb (14.18 m2)

No Asbestos

B00K - R0010 - Personal Effects Storage (3.76 m2)

No Asbestos

B00K - R0011 - Home Base Store (6.1 m2)

No Asbestos

B00K - R0012 - Home Base (60.34 m2)

No Asbestos

B00K - R0013 - Withdrawal Space - 2hb (11.55 m2)

No Asbestos

B00K - R0014 - Practical Activities - 1hb (14.32 m2)

No Asbestos

B00K - R0015 - Personal Effects Storage (4.7 m2)

No Asbestos

B00K - R0016 - Home Base Store (6.08 m2)

No Asbestos

B00K - R0017 - Home Base (60.28 m2)

No Asbestos

B00K - R0018 - External Movement (90.85 m2)

No Asbestos

B00K - R0019 - Distribution Board (0.44 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00K - R0020 - General Storeroom (8.25 m2)

No Asbestos

B00K - R0021 - External Stairs (8.61 m2)

No Asbestos

B00K - R0022 - External Stairs (21.24 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
	No Asbestos					
	B00K - R1001 - Practical Activities - 1hb (13.79 m2)					
	No Asbestos					
	B00K - R1002 - Personal Effects Storage (3.8 m2)					
	No Asbestos					
	B00K - R1003 - Home Base Store (6.11 m2)					
	No Asbestos					
	B00K - R1004 - Home Base (60.34 m2)					
	No Asbestos					
	B00K - R1005 - Withdrawal Space - 2hb (11.51 m2)					
	No Asbestos					
	B00K - R1006 - Practical Activities - 1hb (14.11 m2)					
	No Asbestos					
	B00K - R1007 - Personal Effects Storage (4.68 m2)					
	No Asbestos					
	B00K - R1008 - Home Base Store (6.09 m2)					
	No Asbestos					
	B00K - R1009 - Home Base (60.34 m2)					
	No Asbestos					
	B00K - R1010 - Practical Activities - 1hb (16.39 m2)					
	No Asbestos					
	B00K - R1011 - Personal Effects Storage (5.31 m2)					
	No Asbestos					
	B00K - R1012 - Home Base (57.17 m2)					
	No Asbestos					
	B00K - R1013 - Home Base Store (5.85 m2)					
	No Asbestos					
	B00K - R1014 - Withdrawal Space - 1hb (9.14 m2)					
	No Asbestos					
	B00K - R1015 - External Movement (70.06 m2)					
	No Asbestos					
	B00K - R1016 - Distribution Board (0.42 m2)					Note: No inspection of live electrical installation.
	No Asbestos					
	B00K - R1017 - External Stairs (21.24 m2)					
	No Asbestos					
	B00K - R1018 - External Stairs (17.76 m2)					
	No Asbestos					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D10057 - Learning Unit - Standard With P.A.A. : Placement Date - 25/03/2013

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

NS 020 - D10508 - Staff Study/Store : Placement Date - 18/01/2000

Exterior

No Asbestos Found.

Interior

R1 - Staff Room

No Asbestos Found.

R2 - Store

No Asbestos Found.

R3 - Entry

No Asbestos Found.

OS 602 - D12501 - Learning Unit - Standard With P.A.A. : Placement Date - 13/05/1997

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Learning space/withdrawal/entry

Ceiling	Flat AC Sheet	Assumed Asbestos	70 m2
---------	---------------	------------------	-------

R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	3 m2

OS 601 - D15317 - Learning Unit - Standard/Withdrawal : Placement Date - 30/06/1995

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2
---------	---------------	------------------	-------

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017