

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Bert Oldfield Public School (4192)
Region : Western Sydney
State Electorate : Seven Hills
Local Government Area : Blacktown

Initial Survey : Noel Arnold & Associates : 04 - Apr - 2008
Reviewed By : Parsons Brinckerhoff : 14 - May - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration - 1960 - Brick/Veneer (Brick/Veneer)

Exterior

Eaves Linings	Flat AC Sheeting	50m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4192/B00A/Eaves Linings/S22				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Gable Verge Lining	Flat AC Sheeting	10m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4192/B00A/Gable Verge Lining/S23				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Ceiling Voids	No Asbestos Found					

Interior

B00A - R0001 - Principal

No Asbestos

B00A - R0002 - Entry Vestibule

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4192/B00A/R0007/Ceiling Structures/Linings/S1				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00A - R0003 - Movement

In-fill-panel	Flat AC Sheeting	3m	East, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4192/B00A/R0003/In-fill-panel/S21				Chrysotile (white asbestos)	

B00A - R0004 - Deputy Principal

No Asbestos

B00A - R0005 - Cleaning Distributed Store

No Asbestos

B00A - R0006 - Staff Room

No Asbestos

B00A - R0007 - Entry Vestibule

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4192/B00A/R0007/Ceiling Structures/Linings/S1				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00A - R0008 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4192/B00A/R0008/Wall Linings Internal/S2				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4192/B00A/R0007/Ceiling Structures/Linings/S1				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00A - R0009 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4192/B00A/R0008/Wall Linings Internal/S2				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4192/B00A/R0007/Ceiling Structures/Linings/S1				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00A - R0010 - General Storeroom

Floor Coverings Res/Textile	Vinyl Tiles					
	4192/B00A/R0010/Floor Coverings Res/Textile/S3				No Asbestos Detected	

B00A - R0011 - Distribution Board

Note: No inspection of live electrical installation.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Wall Linings Internal	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4192/B00A/R0011/Wall Linings Internal/S4					Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Some Damage - Unsealed (3)	Medium (2)	Medium Priority (4-5)
4192/B00A/R0011/Ceiling Structures/Linings/S27					Chrysotile (white asbestos)	
B00A - R0012 - Sick Bay						
Floor Coverings Res/Textile	Vinyl Tiles					
4192/B00A/R0010/Floor Coverings Res/Textile/S3					No Asbestos Detected	
B00A - R0013 - Clerical Office						
No Asbestos						
B00A - R0014 - General Storeroom						
No Asbestos						
B00A - R0015 - Staff Toilet						
Wall Linings Internal	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4192/B00A/R0008/Wall Linings Internal/S2					Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4192/B00A/R0007/Ceiling Structures/Linings/S1					Chrysotile (white asbestos) , Amosite (brown asbestos)	
B00A - R0016 - General Storeroom						
No Asbestos						
B00A - R0017 - General Storeroom						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Communal Facilities/General Learning - 1960 - Brick/Veneer (Brick/Veneer)

Exterior

Eaves Linings	Flat AC Sheeting	80m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4192/B00A/Eaves Linings/S22				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Gable Verge Lining	Flat AC Sheeting	10m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4192/B00A/Gable Verge Lining/S23				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00B - R0001 - General Storeroom

No Asbestos

B00B - R0002 - Personal Effects Storage

No Asbestos

B00B - R0003 - Movement

No Asbestos

B00B - R0004 - Entry Vestibule

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4192/B00B/R0012/Ceiling Structures/Linings/S28				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	

B00B - R0005 - Communal Space

No Asbestos

B00B - R0006 - Communal Space

No Asbestos

B00B - R0007 - General Storeroom

No Asbestos

B00B - R0008 - General Storeroom

No Asbestos

B00B - R0009 - Personal Effects Storage

No Asbestos

B00B - R0010 - Movement

No Asbestos

B00B - R0011 - Plant

No Asbestos

B00B - R0012 - Entry Vestibule

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4192/B00B/R0012/Ceiling Structures/Linings/S28				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	

B00B - R0013 - Cleaning Distributed Store

No Asbestos

B00B - R0014 - Home Base

No Asbestos

B00B - R0015 - Entry Vestibule

In-fill-panel	Flat AC Sheeting	1m	North, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4192/B00B/R0015/In-fill-panel/S7				Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4192/B00B/R0012/Ceiling Structures/Linings/S28				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00B - R0016 - Movement						
No Asbestos						
B00B - R0017 - Personal Effects Storage						
No Asbestos						
B00B - R0018 - Home Base Store						
No Asbestos						
B00B - R0019 - Home Base						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Other-Regional Use - 1960 - Brick/Veneer (Brick/Veneer)

Exterior

Eaves Linings	Flat AC Sheeting	40m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4192/B00A/Eaves Linings/S22				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Gable Verge Lining	Flat AC Sheeting	10m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4192/B00A/Gable Verge Lining/S23				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00C - R0001 - Entry Vestibule

In-fill-panel	Flat AC Sheeting	1m	South, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4192/B00C/R0001/In-fill-panel/S5				Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4192/B00C/R0001/Ceiling Structures/Linings/S6				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00C - R0002 - Entry Vestibule

In-fill-panel	Flat AC Sheeting	1m	South, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4192/B00C/R0001/In-fill-panel/S5				Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4192/B00C/R0001/Ceiling Structures/Linings/S6				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00C - R0003 - Movement

No Asbestos

B00C - R0004 - Other - Regional Use

No Asbestos

B00C - R0005 - Other - Regional Use

No Asbestos

B00C - R0006 - Other - Regional Use

No Asbestos

B00C - R0007 - Other - Regional Use

No Asbestos

B00C - R0008 - Other - Regional Use

No Asbestos

B00C - R0009 - Other - Regional Use

No Asbestos

B00C - R0010 - Other - Regional Use

No Asbestos

B00C - R0011 - Other - Regional Use

No Asbestos

B00C - R0012 - Other - Regional Use

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Pupil Facilities - 1960 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	20m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	4192/B00A/Eaves Linings/S22					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00D - R0001 - Drinking Facilities

No Asbestos

B00D - R0002 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet					No Asbestos Detected
	4192/B00D/R0002/Partition Walls (Cubicles)/S8					

B00D - R0003 - Cleaning Distributed Store

No Asbestos

B00D - R0004 - P.E. Store

No Asbestos

B00D - R0005 - General Storeroom

No Asbestos

B00D - R0006 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet					No Asbestos Detected
	4192/B00D/R0002/Partition Walls (Cubicles)/S8					

B00D - R0007 - Drinking Facilities

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning - 1970 - Brick/Veneer (Brick/Veneer)

Exterior

Eaves Linings	Flat AC Sheeting	40m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4192/B00A/Eaves Linings/S22				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Gable Verge Lining	Flat AC Sheeting	10m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4192/B00A/Gable Verge Lining/S23				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00E - R0001 - Home Base

No Asbestos

B00E - R0002 - Home Base Store

No Asbestos

B00E - R0003 - Personal Effects Storage

No Asbestos

B00E - R0004 - Movement

No Asbestos

B00E - R0005 - Cleaning Distributed Store

No Asbestos

B00E - R0006 - Entry Vestibule

In-fill-panel	Flat AC Sheeting	1m	North, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4192/B00E/R0006/In-fill-panel/S9				Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4192/B00E/R0006/Ceiling Structures/Linings/S10				Chrysotile (white asbestos)	

B00E - R0007 - Cleaning Distributed Store

No Asbestos

B00E - R0008 - Home Base Store

No Asbestos

B00E - R0009 - Home Base

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Library - 1970 - Brick/Veneer (Brick/Veneer)

Exterior

Eaves Linings	Flat AC Sheeting	20m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	4192/B00A/Eaves Linings/S22				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Gable Verge Lining	Flat AC Sheeting	10m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4192/B00A/Gable Verge Lining/S23				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
In-fill-panel	Flat AC Sheeting	8m2	East, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4192/B00F/In-fill-panel/S11				Chrysotile (white asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00F - R0001 - General Storeroom

No Asbestos

B00F - R0002 - Reading Area

No Asbestos

B00F - R0003 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	27m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4192/B00F/R0003/Ceiling Structures/Linings/S12				Chrysotile (white asbestos)	
In-fill-panel	Flat AC Sheeting	1m	East, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4192/B00F/In-fill-panel/S11				Chrysotile (white asbestos)	

B00F - R0004 - Library Office/Workroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Pupil Facilities - 1960 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4192/B00A/Eaves Linings/S22					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00G - R0001 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4192/B00G/R0005/Ceiling Structures/Linings/S20					Chrysotile (white asbestos)

B00G - R0002 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4192/B00G/R0005/Ceiling Structures/Linings/S20					Chrysotile (white asbestos)

B00G - R0003 - Canteen Office/Store

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4192/B00G/R0005/Ceiling Structures/Linings/S20					Chrysotile (white asbestos)

B00G - R0004 - Canteen Office/Store

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4192/B00G/R0005/Ceiling Structures/Linings/S20					Chrysotile (white asbestos)

B00G - R0005 - Canteen

Ceiling Structures/Linings	Flat AC Sheeting	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4192/B00G/R0005/Ceiling Structures/Linings/S20					Chrysotile (white asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - General Learning - 1959 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting 4192/B00H/Eaves Linings/S26					No Asbestos Detected
Gable Ends	Flat AC Sheeting 4192/B00H/Gable Ends/S25	6m2	East	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00H - R0001 - Home Base Store

No Asbestos

B00H - R0002 - Movement

Floor Coverings Res/Textile	Vinyl Tiles 4192/B00H/R0004/Floor Coverings Res/Textile/S13	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
-----------------------------	--	------	------------	--------------------	---------	--

B00H - R0003 - Craft Store

Ceiling Structures/Linings	Flat AC Sheeting 4192/B00H/R0003/Ceiling Structures/Linings/S14	5m2	East	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	--	-----	------	--------------------	---------	--

B00H - R0004 - Home Base

Floor Coverings Res/Textile	Vinyl Tiles 4192/B00H/R0004/Floor Coverings Res/Textile/S13	48m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
-----------------------------	--	------	------------	--------------------	---------	--

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - General Learning - 1959 - Brick/Veneer (Brick/Veneer)

Exterior

Eaves Linings	Flat AC Sheeting	60m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4192/B00A/Eaves Linings/S22				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Gable Verge Lining	Flat AC Sheeting	10m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4192/B00A/Gable Verge Lining/S23				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00J - R0001 - Home Base

No Asbestos

B00J - R0002 - Personal Effects Storage

No Asbestos

B00J - R0003 - Movement

No Asbestos

B00J - R0004 - General Storeroom

No Asbestos

B00J - R0005 - Staff Room Annexe

No Asbestos

B00J - R0006 - Personal Effects Storage

No Asbestos

B00J - R0007 - Home Base

No Asbestos

B00J - R0008 - Movement

In-fill-panel	Flat AC Sheeting	1m	South, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4192/B00J/R0008/In-fill-panel/S16				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4192/B00J/R0008/Ceiling Structures/Linings/S15				Chrysotile (white asbestos) , Amosite (brown asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - General Learning - 1960 - Brick/Veneer (Brick/Veneer)

Exterior

Eaves Linings	Flat AC Sheeting	80m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4192/B00A/Eaves Linings/S22				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Gable Verge Lining	Flat AC Sheeting	10m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4192/B00A/Gable Verge Lining/S23				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00K - R0001 - Home Base

No Asbestos

B00K - R0002 - Personal Effects Storage

No Asbestos

B00K - R0003 - General Storeroom

No Asbestos

B00K - R0004 - Movement

No Asbestos

B00K - R0005 - Cleaning Distributed Store

No Asbestos

B00K - R0006 - Staff Room Annexe

No Asbestos

B00K - R0007 - General Storeroom

No Asbestos

B00K - R0008 - Home Base

No Asbestos

B00K - R0009 - Movement

In-fill-panel	Flat AC Sheeting	1m	South, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4192/B00K/R0009/In-fill-panel/S17				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00K - R0010 - Movement

In-fill-panel	Flat AC Sheeting	1m	South, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4192/B00K/R0009/In-fill-panel/S17				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00K - R0011 - Home Base

No Asbestos

B00K - R0012 - Personal Effects Storage

No Asbestos

B00K - R0013 - Movement

No Asbestos

B00K - R0014 - Staff Toilet

No Asbestos

B00K - R0016 - Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Pupil Facilities - 1960 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					
Sheeting and Debris	AC Fragments/Debris					
	4192/B00L/Sheeting and Debris/S29					No Asbestos Detected

Interior

B00L - R0001 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet					
	4192/B00L/R0002/Partition Walls (Cubicles)/S18					No Asbestos Detected

B00L - R0002 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet					
	4192/B00L/R0002/Partition Walls (Cubicles)/S18					No Asbestos Detected

B00L - R0003 - Drinking Facilities

No Asbestos

B00L - R0004 - Drinking Facilities

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - General Learning - 1960 - Brick/Veneer (Brick/Veneer)

Exterior

Eaves Linings	Flat AC Sheeting	60m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4192/B00A/Eaves Linings/S22				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4192/B00A/Gable Verge Lining/S23				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00M - R0001 - Home Base

No Asbestos

B00M - R0002 - Personal Effects Storage

No Asbestos

B00M - R0003 - Movement

No Asbestos

B00M - R0004 - General Storeroom

No Asbestos

B00M - R0005 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4192/B00M/R0008/Ceiling Structures/Linings/S19				Chrysotile (white asbestos)	

B00M - R0006 - Staff Room Annexe

No Asbestos

B00M - R0007 - Home Base

No Asbestos

B00M - R0008 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4192/B00M/R0008/Ceiling Structures/Linings/S19				Chrysotile (white asbestos)	

B00M - R0009 - Movement

No Asbestos

B00M - R0010 - P.E. Store

No Asbestos

B00M - R0011 - Personal Effects Storage

No Asbestos

B00M - R0012 - Home Base

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00N - Pupil Facilities/Communal Facilities - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00N - R0001 - Communal Space

No Asbestos

B00N - R0002 - Raised Platform

No Asbestos

B00N - R0003 - Movement

No Asbestos

B00N - R0004 - Movement

No Asbestos

B00N - R0005 - Movement

No Asbestos

B00N - R0006 - Hall Chair Store

No Asbestos

B00N - R0007 - Communal/Performance Store

No Asbestos

B00N - R0008 - P.E. Store

No Asbestos

B00N - R0009 - Toilet - Lobby

No Asbestos

B00N - R0010 - Toilets - Girls

No Asbestos

B00N - R0011 - Sound Cupboard

No Asbestos

B00N - R0012 - Toilet - Lobby

No Asbestos

B00N - R0013 - Toilets - Boys

No Asbestos

B00N - R0014 - Cleaning Distributed Store

No Asbestos

B00N - R0015 - Toilet - P

No Asbestos

B00N - R0016 - Main Switch Board

No Asbestos

B00N - R0017 - Covered Outdoor Learning Area

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017