

# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Blacksmiths Public School (4197)  
**Region :** Hunter/Central Coast  
**State Electorate :** Swansea  
**Local Government Area :** Lake Macquarie

**Initial Survey :** Noel Arnold & Associates : 28 - May - 2008  
**Reviewed By :** AECOM : 27 - Jun - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - General Learning/Administration - 1963 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible no access points.					
In-fill-panel	Flat AC Sheeting 4197/B00A/Panelling Under all Windows/S6					<b>No Asbestos Detected</b>
Eaves Linings	Flat AC Sheeting 4197/B00A/R0026/Ceiling Structures/Linings/S14	100m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
Underfloor Voids	AC Fragments/Debris 4197/B00A/Underfloor Voids/S15	0.02m2	Debris fcs panel to ground, directly below AR0002	Poor Condition - Extensive Damage (4)	Medium (2)	High Priority (6-8)
						<b>Chrysotile (white asbestos)</b>

**Interior**

**B00A - R0002 - Principal**

Floor Coverings Res/Textile	Vinyl Tiles 4197/B00A/R0002/Floor Coverings Res/Textile/S1					<b>No Asbestos Detected</b>
-----------------------------	---	--	--	--	--	-----------------------------

**B00A - R0003 - Staff Toilet**

Floor Coverings Res/Textile	Vinyl Tiles 4197/B00A/R0002/Floor Coverings Res/Textile/S1					<b>No Asbestos Detected</b>
-----------------------------	---	--	--	--	--	-----------------------------

**B00A - R0004 - Staff Toilet**

Floor Coverings Res/Textile	Vinyl Tiles 4197/B00A/R0002/Floor Coverings Res/Textile/S1					<b>No Asbestos Detected</b>
-----------------------------	---	--	--	--	--	-----------------------------

**B00A - R0005 - Staff Room**

Floor Coverings Res/Textile	Vinyl Tiles 4197/B00A/R0002/Floor Coverings Res/Textile/S1					<b>No Asbestos Detected</b>
-----------------------------	---	--	--	--	--	-----------------------------

**B00A - R0006 - Duplicating Workroom**

Floor Coverings Res/Textile	Vinyl Sheet 4197/B00A/R0008/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>
-----------------------------	---	--	--	--	--	-----------------------------

**B00A - R0007 - Clerical Office**

No Asbestos

**B00A - R0008 - Entry Vestibule**

Floor Coverings Res/Textile	Vinyl Sheet 4197/B00A/R0008/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>
In-fill-panel	Flat AC Sheeting 4197/B00A/R0014/Wall Linings Internal/S4					<b>No Asbestos Detected</b>

**B00A - R0009 - Home Base Store**

No Asbestos

**B00A - R0010 - Home Base**

No Asbestos

**B00A - R0011 - Home Base**

No Asbestos

**B00A - R0012 - Home Base Store**

No Asbestos

**B00A - R0013 - P.E. Store**

No Asbestos

**B00A - R0014 - Movement**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No						Test Result
Floor Coverings Res/Textile	Vinyl Sheet					
	4197/B00A/R0008/Floor Coverings Res/Textile/S2					No Asbestos Detected
In-fill-panel	Flat AC Sheeting					
	4197/B00A/R0014/Wall Linings Internal/S4					No Asbestos Detected
<b>B00A - R0016 - Library Office/Workroom</b>						
No Asbestos						
<b>B00A - R0017 - K.L.A. Store</b>						
No Asbestos						
<b>B00A - R0018 - Reading Area</b>						
No Asbestos						
<b>B00A - R0019 - Home Base</b>						
No Asbestos						
<b>B00A - R0020 - Practical Activities - 1hb</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	4197/B00A/R0002/Floor Coverings Res/Textile/S1					No Asbestos Detected
<b>B00A - R0021 - Toilets - Boys/Girls</b>						
Wall Linings Internal	Flat AC Sheeting	20m2	Throughout, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4197/B00A/R0021/Wall Linings Internal/S5					Chrysotile (white asbestos)
<b>B00A - R0022 - Home Base Store</b>						
No Asbestos						
<b>B00A - R0023 - Personal Effects Storage</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	4197/B00A/R0002/Floor Coverings Res/Textile/S1					No Asbestos Detected
<b>B00A - R0024 - Movement</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	4197/B00A/R0002/Floor Coverings Res/Textile/S1					No Asbestos Detected
In-fill-panel	Flat AC Sheeting					
	4197/B00A/R0014/Wall Linings Internal/S4					No Asbestos Detected
<b>B00A - R0026 - External Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting	36m2	North awning linings x 3	Good Condition (1)	Low (1)	Low Priority (2-3)
	4197/B00A/R0026/Ceiling Structures/Linings/S14					Chrysotile (white asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - General Learning/Pupil Facilities - 1962 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Packing to Floor Joists	No Asbestos Found					
Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible no access points.					
Eaves Linings	Flat AC Sheeting	50m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4197/B00B/R0005/Ceiling Structures/Linings/S8				<b>Chrysotile (white asbestos)</b>	
In-fill-panel	Flat AC Sheeting	40m2	North, South, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4197/B00B/Panelling Under all Windows/S7				<b>Chrysotile (white asbestos)</b>	

**Interior**

**B00B - R0001 - Canteen**

Floor Coverings Res/Textile	Vinyl Tiles					
	4197/B00B/R0003/Floor Coverings Res/Textile/S9				<b>No Asbestos Detected</b>	

**B00B - R0002 - General Storeroom**

No Asbestos

**B00B - R0003 - General Storeroom**

Floor Coverings Res/Textile	Vinyl Tiles					
	4197/B00B/R0003/Floor Coverings Res/Textile/S9				<b>No Asbestos Detected</b>	

**B00B - R0004 - Movement**

Floor Coverings Res/Textile	Vinyl Tiles					
	4197/B00B/R0003/Floor Coverings Res/Textile/S9				<b>No Asbestos Detected</b>	
In-fill-panel	Flat AC Sheeting					
	4197/B00B/R0004/Panel Above Doorway/S10				<b>No Asbestos Detected</b>	

**B00B - R0005 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4197/B00B/R0005/Ceiling Structures/Linings/S8				<b>Chrysotile (white asbestos)</b>	

**B00B - R0006 - Home Base**

No Asbestos

**B00B - R0007 - Home Base Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - Pupil Facilities/Building Services - 1963 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible no access points.					
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible slab to ground, no access points					
In-fill-panel	Flat AC Sheeting 4197/B00C/Panels Above Windows/S12					<b>No Asbestos Detected</b>

**Interior**

**B00C - R0001 - Toilets - Girls**

Ceiling Structures/Linings	Flat AC Sheeting	21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4197/B00C/R0001/Ceiling Structures/Linings/S11					<b>Chrysotile (white asbestos)</b>

**B00C - R0002 - General Storeroom**

Ceiling Structures/Linings	Flat AC Sheeting	33m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4197/B00C/R0001/Ceiling Structures/Linings/S11					<b>Chrysotile (white asbestos)</b>

**B00C - R0003 - Toilets - Boys**

Ceiling Structures/Linings	Flat AC Sheeting	21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4197/B00C/R0001/Ceiling Structures/Linings/S11					<b>Chrysotile (white asbestos)</b>

**B00C - R0004 - General Assistant/Bulk Store**

Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4197/B00C/R0001/Ceiling Structures/Linings/S11					<b>Chrysotile (white asbestos)</b>

**B00C - R0005 - Sports Store**

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4197/B00C/R0001/Ceiling Structures/Linings/S11					<b>Chrysotile (white asbestos)</b>

**B00C - R0006 - Cleaning Distributed Store**

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4197/B00C/R0001/Ceiling Structures/Linings/S11					<b>Chrysotile (white asbestos)</b>

**B00C - R0007 - External Movement**

Ceiling Structures/Linings	Flat AC Sheeting	26m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4197/B00C/R0001/Ceiling Structures/Linings/S11					<b>Chrysotile (white asbestos)</b>
In-fill-panel	Flat AC Sheeting	1m	West, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4197/B00C/R0007/Panel Above Window/S13					<b>Chrysotile (white asbestos)</b>

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - General Learning - 1962 - Fibre Cement Clad (Fibre Cement Clad)**

**Exterior**

Underfloor Voids - Slab on Ground      Non Accessible Area  
 - Area inaccessible no access point.

Ceiling Voids - Flat Roof      No Asbestos Found

**Interior**

**B00D - R0001 - Outdoor Learning Area**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - Communal Facilities/Pupil Facilities - 2010 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible no access points.
Ceiling Voids	No Asbestos Found

**Interior**

**B00E - R0001 - Covered Outdoor Learning Area**

No Asbestos

**B00E - R0002 - Access Shower/Toilet**

No Asbestos

**B00E - R0003 - Communal Space**

No Asbestos

**B00E - R0004 - P.E. Store**

No Asbestos

**B00E - R0005 - Main Switch Board**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

## Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 505 - D16084 - Admin Staff/Principal/Secure Store : Placement Date - 24/10/2002

### Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2

### Interior

#### R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2

#### R2 - Principal

Ceiling	Flat AC Sheet	Assumed Asbestos				16 m2
---------	---------------	------------------	--	--	--	-------

#### R3 - Staff Room

Ceiling	Flat AC Sheet	Assumed Asbestos				20 m2
---------	---------------	------------------	--	--	--	-------

#### R4 - Security Store

Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
---------	---------------	------------------	--	--	--	------

#### R5 - Clerical Office

End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				18 m2

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017