

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Burraneer Bay Public School (4259)
Region : Sydney
State Electorate : Cronulla
Local Government Area : Sutherland

Initial Survey : Noel Arnold & Associates : 21 - Mar - 2008
Reviewed By : Parsons Brinckerhoff : 01 - Nov - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00A - Administration/General Learning - 1950 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4259/B00B/Eaves Linings/S17				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Gable verge lining	Flat AC Sheeting	15m	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Includes Gable ends					
Ceiling lining	Flat AC Sheeting	8m2	Walkway between B00A and B00B	Good Condition (1)	Low (1)	Low Priority (2-3)
	4259/B00A/Ceiling lining/S49				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Gable Ends	Corrugated AC Sheeting	20m2	East & West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4259/B00A/Gable Ends/S26				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Underfloor Voids	AC Fragments/Debris				No Asbestos Detected	
	4259/B00A/Underfloor Voids/S31					
Ceiling Void	No Asbestos Found					

Interior

B00A - R0001 - Home Base

Wall Linings Internal	Flat AC Sheeting	1m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	4259/B00A/R0001/Wall Linings Internal/S6				Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering)	57m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4259/B00A/R0022/Floor Coverings Res/Textile/S43				Chrysotile (white asbestos)	

B00A - R0002 - Home Base Store

No Asbestos

B00A - R0003 - Personal Effects Storage

No Asbestos

B00A - R0004 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting				No Asbestos Detected	
	4259/B00A/R0027/Ceiling Structures/Linings/S5					
Infill panel	Flat AC Sheeting	0.2m2	Above northern doorway	Good Condition (1)	Low (1)	Low Priority (2-3)
	4259/B00A/R0027/Infill panel/S39				Chrysotile (white asbestos)	

B00A - R0021 - Home Base/Practical Activities

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering)	65m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4259/B00A/R0022/Floor Coverings Res/Textile/S43				Chrysotile (white asbestos)	

B00A - R0022 - Entry Vestibule

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering)	6.5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4259/B00A/R0022/Floor Coverings Res/Textile/S43				Chrysotile (white asbestos)	

B00A - R0023 - Special Programs Room

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering)	44m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4259/B00A/R0022/Floor Coverings Res/Textile/S43				Chrysotile (white asbestos)	

B00A - R0024 - Special Programs Store

No Asbestos

B00A - R0025 - Home Base Store

No Asbestos

B00A - R0026 - Main Switch Board

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R0027 - External Movement						
Ceiling Structures/Linings	Flat AC Sheeting 4259/B00A/R0027/Ceiling Structures/Linings/S5				No Asbestos Detected	
Infill panel	Flat AC Sheeting 4259/B00A/R0027/Infill panel/S39	0.2m2	Above northern doorway	Good Condition (1)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos)	
B00A - R9001 - Sports Store						
Ceiling Structures/Linings	Flat AC Sheeting 4259/B00A/R9001/Ceiling Structures/Linings/S7	21m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos) , Amosite (brown asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 1950 - Concrete (Concrete)

Exterior

Eaves Linings	Flat AC Sheeting 4259/B00B/Eaves Linings/S17	4m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Gable verge lining	Flat AC Sheeting 4259/B00B/Gable verge lining/S22	10m	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Gable Ends	Flat AC Sheeting 4259/B00B/Gable Ends/S27	3m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos) , Amosite (brown asbestos)	
Underfloor Voids	Flat AC Sheeting 4259/B00B/Underfloor Voids/S33	1m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
					Chrysotile (white asbestos)	
Ceiling Void	No Asbestos Found					

Interior

B00B - R0001 - Home Base

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering) 4259/B00B/R0001/Floor Coverings Res/Textile/S44					No Asbestos Detected
-----------------------------	---------------------------------------------------------------------------------------	--	--	--	--	-----------------------------

B00B - R0002 - Home Base Store

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering) 4259/B00B/R0001/Floor Coverings Res/Textile/S44					No Asbestos Detected
-----------------------------	---------------------------------------------------------------------------------------	--	--	--	--	-----------------------------

B00B - R0003 - Personal Effects Storage

No Asbestos

B00B - R0004 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00B - R0005 - Movement

No Asbestos

B00B - R0006 - Home Base

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering) 4259/B00B/R0001/Floor Coverings Res/Textile/S44					No Asbestos Detected
-----------------------------	---------------------------------------------------------------------------------------	--	--	--	--	-----------------------------

B00B - R0007 - Home Base Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00C - General Learning/Music - 1950 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting 4259/B00B/Eaves Linings/S17	40m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
Gable verge lining	Flat AC Sheeting 4259/B00B/Gable verge lining/S22	10m	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
Underfloor Voids	AC Fragments/Debris 4259/B00C/Underfloor Voids/S32	1m2	Variable positions	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ground Area	AC Fragments/Debris 4259/B00C/Ground Area/S35	1m2	Apparently found near Demountable D13713 by student	Poor Condition - Extensive Damage (4)	Medium (2)	High Priority (6-8)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Void	No Asbestos Found					

Interior**B00C - R0001 - Home Base**

No Asbestos

B00C - R0002 - Home Base Store

No Asbestos

B00C - R0003 - Movement

No Asbestos

B00C - R0004 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 4259/B00C/R0011/Ceiling Structures/Linings/S10	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		
Infill panel	Flat AC Sheeting 4259/B00A/R0027/Infill panel/S39	0.2m2	Above northern doorway	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos)		

B00C - R0005 - Craft Store

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering) 4259/B00C/R0005/Floor Coverings Res/Textile/S45	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos)		

B00C - R0006 - Home Base Store

No Asbestos

B00C - R0007 - Home Base

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering) 4259/B00C/R0005/Floor Coverings Res/Textile/S45	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos)		

B00C - R0008 - Home Base Store

Floor Coverings Res/Textile	Vinyl Tiles 4259/B00C/R0013/Floor Coverings Res/Textile/S11	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos)		

B00C - R0009 - Personal Effects Storage

No Asbestos

B00C - R0010 - Movement

No Asbestos

B00C - R0011 - Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4259/B00C/R0011/Ceiling Structures/Linings/S10				Chrysotile (white asbestos) , Amosite (brown asbestos)		
Infill panel	Flat AC Sheeting	0.2m2	Above northern doorway	Good Condition (1)	Low (1)	Low Priority (2-3)
4259/B00A/R0027/Infill panel/S39				Chrysotile (white asbestos)		
B00C - R0012 - Home Base						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering)	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4259/B00C/R0005/Floor Coverings Res/Textile/S45				Chrysotile (white asbestos)		
B00C - R0013 - Home Base Store						
Floor Coverings Res/Textile	Vinyl Tiles	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4259/B00C/R0013/Floor Coverings Res/Textile/S11				Chrysotile (white asbestos)		
B00C - R9001 - Practical Activities - 1hb						
Ceiling Structures/Linings	Flat AC Sheeting	55m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4259/B00C/R9001/Ceiling Structures/Linings/S8				Chrysotile (white asbestos)		
Floor Coverings Res/Textile	Vinyl Tiles	55m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
4259/B00C/R9001/Floor Coverings Res/Textile/S9				Chrysotile (white asbestos)		
B00C - R9002 - Security Store						
No Asbestos						
B00C - R9003 - Out Of School Hours Care Centre						
No Asbestos						
B00C - R9004 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	56m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4259/B00C/R9001/Ceiling Structures/Linings/S8				Chrysotile (white asbestos)		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning/Library - 1950 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	65m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4259/B00E/Eaves Linings/S18				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Gable verge lining	Flat AC Sheeting	5m	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4259/B00E/Gable verge lining/S23				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Void	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00E - R0001 - Home Base**

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering)					
	4259/B00E/R0001/Floor Coverings Res/Textile/S46				No Asbestos Detected	

B00E - R0002 - Home Base Store

Floor Coverings Res/Textile	Vinyl Tiles	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4259/B00C/R0013/Floor Coverings Res/Textile/S11				Chrysotile (white asbestos)	

B00E - R0003 - Personal Effects Storage

No Asbestos

B00E - R0004 - Movement

No Asbestos

B00E - R0005 - External Movement

No Asbestos

B00E - R0006 - Personal Effects Storage

No Asbestos

B00E - R0007 - Home Base Store

Floor Coverings Res/Textile	Vinyl Tiles	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4259/B00C/R0013/Floor Coverings Res/Textile/S11				Chrysotile (white asbestos)	

B00E - R0008 - Home Base

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering)					
	4259/B00E/R0001/Floor Coverings Res/Textile/S46				No Asbestos Detected	

B00E - R0013 - External Movement

No Asbestos

B00E - R0024 - External Movement

No Asbestos

B00E - R0025 - Reading Area

No Asbestos

B00E - R0026 - Library Office/Workroom

No Asbestos

B00E - R0027 - Communications Room

No Asbestos

B00E - R0028 - K.L.A. Store

No Asbestos

B00E - R0029 - Staff Toilet

No Asbestos

B00E - R0030 - Main Switch Board

No Asbestos

B00E - R0031 - Entry Vestibule

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Pupil Facilities - 1950 - Concrete (Concrete)

Exterior

Eaves Linings	Flat AC Sheeting	40m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4259/B00F/Eaves Linings/S1				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Infill panel	Fibre cement sheeting				No Asbestos Detected	
	4259/B00F/Infill panel/S38					
Eaves Linings	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4259/B00F/Eaves Linings/S19				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Ceiling Void	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00F - R0003 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting	34m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4259/B00F/R0004/Ceiling Structures/Linings/S2				Chrysotile (white asbestos)	
Wall Linings Internal	Flat AC Sheeting				No Asbestos Detected	
	4259/B00F/R0004/Wall Linings Internal/S3					
Infill panels	Flat AC Sheeting	0.8m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	4259/B00F/R0003/Infill panels/S42				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	

B00F - R0004 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting	33m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4259/B00F/R0004/Ceiling Structures/Linings/S2				Chrysotile (white asbestos)	
Wall Linings Internal	Flat AC Sheeting				No Asbestos Detected	
	4259/B00F/R0004/Wall Linings Internal/S3					
Infill panels	Flat AC Sheeting	0.8m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	4259/B00F/R0003/Infill panels/S42				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	

B00F - R0005 - Cleaning Distributed Store

Ceiling Structures/Linings	Flat AC Sheeting	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4259/B00F/R0004/Ceiling Structures/Linings/S2				Chrysotile (white asbestos)	
Wall Linings Internal	Flat AC Sheeting				No Asbestos Detected	
	4259/B00F/R0004/Wall Linings Internal/S3					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Pupil Facilities - 1950 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	11m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	4259/B00G/Eaves Linings/S4			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Void	AC Fragments/Debris	1m2	Variable positions	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5)
	4259/B00G/Ceiling Void/S29			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Void	Flat AC Sheeting	50m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
	4259/B00G/Ceiling Void/S30			Chrysotile (white asbestos) , Amosite (brown asbestos)		

Interior

B00G - R0001 - Drinking Facilities

No Asbestos

B00G - R0009 - Drinking Facilities

No Asbestos

B00G - R0011 - Canteen

No Asbestos

B00G - R0012 - Staff Toilet

No Asbestos

B00G - R0013 - Canteen Office/Store

No Asbestos

B00G - R0014 - Canteen Covered Area

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - General Learning - 1950 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting 4259/B00J/Eaves Linings/S20	8m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Crocidolite (blue asbestos)
Gable verge lining	Flat AC Sheeting 4259/B00J/Gable verge lining/S24	10m	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
Wall Cladding	Flat AC Sheeting 4259/B00J/Wall Cladding/S12					No Asbestos Detected
Ceiling Void	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00J - R0001 - Home Base

No Asbestos

B00J - R0002 - Personal Effects Storage

No Asbestos

B00J - R0003 - Movement

No Asbestos

B00J - R0004 - Movement

No Asbestos

B00J - R0005 - Toilets - Boys/Girls

No Asbestos

B00J - R0006 - Hall Chair Store

Wall Linings Internal	Flat AC Sheeting 4259/B00J/Wall Cladding/S12					No Asbestos Detected
-----------------------	-------------------------------------------------	--	--	--	--	-----------------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - General Learning/Pupil Facilities - 1950 - Concrete (Concrete)**Exterior**

Eaves Linings	Flat AC Sheeting 4259/B00L/Eaves Linings/S21	8m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Gable verge lining	Flat AC Sheeting 4259/B00L/Gable verge lining/S25	10m	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos) , Amosite (brown asbestos)	
Wall Cladding	Compressed AC Sheet 4259/B00L/Wall Cladding/S37					No Asbestos Detected
Underfloor Voids	Flat AC Sheeting 4259/B00L/Underfloor Voids/S34	1m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
					Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Void	AC Fragments/Debris 4259/B00L/Ceiling Void/S28					No Asbestos Detected

Interior**B00L - R0001 - Movement**

Wall Linings Internal	Flat AC Sheeting 4259/B00L/R0001/Wall Linings Internal/S13					No Asbestos Detected
-----------------------	---------------------------------------------------------------	--	--	--	--	-----------------------------

B00L - R0002 - Home Base

No Asbestos

B00L - R0003 - Practical Activities - 1hb

No Asbestos

B00L - R0004 - Personal Effects Storage

No Asbestos

B00L - R0005 - Staff Toilet

No Asbestos

B00L - R0006 - Movement

No Asbestos

B00L - R0007 - Withdrawal Space - 1hb

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering) 4259/B00L/R0021/Floor Coverings Res/Textile/S48					No Asbestos Detected
--------------------------------	------------------------------------------------------------------------------------------	--	--	--	--	-----------------------------

B00L - R0008 - General Storeroom

No Asbestos

B00L - R0009 - Movement

No Asbestos

B00L - R0010 - Cleaning Distributed Store

No Asbestos

B00L - R0011 - Movement

Floor Coverings Res/Textile	Vinyl Tiles 4259/B00L/R0011/Floor Coverings Res/Textile/S16					No Asbestos Detected
--------------------------------	----------------------------------------------------------------	--	--	--	--	-----------------------------

Ceiling Structures/Linings	Flat AC Sheeting 4259/B00L/R0011/Ceiling Structures/Linings/S15	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos) , Amosite (brown asbestos)	

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering) 4259/B00L/R0021/Floor Coverings Res/Textile/S48					No Asbestos Detected
--------------------------------	------------------------------------------------------------------------------------------	--	--	--	--	-----------------------------

B00L - R0012 - Personal Effects Storage

No Asbestos

B00L - R0013 - Home Base Store

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
No Asbestos						
B00L - R0014 - Home Base						
No Asbestos						
B00L - R0017 - Home Base						
Ceiling Structures/Linings	Flat AC Sheeting	50m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4259/B00L/R0021/Ceiling Structures/Linings/S36				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering)	3m2	Residual floor around perimeter of room	Poor Condition (Extensive Damage) - (4)	Medium (2)	High Priority (6-8)
	4259/B00L/R0018/Floor Coverings Res/Textile/S47				Chrysotile (white asbestos)	
Wall Linings Internal	Flat AC Sheeting	20m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4259/B00L/R0018/Wall Linings Internal/S40				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
B00L - R0018 - Home Base						
Ceiling Structures/Linings	Flat AC Sheeting	50m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4259/B00L/R0021/Ceiling Structures/Linings/S36				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Wall Linings Internal	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4259/B00L/R0018/Wall Linings Internal/S40				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering)	50m2	Residual floor around perimeter of room	Good Condition (1)	Low (1)	Low Priority (2-3)
	4259/B00L/R0018/Floor Coverings Res/Textile/S47				Chrysotile (white asbestos)	
B00L - R0019 - Duplicating Workroom						
Floor Coverings Res/Textile	Vinyl Tiles	13m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4259/B00L/R0019/Floor Coverings Res/Textile/S14				Chrysotile (white asbestos)	
B00L - R0020 - General Storeroom						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4259/B00L/R0011/Ceiling Structures/Linings/S15				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Wall Linings Internal	Flat AC Sheeting	3.5m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	4259/B00L/R0018/Wall Linings Internal/S40				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
B00L - R0021 - Movement						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering)					No Asbestos Detected
	4259/B00L/R0011/Floor Coverings Res/Textile/S16					
Ceiling Structures/Linings	Flat AC Sheeting	58m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4259/B00L/R0011/Ceiling Structures/Linings/S15				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	4259/B00L/R0021/Wall Linings Internal/S41					
Ceiling Structures/Linings	Flat AC Sheeting	58m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4259/B00L/R0021/Ceiling Structures/Linings/S36				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					No Asbestos Detected
	4259/B00L/R0021/Floor Coverings Res/Textile/S48					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00L - R0022 - Sports Store						
No Asbestos						
B00L - R0023 - Movement						
No Asbestos						
B00L - R0025 - Home Base						
Ceiling Structures/Linings	Flat AC Sheeting	50m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4259/B00L/R0021/Ceiling Structures/Linings/S36			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
Wall Linings Internal	Flat AC Sheeting	20m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4259/B00L/R0018/Wall Linings Internal/S40			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
B00L - R0026 - Home Base						
Ceiling Structures/Linings	Flat AC Sheeting	50m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4259/B00L/R0021/Ceiling Structures/Linings/S36			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
Wall Linings Internal	Flat AC Sheeting	20m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4259/B00L/R0018/Wall Linings Internal/S40			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - Administration - 2006 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior**B00M - R0001 - Interview**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0002 - Entry Vestibule

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0003 - Movement

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0004 - Clerical Office

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0005 - Sick Bay

No Asbestos

B00M - R0006 - Access Shower/Toilet

No Asbestos

B00M - R0007 - Duplicating Workroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0008 - Cleaning Distributed Store

No Asbestos

B00M - R0009 - Main Switch Board

No Asbestos

B00M - R0010 - Security Store

No Asbestos

B00M - R0011 - Staff Toilet

No Asbestos

B00M - R0012 - Staff Toilet

No Asbestos

B00M - R0013 - Staff Toilet

No Asbestos

B00M - R0014 - Staff Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0015 - Staff Room Annexe

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0016 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0017 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0018 - Principal

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0019 - External Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - R0020 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00N - Communal Facilities - 2008 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00N - R0001 - Communal Space

No Asbestos

B00N - R0002 - Movement

No Asbestos

B00N - R0003 - Raised Platform

No Asbestos

B00N - R0004 - Ramp

No Asbestos

B00N - R0005 - Movement

No Asbestos

B00N - R0006 - External Stairs

No Asbestos

B00N - R0007 - External Movement

No Asbestos

B00N - R0008 - Communal/Performance Store

No Asbestos

B00N - R0009 - Cleaning Distributed Store

No Asbestos

B00N - R0010 - Main Switch Board

No Asbestos

B00N - R0011 - Cleaning Supplies

No Asbestos

B00N - R0012 - Sports Store

No Asbestos

B00N - R0013 - Toilets - Boys/Disabled Cubicle

No Asbestos

B00N - R0014 - Sound Cupboard

No Asbestos

B00N - R0015 - Toilet - Lobby

No Asbestos

B00N - R0016 - Access Shower/Toilet

No Asbestos

B00N - R0017 - Covered Outdoor Learning Area

No Asbestos

B00N - R0018 - External Movement

No Asbestos

B00N - R0019 - Toilets - Girls/Disabled Cubicle

No Asbestos

B00N - R0020 - Plant

No Asbestos

B00N - R0021 - General Assistant/Bulk Store

No Asbestos

B00N - R0022 - Hall Chair Store

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00N - R0023 - Staff Kitchen						
No Asbestos						
B00N - R0024 - Movement						
No Asbestos						
B00N - R0025 - Hall Chair Store						
No Asbestos						
B00N - R0026 - Kiln Room						
No Asbestos						
B00N - R0027 - External Stairs						
No Asbestos						
B00N - R0028 - External Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B000 - General Learning - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B000 - R0001 - Home Base/Practical Activities

No Asbestos

B000 - R0002 - Home Base Store

No Asbestos

B000 - R0003 - Withdrawal Space - 1hb

No Asbestos

B000 - R0004 - Practical Activities/Movement - 1hb

No Asbestos

B000 - R0005 - Home Base/Practical Activities

No Asbestos

B000 - R0006 - Practical Activities/Movement - 1hb

No Asbestos

B000 - R0007 - Home Base Store

No Asbestos

B000 - R0008 - Withdrawal Space - 2hb

No Asbestos

B000 - R0009 - Home Base/Practical Activities

No Asbestos

B000 - R0010 - Practical Activities/Movement - 1hb

No Asbestos

B000 - R0011 - Home Base Store

No Asbestos

B000 - R0012 - Special Programs Store

No Asbestos

B000 - R0013 - Special Programs Room - Type 1

No Asbestos

B000 - R0014 - External Movement

No Asbestos

B000 - R0015 - General Storeroom

No Asbestos

B000 - R0016 - Stairs

No Asbestos

B000 - R0017 - External Stairs

No Asbestos

B000 - R1001 - Home Base/Practical Activities

No Asbestos

B000 - R1002 - Home Base Store

No Asbestos

B000 - R1003 - Withdrawal Space - 1hb

No Asbestos

B000 - R1004 - Practical Activities/Movement - 1hb

No Asbestos

B000 - R1005 - Home Base/Practical Activities

No Asbestos

B000 - R1006 - Practical Activities/Movement - 1hb

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B000 - R1007 - Home Base Store

No Asbestos

B000 - R1008 - Withdrawal Space - 2hb

No Asbestos

B000 - R1009 - Home Base/Practical Activities

No Asbestos

B000 - R1010 - Practical Activities/Movement - 1hb

No Asbestos

B000 - R1011 - Home Base Store

No Asbestos

B000 - R1012 - External Movement

No Asbestos

B000 - R1013 - Stairs

No Asbestos

B000 - R1014 - External Stairs

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D12551 - Learning Unit - Standard With P.A.A. : Placement Date - 28/05/2009

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 601 - D13625 - Learning Unit - Standard/Withdrawal : Placement Date - 4/05/2005

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2
---------	---------------	------------------	-------

OS 601 - D13713 - Learning Unit - Standard/Withdrawal : Placement Date - 21/04/2004

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2
---------	---------------	------------------	-------

OS 603 - D14126 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 9/11/2004

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 601 - D14932 - Learning Unit - Standard/Withdrawal : Placement Date - 9/02/2008						
Exterior						
Step Treads	Compressed AC Sheet	Assumed Asbestos			1.08 m2	
Landing	Compressed AC Sheet	Assumed Asbestos			1.2 m2	
Eave Lining	Flat AC Sheet	Assumed Asbestos			11.52 m2	
Interior						
R1 - Entry						
End wall panel	Flat AC Sheet	Assumed Asbestos			18 m2	
Ceiling	Flat AC Sheet	Assumed Asbestos			8 m2	
R2 - General Learning Space						
End wall panel	Flat AC Sheet	Assumed Asbestos			18 m2	
Ceiling	Flat AC Sheet	Assumed Asbestos			55 m2	
R3 - Store						
Ceiling	Flat AC Sheet	Assumed Asbestos			10 m2	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

Available Asbestos Related Electronic Files

4259_ASB_150514_AMP.pdf

* Note : Refer to AMS for details of the attachment(s).

2017