

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Blaxland East Public School (4313)
Region : Western Sydney
State Electorate : Blue Mountains
Local Government Area : Blue Mountains

Initial Survey : Noel Arnold & Associates : 26 - Mar - 2008
Reviewed By : Parsons Brinckerhoff : 28 - May - 2015

4313 - Blaxland East Public School
Site Plan (10144)



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning/Pupil Facilities - 1978 - Brick/Veneer (Brick/Veneer)

Exterior

Gable Ends	Flat AC Sheeting 4313/B00A/Gable Ends/S10					No Asbestos Detected
Eaves Linings	Flat AC Sheeting 4313/B00C/Eaves Linings/S8	60m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
Gable Verge Lining	Flat AC Sheeting 4313/B00C/Gable Verge Lining/S9	10m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
Gable Ends	Corrugated AC Sheeting 4313/B00C/Gable Ends/S11	2m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00A - R0001 - Outdoor Learning Area (130.65 m2)

No Asbestos

B00A - R0002 - Toilets - Boys/Girls (1.48 m2)

No Asbestos

B00A - R0003 - Cleaning Distributed Store (1.45 m2)

No Asbestos

B00A - R0004 - Personal Effects Storage (11.77 m2)

No Asbestos

B00A - R0005 - Movement (4.99 m2)

No Asbestos

B00A - R0006 - Home Base (67.58 m2)

No Asbestos

B00A - R0007 - Practical Activities - 1hb (11.75 m2)

No Asbestos

B00A - R0008 - Home Base (85.71 m2)

No Asbestos

B00A - R0009 - Toilets - Boys/Girls (2.77 m2)

No Asbestos

B00A - R0010 - Practical Activities - 1hb (6.9 m2)

No Asbestos

B00A - R0011 - Movement (6.46 m2)

No Asbestos

B00A - R0012 - Personal Effects Storage (11.06 m2)

No Asbestos

B00A - R0013 - Home Base (57.04 m2)

No Asbestos

B00A - R0014 - Movement (6.39 m2)

No Asbestos

B00A - R0015 - General Storeroom (10.8 m2)

No Asbestos

B00A - R0016 - Movement (2.03 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00A - R0017 - Interview (17.49 m2)

No Asbestos

B00A - R0018 - General Storeroom (2.91 m2)

No Asbestos

B00A - R0019 - Distribution Board (1.02 m2)

Note: No inspection of live electrical installation.

Wall Linings Internal	Flat AC Sheeting	2m2	North facing, South facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
4313/B00A/R0019/Wall Linings Internal/S2					Chrysotile (white asbestos)	

B00A - R0020 - Movement (87.18 m2)

Ceiling Structures/Linings	Flat AC Sheeting	88m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4313/Build+1/Room+1/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00B - General Learning/Staff Facilities - 1967 - Brick/Veneer (Brick/Veneer)**Exterior**

Eaves Linings	Flat AC Sheeting	30m2	South facing, East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/B00C/Eaves Linings/S8			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Gable Verge Lining	Flat AC Sheeting	10m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/B00C/Gable Verge Lining/S9			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Wall Cladding	Corrugated AC Sheeting	10m2	East	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4313/B00C/Gable Ends/S11			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
Ceiling Voids	AC Fragments/Debris	1m	West	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
	4313/B00B/Ceiling Voids/S13			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
Ceiling Voids	AC Fragments/Debris	5m2	West	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5)
	4313/B00B/Ceiling Voids/S14			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Underfloor Voids	No Asbestos Found					

Interior**B00B - R0001 - Movement (65.96 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	66m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/Build+1/Room+1/Ceiling Structures/Linings/S1			Chrysotile (white asbestos)		

B00B - R0002 - Home Base (57.27 m2)

No Asbestos

B00B - R0003 - Personal Effects Storage (9.07 m2)

No Asbestos

B00B - R0004 - Movement (5.7 m2)

No Asbestos

B00B - R0005 - Home Base Store (0.55 m2)

No Asbestos

B00B - R0006 - Movement (1.5 m2)

Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/Build+1/Room+1/Ceiling Structures/Linings/S1			Chrysotile (white asbestos)		

In-fill panel above door	Flat AC Sheeting	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/B00A/R0019/Wall Linings Internal/S2			Chrysotile (white asbestos)		

B00B - R0007 - Home Base Store (0.55 m2)

No Asbestos

B00B - R0008 - Personal Effects Storage (9.12 m2)

No Asbestos

B00B - R0009 - Home Base (57.04 m2)

No Asbestos

B00B - R0010 - Home Base (56.96 m2)

No Asbestos

B00B - R0011 - Personal Effects Storage (9.07 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00B - R0012 - Movement (5.7 m2)						
No Asbestos						
B00B - R0013 - Home Base Store (0.56 m2)						
No Asbestos						
B00B - R0014 - Movement (1.49 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4313/Build+1/Room+1/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	
In-fill panel above door	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4313/B00A/R0019/Wall Linings Internal/S2					Chrysotile (white asbestos)	
B00B - R0015 - Cleaning Distributed Store (0.56 m2)						
No Asbestos						
B00B - R0016 - General Storeroom (19.83 m2)						
Floor Coverings Res/Textile	Vinyl Tiles					
4313/B00B/R0016/Floor Coverings Res/Textile/S3					No Asbestos Detected	
B00B - R0017 - Staff Toilet (3.91 m2)						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00C - General Learning - 1978 - Brick/Veneer (Brick/Veneer)

Exterior

Eaves Linings	Flat AC Sheeting	20m2	North facing, South facing, East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/B00C/Eaves Linings/S8			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Gable Verge Lining	Flat AC Sheeting	10m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/B00C/Gable Verge Lining/S9			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Gable Ends	Corrugated AC Sheeting	20m2	East facing, west facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/B00C/Gable Ends/S11			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Packing to Floor Joists	Flat AC Sheeting	1m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
	4313/B00C/Underfloor Voids - Packing to Floor Joists/S15			Chrysotile (white asbestos) , Amosite (brown asbestos)		

Interior

B00C - R0001 - Community Clinic (17.63 m2)

No Asbestos

B00C - R0002 - Community Clinic (1.96 m2)

No Asbestos

B00C - R0003 - Main Switch Board (2.98 m2)

No Asbestos

B00C - R0004 - General Storeroom (1.58 m2)

No Asbestos

B00C - R0005 - Community Clinic (4.99 m2)

No Asbestos

B00C - R0006 - General Storeroom (0.67 m2)

Wall Linings Internal	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/B00C/R0006/Wall Linings Internal/S22			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/B00C/R0006/Wall Linings Internal/S22			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		

B00C - R0007 - Movement (1.45 m2)

Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/Build+1/Room+1/Ceiling Structures/Linings/S1			Chrysotile (white asbestos)		

B00C - R0008 - Cleaning Distributed Store (0.71 m2)

No Asbestos

B00C - R0009 - Movement (5.25 m2)

No Asbestos

B00C - R0010 - Personal Effects Storage (9.04 m2)

No Asbestos

B00C - R0011 - Home Base Store (7.8 m2)

No Asbestos

B00C - R0012 - Home Base (56.91 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00C - R0013 - Home Base (56.75 m2)						
No Asbestos						
B00C - R0014 - Home Base Store (5.86 m2)						
No Asbestos						
B00C - R0015 - Personal Effects Storage (6.26 m2)						
No Asbestos						
B00C - R0016 - Movement (5.72 m2)						
No Asbestos						
B00C - R0017 - General Storeroom (0.58 m2)						
No Asbestos						
B00C - R0018 - Movement (1.49 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4313/Build+1/Room+1/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	
B00C - R0019 - General Storeroom (0.68 m2)						
No Asbestos						
B00C - R0020 - Home Base Store (5.86 m2)						
No Asbestos						
B00C - R0021 - Special Programs Room (57.2 m2)						
No Asbestos						
B00C - R0022 - Home Base (57.11 m2)						
No Asbestos						
B00C - R0023 - Practical Activities - 1hb (10.08 m2)						
No Asbestos						
B00C - R0024 - Movement (3.1 m2)						
No Asbestos						
B00C - R0025 - Personal Effects Storage (6.48 m2)						
No Asbestos						
B00C - R0026 - Withdrawal Space - 1hb (21.31 m2)						
No Asbestos						
B00C - R0027 - Movement (105.3 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	106m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4313/Build+1/Room+1/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	
Wall Linings Internal	Flat AC Sheeting	20m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
4313/B00C/R0027/Wall Linings Internal/S23					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning - 1964 - Brick/Veneer (Brick/Veneer)

Exterior

Eaves Linings	Flat AC Sheeting	30m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/B00C/Eaves Linings/S8				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Gable Verge Lining	Flat AC Sheeting	10m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/B00C/Gable Verge Lining/S9				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00D - R0001 - Movement (82.09 m2)

Ceiling Structures/Linings	Flat AC Sheeting	83m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/Build+1/Room+1/Ceiling Structures/Linings/S1				Chrysotile (white asbestos)	
Wall Linings Internal	Flat AC Sheeting	15m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/B00C/R0027/Wall Linings Internal/S23				Chrysotile (white asbestos)	

B00D - R0002 - Home Base (57.19 m2)

No Asbestos

B00D - R0003 - Home Base Store (5.02 m2)

No Asbestos

B00D - R0004 - General Storeroom (5.98 m2)

No Asbestos

B00D - R0005 - Personal Effects Storage (4.24 m2)

No Asbestos

B00D - R0006 - Movement (6.41 m2)

No Asbestos

B00D - R0007 - Home Base Store (5.04 m2)

No Asbestos

B00D - R0008 - Home Base (57.11 m2)

No Asbestos

B00D - R0009 - Home Base (57.11 m2)

No Asbestos

B00D - R0010 - Home Base Store (5.01 m2)

No Asbestos

B00D - R0011 - General Storeroom (5.98 m2)

No Asbestos

B00D - R0012 - Personal Effects Storage (4.45 m2)

No Asbestos

B00D - R0013 - Movement (6.41 m2)

No Asbestos

B00D - R0014 - Home Base Store (4.98 m2)

No Asbestos

B00D - R0015 - Home Base (56.87 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning - 1978 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	10m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/B00C/Eaves Linings/S8				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Gable Verge Lining	Flat AC Sheeting	10m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/B00C/Gable Verge Lining/S9				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00E - R0001 - Movement (40.61 m2)

Ceiling Structures/Linings	Flat AC Sheeting	41m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/Build+1/Room+1/Ceiling Structures/Linings/S1				Chrysotile (white asbestos)	
Infill Panel	Flat AC Sheeting	7m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/B00E/R0001/Infill Panel/S12				Chrysotile (white asbestos)	

B00E - R0002 - General Storeroom (12.92 m2)

Floor Coverings Res/Textile	Vinyl Tiles					
	4313/B00B/R0016/Floor Coverings Res/Textile/S3				No Asbestos Detected	

B00E - R0003 - Distribution Board (0.9 m2)

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/Build+1/Room+1/Ceiling Structures/Linings/S1				Chrysotile (white asbestos)	

B00E - R0004 - Withdrawal Space - 1hb (13.63 m2)

No Asbestos

B00E - R0005 - Home Base (64.78 m2)

No Asbestos

B00E - R0006 - Movement (18.72 m2)

Ceiling Structures/Linings	Flat AC Sheeting	19m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/Build+1/Room+1/Ceiling Structures/Linings/S1				Chrysotile (white asbestos)	
Infill Panel	Flat AC Sheeting	5m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/B00E/R0001/Infill Panel/S12				Chrysotile (white asbestos)	

B00E - R0007 - Practical Activities - 1hb (17.91 m2)

No Asbestos

B00E - R0008 - Movement (11.4 m2)

Ceiling Structures/Linings	Flat AC Sheeting	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/Build+1/Room+1/Ceiling Structures/Linings/S1				Chrysotile (white asbestos)	
Infill Panel	Flat AC Sheeting	3m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/B00E/R0001/Infill Panel/S12				Chrysotile (white asbestos)	

B00E - R0009 - Home Base (64.77 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Pupil Facilities - 1964 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	10m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/B00C/Eaves Linings/S8				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00F - R0001 - Movement (22.57 m2)

Ceiling Structures/Linings	Flat AC Sheeting	23m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/Build+1/Room+1/Ceiling Structures/Linings/S1				Chrysotile (white asbestos)	

B00F - R0002 - Canteen Office/Store (6.21 m2)

No Asbestos

B00F - R0003 - Canteen (43.44 m2)

No Asbestos

B00F - R0004 - Canteen Office/Store (2.94 m2)

No Asbestos

B00F - R0005 - Staff Toilet (3.24 m2)

No Asbestos

B00F - R0006 - Movement (20.77 m2)

Ceiling Structures/Linings	Flat AC Sheeting	21m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/Build+1/Room+1/Ceiling Structures/Linings/S1				Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Library/Pupil Facilities - 1978 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	10m2	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/B00C/Eaves Linings/S8				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Gable Verge Lining	Flat AC Sheeting	10m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/B00C/Gable Verge Lining/S9				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Infill panels	Flat AC Sheeting	4m2	East & West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/B00I/R0001/Ceiling Structures/Linings/S5				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					
Gable Ends	Corrugated AC Sheeting	10m2	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/B00C/Gable Ends/S11				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	

Interior

B00G - R0001 - Movement (117.39 m2)

Ceiling Structures/Linings	Flat AC Sheeting	118m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/Build+1/Room+1/Ceiling Structures/Linings/S1				Chrysotile (white asbestos)	
Infill Panel	Flat AC Sheeting	4m2	East & West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/B00E/R0001/Infill Panel/S12				Chrysotile (white asbestos)	

B00G - R0002 - Movement (12.27 m2)

No Asbestos

B00G - R0003 - Distribution Board (1.11 m2)

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/Build+1/Room+1/Ceiling Structures/Linings/S1				Chrysotile (white asbestos)	

B00G - R0004 - Toilets - Boys (3.72 m2)

Partition Walls (Cubicles)	Compressed AC Sheet	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/B00G/R0004/Partition Walls (Cubicles)/S17				Chrysotile (white asbestos)	

B00G - R0005 - Cleaning Distributed Store (1.81 m2)

No Asbestos

B00G - R0006 - Toilets - Girls (4.41 m2)

Partition Walls (Cubicles)	Compressed AC Sheet	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/B00G/R0004/Partition Walls (Cubicles)/S17				Chrysotile (white asbestos)	

B00G - R0007 - Movement (13.9 m2)

No Asbestos

B00G - R0008 - Reading Area (158.92 m2)

Ceiling Structures/Linings	Flat AC Sheeting	210m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/B00G/R0008/Ceiling Structures/Linings/S20				Chrysotile (white asbestos)	
Infill Panel	Flat AC Sheeting	10m2	East & West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/B00G/R0008/Ceiling Structures/Linings/S20				Chrysotile (white asbestos)	

B00G - R0009 - Seminar/Study (10.58 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Infill Panel	Flat AC Sheeting	2m2	North & East	Good Condition (1)	Low (1)	Low Priority (2-3)
4313/B00G/R0008/Ceiling Structures/Linings/S20					Chrysotile (white asbestos)	
B00G - R0010 - Seminar/Study (10.58 m2)						
Infill Panel	Flat AC Sheeting	2m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
4313/B00G/R0008/Ceiling Structures/Linings/S20					Chrysotile (white asbestos)	
B00G - R0011 - Movement (1.8 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4313/B00G/R0008/Ceiling Structures/Linings/S20					Chrysotile (white asbestos)	
B00G - R0012 - Library Office/Workroom (8.66 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4313/B00G/R0008/Ceiling Structures/Linings/S20					Chrysotile (white asbestos)	
B00G - R0013 - Communications Room (11.86 m2)						
Floor Coverings Res/Textile	Vinyl Tiles					
4313/B00H/R0003/Floor Coverings Res/Textile/S4					No Asbestos Detected	
B00G - R0014 - Library Office/Workroom (17.77 m2)						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Communal Facilities/Pupil Facilities - 1964 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/B00C/Eaves Linings/S8				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Voids	AC Fragments/Debris	5m2	East	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5)
	4313/B00B/Ceiling Voids/S14				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Underfloor Voids	No Asbestos Found					

Interior

B00H - R0001 - Movement (9.79 m2)

Ceiling Structures/Linings	Flat AC Sheeting	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/Build+1/Room+1/Ceiling Structures/Linings/S1				Chrysotile (white asbestos)	

B00H - R0002 - Movement (122.36 m2)

Ceiling Structures/Linings	Flat AC Sheeting	123m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/Build+1/Room+1/Ceiling Structures/Linings/S1				Chrysotile (white asbestos)	

B00H - R0003 - Movement (0.91 m2)

Floor Coverings Res/Textile	Vinyl Tiles					
	4313/B00H/R0003/Floor Coverings Res/Textile/S4				No Asbestos Detected	

B00H - R0004 - Cleaning Supplies (10.92 m2)

Floor Coverings Res/Textile	Vinyl Tiles					
	4313/B00H/R0003/Floor Coverings Res/Textile/S4				No Asbestos Detected	

B00H - R0005 - Raised Platform (38.34 m2)

No Asbestos

B00H - R0006 - P.E. Store (20.1 m2)

No Asbestos

B00H - R0007 - Toilets - Boys (2.67 m2)

No Asbestos

B00H - R0008 - Distribution Board (1.68 m2)

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/Build+1/Room+1/Ceiling Structures/Linings/S1				Chrysotile (white asbestos)	

B00H - R0009 - Communal Space (178.16 m2)

No Asbestos

B00H - R0010 - Cleaning Distributed Store (1.65 m2)

No Asbestos

B00H - R0011 - Toilets - Girls (3.33 m2)

No Asbestos

B00H - R0012 - Music Store (3.22 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B001 - Pupil Facilities - 1978 - Brick/Block (Brick/Block)

Exterior

Gable Verge Lining	Flat AC Sheeting	5m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/B00J/Gable Verge Lining/S7			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
Eaves Linings	Flat AC Sheeting	20m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/B00J/Eaves Linings/S6			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B001 - R0001 - Toilets - Girls (35.43 m2)

Ceiling Structures/Linings	Flat AC Sheeting	36m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/B00I/R0001/Ceiling Structures/Linings/S5			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Partition Walls (Cubicles)	Fibre cement sheeting					
	4313/B00J/R0001/Partition Walls (Cubicles)/S16			No Asbestos Detected		

B001 - R0002 - Movement (7.51 m2)

Ceiling Structures/Linings	Flat AC Sheeting	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/B00I/R0001/Ceiling Structures/Linings/S5			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Wall Linings Internal	Compressed fibre cement sheeting					
	4313/B00I/R0004/Wall Linings Internal/S21			No Asbestos Detected		

B001 - R0003 - General Assistant/Bulk Store (9.37 m2)

Ceiling Structures/Linings	Flat AC Sheeting	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/B00I/R0001/Ceiling Structures/Linings/S5			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B001 - R0004 - Movement (7.44 m2)

Ceiling Structures/Linings	Flat AC Sheeting	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/B00I/R0001/Ceiling Structures/Linings/S5			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Wall Linings Internal	Compressed fibre cement sheeting					
	4313/B00I/R0004/Wall Linings Internal/S21			No Asbestos Detected		

B001 - R0005 - Toilets - Boys (35.43 m2)

Ceiling Structures/Linings	Flat AC Sheeting	36m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/B00I/R0001/Ceiling Structures/Linings/S5			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Partition Walls (Cubicles)	Fibre cement sheeting					
	4313/B00J/R0001/Partition Walls (Cubicles)/S16			No Asbestos Detected		

B001 - R0006 - Cleaning Supplies (7.56 m2)

Ceiling Structures/Linings	Flat AC Sheeting	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/B00I/R0001/Ceiling Structures/Linings/S5			Chrysotile (white asbestos) , Amosite (brown asbestos)		

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - Pupil Facilities/Building Services - 1978 - Brick/Block (Brick/Block)

Exterior

Gable Verge Lining	Flat AC Sheeting	5m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/B00J/Gable Verge Lining/S7			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
Eaves Linings	Flat AC Sheeting	30m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/B00J/Eaves Linings/S6			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00J - R0001 - Toilets - Girls (36.87 m2)

Ceiling Structures/Linings	Flat AC Sheeting	37m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/B00J/R0001/Ceiling Structures/Linings/S5			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Partition Walls (Cubicles)	Fibre cement sheeting					No Asbestos Detected
	4313/B00J/R0001/Partition Walls (Cubicles)/S16					

B00J - R0002 - Toilets - Boys (41.09 m2)

Ceiling Structures/Linings	Flat AC Sheeting	42m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/B00J/R0001/Ceiling Structures/Linings/S5			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Partition Walls (Cubicles)	Fibre cement sheeting					No Asbestos Detected
	4313/B00J/R0001/Partition Walls (Cubicles)/S16					

B00J - R0003 - General Assistant/Bulk Store (34.21 m2)

Ceiling Structures/Linings	Flat AC Sheeting	35m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/B00J/R0001/Ceiling Structures/Linings/S5			Chrysotile (white asbestos) , Amosite (brown asbestos)		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Administration/Staff Facilities - 1978 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	10m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/B00C/Eaves Linings/S8				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Gable Verge Lining	Flat AC Sheeting	10m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/B00C/Gable Ends/S11				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Infill Panel	Flat AC Sheeting	5m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/B00E/R0001/Infill Panel/S12				Chrysotile (white asbestos)	
Wall Cladding	Corrugated AC Sheeting	5m2	East	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4313/B00C/Gable Ends/S11				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00K - R0001 - Movement (142.32 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	143m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/Build+1/Room+1/Ceiling Structures/Linings/S1				Chrysotile (white asbestos)	

B00K - R0002 - Principal (21.79 m2)

No Asbestos

B00K - R0003 - Clerical Office/Workroom (12.54 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4313/B00K/R0005/Ceiling Structures/Linings/S19				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	

B00K - R0004 - General Storeroom (13.93 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4313/B00K/R0005/Ceiling Structures/Linings/S19				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	

Floor Coverings Res/Textile	Vinyl Tiles					No Asbestos Detected
	4313/B00H/R0003/Floor Coverings Res/Textile/S4					

B00K - R0005 - Movement (30.19 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4313/B00K/R0005/Ceiling Structures/Linings/S19				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	

B00K - R0006 - Interview (15.21 m2)

No Asbestos

B00K - R0007 - Staff Toilet (5.48 m2)

Partition Walls (Cubicles)	Compressed fibre cement sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/B00K/R0007/Partition Walls (Cubicles)/S18				Chrysotile (white asbestos)	

B00K - R0008 - Staff Toilet (5.17 m2)

Partition Walls (Cubicles)	Compressed fibre cement sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/B00K/R0007/Partition Walls (Cubicles)/S18				Chrysotile (white asbestos)	

B00K - R0009 - Sick Bay (8.98 m2)

Floor Coverings Res/Textile	Vinyl Tiles					No Asbestos Detected
	4313/B00H/R0003/Floor Coverings Res/Textile/S4					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00K - R0010 - Cleaning Distributed Store (2.68 m2)						
Floor Coverings Res/Textile	Vinyl Tiles					
	4313/B00H/R0003/Floor Coverings Res/Textile/S4					No Asbestos Detected
B00K - R0011 - Distribution Board (1.24 m2)					<i>Note: No inspection of live electrical installation.</i>	
Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/Build+1/Room+1/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)
B00K - R0012 - Duplicating Workroom (21.68 m2)						
Floor Coverings Res/Textile	Vinyl Tiles					
	4313/B00H/R0003/Floor Coverings Res/Textile/S4					No Asbestos Detected
B00K - R0013 - Clerical Office (17.37 m2)						
No Asbestos						
B00K - R0014 - Entry Vestibule (15.48 m2)						
Ceiling Structures/Linings	Vermiculite					
	4313/B00K/R0005/Ceiling Structures/Linings/S19					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00K - R0015 - Deputy Principal (17.52 m2)						
No Asbestos						
B00K - R1001 - Staff Room (54.98 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	55m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4313/Build+1/Room+1/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 601 - D14575 - Learning Unit - Standard/Withdrawal : Placement Date - 11/05/2010

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2
---------	---------------	------------------	--	--	--	-------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017