

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Bilgola Plateau Public School (4359)
Region : Northern Sydney
State Electorate : Pittwater
Local Government Area : Pittwater

Initial Survey : Noel Arnold & Associates : 10 - Mar - 2008
Reviewed By : AECOM : 28 - Jun - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/General Learning - 1965 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible, slab to ground / no access points.					
Ceiling Voids - Flat Roof	Non Accessible Area - Height Restriction 3.2m					
Gable verge lining	Flat AC Sheeting 4359/B00A/Gable verge lining/S7	80m	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Eaves Linings	Flat AC Sheeting 4359/B00A/R2009/Ceiling Structures/Linings/S1	60m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

Interior**B00A - M2001 - Reading Area (64.26 m2)**

No Asbestos

B00A - M2002 - Movement (4.98 m2)

No Asbestos

B00A - M2003 - Stairs (3.79 m2)

Recently Modified Space Requires Inspection

B00A - R0001 - K.L.A. Store (23.35 m2)

No Asbestos

B00A - R0002 - External Movement (64.34 m2)

Ceiling Structures/Linings	Flat AC Sheeting 4359/B00A/R2009/Ceiling Structures/Linings/S1	65m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	---	------	--------------	--------------------	---------	--

B00A - R0003 - Toilets - Boys (11.66 m2)

Ceiling Structures/Linings	Vermiculite 4359/B00A/R1012/Ceiling Structures/Linings/S4					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
----------------------------	--	--	--	--	--	---

Partition Walls (Cubicles)	Compressed AC Sheet 4359/B00A/R2005/Partition Walls (Cubicles)/S2	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	--	-----	--------------	--------------------	---------	--

B00A - R0004 - General Storeroom (11.24 m2)

No Asbestos

B00A - R0005 - Practical Activities - 1hb (23.17 m2)

No Asbestos

B00A - R0006 - Movement (5.82 m2)

Ceiling Structures/Linings	Flat AC Sheeting 4359/B00A/R2009/Ceiling Structures/Linings/S1	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	---	-----	--------------	--------------------	---------	--

B00A - R0007 - Home Base (67.11 m2)

No Asbestos

B00A - R0008 - Movement (10.94 m2)

Ceiling Structures/Linings	Flat AC Sheeting 4359/B00A/R2009/Ceiling Structures/Linings/S1	11m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	---	------	--------------	--------------------	---------	--

B00A - R0009 - Home Base (67.11 m2)

No Asbestos

B00A - R0010 - Practical Activities - 1hb (23.17 m2)

No Asbestos

B00A - R0011 - Movement (10.86 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Ceiling Structures/Linings	Flat AC Sheeting	11m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4359/B00A/R2009/Ceiling Structures/Linings/S1				Chrysotile (white asbestos)		
B00A - R0012 - Practical Activities - 1hb (11.2 m2)						
No Asbestos						
B00A - R0014 - Movement (5.31 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4359/B00A/R2009/Ceiling Structures/Linings/S1				Chrysotile (white asbestos)		
B00A - R0015 - Personal Effects Storage (12.42 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	13m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4359/B00A/R2009/Ceiling Structures/Linings/S1				Chrysotile (white asbestos)		
B00A - R0016 - Personal Effects Storage (12.42 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	13m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4359/B00A/R2009/Ceiling Structures/Linings/S1				Chrysotile (white asbestos)		
B00A - R0017 - Personal Effects Storage (12.61 m2)						
No Asbestos						
B00A - R0018 - Home Base (60.99 m2)						
Recently Modified Space	Requires Inspection					
B00A - R0019 - Home Base (62.98 m2)						
Recently Modified Space	Requires Inspection					
B00A - R1001 - Canteen (23.58 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	24m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4359/B00A/R2009/Ceiling Structures/Linings/S1				Chrysotile (white asbestos)		
B00A - R1002 - Canteen Office/Store (4.2 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4359/B00A/R2009/Ceiling Structures/Linings/S1				Chrysotile (white asbestos)		
B00A - R1003 - Canteen Office/Store (5.07 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4359/B00A/R2009/Ceiling Structures/Linings/S1				Chrysotile (white asbestos)		
B00A - R1004 - Staff Toilet (5.21 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4359/B00A/R2009/Ceiling Structures/Linings/S1				Chrysotile (white asbestos)		
B00A - R1005 - Cleaning Supplies (7.39 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4359/B00A/R2009/Ceiling Structures/Linings/S1				Chrysotile (white asbestos)		
B00A - R1006 - General Storeroom (6.83 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4359/B00A/R2009/Ceiling Structures/Linings/S1				Chrysotile (white asbestos)		
B00A - R1007 - Cleaning Distributed Store (6.83 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4359/B00A/R2009/Ceiling Structures/Linings/S1				Chrysotile (white asbestos)		
B00A - R1008 - Garden Store (15.34 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	16m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4359/B00A/R2009/Ceiling Structures/Linings/S1				Chrysotile (white asbestos)		

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R1009 - External Movement (6.09 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4359/B00A/R2009/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	
B00A - R1010 - General Assistant/Bulk Store (19.71 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4359/B00A/R2009/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	
B00A - R1011 - K.L.A. Store (14.65 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4359/B00A/R2009/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	
B00A - R1012 - Staff Toilet (4.16 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
4359/B00A/R1012/Ceiling Structures/Linings/S4					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
Partition Walls (Cubicles)	Compressed AC Sheet	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4359/B00A/R2005/Partition Walls (Cubicles)/S2					Chrysotile (white asbestos)	
B00A - R1013 - Staff Toilet (4.16 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
4359/B00A/R1012/Ceiling Structures/Linings/S4					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
Partition Walls (Cubicles)	Compressed AC Sheet	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4359/B00A/R2005/Partition Walls (Cubicles)/S2					Chrysotile (white asbestos)	
B00A - R1014 - Staff Toilet (2.1 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
4359/B00A/R1012/Ceiling Structures/Linings/S4					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
B00A - R1015 - Staff Shower/Change (2.4 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
4359/B00A/R1012/Ceiling Structures/Linings/S4					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
B00A - R1016 - Community Clinic (14.62 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
4359/B00A/R1012/Ceiling Structures/Linings/S4					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
B00A - R1017 - External Movement (147.81 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	120m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
4359/B00A/R2009/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	
B00A - R1018 - Staff Room (49.05 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
4359/B00A/R1012/Ceiling Structures/Linings/S4					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
B00A - R1019 - Staff Room Annexe (16.98 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
4359/B00A/R1012/Ceiling Structures/Linings/S4					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
B00A - R1020 - Craft Store (4.51 m2)						
No Asbestos						
B00A - R1021 - Toilets - Boys/Girls (5.95 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Ceiling Structures/Linings	Vermiculite 4359/B00A/R1012/Ceiling Structures/Linings/S4					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Partition Walls (Cubicles)	Compressed AC Sheet 4359/B00A/R2005/Partition Walls (Cubicles)/S2	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00A - R1022 - Toilets - Boys/Girls (6.3 m2)						
Ceiling Structures/Linings	Vermiculite 4359/B00A/R1012/Ceiling Structures/Linings/S4					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Partition Walls (Cubicles)	Compressed AC Sheet 4359/B00A/R2005/Partition Walls (Cubicles)/S2	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00A - R1023 - Staff Room Annexe (13.2 m2)						
Ceiling Structures/Linings	Vermiculite 4359/B00A/R1012/Ceiling Structures/Linings/S4					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00A - R1024 - External Movement (76.38 m2)						
Ceiling Structures/Linings	Flat AC Sheeting 4359/B00A/R2009/Ceiling Structures/Linings/S1	4m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00A - R1025 - Personal Effects Storage (13.29 m2)						
Ceiling Structures/Linings	Flat AC Sheeting 4359/B00A/R2009/Ceiling Structures/Linings/S1	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00A - R1026 - Practical Activities - 1hb (20.62 m2)						
Ceiling Structures/Linings	Flat AC Sheeting 4359/B00A/R2009/Ceiling Structures/Linings/S1	21m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00A - R1027 - Home Base (47.92 m2)						
Ceiling Structures/Linings	Flat AC Sheeting 4359/B00A/R2009/Ceiling Structures/Linings/S1	48m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00A - R1028 - Personal Effects Storage (13.29 m2)						
Ceiling Structures/Linings	Flat AC Sheeting 4359/B00A/R2009/Ceiling Structures/Linings/S1	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00A - R1029 - Practical Activities - 1hb (20.63 m2)						
Ceiling Structures/Linings	Flat AC Sheeting 4359/B00A/R2009/Ceiling Structures/Linings/S1	21m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00A - R1030 - Home Base (47.91 m2)						
Ceiling Structures/Linings	Flat AC Sheeting 4359/B00A/R2009/Ceiling Structures/Linings/S1	48m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00A - R1031 - Movement (9.96 m2)						
Ceiling Structures/Linings	Flat AC Sheeting 4359/B00A/R2009/Ceiling Structures/Linings/S1	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00A - R1032 - Stairs (12.26 m2)						
Recently Modified Space	Requires Inspection					
B00A - R2001 - Library Office/Workroom (7.69 m2)						
No Asbestos						
B00A - R2002 - Library Office/Workroom (16.31 m2)						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R2003 - K.L.A. Store (25.96 m2)						
No Asbestos						
B00A - R2004 - Reading Area (149.59 m2)						
No Asbestos						
B00A - R2005 - Cleaning Distributed Store (5.95 m2)						
Partition Walls (Cubicles)	Compressed AC Sheet	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4359/B00A/R2005/Partition Walls (Cubicles)/S2					Chrysotile (white asbestos)	
B00A - R2006 - Sports Store (6.23 m2)						
Partition Walls (Cubicles)	Compressed AC Sheet	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4359/B00A/R2005/Partition Walls (Cubicles)/S2					Chrysotile (white asbestos)	
B00A - R2007 - Deputy Principal (13.23 m2)						
No Asbestos						
B00A - R2008 - General Storeroom (11.21 m2)						
No Asbestos						
B00A - R2009 - Movement (50.4 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	18m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
4359/B00A/R2009/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	
B00A - R2010 - Staff Toilet (3.49 m2)						
Wall Linings Internal	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4359/B00A/R2009/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	
B00A - R2011 - General Storeroom (11.06 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4359/B00A/R2011/Floor Coverings Res/Textile/S3					Chrysotile (white asbestos)	
B00A - R2012 - Duplicating Workroom (20.46 m2)						
No Asbestos						
B00A - R2013 - Clerical Office (14.76 m2)						
No Asbestos						
B00A - R2014 - Movement (5.16 m2)						
No Asbestos						
B00A - R2015 - Entry Vestibule (20.62 m2)						
No Asbestos						
B00A - R2016 - Principal (19.98 m2)						
No Asbestos						
B00A - R2017 - Movement (7.91 m2)						
No Asbestos						
B00A - R2018 - Main Switch Board (3.53 m2)						
Wall Linings Internal	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4359/B00A/R2009/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	
B00A - R2019 - Staff Toilet (3.49 m2)						
Wall Linings Internal	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4359/B00A/R2009/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	
B00A - R2020 - Sick Bay (7.25 m2)						
No Asbestos						
B00A - R2021 - Home Base (56.04 m2)						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R2022 - Home Base Store (5.01 m2)						
No Asbestos						
B00A - R2023 - General Storeroom (0.55 m2)						
No Asbestos						
B00A - R2024 - Movement (5.33 m2)						
No Asbestos						
B00A - R2025 - Personal Effects Storage (7.88 m2)						
No Asbestos						
B00A - R2026 - Craft Store (0.55 m2)						
No Asbestos						
B00A - R2027 - Home Base Store (5.01 m2)						
No Asbestos						
B00A - R2028 - Home Base (56.04 m2)						
No Asbestos						
B00A - R2029 - Home Base (56.04 m2)						
No Asbestos						
B00A - R2030 - Home Base Store (5.01 m2)						
No Asbestos						
B00A - R2031 - Craft Store (0.55 m2)						
No Asbestos						
B00A - R2032 - Movement (5.33 m2)						
No Asbestos						
B00A - R2033 - Personal Effects Storage (7.85 m2)						
No Asbestos						
B00A - R2034 - Craft Store (0.55 m2)						
No Asbestos						
B00A - R2035 - Home Base Store (5.01 m2)						
No Asbestos						
B00A - R2036 - Home Base (56.04 m2)						
No Asbestos						
B00A - R2037 - External Movement (91.68 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	92m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
4359/B00A/R2009/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	
B00A - R2038 - Stairs (16.05 m2)						
Recently Modified Space	Requires Inspection					
B00A - R2039 - Stairs (8.35 m2)						
Recently Modified Space	Requires Inspection					
B00A - R9001 - External Movement (76.93 m2)						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Pupil Facilities - 1965 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area					
	- Area inaccessible, slab to ground / no access points.					
Ceiling Voids - Raked Ceiling	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	10m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Height Restriction 3.84m						

Interior

B00G - R0001 - Toilets - Girls (26.61 m2)

Partition Walls (Cubicles)	Compressed AC Sheet	18m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4359/B00A/R2005/Partition Walls (Cubicles)/S2						Chrysotile (white asbestos)

B00G - R0002 - Cleaning Distributed Store (1.58 m2)

No Asbestos

B00G - R0003 - Drinking Facilities (11.75 m2)

No Asbestos

B00G - R0004 - Sports Store (7.71 m2)

No Asbestos

B00G - R0005 - General Storeroom (7.71 m2)

No Asbestos

B00G - R0006 - Drinking Facilities (11.75 m2)

No Asbestos

B00G - R0007 - Cleaning Distributed Store (1.58 m2)

No Asbestos

B00G - R0008 - Toilets - Boys (26.71 m2)

Partition Walls (Cubicles)	Compressed AC Sheet	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4359/B00A/R2005/Partition Walls (Cubicles)/S2						Chrysotile (white asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - General Learning - 1965 - Timber (Timber)

Exterior

Underfloor Voids - Packing to Floor Joists No Asbestos Found

Ceiling Voids - Flat Roof Non Accessible Area
- Height Restriction 3.4m

Interior

B00H - R0001 - Special Programs Room (46.7 m2)

Ceiling Structures/Linings	Flat AC Sheeting	45m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	------	--------------	--------------------	---------	--------------------

Assumed Asbestos - Height Restriction 3.4m

B00H - R0002 - Special Programs Room (46.7 m2)

Ceiling Structures/Linings	Flat AC Sheeting	47m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	------	--------------	--------------------	---------	--------------------

Assumed Asbestos - Height Restriction 3.4m

B00H - R0003 - External Movement (24.65 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - General Learning - 1965 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Packing to Floor Joists	No Asbestos Found					
Ceiling Voids - Flat Roof	No Asbestos Found					
Gable verge lining	Flat AC Sheeting	30m	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4359/B00J/Gable verge lining/S6				Chrysotile (white asbestos)	
In-fill panel below window	Compressed AC Sheet	40m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4359/B00J/Under Window Panel/S5				Chrysotile (white asbestos)	

Interior

B00J - R0001 - Home Base (57.69 m2)

No Asbestos

B00J - R0002 - Home Base Store (3.61 m2)

No Asbestos

B00J - R0003 - Practical Activities - 1hb (20.1 m2)

No Asbestos

B00J - R0004 - Home Base Store (3.61 m2)

No Asbestos

B00J - R0005 - Home Base (56.91 m2)

No Asbestos

B00J - R0006 - Home Base (56.91 m2)

No Asbestos

B00J - R0007 - Home Base Store (3.61 m2)

No Asbestos

B00J - R0008 - Practical Activities - 1hb (20.1 m2)

No Asbestos

B00J - R0009 - Home Base Store (3.61 m2)

No Asbestos

B00J - R0010 - Home Base (57.7 m2)

No Asbestos

B00J - R0011 - External Movement (67.21 m2)

Ceiling Structures/Linings	Flat AC Sheeting	68m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4359/B00A/R2009/Ceiling Structures/Linings/S1				Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00K - Communal Facilities - 2011 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Packing to Floor Joists No Asbestos Found

Ceiling Voids No Asbestos Found

Interior**B00K - R0001 - Covered Outdoor Learning Area (248.87 m2)**

No Asbestos

B00K - R0002 - Communal Space (198.66 m2)

No Asbestos

B00K - R0003 - Raised Platform (56.83 m2)

No Asbestos

B00K - R0004 - P.E. Store (16.9 m2)

No Asbestos

B00K - R0005 - Communal/Performance Store (10.95 m2)

No Asbestos

B00K - R0006 - Chair Storeroom (11.16 m2)

No Asbestos

B00K - R0007 - Main Switch Board (3.26 m2)

No Asbestos

B00K - R0008 - Access Shower/Toilet (6.84 m2)

No Asbestos

B00K - R0009 - Cleaning Distributed Store (3.58 m2)

No Asbestos

B00K - R0010 - Plant (1.91 m2)

No Asbestos

B00K - R0011 - Toilet - Lobby (3.48 m2)

No Asbestos

B00K - R0012 - Toilets - Boys (5.77 m2)

No Asbestos

B00K - R0013 - Sound Cupboard (2.06 m2)

No Asbestos

B00K - R0014 - Toilet - Lobby (2.53 m2)

No Asbestos

B00K - R0015 - Toilets - Girls (7.38 m2)

No Asbestos

B00K - R0016 - Movement (17.09 m2)

No Asbestos

B00K - R0017 - Movement (7.21 m2)

No Asbestos

B00K - R0018 - Ramp (12.96 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - General Learning - 2010 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Underfloor Voids - Packing to Floor Joists No Asbestos Found

Ceiling Voids No Asbestos Found

Interior

B00L - R0001 - External Movement (36.72 m2)

No Asbestos

B00L - R0002 - Practical Activities - 1hb (19.63 m2)

No Asbestos

B00L - R0003 - Home Base Store (6.49 m2)

No Asbestos

B00L - R0004 - Home Base (58.97 m2)

No Asbestos

B00L - R0005 - Withdrawal Space - 2hb (10.93 m2)

No Asbestos

B00L - R0006 - Home Base (58.97 m2)

No Asbestos

B00L - R0007 - Home Base Store (6.49 m2)

No Asbestos

B00L - R0008 - Practical Activities - 1hb (19.63 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - Other-After School Care - 2010 - Steel (Steel)

Exterior

Underfloor Voids - Packing to Floor Joists No Asbestos Found

Ceiling Voids No Asbestos Found

Interior

B00M - R0001 - Other-Community Use (65.02 m2)

No Asbestos

B00M - R0002 - Other-Community Use (23.06 m2)

No Asbestos

B00M - R0003 - External Movement (19.65 m2)

No Asbestos

B00M - R0004 - Other-After School Care (22.36 m2)

No Asbestos

B00M - R0005 - Staff Toilet (3.51 m2)

No Asbestos

B00M - R0006 - Toilets - Girls (2.38 m2)

No Asbestos

B00M - R0007 - Toilets - Boys (2.43 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D11897 - Learning Unit - Standard With P.A.A. : Placement Date - 29/03/2014

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D12638 - Learning Unit - Standard With P.A.A. : Placement Date - 15/03/2012

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 603 - D13025 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 4/03/2009

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 603 - D15196 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 9/03/2005

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017