

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Baulkham Hills North Public School (4377)
Region : Northern Sydney
State Electorate : Baulkham Hills
Local Government Area : The Hills

Initial Survey : Noel Arnold & Associates : 10 - Mar - 2008
Reviewed By : Grencap-NAA : 13 - Aug - 2014



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00A - General Learning - 1967 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting 4377/B00D/Eaves Linings/S19	12m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Gable verge lining	Flat AC Sheeting 4377/B00D/Gable Verge Lining/S20	20m	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Window panels	Flat AC Sheeting 4377/B00A/R0006/Window panel/S2	8m2	South facing, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Packing to Floor Joists	Flat AC Sheeting 4377/B00E/Underfloor Voids - Packing to Floor Joists/S25	1m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
Underfloor Voids	Resinous Membrane 4377/B00A/Underfloor Voids/S27	No Asbestos Detected				
Underfloor Voids	AC Fragments/Debris 4377/B00A/Underfloor Voids/S28	1m2	Throughout	Some Damage - Unsealed (3)	Medium (2)	Medium Priority (4-5) Chrysotile (white asbestos)

Interior**B00A - R0001 - Home Base**

Thermacon Heater	Encapsulated Insulation material within unit Assumed Asbestos - Sealed unit	2Unit	North facing, South facing	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
------------------	---	-------	-------------------------------	----------------------	---------	--------------------

B00A - R0002 - Home Base Store

No Asbestos

B00A - R0003 - Personal Effects Storage

Electrical Backing Board	Compressed AC Sheet Assumed Asbestos - Electrical Hazard	1Unit	West	Good Condition (1)	Low (1)	Low Priority (2-3)
--------------------------	--	-------	------	--------------------	---------	--------------------

B00A - R0004 - Home Base

Thermacon Heater	Encapsulated Insulation material within unit Assumed Asbestos - Sealed unit	1Unit	South facing	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
------------------	---	-------	--------------	----------------------	---------	--------------------

B00A - R0005 - Home Base Store

No Asbestos

B00A - R0006 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 4377/B00A/R0006/Ceiling Structures/Linings/S1	44m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Window panels	Flat AC Sheeting 4377/B00A/R0006/Window panel/S2	8m2	South facing, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

B00A - R0007 - Stairs

Ceiling Structures/Linings	Flat AC Sheeting 4377/B00A/R0006/Ceiling Structures/Linings/S1	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	---	------	------------	--------------------	---------	--

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 1967 - Brick/Veneer (Brick/Veneer)

Exterior

Gable verge lining	Flat AC Sheeting	20m	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00D/Gable Verge Lining/S20				Chrysotile (white asbestos)	
Eaves Linings	Flat AC Sheeting	20m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00D/Eaves Linings/S19				Chrysotile (white asbestos)	
Window panels	Flat AC Sheeting	15m2	West facing, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00A/R0006/Window panel/S2				Chrysotile (white asbestos)	
Underfloor Voids	No Asbestos Found					
Ceiling Voids	Non Accessible Area - Height Restriction					

Interior

B00B - R0001 - Movement

Window panel	Flat AC Sheeting	12m2	West facing, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00A/R0006/Window panel/S2				Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	50m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00A/R0006/Ceiling Structures/Linings/S1				Chrysotile (white asbestos)	

B00B - R0002 - Home Base

Floor Coverings Res/Textile	Vinyl Sheet					
	4377/B00B/R0003/Floor Coverings Res/Textile/S29					No Asbestos Detected

B00B - R0003 - Home Base

Floor Coverings Res/Textile	Vinyl Sheet					
	4377/B00B/R0003/Floor Coverings Res/Textile/S29					No Asbestos Detected

B00B - R0004 - Home Base

Floor Coverings Res/Textile	Vinyl Sheet					
	4377/B00B/R0003/Floor Coverings Res/Textile/S29					No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00C - General Learning/Other-After School Care - 1967 - Brick/Block (Brick/Block)

Exterior

Window panels	Flat AC Sheeting	12m2	North facing, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00A/R0006/Window panel/S2			Chrysotile (white asbestos)		
Eaves Linings	Flat AC Sheeting	20m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00D/Eaves Linings/S19			Chrysotile (white asbestos)		
Gable verge lining	Flat AC Sheeting	20m	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00D/Gable Verge Lining/S20			Chrysotile (white asbestos)		
Underfloor Voids - Packing to Floor Joists	Flat AC Sheeting	1m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4377/B00E/Underfloor Voids - Packing to Floor Joists/S25			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Voids	No Asbestos Found					

Interior

B00C - R0001 - Movement

Window panels	Flat AC Sheeting	12m2	North facing, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00A/R0006/Window panel/S2			Chrysotile (white asbestos)		
Ceiling Structures/Linings	Flat AC Sheeting	90m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00A/R0006/Ceiling Structures/Linings/S1			Chrysotile (white asbestos)		

B00C - R0002 - Home Base Store

No Asbestos

B00C - R0003 - Personal Effects Storage

No Asbestos

B00C - R0004 - Home Base

Thermacon Heater	Encapsulated Insulation material within unit	2Unit	North facing, South facing	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Sealed unit					

B00C - R0005 - Home Base

Thermacon Heater	Encapsulated Insulation material within unit	2Unit	North facing, South facing	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Sealed unit					

B00C - R0006 - Home Base Store

No Asbestos

B00C - R0007 - Personal Effects Storage

No Asbestos

B00C - R0008 - Home Base

Thermacon Heater	Encapsulated Insulation material within unit	2Unit	North facing, South facing	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Sealed unit					

B00C - R0009 - Home Base Store

No Asbestos

B00C - R9003 - Other-After School Care

Ceiling Structures/Linings	Flat AC Sheeting	3Unit	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00C/R9003/Ceiling Structures/Linings/S30			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Structures/Linings	Flat AC Sheeting	80m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00C/R9003/Ceiling Structures/Linings/S30			Chrysotile (white asbestos) , Amosite (brown asbestos)		

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Floor Coverings
Res/Textile

Vinyl Sheet

4377/B00C/R9003/Floor Coverings Res/Textile/S31

No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00D - Administration - 1967 - Brick/Block (Brick/Block)**Exterior**

Window panels	Flat AC Sheeting	28m2	North facing, South facing, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00A/R0006/Window panel/S2				Chrysotile (white asbestos)	
Eaves Linings	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00D/Eaves Linings/S19				Chrysotile (white asbestos)	
Gable Verge Lining	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00D/Gable Verge Lining/S20				Chrysotile (white asbestos)	
Underfloor Voids	No Asbestos Found					
Ceiling Voids						

Interior**B00D - R0001 - Staff Toilet**

Wall Linings Internal	Flat AC Sheeting	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00D/R0001/Wall Linings Internal/S11				Chrysotile (white asbestos)	
Incinerette	Encapsulated Insulation material within unit	1Unit	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Electrical Hazard					

B00D - R0002 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00D/R0002/Wall Linings Internal/S17				Chrysotile (white asbestos)	

B00D - R0003 - Principal

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00D/R0022/Floor Coverings Res/Textile/S22				Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive					
	4377/B00D/R0003/Floor Coverings Res/Textile/S38				No Asbestos Detected	

B00D - R0004 - Interview

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00D/R0009/Floor Coverings Res/Textile/S21				Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive					
	4377/B00D/R0004/Floor Coverings Res/Textile/S37				No Asbestos Detected	

B00D - R0005 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00A/R0006/Ceiling Structures/Linings/S1				Chrysotile (white asbestos)	

B00D - R0006 - Entry Vestibule

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00D/R0009/Floor Coverings Res/Textile/S21				Chrysotile (white asbestos)	

B00D - R0007 - Movement

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	10m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00D/R0022/Floor Coverings Res/Textile/S22				Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	20m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00D/R0009/Floor Coverings Res/Textile/S21				Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	2m2	Central EDB Cupboard	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00D/R0007/Floor Coverings Res/Textile/S23				Chrysotile (white asbestos)	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Adhesive					
	4377/B00D/R0007/Floor Coverings Res/Textile/S39					No Asbestos Detected
B00D - R0008 - Deputy Principal						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00D/R0009/Floor Coverings Res/Textile/S21					Chrysotile (white asbestos)
B00D - R0009 - Interview						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00D/R0009/Floor Coverings Res/Textile/S21					Chrysotile (white asbestos)
B00D - R0010 - Clerical Office						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00D/R0009/Floor Coverings Res/Textile/S21					Chrysotile (white asbestos)
B00D - R0013 - Community Clinic						
No Asbestos						
B00D - R0016 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	65m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00D/R0016/Ceiling Structures/Linings/S10					Chrysotile (white asbestos)
B00D - R0017 - Distribution Board						
					Note: No inspection of live electrical installation.	
No Asbestos						
B00D - R0018 - Sick Bay						
No Asbestos						
B00D - R0019 - General Storeroom						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00D/R0009/Floor Coverings Res/Textile/S21					Chrysotile (white asbestos)
B00D - R0020 - Duplicating Workroom						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00D/R0009/Floor Coverings Res/Textile/S21					Chrysotile (white asbestos)
B00D - R0021 - Clerical Office						
No Asbestos						
B00D - R0022 - Toilet - Lobby						
Floor Coverings Res/Textile	Vinyl Tiles	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00D/R0022/Floor Coverings Res/Textile/S22					Chrysotile (white asbestos)
B00D - R0023 - Staff Toilet						
No Asbestos						
B00D - R0024 - Toilet - Lobby						
Floor Coverings Res/Textile	Vinyl Tiles	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00D/R0022/Floor Coverings Res/Textile/S22					Chrysotile (white asbestos)
B00D - R0025 - Staff Toilet						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning - 1967 - Brick/Block (Brick/Block)

Exterior

Window panels	Flat AC Sheeting 4377/B00A/R0006/Window panel/S2	16m2	West facing, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Eaves Linings	Flat AC Sheeting 4377/B00D/Eaves Linings/S19	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting 4377/B00D/Gable Verge Lining/S20	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Packing to Floor Joists	Flat AC Sheeting 4377/B00E/Underfloor Voids - Packing to Floor Joists/S25	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
Underfloor Voids	Flat AC Sheeting 4377/B00E/Underfloor Voids/S26	1m2	North	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5) Chrysotile (white asbestos)

Interior

B00E - R0001 - Personal Effects Storage

No Asbestos

B00E - R0002 - Home Base Store

No Asbestos

B00E - R0003 - Home Base

Thermacon Heater	Encapsulated Insulation material within unit	1Unit	East facing	Friable Asbestos (5)	Low (1)	Low Priority (2-3) Assumed Asbestos - Electrical Hazard
------------------	--	-------	-------------	----------------------	---------	---

B00E - R0004 - Home Base

Thermacon Heater	Encapsulated Insulation material within unit	2Unit	East facing, West facing	Friable Asbestos (5)	Low (1)	Low Priority (2-3) Assumed Asbestos - Electrical Hazard
------------------	--	-------	-----------------------------	----------------------	---------	---

B00E - R0005 - Personal Effects Storage

No Asbestos

B00E - R0006 - Home Base Store

No Asbestos

B00E - R0007 - Home Base

Floor Coverings Res/Textile	Vinyl Sheet 4377/B00E/R0008/Floor Coverings Res/Textile/S24					No Asbestos Detected
--------------------------------	--	--	--	--	--	-----------------------------

B00E - R0008 - Movement

Floor Coverings Res/Textile	Vinyl Sheet 4377/B00E/R0008/Floor Coverings Res/Textile/S24					No Asbestos Detected
--------------------------------	--	--	--	--	--	-----------------------------

B00E - R0009 - Special Programs Room

No Asbestos

B00E - R0010 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 4377/B00A/R0006/Ceiling Structures/Linings/S1	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	---	-----	--------------	--------------------	---------	--

B00E - R0011 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 4377/B00A/R0006/Ceiling Structures/Linings/S1	86m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Window panels	Flat AC Sheeting 4377/B00A/R0006/Window panel/S2	11m2	West facing, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00E - R9001 - General Storeroom						
Ceiling hatch	Flat AC Sheeting	0.5m2	North facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00E/R9001/Ceiling hatch/S13				Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Pupil Facilities/Staff Facilities - 1967 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	40m2	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00D/Eaves Linings/S19				Chrysotile (white asbestos)	
Gable verge lining	Flat AC Sheeting	20m	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00D/Gable Verge Lining/S20				Chrysotile (white asbestos)	
Ceiling Voids	Non Accessible Area - Height Restriction					
Underfloor Voids	Non Accessible Area - Area inaccessible					

Interior

B00F - R0001 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting	45m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00C/R9003/Ceiling Structures/Linings/S30				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00F - R0002 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00C/R9003/Ceiling Structures/Linings/S30				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00F - R0003 - Cleaning Supplies

Ceiling Structures/Linings	Flat AC Sheeting	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00C/R9003/Ceiling Structures/Linings/S30				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00F - R0004 - Main Switch Board

Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00C/R9003/Ceiling Structures/Linings/S30				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00F - R0005 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting	45m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00C/R9003/Ceiling Structures/Linings/S30				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00F - R0006 - Staff Room

Floor Coverings Res/Textile	Vinyl Sheet					
	4377/B00C/R9003/Floor Coverings Res/Textile/S31				No Asbestos Detected	

B00F - R0007 - Sports Store

Floor Coverings Res/Textile	Vinyl Sheet	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00D/R0007/Floor Coverings Res/Textile/S23				Chrysotile (white asbestos)	

B00F - R0008 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	26m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00A/R0006/Ceiling Structures/Linings/S1				Chrysotile (white asbestos)	

B00F - R0009 - Canteen

No Asbestos

B00F - R0010 - Canteen Office/Store

No Asbestos

B00F - R0011 - Canteen Office/Store

No Asbestos

B00F - R0012 - Staff Toilet

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Incinerator	Encapsulated Insulation material within unit	1Unit(s)	North facing	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Electrical Hazard						
B00F - R0013 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	37m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4377/B00A/R0006/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	
B00F - R0014 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	28m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4377/B00A/R0006/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning - 1967 - Brick/Block (Brick/Block)

Exterior

Gable verge lining	Flat AC Sheeting	20m	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00D/Gable Verge Lining/S20				Chrysotile (white asbestos)	
Eaves Linings	Flat AC Sheeting	18m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00D/Eaves Linings/S19				Chrysotile (white asbestos)	
Underfloor Voids	AC Fragments/Debris	1m2	East	Some Damage - Unsealed (3)	High (3)	High Priority (6-8)
	4377/B00G/Underfloor Voids/S32				Chrysotile (white asbestos)	
Underfloor Voids - Packing to Floor Joists	Flat AC Sheeting	1m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4377/B00E/Underfloor Voids - Packing to Floor Joists/S25				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Voids	No Asbestos Found					

Interior

B00G - R0001 - Movement

Window panels	Flat AC Sheeting	10m2	North facing, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00A/R0006/Window panel/S2				Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	43m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00A/R0006/Ceiling Structures/Linings/S1				Chrysotile (white asbestos)	

B00G - R0003 - Home Base Store

No Asbestos

B00G - R0004 - Personal Effects Storage

No Asbestos

B00G - R0005 - Home Base

No Asbestos

B00G - R0006 - Practical Activities - 1hb

No Asbestos

B00G - R0007 - Home Base

No Asbestos

B00G - R0008 - Personal Effects Storage

No Asbestos

B00G - R0009 - Home Base Store

No Asbestos

B00G - R0010 - Toilet - Lobby

Wall Linings Internal	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00G/R0002/Wall Linings Internal/S3				Chrysotile (white asbestos)	

B00G - R0011 - Toilets-Unisex

Wall Linings Internal	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00G/R0002/Wall Linings Internal/S3				Chrysotile (white asbestos)	

B00G - R9001 - Cleaning Supplies

Ceiling Structures/Linings	Flat AC Sheeting	56m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00G/R9001/Ceiling Structures/Linings/S9				Chrysotile (white asbestos)	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - General Learning - 1967 - Brick/Block (Brick/Block)

Exterior

Gable verge lining	Flat AC Sheeting	20m	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00D/Gable Verge Lining/S20				Chrysotile (white asbestos)	
Eaves Linings	Flat AC Sheeting	50m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00D/Eaves Linings/S19				Chrysotile (white asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Packing to Floor Joists	Flat AC Sheeting	1m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4377/B00E/Underfloor Voids - Packing to Floor Joists/S25				Chrysotile (white asbestos) , Amosite (brown asbestos)	

Interior

B00H - R0001 - Toilets - Boys/Girls

No Asbestos

B00H - R0002 - Practical Activities - 1hb

Floor Coverings Res/Textile	Vinyl Tiles	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00H/R0002/Floor Coverings Res/Textile/S6				Chrysotile (white asbestos)	

B00H - R0003 - Home Base

No Asbestos

B00H - R0004 - Home Base

No Asbestos

B00H - R0005 - Practical Activities - 1hb

Floor Coverings Res/Textile	Vinyl Tiles	18m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00H/R0002/Floor Coverings Res/Textile/S6				Chrysotile (white asbestos)	

B00H - R0006 - Home Base

Thermacon Heater	Encapsulated Insulation material within unit	2Unit	North facing, South facing	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Sealed unit					

B00H - R0007 - Home Base Store

No Asbestos

B00H - R0008 - Practical Activities - 1hb

Wall lining above sink	Flat AC Sheeting	0.5m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00H/R0008/Wall lining above sink/S5				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00H - R0009 - Movement

No Asbestos

B00H - R0010 - Home Base

Thermacon Heater	Encapsulated Insulation material within unit	1Unit	South facing	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Sealed unit					

B00H - R0011 - Home Base Store

No Asbestos

B00H - R0012 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	26m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00H/R0012/Ceiling Structures/Linings/S15				Chrysotile (white asbestos)	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - General Learning - 1967 - Brick/Block (Brick/Block)**Exterior**

Gable verge lining	Flat AC Sheeting	10m	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00D/Gable Verge Lining/S20				Chrysotile (white asbestos)	
Eaves Linings	Flat AC Sheeting	100m2	All surfaces	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
	4377/B00D/Eaves Linings/S19				Chrysotile (white asbestos)	
Underfloor Voids - Packing to Floor Joists	Flat AC Sheeting	1m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
	4377/B00E/Underfloor Voids - Packing to Floor Joists/S25				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Voids	No Asbestos Found					

Interior**B00J - R0001 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting					
	4377/B00J/R0001/Ceiling Structures/Linings/S18				No Asbestos Detected	

B00J - R0002 - Personal Effects Storage

Wall lining above sink	Flat AC Sheeting	0.5m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00H/R0008/Wall lining above sink/S5				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00J - R0003 - Home Base

Thermacon Heater	Encapsulated Insulation material within unit	2Unit	South facing	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Electrical Hazard					

B00J - R0004 - Home Base

No Asbestos

B00J - R0005 - Movement

Ceiling Structures/Linings	Flat AC Sheeting					
	4377/B00J/R0001/Ceiling Structures/Linings/S18				No Asbestos Detected	

B00J - R0006 - Personal Effects Storage

Wall lining above sink	Flat AC Sheeting	0.5m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00H/R0008/Wall lining above sink/S5				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00J - R0007 - Home Base

Thermacon Heater	Encapsulated Insulation material within unit	2Unit	North facing, South facing	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Electrical Hazard					

B00J - R0008 - Movement

Floor Coverings Res/Textile	Vinyl Tiles	11m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00J/R0008/Floor Coverings Res/Textile/S7				Chrysotile (white asbestos)	

B00J - R0009 - Interview

Thermacon Heater	Encapsulated Insulation material within unit	2Unit	North facing, South facing	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Electrical Hazard					

B00J - R0010 - Movement

Ceiling Structures/Linings	Flat AC Sheeting					
	4377/B00J/R0001/Ceiling Structures/Linings/S18				No Asbestos Detected	

B00J - R0012 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00J/R0012/Ceiling Structures/Linings/S36				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	

B00J - R0013 - General Storeroom

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4377/B00J/R0013/Floor Coverings Res/Textile/S35					Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive					
4377/B00J/R0013/Floor Coverings Res/Textile/S40					No Asbestos Detected	
B00J - R0014 - Staff Room Annexe						
Wall lining above sink	Flat AC Sheeting	1.5m2	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
4377/B00H/R0008/Wall lining above sink/S5					Chrysotile (white asbestos) , Amosite (brown asbestos)	
B00J - R0015 - General Storeroom						
No Asbestos						
B00J - R0016 - Distribution Board						
No Asbestos						
B00J - R0019 - Home Base Store						
No Asbestos						
B00J - R0020 - Home Base Store						
No Asbestos						
B00J - R0021 - Toilets - Boys/Girls						
Wall Linings Internal	Flat AC Sheeting	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
4377/B00J/R0021/Wall Linings Internal/S8					Chrysotile (white asbestos) , Amosite (brown asbestos)	
Wall lining above sink	Flat AC Sheeting	0.5m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
4377/B00J/R0021/Wall Linings Internal/S8					Chrysotile (white asbestos) , Amosite (brown asbestos)	
B00J - R0022 - Home Base Store						
No Asbestos						
B00J - R0023 - Disabled Shower/Toilet						
No Asbestos						
B00J - R0024 - Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Communal Facilities - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	Non Accessible Area - Extreme Access Issue - No Access Point into ceiling void identified
Ceiling Voids	Non Accessible Area - Height Restriction - Extreme Access Issue - No Access Point into ceiling void identified
Underfloor Voids	No Asbestos Found

Interior

B00K - R0001 - Communal Space

No Asbestos

B00K - R0002 - Movement

No Asbestos

B00K - R0003 - Movement

No Asbestos

B00K - R0004 - Raised Platform

No Asbestos

B00K - R0005 - Movement

No Asbestos

B00K - R0006 - Covered Outdoor Learning Area

No Asbestos

B00K - R0007 - Chair Storeroom

No Asbestos

B00K - R0008 - General Storeroom

No Asbestos

B00K - R0009 - Other

No Asbestos

B00K - R0010 - Toilets - Girls

No Asbestos

B00K - R0011 - Toilet - Lobby

No Asbestos

B00K - R0012 - Sound Cupboard

No Asbestos

B00K - R0013 - Toilets - Boys

No Asbestos

B00K - R0014 - Toilet - Lobby

No Asbestos

B00K - R0015 - Cleaning Distributed Store

No Asbestos

B00K - R0016 - Other

No Asbestos

B00K - R0017 - Access Shower/Toilet/Change

No Asbestos

B00K - R0018 - Main Switch Board

No Asbestos

B00K - R0019 - External Movement

No Asbestos

B00K - R0020 - External Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Library/Communal Facilities - 1986 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	Non Accessible Area - Height Restriction
Underfloor Voids	No Asbestos Found

Interior

B00L - R0001 - Seminar/Study

No Asbestos

B00L - R0002 - Communications Room

No Asbestos

B00L - R0003 - Library Office/Workroom

No Asbestos

B00L - R0004 - Staff Toilet

No Asbestos

B00L - R0005 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00L - R0006 - Movement

No Asbestos

B00L - R0007 - Staff Toilet

No Asbestos

B00L - R0008 - Cleaning Distributed Store

No Asbestos

B00L - R0009 - Reading Area

No Asbestos

B00L - R0010 - Movement

Ceiling Structures/Linings Flat AC Sheeting
4377/B00L/R0010/Ceiling Structures/Linings/S14

No Asbestos Detected

B00L - R9002 - P.E. Store

No Asbestos

B00L - R9003 - Hall Chair Store

No Asbestos

B00L - R9005 - Movement

No Asbestos

B00L - R9006 - Other

No Asbestos

B00L - R9007 - Home Base

No Asbestos

B00L - R9008 - Home Base

No Asbestos

B00L - R9009 - Practical Activities - 1hb

No Asbestos

B00L - R9010 - Practical Activities - 1hb

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00N - Pupil Facilities - 1986 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	52m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00N/Eaves Linings/S33					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Underfloor Voids	No Asbestos Found					
Incinerator	Encapsulated Insulation material within unit	1Unit	North East	Friable Asbestos (5)	Low (1)	Medium Priority (4-5)
	Assumed Asbestos - Disused unit - access sealed					
Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible					

Interior

B00N - R0001 - Sports Store

Ceiling Structures/Linings	Flat AC Sheeting	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00N/R0005/Ceiling Structures/Linings/S34					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)

B00N - R0002 - Movement

No Asbestos

B00N - R0003 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting	44m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00N/R0005/Ceiling Structures/Linings/S34					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)

B00N - R0004 - Sports Store

Ceiling Structures/Linings	Flat AC Sheeting	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00N/R0005/Ceiling Structures/Linings/S34					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)

B00N - R0005 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting	49m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00N/R0005/Ceiling Structures/Linings/S34					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)

B00N - R0006 - No Access

Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4377/B00N/R0005/Ceiling Structures/Linings/S34					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B000 - General Learning - 2002 - Steel (Steel)

Exterior

Underfloor Voids	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B000 - R0001 - Other-Community Use

No Asbestos

B000 - R0002 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 4377/B000/R0002/Ceiling Structures/Linings/S16	No Asbestos Detected
----------------------------	--	-----------------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 603 - D10093 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 30/12/2005

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D10291 - Learning Unit - Standard With P.A.A. : Placement Date - 7/05/2010

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 603 - D11265 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 16/12/2011

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D12004 - Learning Unit - Standard With P.A.A. : Placement Date - 3/04/2014

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D12509 - Learning Unit - Standard With P.A.A. : Placement Date - 12/12/2008

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

OS 603 - D12767 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 9/01/2008

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 603 - D13035 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 9/01/2008

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D13398 - Learning Unit - Standard With P.A.A. : Placement Date - 27/09/2013

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D13545 - Learning Unit - Standard With P.A.A. : Placement Date - 18/12/2012

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D14922 - Learning Unit - Standard With P.A.A. : Placement Date - 18/12/2012

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D14950 - Learning Unit - Standard With P.A.A. : Placement Date - 12/12/2008

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D15815 - Learning Unit - Standard With P.A.A. : Placement Date - 4/03/2015

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 601 - D15936 - Learning Unit - Standard/Withdrawal : Placement Date - 30/11/2006

Exterior

Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2
---------	---------------	------------------	-------

OS 602 - D17129 - Learning Unit - Standard With P.A.A. : Placement Date - 27/09/2016

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 750 - D17702 - Learning Unit - ESL : Placement Date - 19/05/2011

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Esl

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017