

# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Berinba Public School (4450)  
**Region :** Illawarra and South East  
**State Electorate :** Goulburn  
**Local Government Area :** Yass Valley

**Initial Survey :** Noel Arnold & Associates : 12 - May - 2008  
**Reviewed By :** Grencap-NAA : 25 - Aug - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

**B00A - Staff Facilities - 1972 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids - Flat Roof	No Asbestos Found					
Gable Verge Lining	Flat AC Sheeting	20m2	Southwest/North east	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4450/B00A/Gable Verge Lining/S9			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Underfloor Voids	Flat AC Sheeting	2Unit	Adjacent access door	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	<b>Assumed Asbestos - Area inaccessible Padlock seized</b>					

**Interior****B00A - R0001 - Staff Room**

Floor Coverings Res/Textile	Vinyl Sheet					<b>No Asbestos Detected</b>
	4450/B00A/R0001/Floor Coverings Res/Textile/S3					
Manhole	Low density board	0.2m2	Northeast	Friable Asbestos (5)	Low (1)	Medium Priority (4-5)
	4450/B00A/R0001/Manhole/S8			<b>Chrysotile (white asbestos)</b>		

**B00A - R0002 - Staff Room Annexe**

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	19.2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4450/B00A/R0002/Floor Coverings Res/Textile/S6			<b>Chrysotile (white asbestos)</b>		
Floor Coverings Res/Textile	Adhesive	19.2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4450/B00A/R0002/Floor Coverings Res/Textile/S7			<b>Chrysotile (white asbestos)</b>		

**B00A - R0003 - Staff Toilet**

No Asbestos

**B00A - R0004 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	53m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4450/B00C/R0008/Ceiling Structures/Linings/S1			<b>Chrysotile (white asbestos)</b>		

**B00A - R0005 - Distribution Board**

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4450/B00C/R0008/Ceiling Structures/Linings/S1			<b>Chrysotile (white asbestos)</b>		
Electrical Mounting Board	Resinous Board	2Unit	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	4450/B00A/R0005/Electrical Mounting Board/S5			<b>Chrysotile (white asbestos)</b>		

**B00A - R0006 - Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

**B00B - General Learning - 1972 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids - Packing to Floor Joists	No Asbestos Found					
Ceiling Voids - Raked Ceiling	Non Accessible Area - Area inaccessible					
Gable Verge Lining	Flat AC Sheeting	20m2	North, South	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4450/B00A/Gable Verge Lining/S9			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**Interior**

**B00B - R0001 - Personal Effects Storage**

Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4450/B00C/R0008/Ceiling Structures/Linings/S1			<b>Chrysotile (white asbestos)</b>		
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4450/B00C/R0002/Floor Coverings Res/Textile/S2			<b>Chrysotile (white asbestos)</b>		

**B00B - R0002 - Home Base Store**

Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4450/B00C/R0008/Ceiling Structures/Linings/S1			<b>Chrysotile (white asbestos)</b>		
Floor Coverings Res/Textile	Vinyl Tiles	8m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4450/B00C/R0002/Floor Coverings Res/Textile/S2			<b>Chrysotile (white asbestos)</b>		

**B00B - R0003 - Home Base**

Ceiling Structures/Linings	Flat AC Sheeting	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4450/B00C/R0008/Ceiling Structures/Linings/S1			<b>Chrysotile (white asbestos)</b>		

**B00B - R0004 - Home Base**

Ceiling Structures/Linings	Flat AC Sheeting	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4450/B00C/R0008/Ceiling Structures/Linings/S1			<b>Chrysotile (white asbestos)</b>		

**B00B - R0005 - Home Base Store**

Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4450/B00C/R0008/Ceiling Structures/Linings/S1			<b>Chrysotile (white asbestos)</b>		
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4450/B00C/R0002/Floor Coverings Res/Textile/S2			<b>Chrysotile (white asbestos)</b>		

**B00B - R0006 - Distribution Board**

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4450/B00C/R0008/Ceiling Structures/Linings/S1			<b>Chrysotile (white asbestos)</b>		
Electrical Mounting Board	Resinous Board	1Unit	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	4450/B00A/R0005/Electrical Mounting Board/S5			<b>Chrysotile (white asbestos)</b>		

**B00B - R0007 - Personal Effects Storage**

Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4450/B00C/R0008/Ceiling Structures/Linings/S1			<b>Chrysotile (white asbestos)</b>		
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4450/B00C/R0002/Floor Coverings Res/Textile/S2			<b>Chrysotile (white asbestos)</b>		

**B00B - R0008 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	34m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4450/B00C/R0008/Ceiling Structures/Linings/S1			<b>Chrysotile (white asbestos)</b>		

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00B - R0009 - Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4450/B00C/R0008/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>	
<b>B00B - R9001 - Cleaning Distributed Store</b>						
No Asbestos						
<b>B00B - R9002 - General Storeroom</b>						
No Asbestos						
<b>B00B - R9003 - Cleaning Distributed Store</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - General Learning - 1972 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids - Raked Ceiling	No Asbestos Found					
Underfloor Voids - Packing to Floor Joists	No Asbestos Found					
Gable Verge Lining	Flat AC Sheeting	20m2	North, South	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4450/B00A/Gable Verge Lining/S9					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**Interior****B00C - R0001 - Personal Effects Storage**

Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4450/B00C/R0008/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Vinyl Tiles	8m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4450/B00C/R0002/Floor Coverings Res/Textile/S2					<b>Chrysotile (white asbestos)</b>

**B00C - R0002 - Home Base Store**

Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4450/B00C/R0008/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Vinyl Tiles	8m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4450/B00C/R0002/Floor Coverings Res/Textile/S2					<b>Chrysotile (white asbestos)</b>

**B00C - R0003 - Home Base**

Ceiling Structures/Linings	Flat AC Sheeting	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4450/B00C/R0008/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>

**B00C - R0004 - Home Base**

Ceiling Structures/Linings	Flat AC Sheeting	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4450/B00C/R0008/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>

**B00C - R0005 - Home Base Store**

Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4450/B00C/R0008/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4450/B00C/R0002/Floor Coverings Res/Textile/S2					<b>Chrysotile (white asbestos)</b>

**B00C - R0006 - Distribution Board**

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4450/B00C/R0008/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>
Electrical Mounting Board	Resinous Board	1Unit	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	4450/B00A/R0005/Electrical Mounting Board/S5					<b>Chrysotile (white asbestos)</b>

**B00C - R0007 - Personal Effects Storage**

Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4450/B00C/R0008/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4450/B00C/R0002/Floor Coverings Res/Textile/S2					<b>Chrysotile (white asbestos)</b>

**B00C - R0008 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	34m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4450/B00C/R0008/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

**B00D - General Learning - 1972 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids - Raked Ceiling	No Asbestos Found					
Underfloor Voids - Packing to Floor Joists	No Asbestos Found					
Gable Verge Lining	Flat AC Sheeting	20m2	North, South	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4450/B00A/Gable Verge Lining/S9					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**Interior**

**B00D - R0001 - Personal Effects Storage**

Floor Coverings Res/Textile	Vinyl Tiles	8m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4450/B00C/R0002/Floor Coverings Res/Textile/S2					<b>Chrysotile (white asbestos)</b>

**B00D - R0002 - Distribution Board**

Note: No inspection of live electrical installation.

Electrical Mounting Board	Resinous Board	1Unit	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4450/B00A/R0005/Electrical Mounting Board/S5					<b>Chrysotile (white asbestos)</b>

**B00D - R0003 - Home Base Store**

Floor Coverings Res/Textile	Vinyl Tiles	9m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4450/B00C/R0002/Floor Coverings Res/Textile/S2					<b>Chrysotile (white asbestos)</b>

**B00D - R0004 - Toilets - Boys/Girls**

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4450/B00C/R0008/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>

**B00D - R0005 - Home Base**

Ceiling Structures/Linings	Flat AC Sheeting	90m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4450/B00C/R0008/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>

**B00D - R0006 - Home Base**

Ceiling Structures/Linings	Flat AC Sheeting	90m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4450/B00C/R0008/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>

**B00D - R0007 - Toilets - Boys/Girls**

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4450/B00C/R0008/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>

**B00D - R0008 - Home Base Store**

Floor Coverings Res/Textile	Vinyl Tiles	9m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4450/B00C/R0002/Floor Coverings Res/Textile/S2					<b>Chrysotile (white asbestos)</b>

**B00D - R0009 - Personal Effects Storage**

Floor Coverings Res/Textile	Vinyl Tiles	8m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4450/B00C/R0002/Floor Coverings Res/Textile/S2					<b>Chrysotile (white asbestos)</b>

**B00D - R0010 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	57m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	4450/B00C/R0008/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>

**B00D - R9001 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	80m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4450/B00C/R0008/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos)</b>

**B00D - R9002 - General Assistant/Bulk Store**

No Asbestos

**B00D - R9003 - General Storeroom**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

**B00D - R9004 - Sports Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - Library/Tiered Learning - 1995 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible
Ceiling Voids	No Asbestos Found

**Interior**

**B00E - R0001 - Cleaning Distributed Store**

No Asbestos

**B00E - R0002 - Special Programs Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00E - R0003 - Special Programs Room**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00E - R0004 - Reading Area**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00E - R0005 - Library Office/Workroom**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00E - R0006 - Communications Room**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00E - R0007 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00E - R0008 - Movement**

No Asbestos

**B00E - R0009 - Plant**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - General Learning/Pupil Facilities - 1995 - Brick/Veneer (Brick/Veneer)****Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible
Ceiling Voids	No Asbestos Found

**Interior****B00F - R0001 - Toilets - Boys**

No Asbestos

**B00F - R0002 - Kiln Room**

No Asbestos

**B00F - R0003 - Toilets - Girls**

No Asbestos

**B00F - R0004 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0005 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0006 - Practical Activities - 1hb**

No Asbestos

**B00F - R0007 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0008 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0009 - Practical Activities - 1hb**

No Asbestos

**B00F - R0010 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0011 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0012 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00F - R0013 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0014 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0015 - Practical Activities - 1hb**

No Asbestos

**B00F - R0016 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0017 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0018 - Practical Activities - 1hb**

No Asbestos

**B00F - R0019 - Home Base Store**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00F - R0020 - Withdrawal Space - 1hb</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00F - R0021 - Movement</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - Pupil Facilities - 1995 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible
Ceiling Voids	No Asbestos Found

**Interior**

**B00G - R0001 - Canteen**

No Asbestos

**B00G - R0002 - Canteen Office/Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - Communal Facilities/Pupil Facilities - 1995 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible
Ceiling Voids	No Asbestos Found

**Interior**

**B00H - R0001 - Toilets - Girls**

No Asbestos

**B00H - R0002 - Shower/Change**

No Asbestos

**B00H - R0003 - General Storeroom**

No Asbestos

**B00H - R0004 - Main Switch Board**

No Asbestos

**B00H - R0005 - Interview**

No Asbestos

**B00H - R0006 - Special Programs Room**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00H - R0007 - Plant**

No Asbestos

**B00H - R0008 - Communal Space**

No Asbestos

**B00H - R0009 - Raised Platform**

No Asbestos

**B00H - R0010 - Toilets - Boys**

No Asbestos

**B00H - R0011 - Plant**

No Asbestos

**B00H - R0012 - General Storeroom**

No Asbestos

**B00H - R0013 - General Storeroom**

No Asbestos

**B00H - R0014 - Hall Chair Store**

No Asbestos

**B00H - R0015 - Cleaning Distributed Store**

No Asbestos

**B00H - R0016 - Disabled Toilet**

No Asbestos

**B00H - R0017 - Movement**

No Asbestos

**B00H - R0018 - Movement**

No Asbestos

**B00H - R0019 - Movement**

No Asbestos

**B00H - R0020 - Special Programs Room**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00J - Administration - 1995 - Brick/Veneer (Brick/Veneer)****Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
Ceiling Voids	No Asbestos Found					
Eaves Linings	Flat AC Sheeting 4450/B00J/R0001/Ceiling Structures/Linings/S4					<b>No Asbestos Detected</b>

**Interior****B00J - R0001 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting 4450/B00J/R0001/Ceiling Structures/Linings/S4					<b>No Asbestos Detected</b>
----------------------------	---	--	--	--	--	-----------------------------

**B00J - R0002 - Entry Vestibule**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

**B00J - R0003 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00J - R0004 - Clerical Office**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

**B00J - R0005 - Sick Bay**

No Asbestos

**B00J - R0006 - Sick Bay - Shower/Toilet**

No Asbestos

**B00J - R0007 - Interview**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

**B00J - R0008 - Principal**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

**B00J - R0009 - Deputy Principal**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

**B00J - R0010 - Movement**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

**B00J - R0011 - Staff Toilet**

No Asbestos

**B00J - R0012 - Staff Toilet**

No Asbestos

**B00J - R0013 - Staff Toilet**

No Asbestos

**B00J - R0014 - Cleaning Distributed Store**

No Asbestos

**B00J - R0015 - Staff Room Annexe**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

**B00J - R0016 - Security Store**

No Asbestos

**B00J - R0017 - Duplicating Workroom**

No Asbestos

**B00J - R0018 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting 4450/B00J/R0001/Ceiling Structures/Linings/S4					<b>No Asbestos Detected</b>
----------------------------	---	--	--	--	--	-----------------------------

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00K - General Learning - 2010 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Packing to Floor Joists	No Asbestos Found
Ceiling Voids	No Asbestos Found

**Interior**

**B00K - R0001 - Movement**

No Asbestos

**B00K - R0002 - Special Programs Store**

No Asbestos

**B00K - R0003 - Special Programs Store**

No Asbestos

**B00K - R0004 - Special Programs Room - Type 1**

No Asbestos

**B00K - R0005 - Home Base**

No Asbestos

**B00K - R0006 - Home Base Store**

No Asbestos

**B00K - R0007 - Practical Activities - 1hb**

No Asbestos

**B00K - R0008 - Withdrawal Space - 2hb**

No Asbestos

**B00K - R0009 - Home Base**

No Asbestos

**B00K - R0010 - Home Base Store**

No Asbestos

**B00K - R0011 - Practical Activities - 1hb**

No Asbestos

**B00K - R0012 - External Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Demountables**

**Demountable details as per the AMS records as of 15 Feb 2017.**

**OS 602 - D12605 - Learning Unit - Standard With P.A.A. : Placement Date - 22/04/2014**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 602 - D13958 - Learning Unit - Standard With P.A.A. : Placement Date - 16/12/2009**

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 603 - D14663 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 16/03/2007**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017