

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Blackett Public School (4453)
Region : Western Sydney
State Electorate : Mount DrUITt
Local Government Area : Blacktown

Initial Survey : Noel Arnold & Associates : 01 - May - 2008
Reviewed By : Parsons Brinckerhoff : 17 - Jun - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/Staff Facilities - 1971 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00A - R0001 - Interview (15.81 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4453/B00A/R0025/Ceiling Structures/Linings/S4					
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

B00A - R0002 - Staff Toilet (2.49 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4453/B00A/R0025/Ceiling Structures/Linings/S4					
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

B00A - R0003 - General Storeroom (3.35 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4453/B00A/R0025/Ceiling Structures/Linings/S4					
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4453/B00B/R0009/Floor Coverings Res/Textile/S3					Chrysotile (white asbestos)

B00A - R0004 - General Storeroom (9.66 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4453/B00A/R0025/Ceiling Structures/Linings/S4					
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

Floor Coverings Res/Textile	Vinyl Tiles	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4453/B00B/R0009/Floor Coverings Res/Textile/S3					Chrysotile (white asbestos)

B00A - R0005 - General Storeroom (5.61 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4453/B00A/R0025/Ceiling Structures/Linings/S4					
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

B00A - R0006 - Movement (15.97 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4453/B00A/R0025/Ceiling Structures/Linings/S4					
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

Floor Coverings Res/Textile	Vinyl Tiles	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4453/B00B/R0009/Floor Coverings Res/Textile/S3					Chrysotile (white asbestos)

B00A - R0007 - Interview (11.96 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4453/B00A/R0025/Ceiling Structures/Linings/S4					
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

Floor Coverings Res/Textile	Vinyl Tiles	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4453/B00B/R0009/Floor Coverings Res/Textile/S3					Chrysotile (white asbestos)

Thermacon Heater	Encapsulated Insulation material within unit					No Asbestos Detected
	4453/B00D/R0017/Thermacon Heater/S14					

B00A - R0008 - Cleaning Supplies (5.68 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4453/B00A/R0025/Ceiling Structures/Linings/S4					
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

B00A - R0009 - Staff Room (112.76 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Ceiling Structures/Linings	Vermiculite 4453/B00A/R0025/Ceiling Structures/Linings/S4					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles 4453/B00B/R0009/Floor Coverings Res/Textile/S3	50m2	East	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00A - R0010 - Movement (5.79 m2)						
Ceiling Structures/Linings	Vermiculite 4453/B00A/R0025/Ceiling Structures/Linings/S4					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00A - R0011 - Staff Toilet (6.35 m2)						
Ceiling Structures/Linings	Vermiculite 4453/B00A/R0025/Ceiling Structures/Linings/S4					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Partition Walls (Cubicles)	Compressed AC Sheet 4453/B00B/R0006/Partition Walls (Cubicles)/S1	4m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00A - R0012 - Staff Toilet (6.68 m2)						
Ceiling Structures/Linings	Vermiculite 4453/B00A/R0025/Ceiling Structures/Linings/S4					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Partition Walls (Cubicles)	Compressed AC Sheet 4453/B00B/R0006/Partition Walls (Cubicles)/S1	2m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00A - R0013 - Movement (63.26 m2)						
No Asbestos						
B00A - R0014 - Movement (19.07 m2)						
No Asbestos						
B00A - R0015 - External Movement (166.74 m2)						
No Asbestos						
B00A - R0016 - Main Switch Board (10.56 m2)						
Kiln	Encapsulated Insulation material within unit 4453/B00A/R0016/Kiln (jeko)/S15					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting 4453/B00A/R0016/Ceiling Structures/Linings/S5	11m2	Throughout	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
Electrical Mounting Board	Resinous Board 4453/B00A/R0016/Electrical Mounting Board/S17					No Asbestos Detected
Minior Debris	Flat AC Sheeting 4453/B00A/R0016/Ceiling Structures/Linings/S5	4m2	East	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
Electrical Backing Board	Resinous Board 4453/B00C/R0014/Electrical Mounting Board/S18	1Unit	North	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00A - R0017 - Canteen (26.64 m2)						
Ceiling Structures/Linings	Vermiculite 4453/B00A/R0025/Ceiling Structures/Linings/S4					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles 4453/B00B/R0009/Floor Coverings Res/Textile/S3	27m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00A - R0018 - Canteen Office/Store (4.26 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite 4453/B00A/R0025/Ceiling Structures/Linings/S4					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Vinyl Tiles 4453/B00B/R0009/Floor Coverings Res/Textile/S3	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00A - R0019 - Movement (2.36 m2)						
Ceiling Structures/Linings	Vermiculite 4453/B00A/R0025/Ceiling Structures/Linings/S4					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00A - R0020 - Staff Toilet (1.84 m2)						
Ceiling Structures/Linings	Vermiculite 4453/B00A/R0025/Ceiling Structures/Linings/S4					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00A - R0021 - Interview (16.03 m2)						
Ceiling Structures/Linings	Vermiculite 4453/B00A/R0025/Ceiling Structures/Linings/S4					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Thermacon Heater	Encapsulated Insulation material within unit 4453/B00D/R0017/Thermacon Heater/S14					No Asbestos Detected
B00A - R0022 - Home Base (87.78 m2)						
Thermacon Heater	Encapsulated Insulation material within unit 4453/B00D/R0017/Thermacon Heater/S14					No Asbestos Detected
B00A - R0023 - Duplicating Workroom (27.18 m2)						
No Asbestos						
B00A - R0024 - Sick Bay (8 m2)						
Ceiling Structures/Linings	Vermiculite 4453/B00A/R0025/Ceiling Structures/Linings/S4					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00A - R0025 - Entry Vestibule (21.45 m2)						
Ceiling Structures/Linings	Vermiculite 4453/B00A/R0025/Ceiling Structures/Linings/S4					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00A - R0026 - Community Clinic (22.13 m2)						
Ceiling Structures/Linings	Vermiculite 4453/B00A/R0025/Ceiling Structures/Linings/S4					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Vinyl Tiles 4453/B00B/R0009/Floor Coverings Res/Textile/S3	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Thermacon Heater	Encapsulated Insulation material within unit 4453/B00D/R0017/Thermacon Heater/S14					No Asbestos Detected
B00A - R0027 - Community Clinic (6.03 m2)						
Ceiling Structures/Linings	Vermiculite 4453/B00A/R0025/Ceiling Structures/Linings/S4					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Vinyl Tiles 4453/B00B/R0009/Floor Coverings Res/Textile/S3	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00A - R0028 - Clerical Office/Workroom (12.35 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite					
	4453/B00A/R0025/Ceiling Structures/Linings/S4					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R0029 - Clerical Office/Workroom (8.79 m2)						
Ceiling Structures/Linings	Vermiculite					
	4453/B00A/R0025/Ceiling Structures/Linings/S4					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R0030 - Security Store (7.3 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4453/B00B/R0009/Floor Coverings Res/Textile/S3					Chrysotile (white asbestos)
B00A - R0031 - Clerical Office (18.58 m2)						
Ceiling Structures/Linings	Vermiculite					
	4453/B00A/R0025/Ceiling Structures/Linings/S4					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R0032 - Deputy Principal (13.02 m2)						
Ceiling Structures/Linings	Vermiculite					
	4453/B00A/R0025/Ceiling Structures/Linings/S4					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R0033 - Principal (17.51 m2)						
Ceiling Structures/Linings	Vermiculite					
	4453/B00A/R0025/Ceiling Structures/Linings/S4					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R0034 - General Storeroom (2.62 m2)						
Ceiling Structures/Linings	Vermiculite					
	4453/B00A/R0025/Ceiling Structures/Linings/S4					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R0035 - Staff Toilet (3.75 m2)						
Ceiling Structures/Linings	Vermiculite					
	4453/B00A/R0025/Ceiling Structures/Linings/S4					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning/Pupil Facilities - 1971 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior**B00B - R0001 - Home Base (89.36 m2)**

Ceiling Structures/Linings	Vermiculite 4453/B00B/R0005/Ceiling Structures/Linings/S2					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Thermacon Heater	Encapsulated Insulation material within unit 4453/B00D/R0017/Thermacon Heater/S14					No Asbestos Detected

B00B - R0002 - Toilets - Boys/Girls (3.42 m2)

Partition Walls (Cubicles)	Compressed AC Sheet	2m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	4453/B00B/R0006/Partition Walls (Cubicles)/S1					Chrysotile (white asbestos)

B00B - R0003 - Home Base Store (5.75 m2)

Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4453/B00B/R0009/Floor Coverings Res/Textile/S3					Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite 4453/B00B/R0005/Ceiling Structures/Linings/S2					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>

B00B - R0004 - Personal Effects Storage (8.69 m2)

Floor Coverings Res/Textile	Vinyl Tiles	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4453/B00B/R0009/Floor Coverings Res/Textile/S3					Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite 4453/B00B/R0005/Ceiling Structures/Linings/S2					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>

B00B - R0005 - Home Base (93.95 m2)

Ceiling Structures/Linings	Vermiculite 4453/B00B/R0005/Ceiling Structures/Linings/S2					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Thermacon Heater	Encapsulated Insulation material within unit 4453/B00D/R0017/Thermacon Heater/S14					No Asbestos Detected

B00B - R0006 - Toilets - Boys/Girls (3.4 m2)

Partition Walls (Cubicles)	Compressed AC Sheet	2m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	4453/B00B/R0006/Partition Walls (Cubicles)/S1					Chrysotile (white asbestos)

B00B - R0007 - Home Base Store (6.84 m2)

Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4453/B00B/R0009/Floor Coverings Res/Textile/S3					Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite 4453/B00B/R0005/Ceiling Structures/Linings/S2					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>

B00B - R0008 - Distribution Board (1.14 m2)

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Vermiculite 4453/B00B/R0005/Ceiling Structures/Linings/S2					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Electrical Backing Board	Resinous Board	1m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	4453/B00C/R0014/Electrical Mounting Board/S18					Chrysotile (white asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Wall Linings Internal	Flat AC Sheeting	5m2	South	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
4453/B00C/R1002/Wall Linings Internal/S16				Chrysotile (white asbestos)		
B00B - R0009 - Personal Effects Storage (9.23 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4453/B00B/R0009/Floor Coverings Res/Textile/S3				Chrysotile (white asbestos)		
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
4453/B00B/R0005/Ceiling Structures/Linings/S2				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		
B00B - R0010 - Toilets - Girls (20.03 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
4453/B00B/R0005/Ceiling Structures/Linings/S2				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		
Partition Walls (Cubicles)	Compressed AC Sheet	10m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
4453/B00B/R0006/Partition Walls (Cubicles)/S1				Chrysotile (white asbestos)		
B00B - R0011 - Cleaning Distributed Store (0.48 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
4453/B00B/R0005/Ceiling Structures/Linings/S2				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		
B00B - R0012 - Toilets - Boys (16.26 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
4453/B00B/R0005/Ceiling Structures/Linings/S2				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		
Partition Walls (Cubicles)	Compressed AC Sheet	5m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
4453/B00B/R0006/Partition Walls (Cubicles)/S1				Chrysotile (white asbestos)		
B00B - R0013 - Toilets - Boys/Girls (2.9 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
4453/B00B/R0005/Ceiling Structures/Linings/S2				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		
Partition Walls (Cubicles)	Compressed AC Sheet	2m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
4453/B00B/R0006/Partition Walls (Cubicles)/S1				Chrysotile (white asbestos)		
B00B - R0014 - Personal Effects Storage (9.61 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4453/B00B/R0009/Floor Coverings Res/Textile/S3				Chrysotile (white asbestos)		
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
4453/B00B/R0005/Ceiling Structures/Linings/S2				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		
B00B - R0015 - Home Base (86.83 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
4453/B00B/R0005/Ceiling Structures/Linings/S2				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		
Thermacon Heater	Encapsulated Insulation material within unit					No Asbestos Detected
4453/B00D/R0017/Thermacon Heater/S14						
B00B - R0016 - Home Base Store (7.04 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4453/B00B/R0009/Floor Coverings Res/Textile/S3				Chrysotile (white asbestos)		
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
4453/B00B/R0005/Ceiling Structures/Linings/S2				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
---------	----------------------	--------	--------------------	--------------------	-------------	------------------

Sample No	Test Result
-----------	-------------

B00B - R0017 - External Movement (92.33 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning/Pupil Facilities - 1971 - Brick/Block (Brick/Block)

Exterior

In-fill-panel	Flat AC Sheeting	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4453/B00C/In-fill-panel/S8					Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00C - R0001 - Home Base (65.89 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4453/B00A/R0025/Ceiling Structures/Linings/S4					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Thermacon Heater	Encapsulated Insulation material within unit					No Asbestos Detected
	4453/B00D/R0017/Thermacon Heater/S14					
In-fill-panel	Flat AC Sheeting	3m	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	4453/B00C/In-fill-panel/S8					Chrysotile (white asbestos)

B00C - R0002 - Cleaning Distributed Store (0.31 m2)

No Asbestos

B00C - R0003 - Distribution Board (0.48 m2)

Note: No inspection of live electrical installation.

Wall Linings Internal	Flat AC Sheeting	4m2	Back of doors	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
	4453/B00C/R0003/Wall Linings Internal/S9					Chrysotile (white asbestos)
Electrical Mounting Board	Resinous Board	1Unit	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	4453/B00C/R0014/Electrical Mounting Board/S18					Chrysotile (white asbestos)

B00C - R0004 - Interview (18.03 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4453/B00A/R0025/Ceiling Structures/Linings/S4					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4453/B00C/R0004/Floor Coverings Res/Textile/S10					Chrysotile (white asbestos)

B00C - R0005 - Home Base (68.69 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4453/B00A/R0025/Ceiling Structures/Linings/S4					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Thermacon Heater	Encapsulated Insulation material within unit					No Asbestos Detected
	4453/B00D/R0017/Thermacon Heater/S14					
In-fill-panel	Flat AC Sheeting	6m	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4453/B00C/In-fill-panel/S8					Chrysotile (white asbestos)

B00C - R0006 - Home Base (65.94 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4453/B00A/R0025/Ceiling Structures/Linings/S4					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Thermacon Heater	Encapsulated Insulation material within unit					No Asbestos Detected
	4453/B00D/R0017/Thermacon Heater/S14					
In-fill-panel	Flat AC Sheeting	6m	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4453/B00C/In-fill-panel/S8					Chrysotile (white asbestos)

B00C - R0007 - Other-Community Use (65.63 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite 4453/B00A/R0025/Ceiling Structures/Linings/S4				Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>	
Thermacon Heater	Encapsulated Insulation material within unit 4453/B00D/R0017/Thermacon Heater/S14				No Asbestos Detected	
In-fill-panel	Flat AC Sheeting 4453/B00C/In-fill-panel/S8	6m	North	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00C - R0008 - Movement (89.59 m2)						
No Asbestos						
B00C - R0009 - P.E. Store (7.59 m2)						
No Asbestos						
B00C - R0010 - Toilets - Boys (44.49 m2)						
Partition Walls (Cubicles)	Compressed AC Sheet 4453/B00C/R0010/Partition Walls (Cubicles)/S7	10m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00C - R0011 - General Assistant/Bulk Store (17.85 m2)						
No Asbestos						
B00C - R0012 - Staff Toilet (2.04 m2)						
No Asbestos						
B00C - R0013 - General Storeroom (14.49 m2)						
No Asbestos						
B00C - R0014 - Distribution Board (0.62 m2)						
Note: No inspection of live electrical installation.						
Wall Linings Internal	Flat AC Sheeting 4453/B00C/R0024/Wall Linings Internal/S6				No Asbestos Detected	
Electrical Mounting Board	Resinous Board 4453/B00C/R0014/Electrical Mounting Board/S18	1Unit	West	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Electrical Mounting Board	Resinous Board 4453/B00C/R0014/Electrical Mounting Board/S18	1Unit	West	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00C - R0017 - Staff Toilet (2.07 m2)						
No Asbestos						
B00C - R0018 - Cleaning Supplies (7.31 m2)						
No Asbestos						
B00C - R0019 - Toilets - Girls (40.6 m2)						
Partition Walls (Cubicles)	Compressed AC Sheet 4453/B00C/R0010/Partition Walls (Cubicles)/S7	14m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00C - R0020 - Cleaning Distributed Store (2.6 m2)						
No Asbestos						
B00C - R0021 - External Movement (171.28 m2)						
No Asbestos						
B00C - R0022 - Sports Store (7.41 m2)						
No Asbestos						
B00C - R0023 - Sports Store (29.9 m2)						
No Asbestos						
B00C - R0024 - Movement (126.97 m2)						
Wall Linings Internal	Flat AC Sheeting 4453/B00C/R0024/Wall Linings Internal/S6				No Asbestos Detected	
B00C - R0025 - Garden Store (16.65 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
B00C - R0026 - Stairs (9.67 m2)						
No Asbestos						
B00C - R0027 - Stairs (10.03 m2)						
No Asbestos						
B00C - R1001 - Home Base (65.55 m2)						
Ceiling Structures/Linings	Vermiculite 4453/B00A/R0025/Ceiling Structures/Linings/S4					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Thermacon Heater	Encapsulated Insulation material within unit 4453/B00D/R0017/Thermacon Heater/S14					No Asbestos Detected
In-fill-panel	Flat AC Sheeting 4453/B00C/In-fill-panel/S8	6m	North	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00C - R1002 - Cleaning Distributed Store (0.27 m2)						
Wall Linings Internal	Flat AC Sheeting 4453/B00C/R1002/Wall Linings Internal/S16	3m2	West	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5) Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite 4453/B00C/R1002/Ceiling Structures/Linings/S20					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00C - R1003 - General Storeroom (18.26 m2)						
Ceiling Structures/Linings	Vermiculite 4453/B00A/R0025/Ceiling Structures/Linings/S4					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Vinyl Tiles 4453/B00C/R0004/Floor Coverings Res/Textile/S10	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00C - R1004 - Home Base (66.57 m2)						
Ceiling Structures/Linings	Vermiculite 4453/B00A/R0025/Ceiling Structures/Linings/S4					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
In-fill-panel	Flat AC Sheeting 4453/B00C/In-fill-panel/S8	6m	South	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00C - R1005 - Home Base (66.42 m2)						
Ceiling Structures/Linings	Vermiculite 4453/B00A/R0025/Ceiling Structures/Linings/S4					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Thermacon Heater	Encapsulated Insulation material within unit 4453/B00D/R0017/Thermacon Heater/S14					No Asbestos Detected
In-fill-panel	Flat AC Sheeting 4453/B00C/In-fill-panel/S8	6m	South	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00C - R1006 - Home Base (65.7 m2)						
Ceiling Structures/Linings	Vermiculite 4453/B00A/R0025/Ceiling Structures/Linings/S4					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Thermacon Heater	Encapsulated Insulation material within unit 4453/B00D/R0017/Thermacon Heater/S14					No Asbestos Detected

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
In-fill-panel	Flat AC Sheeting	6m	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	4453/B00C/In-fill-panel/S8					Chrysotile (white asbestos)
B00C - R1007 - Raised Platform (26.12 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4453/B00A/R0025/Ceiling Structures/Linings/S4					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
In-fill-panel	Flat AC Sheeting	3m	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4453/B00C/In-fill-panel/S8					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles	27m2	Throughout, under stage	Good Condition (1)	Low (1)	Low Priority (2-3)
	4453/B00C/R0004/Floor Coverings Res/Textile/S10					Chrysotile (white asbestos)
B00C - R1008 - Communal Space (34.98 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4453/B00A/R0025/Ceiling Structures/Linings/S4					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Thermacon Heater	Encapsulated Insulation material within unit					No Asbestos Detected
	4453/B00D/R0017/Thermacon Heater/S14					
In-fill-panel	Flat AC Sheeting	3m	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4453/B00C/In-fill-panel/S8					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles	35m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4453/B00C/R0004/Floor Coverings Res/Textile/S10					Chrysotile (white asbestos)
B00C - R1009 - Communal Space (66.4 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4453/B00A/R0025/Ceiling Structures/Linings/S4					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Thermacon Heater	Encapsulated Insulation material within unit					No Asbestos Detected
	4453/B00D/R0017/Thermacon Heater/S14					
In-fill-panel	Flat AC Sheeting	6m	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4453/B00C/In-fill-panel/S8					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles	67m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4453/B00C/R0004/Floor Coverings Res/Textile/S10					Chrysotile (white asbestos)
B00C - R1010 - Home Base (65.92 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4453/B00A/R0025/Ceiling Structures/Linings/S4					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Thermacon Heater	Encapsulated Insulation material within unit					No Asbestos Detected
	4453/B00D/R0017/Thermacon Heater/S14					
In-fill-panel	Flat AC Sheeting	6m	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	4453/B00C/In-fill-panel/S8					Chrysotile (white asbestos)
B00C - R1011 - Home Base (66.07 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4453/B00A/R0025/Ceiling Structures/Linings/S4					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Thermacon Heater	Encapsulated Insulation material within unit					No Asbestos Detected
	4453/B00D/R0017/Thermacon Heater/S14					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
In-fill-panel	Flat AC Sheeting	6m	North	Good Condition (1)	Low (1)	Low Priority (2-3)
4453/B00C/In-fill-panel/S8					Chrysotile (white asbestos)	

B00C - R1012 - Movement (141.45 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
4453/B00A/R0025/Ceiling Structures/Linings/S4					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	

B00C - R1013 - Stairs (17.11 m2)

No Asbestos

B00C - R1014 - Stairs (16.3 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning/Library - 1971 - Brick/Block (Brick/Block)

Exterior

In-fill-panel	Flat AC Sheeting	40m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	4453/B00C/In-fill-panel/S8					Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00D - R0003 - Cleaning Distributed Store (0.34 m2)

No Asbestos

B00D - R0004 - Distribution Board (0.54 m2)

Note: No inspection of live electrical installation.

Wall Linings Internal	Flat AC Sheeting	4m2	Back of doors	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
	4453/B00C/R0003/Wall Linings Internal/S9					Chrysotile (white asbestos)
Electrical Mounting Board	Resinous Board	1Unit	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	4453/B00C/R0014/Electrical Mounting Board/S18					Chrysotile (white asbestos)

B00D - R0005 - K.L.A. Store (17.97 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4453/B00D/R0007/Ceiling Structures/Linings/S11					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

Floor Coverings Res/Textile	Vinyl Tiles	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4453/B00C/R0004/Floor Coverings Res/Textile/S10					Chrysotile (white asbestos)

B00D - R0006 - Library Office/Workroom (34.86 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	4453/B00D/R0007/Ceiling Structures/Linings/S11					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

In-fill-panel	Flat AC Sheeting	3m	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4453/B00C/In-fill-panel/S8					Chrysotile (white asbestos)

B00D - R0008 - Movement (49.91 m2)

No Asbestos

B00D - R0009 - General Storeroom (7.51 m2)

No Asbestos

B00D - R0010 - Toilets - Boys (67.56 m2)

Partition Walls (Cubicles)	Compressed AC Sheet	15m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	4453/B00C/R0010/Partition Walls (Cubicles)/S7					Chrysotile (white asbestos)

B00D - R0011 - Staff Toilet (2.12 m2)

No Asbestos

B00D - R0012 - General Storeroom (44.62 m2)

No Asbestos

B00D - R0013 - No Access (2.44 m2)

No Asbestos

B00D - R0014 - Distribution Board (2.15 m2)

Note: No inspection of live electrical installation.

Electrical Mounting Board	Resinous Board	1Unit	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4453/B00C/R0014/Electrical Mounting Board/S18					Chrysotile (white asbestos)

B00D - R0015 - Staff Toilet (1.94 m2)

No Asbestos

B00D - R0016 - Toilets - Girls (64.12 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Partition Walls (Cubicles)	Compressed AC Sheet	25m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	4453/B00C/R0010/Partition Walls (Cubicles)/S7					Chrysotile (white asbestos)
B00D - R0017 - Communal Space (127.37 m2)						
Thermacon Heater	Encapsulated Insulation material within unit					
	4453/B00D/R0017/Thermacon Heater/S14					No Asbestos Detected
B00D - R0018 - Sports Store (7.45 m2)						
No Asbestos						
B00D - R0019 - Movement (82.37 m2)						
Ceiling Structures/Linings	Vermiculite					
	4453/B00D/R0007/Ceiling Structures/Linings/S11					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
B00D - R0020 - Home Base (66.75 m2)						
Ceiling Structures/Linings	Vermiculite					
	4453/B00D/R0007/Ceiling Structures/Linings/S11					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
In-fill-panel	Flat AC Sheeting	6m	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4453/B00C/In-fill-panel/S8					Chrysotile (white asbestos)
Thermacon Heater	Encapsulated Insulation material within unit					
	4453/B00D/R0017/Thermacon Heater/S14					No Asbestos Detected
B00D - R0021 - Home Base (66.32 m2)						
Ceiling Structures/Linings	Vermiculite					
	4453/B00D/R0007/Ceiling Structures/Linings/S11					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
In-fill-panel	Flat AC Sheeting	6m	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4453/B00C/In-fill-panel/S8					Chrysotile (white asbestos)
B00D - R0022 - Cleaning Distributed Store (0.19 m2)						
No Asbestos						
B00D - R0023 - Distribution Board (0.49 m2)						
Note: No inspection of live electrical installation.						
Wall Linings Internal	Flat AC Sheeting	4m2	Back of doors	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
	4453/B00C/R0003/Wall Linings Internal/S9					Chrysotile (white asbestos)
Electrical Mounting Board	Resinous Board	1Unit	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4453/B00C/R0014/Electrical Mounting Board/S18					Chrysotile (white asbestos)
B00D - R0024 - Sports Store (17.99 m2)						
Ceiling Structures/Linings	Vermiculite					
	4453/B00D/R0007/Ceiling Structures/Linings/S11					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
Floor Coverings Res/Textile	Vinyl Tiles	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4453/B00C/R0004/Floor Coverings Res/Textile/S10					Chrysotile (white asbestos)
B00D - R0025 - Home Base - M (65.88 m2)						
Ceiling Structures/Linings	Vermiculite					
	4453/B00D/R0007/Ceiling Structures/Linings/S11					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						
In-fill-panel	Flat AC Sheeting	6m	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	4453/B00C/In-fill-panel/S8					Chrysotile (white asbestos)
Thermacon Heater	Encapsulated Insulation material within unit					
	4453/B00D/R0017/Thermacon Heater/S14					No Asbestos Detected

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
B00D - R0026 - Special Programs Room (65.81 m2)						
Ceiling Structures/Linings	Vermiculite 4453/B00D/R0007/Ceiling Structures/Linings/S11					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles 4453/B00C/R0004/Floor Coverings Res/Textile/S10	66m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
In-fill-panel	Flat AC Sheeting 4453/B00C/In-fill-panel/S8	6m	North	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Thermacon Heater	Encapsulated Insulation material within unit 4453/B00D/R0017/Thermacon Heater/S14					No Asbestos Detected
B00D - R0027 - External Movement (22.05 m2)						
No Asbestos						
B00D - R0028 - External Movement (223.5 m2)						
No Asbestos						
B00D - R0029 - Reading Area (200.76 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 4453/B00D/R0031/Floor Coverings Res/Textile/S19	201m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite 4453/B00C/R1002/Ceiling Structures/Linings/S20					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00D - R0030 - K.L.A. Store (25.56 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 4453/B00D/R0031/Floor Coverings Res/Textile/S19	26m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite 4453/B00C/R1002/Ceiling Structures/Linings/S20					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00D - R0031 - K.L.A. Store (34.93 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 4453/B00D/R0031/Floor Coverings Res/Textile/S19	35m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite 4453/B00C/R1002/Ceiling Structures/Linings/S20					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00D - R0032 - Stairs (7.67 m2)						
No Asbestos						
B00D - R0033 - Stairs (9.67 m2)						
No Asbestos						
B00D - R1001 - Home Base (65.72 m2)						
Ceiling Structures/Linings	Vermiculite 4453/B00D/R0007/Ceiling Structures/Linings/S11					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles 4453/B00C/R0004/Floor Coverings Res/Textile/S10	66m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
In-fill-panel	Flat AC Sheeting 4453/B00C/In-fill-panel/S8	6m	North	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Thermacon Heater	Encapsulated Insulation material within unit 4453/B00D/R0017/Thermacon Heater/S14					No Asbestos Detected

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00D - R1002 - Cleaning Distributed Store (0.35 m2)						
No Asbestos						
B00D - R1003 - Aboriginal Resource Centre (18.73 m2)						
Ceiling Structures/Linings	Vermiculite 4453/B00D/R0007/Ceiling Structures/Linings/S11				Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>	
In-fill-panel	Flat AC Sheeting 4453/B00C/In-fill-panel/S8	3m	East	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00D - R1004 - Home Base (65.74 m2)						
Ceiling Structures/Linings	Vermiculite 4453/B00D/R0007/Ceiling Structures/Linings/S11				Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>	
In-fill-panel	Flat AC Sheeting 4453/B00C/In-fill-panel/S8	6m	South	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00D - R1005 - Home Base (66.09 m2)						
Ceiling Structures/Linings	Vermiculite 4453/B00D/R0007/Ceiling Structures/Linings/S11				Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>	
In-fill-panel	Flat AC Sheeting 4453/B00C/In-fill-panel/S8	6m	South	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00D - R1006 - Home Base (65.74 m2)						
Ceiling Structures/Linings	Vermiculite 4453/B00D/R0007/Ceiling Structures/Linings/S11				Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>	
Floor Coverings Res/Textile	Vinyl Tiles 4453/B00C/R0004/Floor Coverings Res/Textile/S10	66m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
In-fill-panel	Flat AC Sheeting 4453/B00C/In-fill-panel/S8	6m	North	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Thermacon Heater	Encapsulated Insulation material within unit 4453/B00D/R0017/Thermacon Heater/S14				No Asbestos Detected	
B00D - R1007 - Home Base (66.06 m2)						
Ceiling Structures/Linings	Vermiculite 4453/B00D/R0007/Ceiling Structures/Linings/S11				Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>	
In-fill-panel	Flat AC Sheeting 4453/B00C/In-fill-panel/S8	6m	South	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00D - R1008 - Home Base (66.14 m2)						
Ceiling Structures/Linings	Vermiculite 4453/B00D/R0007/Ceiling Structures/Linings/S11				Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>	
In-fill-panel	Flat AC Sheeting 4453/B00C/In-fill-panel/S8	6m	South	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00D - R1009 - Home Base (65.57 m2)						
Ceiling Structures/Linings	Vermiculite 4453/B00D/R0007/Ceiling Structures/Linings/S11				Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Floor Coverings Res/Textile	Vinyl Tiles 4453/B00C/R0004/Floor Coverings Res/Textile/S10	66m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos)		
In-fill-panel	Flat AC Sheeting 4453/B00C/In-fill-panel/S8	6m	North	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos)		
Thermacon Heater	Encapsulated Insulation material within unit 4453/B00D/R0017/Thermacon Heater/S14					No Asbestos Detected
B00D - R1010 - Home Base (64.97 m2)						
Ceiling Structures/Linings	Vermiculite 4453/B00D/R0007/Ceiling Structures/Linings/S11					Limited Samples Taken
				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		
In-fill-panel	Flat AC Sheeting 4453/B00C/In-fill-panel/S8	6m	North	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos)		
B00D - R1011 - Home Base (66.15 m2)						
Ceiling Structures/Linings	Vermiculite 4453/B00D/R0007/Ceiling Structures/Linings/S11					Limited Samples Taken
				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		
In-fill-panel	Flat AC Sheeting 4453/B00C/In-fill-panel/S8	6m	South	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos)		
Thermacon Heater	Encapsulated Insulation material within unit 4453/B00D/R0017/Thermacon Heater/S14					No Asbestos Detected
B00D - R1012 - Home Base (66.14 m2)						
Ceiling Structures/Linings	Vermiculite 4453/B00D/R0007/Ceiling Structures/Linings/S11					Limited Samples Taken
				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		
In-fill-panel	Flat AC Sheeting 4453/B00C/In-fill-panel/S8	6m	South	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos)		
Thermacon Heater	Encapsulated Insulation material within unit 4453/B00D/R0017/Thermacon Heater/S14					No Asbestos Detected
B00D - R1013 - Cleaning Distributed Store (0.3 m2)						
No Asbestos						
B00D - R1014 - General Storeroom (18.72 m2)						
Ceiling Structures/Linings	Vermiculite 4453/B00D/R0007/Ceiling Structures/Linings/S11					Limited Samples Taken
				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		
Floor Coverings Res/Textile	Vinyl Tiles 4453/B00C/R0004/Floor Coverings Res/Textile/S10	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos)		
B00D - R1015 - Home Base (65.72 m2)						
Ceiling Structures/Linings	Vermiculite 4453/B00D/R0007/Ceiling Structures/Linings/S11					Limited Samples Taken
				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		
In-fill-panel	Flat AC Sheeting 4453/B00C/In-fill-panel/S8	6m	North	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos)		
B00D - R1016 - Home Base - M (65.89 m2)						
Ceiling Structures/Linings	Vermiculite 4453/B00D/R0007/Ceiling Structures/Linings/S11					Limited Samples Taken
				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
In-fill-panel	Flat AC Sheeting	6m	North	Good Condition (1)	Low (1)	Low Priority (2-3)
4453/B00C/In-fill-panel/S8					Chrysotile (white asbestos)	

B00D - R1017 - Movement (210.28 m2)

Ceiling Structures/Linings	Vermiculite	4453/B00D/R0007/Ceiling Structures/Linings/S11				Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

B00D - R1018 - Stairs (16.64 m2)

No Asbestos

B00D - R1019 - Stairs (15.91 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Other-After School Care - 2004 - Steel (Steel)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00E - R0004 - Out Of School Hours Care Centre (97.71 m2)

No Asbestos

B00E - R0005 - Toilets - Boys/Girls (2.3 m2)

No Asbestos

B00E - R0006 - Out Of School Hours Care Centre (9.93 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00F - Pupil Facilities/Communal Facilities - 2010 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior**B00F - R0001 - Communal Space (146.66 m2)**

No Asbestos

B00F - R0002 - Raised Platform (60.38 m2)

No Asbestos

B00F - R0003 - Movement (6.51 m2)

No Asbestos

B00F - R0004 - Movement (11.67 m2)

No Asbestos

B00F - R0005 - Movement (11.84 m2)

No Asbestos

B00F - R0006 - Hall Chair Store (9.52 m2)

No Asbestos

B00F - R0007 - Communal/Performance Store (9.52 m2)

No Asbestos

B00F - R0008 - P.E. Store (13.1 m2)

No Asbestos

B00F - R0009 - Toilet - Lobby (2.31 m2)

No Asbestos

B00F - R0010 - Toilets - Girls (7.23 m2)

No Asbestos

B00F - R0011 - Sound Cupboard (1.94 m2)

No Asbestos

B00F - R0012 - Toilet - Lobby (3.26 m2)

No Asbestos

B00F - R0013 - Toilets - Boys (5.74 m2)

No Asbestos

B00F - R0014 - Cleaning Distributed Store (5.21 m2)

No Asbestos

B00F - R0015 - Disabled Shower/Toilet (6.92 m2)

No Asbestos

B00F - R0016 - Main Switch Board (3.41 m2)

No Asbestos

B00F - R0017 - Covered Outdoor Learning Area (146.63 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017