


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Brooke Avenue Public School (4566)
Region : Hunter/Central Coast
State Electorate : The Entrance
Local Government Area : Wyong

Initial Survey : Noel Arnold & Associates : 14 - Mar - 2008
Register Issue Date : 23 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning - 1990 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00A - R0001 - External Movement

No Asbestos

B00A - R0002 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0003 - Practical Activities - 1hb

No Asbestos

B00A - R0004 - Special Programs Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0005 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0007 - Practical Activities - 1hb

No Asbestos

B00A - R0008 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0009 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0010 - External Movement

No Asbestos

B00A - R0011 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0012 - Practical Activities - 1hb

No Asbestos

B00A - R0013 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0014 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0015 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0016 - Practical Activities - 1hb

No Asbestos

B00A - R0017 - Cleaning Distributed Store

No Asbestos

B00A - R0018 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0019 - External Movement

No Asbestos

B00A - R0020 - Home Base Store

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0021 - Practical Activities - 1hb

No Asbestos

B00A - R0022 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0023 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0024 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0025 - Practical Activities - 1hb

No Asbestos

B00A - R0026 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0027 - Toilets - Girls

No Asbestos

B00A - R0028 - Toilets - Boys

No Asbestos

B00A - R0030 - Toilets - Girls

No Asbestos

B00A - R0031 - Access Shower/Toilet

No Asbestos

B00A - R0032 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 1990 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00B - R0001 - Kiln Room

No Asbestos

B00B - R0002 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00B - R0003 - Garden Store

No Asbestos

B00B - R0004 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0005 - Practical Activities - 1hb

No Asbestos

B00B - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0007 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0008 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0009 - Practical Activities - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0010 - Movement

No Asbestos

B00B - R0011 - Cleaning Distributed Store

No Asbestos

B00B - R0012 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0013 - Movement

No Asbestos

B00B - R0014 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0015 - Practical Activities - 1hb

No Asbestos

B00B - R0016 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0017 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0018 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0019 - Practical Activities - 1hb

No Asbestos

B00B - R0020 - Home Base Store

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0021 - Toilets - Girls

No Asbestos

B00B - R0022 - Toilets - Boys

No Asbestos

B00B - R0023 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Administration - 1990 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00C - R0001 - Movement

No Asbestos

B00C - R0002 - Entry Vestibule

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0003 - Interview

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0004 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0005 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0006 - Staff Toilet

No Asbestos

B00C - R0007 - Sick Bay

No Asbestos

B00C - R0008 - Staff Room Annexe

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0010 - Cleaning Distributed Store

No Asbestos

B00C - R0011 - Staff Room Annexe

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0012 - Security Store

No Asbestos

B00C - R0015 - Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0016 - Duplicating Workroom

No Asbestos

B00C - R0017 - Clerical Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0018 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0020 - General Assistant/Bulk Store

No Asbestos

B00C - R0021 - Staff Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0022 - Handwashing Facilities

No Asbestos

B00C - R0023 - Staff Toilet

No Asbestos

B00C - R0024 - Staff Toilet

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00C - R0025 - Handwashing Facilities

No Asbestos

B00C - R0026 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Library - 1990 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00D - R0001 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0002 - K.L.A. Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0003 - Reading Area

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0006 - Special Programs Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0007 - Cleaning Distributed Store

No Asbestos

B00D - R0008 - Main Switch Board

No Asbestos

B00D - R0009 - Communications Room

No Asbestos

B00D - R0010 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Communal Facilities - 1990 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00E - R0001 - Communal Space

No Asbestos

B00E - R0002 - Raised Platform

No Asbestos

B00E - R0003 - General Assistant/Bulk Store

No Asbestos

B00E - R0004 - General Storeroom

No Asbestos

B00E - R0005 - Uniform Shop

No Asbestos

B00E - R0006 - Movement

No Asbestos

B00E - R0007 - Shower/Change

No Asbestos

B00E - R0008 - Toilets - Boys

No Asbestos

B00E - R0009 - Drinking Facilities

No Asbestos

B00E - R0010 - Toilets - Girls

No Asbestos

B00E - R0011 - Shower/Change

No Asbestos

B00E - R0012 - Movement

No Asbestos

B00E - R0013 - Sports Store

No Asbestos

B00E - R0014 - Cleaning Supplies

No Asbestos

B00E - R0015 - Disabled Toilet

No Asbestos

B00E - R0016 - Movement

No Asbestos

B00E - R0017 - Canteen Office/Store

No Asbestos

B00E - R0018 - Canteen

No Asbestos

B00E - R0019 - Hall Chair Store

No Asbestos

B00E - R0020 - P.E. Store

No Asbestos

B00E - R0021 - Plant

No Asbestos

B00E - R0022 - Distribution Board

No Asbestos

Note: No inspection of live electrical installation.

B00E - R0024 - External Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00E - R0025 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00F - R0001 - Practical Activities - 1hb

No Asbestos

B00F - R0002 - Personal Effects Storage

No Asbestos

B00F - R0003 - Home Base Store

No Asbestos

B00F - R0004 - Home Base

No Asbestos

B00F - R0005 - Withdrawal Space - 2hb

No Asbestos

B00F - R0006 - Practical Activities - 1hb

No Asbestos

B00F - R0007 - Personal Effects Storage

No Asbestos

B00F - R0008 - Home Base Store

No Asbestos

B00F - R0009 - Home Base

No Asbestos

B00F - R0010 - Practical Activities - 1hb

No Asbestos

B00F - R0011 - Personal Effects Storage

No Asbestos

B00F - R0012 - Withdrawal Space - 1hb

No Asbestos

B00F - R0013 - Home Base Store

No Asbestos

B00F - R0014 - Home Base

No Asbestos

B00F - R0015 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00F - R0016 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00G - R0001 - Practical Activities - 1hb

No Asbestos

B00G - R0002 - Personal Effects Storage

No Asbestos

B00G - R0003 - Home Base Store

No Asbestos

B00G - R0004 - Home Base

No Asbestos

B00G - R0005 - Withdrawal Space - 2hb

No Asbestos

B00G - R0006 - Practical Activities - 1hb

No Asbestos

B00G - R0007 - Personal Effects Storage

No Asbestos

B00G - R0008 - Home Base

No Asbestos

B00G - R0009 - Home Base Store

No Asbestos

B00G - R0010 - Practical Activities - 1hb

No Asbestos

B00G - R0011 - Personal Effects Storage

No Asbestos

B00G - R0012 - Home Base

No Asbestos

B00G - R0013 - Withdrawal Space - 1hb

No Asbestos

B00G - R0014 - Home Base Store

No Asbestos

B00G - R0015 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00G - R0016 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D11337 - Learning Unit - Standard With P.A.A. : Placement Date - 30/06/1995

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Learning space/withdrawal/entry

Ceiling	Flat AC Sheet	Assumed Asbestos	70 m2
---------	---------------	------------------	-------

R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	3 m2

OS 602 - D11339 - Learning Unit - Standard With P.A.A. : Placement Date - 30/06/1995

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Learning space/withdrawal/entry

Ceiling	Flat AC Sheet	Assumed Asbestos	70 m2
---------	---------------	------------------	-------

R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	3 m2

OS 602 - D13756 - Learning Unit - Standard With P.A.A. : Placement Date - 12/11/1998

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Learning space/withdrawal/entry

Ceiling	Flat AC Sheet	Assumed Asbestos	70 m2
---------	---------------	------------------	-------

R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	3 m2

OS 602 - D16096 - Learning Unit - Standard With P.A.A. : Placement Date - 2/05/1997

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Learning space/withdrawal/entry

Ceiling	Flat AC Sheet	Assumed Asbestos	70 m2
---------	---------------	------------------	-------

R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	3 m2

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017