


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Bonnyrigg Heights Public School (4594)
Region : South Western Sydney
State Electorate : Cabramatta
Local Government Area : Fairfield

Initial Survey : Noel Arnold & Associates : 22 - May - 2008
Register Issue Date : 23 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning/Support Unit - 1993 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00A - R0001 - Disabled Toilet

No Asbestos

B00A - R0002 - Kiln Room

No Asbestos

B00A - R0003 - Practical Activities - 1hb

No Asbestos

B00A - R0004 - Special Programs Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0005 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0006 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0007 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0008 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0009 - Practical Activities - 1hb

No Asbestos

B00A - R0010 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0011 - Practical Activities - M - 1hb

No Asbestos

B00A - R0012 - Home Base - M

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0013 - Disabled Toilet

No Asbestos

B00A - R0014 - Home Base Store - M

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0015 - Withdrawal - M

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0016 - Home Base - M

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0017 - Home Base Store - M

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0018 - Disabled Toilet

No Asbestos

B00A - R0019 - Practical Activities - M - 1hb

No Asbestos

B00A - R0020 - Cleaning Distributed Store

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00A - R0021 - Movement

No Asbestos

B00A - R0022 - Home Base - S

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0023 - Withdrawal - S

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0024 - Home Base Store - S

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0025 - Staff Kitchen

No Asbestos

B00A - R0026 - Practical Activities - S - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0027 - Toilet - S

No Asbestos

B00A - R0028 - Laundry - S

No Asbestos

B00A - R0029 - Toilet - S

No Asbestos

B00A - R0030 - Movement

No Asbestos

B00A - R0031 - Home Base - S

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0032 - Home Base Store - S

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0033 - Withdrawal - S

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0034 - Movement

No Asbestos

B00A - R0035 - Wheelchair Store

No Asbestos

B00A - R0036 - Covered Vehicle Area/Porte Cochere

No Asbestos

B00A - R0037 - Movement

No Asbestos

B00A - R0038 - General Storeroom

No Asbestos

B00A - R0039 - Personal Effects Storage

No Asbestos

B00A - R0040 - Personal Effects Storage

No Asbestos

B00A - R0041 - Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 1993 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00B - R0001 - General Storeroom

No Asbestos

B00B - R0002 - Cleaning Distributed Store

No Asbestos

B00B - R0003 - Practical Activities - 1hb

No Asbestos

B00B - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0005 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0006 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0007 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0008 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0009 - Practical Activities - 1hb

No Asbestos

B00B - R0010 - Cleaning Distributed Store

No Asbestos

B00B - R0011 - Practical Activities - 1hb

No Asbestos

B00B - R0012 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0013 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0014 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0015 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0016 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0017 - Practical Activities - 1hb

No Asbestos

B00B - R0018 - Personal Effects Storage

No Asbestos

B00B - R0019 - Personal Effects Storage

No Asbestos

B00B - R0020 - Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00B - R0021 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning - 1993 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00C - R0001 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0002 - Practical Activities - 1hb

No Asbestos

B00C - R0003 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0004 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0005 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0006 - Practical Activities - 1hb

No Asbestos

B00C - R0007 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0008 - Cleaning Distributed Store

No Asbestos

B00C - R0009 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0010 - Practical Activities - 1hb

No Asbestos

B00C - R0011 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0012 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0013 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0014 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0015 - Practical Activities - 1hb

No Asbestos

B00C - R0016 - No Access

No Asbestos

B00C - R0017 - Uniform Shop

No Asbestos

B00C - R0018 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0019 - Movement

No Asbestos

B00C - R0020 - Security Store

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00C - R0021 - Personal Effects Storage

No Asbestos

B00C - R0022 - Personal Effects Storage

No Asbestos

B00C - R0023 - Personal Effects Storage

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning/Pupil Facilities - 1993 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00D - R0001 - Practical Activities - 1hb**

No Asbestos

B00D - R0002 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0003 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0004 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0005 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0006 - Practical Activities - 1hb

No Asbestos

B00D - R0007 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0008 - Cleaning Distributed Store

No Asbestos

B00D - R0009 - Practical Activities - 1hb

No Asbestos

B00D - R0010 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0011 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0012 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0013 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0014 - Practical Activities - 1hb

No Asbestos

B00D - R0015 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0016 - Drinking Facilities

No Asbestos

B00D - R0017 - Handwashing Facilities

No Asbestos

B00D - R0018 - Toilets - Boys

No Asbestos

B00D - R0019 - Toilets - Girls

No Asbestos

B00D - R0020 - Handwashing Facilities

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00D - R0021 - Movement

No Asbestos

B00D - R0022 - Personal Effects Storage

No Asbestos

B00D - R0023 - Personal Effects Storage

No Asbestos

B00D - R0024 - Personal Effects Storage

No Asbestos

B00D - R0025 - Craft Store

No Asbestos

B00D - R0026 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0027 - Security Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Pupil Facilities - 1993 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00E - R0001 - Drinking Facilities

No Asbestos

B00E - R0002 - Handwashing Facilities

No Asbestos

B00E - R0003 - Toilets - Boys

No Asbestos

B00E - R0004 - Handwashing Facilities

No Asbestos

B00E - R0005 - Toilets - Girls

No Asbestos

B00E - R0006 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Pupil Facilities/Building Services - 1993 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00F - R0001 - General Assistant/Bulk Store

No Asbestos

B00F - R0002 - Canteen Office/Store

No Asbestos

B00F - R0003 - Canteen

No Asbestos

B00F - R0004 - Movement

No Asbestos

B00F - R0005 - Main Switch Board

No Asbestos

B00F - R0006 - Cleaning Supplies

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Library - 1993 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00G - R0001 - Reading Area

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00G - R0002 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00G - R0003 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00G - R0004 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00G - R0005 - Special Programs Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00G - R0006 - Special Programs Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00G - R0007 - Plant

No Asbestos

B00G - R0008 - Movement

No Asbestos

B00G - R0009 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00H - Communal Facilities/Pupil Facilities - 1993 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00H - R0001 - Communal Space**

No Asbestos

B00H - R0002 - Toilets - Girls

No Asbestos

B00H - R0003 - Shower/Change

No Asbestos

B00H - R0004 - P.E. Store

No Asbestos

B00H - R0005 - Plant

No Asbestos

B00H - R0006 - Hall Chair Store

No Asbestos

B00H - R0007 - Toilets - Boys

No Asbestos

B00H - R0008 - Shower/Change

No Asbestos

B00H - R0009 - Cleaning Distributed Store

No Asbestos

B00H - R0010 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00H - R0011 - Raised Platform

No Asbestos

B00H - R0012 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B001 - Administration - 1993 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B001 - R0001 - Movement

No Asbestos

B001 - R0002 - Entry Vestibule

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B001 - R0003 - Movement

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B001 - R0004 - Entry Vestibule

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B001 - R0005 - Staff Toilet

No Asbestos

B001 - R0006 - Community Clinic

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B001 - R0007 - Staff Toilet

No Asbestos

B001 - R0008 - Staff Shower/Change

No Asbestos

B001 - R0009 - Sick Bay

No Asbestos

B001 - R0010 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B001 - R0011 - Duplicating Workroom

No Asbestos

B001 - R0012 - Security Store

No Asbestos

B001 - R0013 - Staff Toilet

No Asbestos

B001 - R0014 - Staff Toilet

No Asbestos

B001 - R0015 - Staff Toilet

No Asbestos

B001 - R0016 - Staff Kitchen

No Asbestos

B001 - R0017 - Staff Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B001 - R0018 - Staff Room Annexe

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B001 - R0019 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B001 - R0020 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B001 - R0021 - Clerical Office/Workroom						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B001 - R0022 - Principal						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B001 - R0023 - Clerical Office						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - General Learning - 2007 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00J - R0001 - Movement

No Asbestos

B00J - R0002 - Practical Activities - 1hb

No Asbestos

B00J - R0003 - Home Base Store

No Asbestos

B00J - R0004 - Home Base

No Asbestos

B00J - R0005 - Withdrawal Space - 2hb

No Asbestos

B00J - R0006 - Home Base

No Asbestos

B00J - R0007 - Home Base Store

No Asbestos

B00J - R0008 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - General Learning - 2007 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00K - R0001 - Movement

No Asbestos

B00K - R0002 - Practical Activities - 1hb

No Asbestos

B00K - R0003 - Home Base Store

No Asbestos

B00K - R0004 - Home Base

No Asbestos

B00K - R0005 - Withdrawal Space - 2hb

No Asbestos

B00K - R0006 - Home Base

No Asbestos

B00K - R0007 - Home Base Store

No Asbestos

B00K - R0008 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00L - R0001 - External Movement	No Asbestos
B00L - R0002 - Practical Activities	No Asbestos
B00L - R0003 - Home Base Store	No Asbestos
B00L - R0004 - Home Base	No Asbestos
B00L - R0005 - Withdrawal Space - 2hb	No Asbestos
B00L - R0006 - Home Base	No Asbestos
B00L - R0007 - Home Base Store	No Asbestos
B00L - R0008 - Practical Activities	No Asbestos
B00L - R0009 - Practical Activities	No Asbestos
B00L - R0010 - Withdrawal Space - 1hb	No Asbestos
B00L - R0011 - Home Base Store	No Asbestos
B00L - R0012 - Home Base	No Asbestos
B00L - R0013 - Main Switch Board Cupboard	No Asbestos
B00L - R0014 - Home Base	No Asbestos
B00L - R0015 - Home Base Store	No Asbestos
B00L - R0016 - Withdrawal Space - 1hb	No Asbestos
B00L - R0017 - Practical Activities	No Asbestos
B00L - R0018 - Practical Activities	No Asbestos
B00L - R0019 - Home Base Store	No Asbestos
B00L - R0020 - Home Base	No Asbestos
B00L - R0021 - Withdrawal Space - 2hb	No Asbestos
B00L - R0022 - Home Base	No Asbestos
B00L - R0023 - Home Base Store	No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00L - R0024 - Practical Activities

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - General Learning - 2012 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior

B00M - R0001 - External Movement

No Asbestos

B00M - R0002 - Home Base/Practical Activities

No Asbestos

B00M - R0003 - Home Base Store

No Asbestos

B00M - R0004 - Home Base

No Asbestos

B00M - R0005 - Withdrawal Space - 2hb

No Asbestos

B00M - R0006 - Home Base

No Asbestos

B00M - R0007 - Home Base Store

No Asbestos

B00M - R0008 - Home Base/Practical Activities

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00N - Storage - 2015 - Steel (Steel)

Exterior

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior

B00N - R0001 - Garden Store

No Asbestos

B00N - R0002 - Garage/Carport

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

NS 100 - D10128 - Learning Unit - Single Primary/PAA : Placement Date - 3/07/2014

Exterior

No Asbestos Found.

Interior

R1 - Home Base

No Asbestos Found.

R2 - Practical Activity Area

No Asbestos Found.

R3 - Home Base Store

No Asbestos Found.

R4 - Entry

No Asbestos Found.

NS 100 - D10449 - Learning Unit - Single Primary/PAA : Placement Date - 13/01/2012

Exterior

No Asbestos Found.

Interior

R1 - Home Base

No Asbestos Found.

R2 - Practical Activity Area

No Asbestos Found.

R3 - Home Base Store

No Asbestos Found.

R4 - Entry

No Asbestos Found.

OS 602 - D10813 - Learning Unit - Standard With P.A.A. : Placement Date - 9/10/1996

Exterior

Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2

Interior

R1 - Learning space/withdrawal/entry

Ceiling	Flat AC Sheet	Assumed Asbestos	70 m2
---------	---------------	------------------	-------

R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	3 m2

NS 100 - D11488 - Learning Unit - Single Primary/PAA : Placement Date - 3/05/2012

Exterior

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Interior						
R1 - Home Base						
No Asbestos Found.						
R2 - Practical Activity Area						
No Asbestos Found.						
R3 - Home Base Store						
No Asbestos Found.						
R4 - Entry						
No Asbestos Found.						
OS 602 - D11756 - Learning Unit - Standard With P.A.A. : Placement Date - 8/01/2009						
Exterior						
No Asbestos Found.						
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 602 - D11847 - Learning Unit - Standard With P.A.A. : Placement Date - 15/01/1999						
Exterior						
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Interior						
R1 - Learning space/withdrawal/entry						
Ceiling	Flat AC Sheet	Assumed Asbestos				70 m2
R2 - Home Base Store						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				3 m2
OS 840 - D12034 - Girls Toilet : Placement Date - 3/04/1998						
Exterior						
Eave Lining	Flat AC Sheet	Assumed Asbestos				2.88 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Interior						
R1 - Toilets-Girls						
Toilet partitions	Compressed AC Sheet	Assumed Asbestos				4 m2
End wall panel	Flat AC Sheet	Assumed Asbestos				36 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				18 m2
OS 602 - D12142 - Learning Unit - Standard With P.A.A. : Placement Date - 23/08/1996						
Exterior						
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Interior						
R1 - Learning space/withdrawal/entry						
Ceiling	Flat AC Sheet	Assumed Asbestos				70 m2
R2 - Home Base Store						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				3 m2
OS 602 - D12623 - Learning Unit - Standard With P.A.A. : Placement Date - 30/06/1995						
Exterior						
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Interior						
R1 - Learning space/withdrawal/entry						
Ceiling	Flat AC Sheet	Assumed Asbestos				70 m2
R2 - Home Base Store						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				3 m2
OS 602 - D12645 - Learning Unit - Standard With P.A.A. : Placement Date - 9/02/1998						
Exterior						
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Interior						
R1 - Learning space/withdrawal/entry						
Ceiling	Flat AC Sheet	Assumed Asbestos				70 m2
R2 - Home Base Store						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				3 m2
NS 100 - D12747 - Learning Unit - Single Primary/PAA : Placement Date - 2/07/2014						
Exterior						
No Asbestos Found.						
Interior						
R1 - Home Base						
No Asbestos Found.						
R2 - Practical Activity Area						
No Asbestos Found.						
R3 - Home Base Store						
No Asbestos Found.						
R4 - Entry						
No Asbestos Found.						
OS 751 - D13443 - Learning Unit - ESL : Placement Date - 19/12/2000						
Exterior						
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Interior						
R1 - Esl						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				36 m2
R2 - Esl						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				36 m2
OS 602 - D13461 - Learning Unit - Standard With P.A.A. : Placement Date - 30/06/1995						
Exterior						
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Interior						
R1 - Learning space/withdrawal/entry						
Ceiling	Flat AC Sheet	Assumed Asbestos				70 m2
R2 - Home Base Store						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				3 m2
OS 602 - D14065 - Learning Unit - Standard With P.A.A. : Placement Date - 3/03/2015						
Exterior						
No Asbestos Found.						
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 602 - D14070 - Learning Unit - Standard With P.A.A. : Placement Date - 9/02/1998						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 602 - D14162 - Learning Unit - Standard With P.A.A. : Placement Date - 9/10/1996						
Exterior						
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Interior						
R1 - Learning space/withdrawal/entry						
Ceiling	Flat AC Sheet	Assumed Asbestos				70 m2
R2 - Home Base Store						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				3 m2

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

OS 750 - D14174 - Learning Unit - ESL : Placement Date - 24/06/1998

Exterior

Eave Lining	Flat AC Sheet	Assumed Asbestos				5.76 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2

Interior

R1 - Esl

End wall panel	Flat AC Sheet	Assumed Asbestos				50 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				36 m2

OS 841 - D14276 - Boys Toilet : Placement Date - 22/04/1998

Exterior

Eave Lining	Flat AC Sheet	Assumed Asbestos				2.88 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2

Interior

R1 - Toilets-Boys

Toilet partitions	Compressed AC Sheet	Assumed Asbestos				6 m2
End wall panel	Flat AC Sheet	Assumed Asbestos				36 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				18 m2

OS 602 - D14536 - Learning Unit - Standard With P.A.A. : Placement Date - 30/06/1995

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2

Interior

R1 - Learning space/withdrawal/entry

Ceiling	Flat AC Sheet	Assumed Asbestos				70 m2
---------	---------------	------------------	--	--	--	-------

R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				3 m2

NS 100 - D15045 - Learning Unit - Single Primary/PAA : Placement Date - 13/08/2012

Exterior

No Asbestos Found.

Interior

R1 - Home Base

No Asbestos Found.

R2 - Practical Activity Area

No Asbestos Found.

R3 - Home Base Store

No Asbestos Found.

R4 - Entry

No Asbestos Found.

NS 100 - D15688 - Learning Unit - Single Primary/PAA : Placement Date - 15/04/2010

Exterior

No Asbestos Found.



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Interior						
R1 - Home Base						
No Asbestos Found.						
R2 - Practical Activity Area						
No Asbestos Found.						
R3 - Home Base Store						
No Asbestos Found.						
R4 - Entry						
No Asbestos Found.						
OS 602 - D15702 - Learning Unit - Standard With P.A.A. : Placement Date - 15/01/1999						
Exterior						
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Interior						
R1 - Learning space/withdrawal/entry						
Ceiling	Flat AC Sheet	Assumed Asbestos				70 m2
R2 - Home Base Store						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				3 m2
OS 522 - D15717 - Staff Study : Placement Date - 11/03/1999						
Exterior						
Eave Lining	Flat AC Sheet	Assumed Asbestos				5.76 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Interior						
R1 - Staff Room						
End wall panel	Flat AC Sheet	Assumed Asbestos				36 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				36 m2
OS 602 - D16266 - Learning Unit - Standard With P.A.A. : Placement Date - 2/09/2015						
Exterior						
No Asbestos Found.						
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 602 - D16354 - Learning Unit - Standard With P.A.A. : Placement Date - 3/02/1999						
Exterior						
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Interior						
R1 - Learning space/withdrawal/entry						
Ceiling	Flat AC Sheet	Assumed Asbestos				70 m2
R2 - Home Base Store						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				3 m2
OS 844 - D18134 - Country Toilet - Reltc - Boys/Girls : Placement Date - 22/03/2001						
Exterior						
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				2.88 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Interior						
R1 - Staff Toilet						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				9 m2
R2 - Staff Toilet						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				9 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

Available Asbestos Related Electronic Files

4594_ASB_150514_AMP.pdf

* Note : Refer to AMS for details of the attachment(s).

2017