

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Buninyong Public School (4616)


Region : Western NSW

State Electorate : Dubbo

Local Government Area : Dubbo

Initial Survey : Noel Arnold & Associates : 29 - Mar - 2008

Register Issue Date : 23 - Mar - 2017



2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00A - Administration - 1995 - Brick/Block (Brick/Block)

Exterior

| | |
|------------------|---------------------|
| Ceiling Voids | No Asbestos Found |
| Underfloor Voids | Requires Inspection |

Interior

B00A - R0001 - Staff Room

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00A - R0002 - Main Switch Board

No Asbestos

B00A - R0003 - Cleaning Distributed Store

No Asbestos

B00A - R0004 - Staff Room Annexe

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00A - R0005 - Staff Room Annexe

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00A - R0006 - Duplicating Workroom

No Asbestos

B00A - R0007 - Staff Room Annexe

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00A - R0008 - Staff Room Annexe

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00A - R0009 - Principal

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00A - R0010 - Adjoining School

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00A - R0011 - Adjoining School

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00A - R0012 - Adjoining School

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00A - R0013 - Adjoining School

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00A - R0014 - Entry Vestibule

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00A - R0015 - Movement

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00A - R0016 - Staff Shower/Change

No Asbestos

B00A - R0017 - Staff Toilet

No Asbestos

B00A - R0018 - Staff Toilet

No Asbestos

B00A - R0019 - Sick Bay

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|--|-------------------|--------------------|--------------------|--|------------------|
| Sample No | | | | | Test Result | |
| | No Asbestos | | | | | |
| | B00A - R0020 - Staff Shower/Change | | | | | |
| | No Asbestos | | | | | |
| | B00A - R0021 - Staff Toilet | | | | | |
| | No Asbestos | | | | | |
| | B00A - R0022 - Adjoining School | | | | | |
| | No Asbestos | | | | | |
| | B00A - R0023 - Adjoining School | | | | | |
| | No Asbestos | | | | | |
| | B00A - R0025 - Adjoining School | | | | | |
| | Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found | | | | |
| | B00A - R0026 - Clerical Office/Workroom | | | | | |
| | Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found | | | | |
| | B00A - R0027 - Plant | | | | | |
| | No Asbestos | | | | | |
| | B00A - R0028 - Distribution Board | | | | Note: No inspection of live electrical installation. | |
| | No Asbestos | | | | | |
| | B00A - R0029 - External Movement | | | | | |
| | No Asbestos | | | | | |
| | B00A - R0030 - External Movement | | | | | |
| | No Asbestos | | | | | |

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00C - Library/Special Purpose - 1995 - Brick/Block (Brick/Block)**Exterior**

| | |
|------------------|---------------------|
| Ceiling Voids | No Asbestos Found |
| Underfloor Voids | Requires Inspection |

Interior**B00C - R0001 - Plant**

No Asbestos

B00C - R0002 - Adjoining School

No Asbestos

B00C - R0003 - Toilets - Girls

No Asbestos

B00C - R0004 - Toilets - Boys

No Asbestos

B00C - R0005 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0006 - Special Programs StoreVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00C - R0007 - Special Programs Room**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00C - R0009 - Library Office/Workroom**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00C - R0010 - Adjoining School**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00C - R0011 - Adjoining School**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00C - R0012 - Communications Room**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00C - R0014 - Adjoining School**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00C - R0015 - Adjoining School**

No Asbestos

B00C - R0016 - Adjoining SchoolVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00C - R0017 - Adjoining School**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00C - R0018 - Adjoining School**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00C - R0019 - Adjoining School**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00C - R0020 - Adjoining School**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00C - R0021 - Adjoining School**

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|---------|----------------------|--------|--------------------|--------------------|-------------|--------------------|
| | Sample No | | | | | Test Result |

No Asbestos

B00C - R0022 - Adjoining School

No Asbestos

B00C - R0023 - Adjoining School

No Asbestos

B00C - R0024 - Adjoining School

No Asbestos

B00C - R0025 - Adjoining School

No Asbestos

B00C - R0026 - External Movement

No Asbestos

B00C - R0027 - External Movement

No Asbestos

B00C - R0029 - External Movement

No Asbestos

B00C - R0030 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0031 - Seminar/Study

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0032 - Reading Area

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|---------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| | Sample No | | | | | Test Result |

B00D - General Learning/Support Unit - 1995 - Brick/Block (Brick/Block)**Exterior**

| | |
|------------------|---------------------|
| Ceiling Voids | No Asbestos Found |
| Underfloor Voids | Requires Inspection |

Interior**B00D - R0001 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0002 - Practical Activities - S - 1hb

No Asbestos

B00D - R0003 - Home Base Store - SVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00D - R0004 - Staff Room Annexe**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00D - R0005 - Home Base - S**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00D - R0006 - Practical Activities - S - 1hb**

No Asbestos

B00D - R0007 - Practical ActivitiesVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00D - R0008 - Home Base Store - S**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00D - R0009 - Withdrawal - S**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00D - R0010 - Home Base**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00D - R0012 - Practical Activities - 2hb**

No Asbestos

B00D - R0013 - Home Base StoreVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00D - R0014 - Home Base Store**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00D - R0015 - Withdrawal Space - 1hb**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00D - R0016 - Home Base**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00D - R0017 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0018 - Staff Toilet

No Asbestos

B00D - R0019 - Withdrawal Space - 1hbVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00D - R0021 - External Movement**

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|---------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| | Sample No | | | | | Test Result |

No Asbestos

B00D - R0022 - External Movement

No Asbestos

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00E - Support Unit/General Learning - 1995 - Brick/Block (Brick/Block)**Exterior**

| | |
|------------------|---------------------|
| Ceiling Voids | No Asbestos Found |
| Underfloor Voids | Requires Inspection |

Interior**B00E - R0001 - Withdrawal - S**

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00E - R0002 - Home Base Store - S

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00E - R0003 - Home Base - S

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00E - R0004 - Practical Activities - S - 1hb

No Asbestos

B00E - R0005 - Shower/Change

No Asbestos

B00E - R0006 - Toilet - S

No Asbestos

B00E - R0007 - Laundry - S

No Asbestos

B00E - R0008 - Practical Activities - S - 1hb

No Asbestos

B00E - R0009 - Toilet - S

No Asbestos

B00E - R0010 - Shower/Change

No Asbestos

B00E - R0011 - Home Base - S

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00E - R0012 - Practical Activities - S - 1hb

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00E - R0013 - Withdrawal - S

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00E - R0014 - Home Base Store - S

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00E - R0015 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00E - R0016 - External Movement

No Asbestos

B00E - R0017 - Withdrawal Space - 1hb

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00E - R0018 - Home Base Store

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00E - R0019 - Home Base

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00E - R0020 - Practical Activities - 1hb

No Asbestos Found

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

No Asbestos

B00E - R0021 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0022 - Practical Activities - 1hb

No Asbestos

B00E - R0023 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0024 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0025 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00E - R0026 - Canteen Office/Store

No Asbestos

B00E - R0027 - Communications Cupboard

No Asbestos

B00E - R0028 - Canteen

No Asbestos

B00E - R0029 - External Movement

No Asbestos

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00H - General Learning - 1995 - Brick/Block (Brick/Block)

Exterior

| | |
|------------------|---------------------|
| Ceiling Voids | No Asbestos Found |
| Underfloor Voids | Requires Inspection |

Interior

B00H - R0009 - Home Base Store

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00H - R0010 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00H - R0011 - Adjoining School

No Asbestos

B00H - R0012 - Adjoining School

No Asbestos

B00H - R0013 - Adjoining School

No Asbestos

B00H - R0014 - Adjoining School

No Asbestos

B00H - R0015 - Adjoining School

No Asbestos

B00H - R0016 - Adjoining School

No Asbestos

B00H - R0017 - Adjoining School

No Asbestos

B00H - R0018 - Adjoining School

No Asbestos

B00H - R0019 - Adjoining School

No Asbestos

B00H - R0020 - Adjoining School

No Asbestos

B00H - R0021 - Adjoining School

No Asbestos

B00H - R0022 - Adjoining School

No Asbestos

B00H - R0023 - Adjoining School

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00H - R0024 - Adjoining School

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00H - R0025 - Adjoining School

No Asbestos

B00H - R0026 - Adjoining School

No Asbestos

B00H - R0028 - Adjoining School

No Asbestos

B00H - R0029 - Cleaning Supplies

No Asbestos

B00H - R0030 - Garden Store

No Asbestos

B00H - R0034 - Sports Store

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|---------|--|--------|--------------------|--------------------|-------------|--------------------|
| | Sample No | | | | | Test Result |
| | No Asbestos | | | | | |
| | B00H - R0035 - External Movement | | | | | |
| | No Asbestos | | | | | |
| | B00H - R0036 - External Movement | | | | | |
| | No Asbestos | | | | | |
| | B00H - R0037 - Adjoining School | | | | | |
| | No Asbestos | | | | | |
| | B00H - R0038 - Staff Kitchen | | | | | |
| | No Asbestos | | | | | |
| | B00H - R0039 - Adjoining School | | | | | |
| | No Asbestos | | | | | |
| | B00H - R0040 - Adjoining School | | | | | |
| | No Asbestos | | | | | |
| | B00H - R0041 - Adjoining School | | | | | |
| | No Asbestos | | | | | |
| | B00H - R0042 - Entry Vestibule | | | | | |
| | No Asbestos | | | | | |
| | B00H - R0043 - Clerical Office | | | | | |
| | No Asbestos | | | | | |
| | B00H - R0044 - Clerical Office/Workroom | | | | | |
| | No Asbestos | | | | | |

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00J - Communal Facilities - 1995 - Brick/Veneer (Brick/Veneer)

Exterior

| | |
|------------------|---------------------|
| Ceiling Voids | No Asbestos Found |
| Underfloor Voids | Requires Inspection |

Interior

B00J - R0001 - Disabled Toilet

No Asbestos

B00J - R0002 - Cleaning Distributed Store

No Asbestos

B00J - R0003 - Hall Chair Store

No Asbestos

B00J - R0004 - No Access

No Asbestos

B00J - R0005 - Sports Store

No Asbestos

B00J - R0006 - Toilets - Boys

No Asbestos

B00J - R0007 - Shower/Change

No Asbestos

B00J - R0008 - Toilets - Girls

No Asbestos

B00J - R0009 - Communal Space

No Asbestos

B00J - R0010 - Raised Platform

No Asbestos

B00J - R0011 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00J - R0012 - External Movement

No Asbestos

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00N - Special Purpose - 1993 - Brick/Veneer (Brick/Veneer)

Exterior

| | |
|------------------|---------------------|
| Ceiling Voids | No Asbestos Found |
| Underfloor Voids | Requires Inspection |

Interior

B00N - R0001 - Special Programs Room

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00N - R0002 - Practical Activities - 1hb

No Asbestos

B00N - R0003 - Movement

No Asbestos

B00N - R0004 - Practical Activities - 1hb

No Asbestos

B00N - R0005 - Shower/Change

No Asbestos

B00N - R0006 - Toilets - Boys/Girls

No Asbestos

B00N - R0007 - Special Programs Room

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00N - R0008 - Special Programs Room

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00N - R0009 - Craft Store

No Asbestos

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B000 - Other-Community Use - 2010 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

| | |
|------------------|---------------------|
| Ceiling Voids | No Asbestos Found |
| Underfloor Voids | Requires Inspection |

Interior

B000 - R0001 - Other-Community Use

No Asbestos

B000 - R0002 - Other-Community Use

No Asbestos

B000 - R0003 - Other-Community Use

No Asbestos

B000 - R0004 - Other-Community Use

No Asbestos

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00P - Other-After School Care - 1999 - Steel (Steel)

Exterior

| | |
|------------------|---------------------|
| Ceiling Voids | No Asbestos Found |
| Underfloor Voids | Requires Inspection |

Interior

B00P - R0001 - Other-After School Care

No Asbestos

B00P - R0002 - No Access

No Asbestos

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00Q - Building Services - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

| | |
|------------------|---------------------|
| Ceiling Voids | No Asbestos Found |
| Underfloor Voids | Requires Inspection |

Interior

B00Q - R0001 - General Storeroom

No Asbestos

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00S - Storage - 1998 - Metal Shed (Metal Shed)

Exterior

| | |
|------------------|---------------------|
| Ceiling Voids | No Asbestos Found |
| Underfloor Voids | Requires Inspection |

Interior

B00S - R0001 - General Storeroom

No Asbestos

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B0FF - General Learning/Pupil Facilities - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

| | |
|------------------|---------------------|
| Ceiling Voids | No Asbestos Found |
| Underfloor Voids | Requires Inspection |

Interior

| | |
|--|--|
| B0FF - R0001 - External Movement | No Asbestos |
| B0FF - R0002 - Home Base Store | No Asbestos |
| B0FF - R0003 - Home Base | No Asbestos |
| B0FF - R0004 - Practical Activities - 1hb | No Asbestos |
| B0FF - R0005 - Withdrawal Space - 2hb | No Asbestos |
| B0FF - R0006 - Home Base | No Asbestos |
| B0FF - R0007 - Practical Activities - 1hb | No Asbestos |
| B0FF - R0008 - Home Base Store | No Asbestos |
| B0FF - R0009 - Distribution Board | Note: No inspection of live electrical installation. |
| B0FF - R0010 - External Movement | No Asbestos |
| B0FF - R0011 - Home Base Store | No Asbestos |
| B0FF - R0012 - Home Base | No Asbestos |
| B0FF - R0013 - Practical Activities - 1hb | No Asbestos |
| B0FF - R0014 - Withdrawal Space - 2hb | No Asbestos |
| B0FF - R0015 - Home Base | No Asbestos |
| B0FF - R0016 - Practical Activities - 1hb | No Asbestos |
| B0FF - R0017 - Home Base Store | No Asbestos |
| B0FF - R0018 - General Storeroom | No Asbestos |
| B0FF - R0019 - Home Base Store | No Asbestos |
| B0FF - R0020 - Home Base | No Asbestos |
| B0FF - R0021 - Practical Activities - 1hb | No Asbestos |
| B0FF - R0022 - Withdrawal Space - 2hb | No Asbestos |
| B0FF - R0023 - Home Base | No Asbestos |

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|---------|----------------------|--------|--------------------|--------------------|-------------|--------------------|
| | Sample No | | | | | Test Result |

No Asbestos

B0FF - R0024 - Practical Activities - 1hb

No Asbestos

B0FF - R0025 - Home Base Store

No Asbestos

B0FF - R0026 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B0FF - R0027 - External Movement

No Asbestos

B0FF - R0028 - General Storeroom

No Asbestos

B0FF - R0029 - Toilets - Girls

No Asbestos

B0FF - R0030 - Toilets - Boys/Girls

No Asbestos

B0FF - R0031 - Toilets - Boys

No Asbestos

B0FF - R0032 - External Movement

No Asbestos

B0FF - R0033 - External Movement

No Asbestos

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D12202 - Learning Unit - Standard With P.A.A. : Placement Date - 16/08/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D12360 - Learning Unit - Standard With P.A.A. : Placement Date - 8/04/2014

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D12517 - Learning Unit - Standard With P.A.A. : Placement Date - 16/08/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 621 - D12862 - Single Learning Unit - H/Cap : Placement Date - 28/07/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Home Base-I.O.

No Asbestos Found.

R2 - Toilets-Disabled

No Asbestos Found.

R3 - Laundry

No Asbestos Found.

OS 601 - D13600 - Learning Unit - Standard/Withdrawal : Placement Date - 16/01/2014

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|--|----------------------|------------------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |
| Interior | | | | | | |
| R1 - Entry | | | | | | |
| No Asbestos Found. | | | | | | |
| R2 - General Learning Space | | | | | | |
| No Asbestos Found. | | | | | | |
| R3 - Store | | | | | | |
| No Asbestos Found. | | | | | | |
| OS 534 - D14381 - Library/Group Study/Office/A V Store : Placement Date - 19/07/2005 | | | | | | |
| Exterior | | | | | | |
| Step Treads | Compressed AC Sheet | Assumed Asbestos | | | | 1.08 m2 |
| Landing | Compressed AC Sheet | Assumed Asbestos | | | | 1.2 m2 |
| Eave Lining | Flat AC Sheet | Assumed Asbestos | | | | 23.04 m2 |
| Interior | | | | | | |
| R1 - Clerical Office | | | | | | |
| End wall panel | Flat AC Sheet | Assumed Asbestos | | | | 18 m2 |
| Ceiling | Flat AC Sheet | Assumed Asbestos | | | | 8 m2 |
| R2 - Staff Room | | | | | | |
| Ceiling | Flat AC Sheet | Assumed Asbestos | | | | 36 m2 |
| R3 - Security Store | | | | | | |
| Ceiling | Flat AC Sheet | Assumed Asbestos | | | | 8 m2 |
| R4 - Principal | | | | | | |
| Ceiling | Flat AC Sheet | Assumed Asbestos | | | | 16 m2 |
| R5 - Staff Toilet | | | | | | |
| Toilet partitions | Compressed AC Sheet | Assumed Asbestos | | | | 4 m2 |
| Ceiling | Flat AC Sheet | Assumed Asbestos | | | | 5 m2 |
| R6 - Staff Toilet | | | | | | |
| Toilet partitions | Compressed AC Sheet | Assumed Asbestos | | | | 4 m2 |
| Ceiling | Flat AC Sheet | Assumed Asbestos | | | | 5 m2 |
| R7 - Reading Area | | | | | | |
| Ceiling | Flat AC Sheet | Assumed Asbestos | | | | 54 m2 |
| R8 - Entry | | | | | | |
| Ceiling | Flat AC Sheet | Assumed Asbestos | | | | 14 m2 |
| OS 801 - D14920 - FSU : Placement Date - 10/08/2016 | | | | | | |
| Note: This refurbished demountable may have asbestos present in remnant mastic in window frames. | | | | | | |
| Exterior | | | | | | |
| No Asbestos Found. | | | | | | |
| Interior | | | | | | |
| R1 - Canteen | | | | | | |
| No Asbestos Found. | | | | | | |
| R2 - Covered Area | | | | | | |
| No Asbestos Found. | | | | | | |
| OS 601 - D15142 - Learning Unit - Standard/Withdrawal : Placement Date - 17/08/2000 | | | | | | |
| Exterior | | | | | | |
| Step Treads | Compressed AC Sheet | Assumed Asbestos | | | | 1.08 m2 |
| Landing | Compressed AC Sheet | Assumed Asbestos | | | | 1.2 m2 |
| Eave Lining | Flat AC Sheet | Assumed Asbestos | | | | 11.52 m2 |

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

Interior

R1 - Entry

| | | | | | | |
|----------------|---------------|------------------|--|--|--|-------|
| End wall panel | Flat AC Sheet | Assumed Asbestos | | | | 18 m2 |
| Ceiling | Flat AC Sheet | Assumed Asbestos | | | | 8 m2 |

R2 - General Learning Space

| | | | | | | |
|----------------|---------------|------------------|--|--|--|-------|
| End wall panel | Flat AC Sheet | Assumed Asbestos | | | | 18 m2 |
| Ceiling | Flat AC Sheet | Assumed Asbestos | | | | 55 m2 |

R3 - Store

| | | | | | | |
|---------|---------------|------------------|--|--|--|-------|
| Ceiling | Flat AC Sheet | Assumed Asbestos | | | | 10 m2 |
|---------|---------------|------------------|--|--|--|-------|

OS 621 - D17090 - Single Learning Unit - H/Cap : Placement Date - 28/07/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Home Base-I.O.

No Asbestos Found.

R2 - Toilets-Disabled

No Asbestos Found.

R3 - Laundry

No Asbestos Found.

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017