


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Beaumont Hills Public School (4630)
Region : Western Sydney
State Electorate : Castle Hill
Local Government Area : The Hills

Initial Survey : Noel Arnold & Associates : 23 - May - 2008
Reviewed By : Parsons Brinckerhoff : 24 - May - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/Staff Facilities - 2000 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00A - R0001 - Movement

No Asbestos

B00A - R0002 - Entry Vestibule

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0003 - Clerical Office

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0004 - Sick Bay

No Asbestos

B00A - R0005 - Access Shower/Toilet

No Asbestos

B00A - R0006 - Interview

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0007 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0008 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0009 - Movement

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0010 - Staff Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0011 - Staff Room Annexe

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0012 - Cleaning Distributed Store

No Asbestos

B00A - R0013 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0014 - Staff Toilet

No Asbestos

B00A - R0015 - Staff Toilet

No Asbestos

B00A - R0016 - Staff Toilet

No Asbestos

B00A - R0017 - Security Store

No Asbestos

B00A - R0018 - Principal

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0019 - Duplicating Workroom

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Communal Facilities/Pupil Facilities - 2000 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00B - R0001 - Raised Platform

No Asbestos

B00B - R0002 - Movement

No Asbestos

B00B - R0003 - General Assistant/Bulk Store

No Asbestos

B00B - R0004 - General Assistant/Bulk Store

No Asbestos

B00B - R0005 - Cleaning Supplies

No Asbestos

B00B - R0006 - Garden Store

No Asbestos

B00B - R0007 - Toilets - Girls

No Asbestos

B00B - R0010 - Covered Outdoor Learning Area

No Asbestos

B00B - R0011 - Communal Space

No Asbestos

B00B - R0012 - Access Shower/Toilet

No Asbestos

B00B - R0013 - Toilets - Boys

No Asbestos

B00B - R0014 - Communications Room

No Asbestos

B00B - R0015 - Cleaning Distributed Store

No Asbestos

B00B - R0016 - Main Switch Board

No Asbestos

B00B - R0017 - Hall Chair Store

No Asbestos

B00B - R0018 - P.E. Store

No Asbestos

B00B - R0019 - Sports Store

No Asbestos

B00B - R0020 - Movement

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Pupil Facilities - 2000 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00C - R0001 - Canteen Office/Store

No Asbestos

B00C - R0002 - Canteen

No Asbestos

B00C - R0003 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning - 2000 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00D - R0001 - Home Base Store

No Asbestos

B00D - R0002 - Practical Activities - 1hb

No Asbestos

B00D - R0003 - Movement

No Asbestos

B00D - R0004 - Practical Activities - 1hb

No Asbestos

B00D - R0005 - Home Base Store

No Asbestos

B00D - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0007 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0008 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0009 - Practical Activities - 1hb

No Asbestos

B00D - R0010 - Home Base Store

No Asbestos

B00D - R0011 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0012 - Home Base Store

No Asbestos

B00D - R0013 - Practical Activities - 1hb

No Asbestos

B00D - R0014 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0015 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0016 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0017 - Practical Activities - 1hb

No Asbestos

B00D - R0018 - Home Base Store

No Asbestos

B00D - R0019 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0020 - Home Base Store

No Asbestos

B00D - R0021 - Practical Activities - 1hb

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00D - R0022 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0023 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0024 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Library/General Learning - 2000 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00E - R0001 - Movement

No Asbestos

B00E - R0002 - Toilets - Boys

No Asbestos

B00E - R0003 - Disabled Toilet

No Asbestos

B00E - R0004 - Toilets - Girls

No Asbestos

B00E - R0005 - Staff Toilet

No Asbestos

B00E - R0006 - Cleaning Distributed Store

No Asbestos

B00E - R0007 - General Assistant/Bulk Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0008 - Special Programs Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0009 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00E - R0010 - Communications Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0011 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0012 - Reading Area

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0013 - Home Base Store

No Asbestos

B00E - R0014 - Practical Activities - 1hb

No Asbestos

B00E - R0015 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0016 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0017 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0018 - Practical Activities - 1hb

No Asbestos

B00E - R0019 - Home Base Store

No Asbestos

B00E - R0020 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning/Pupil Facilities - 2000 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00F - R0001 - Movement

No Asbestos

B00F - R0002 - Toilets - Boys

No Asbestos

B00F - R0003 - Kiln Room

No Asbestos

B00F - R0004 - Toilets - Girls

No Asbestos

B00F - R0005 - Home Base Store

No Asbestos

B00F - R0006 - Practical Activities - 1hb

No Asbestos

B00F - R0007 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0008 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0009 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0010 - Practical Activities - 1hb

No Asbestos

B00F - R0011 - Home Base Store

No Asbestos

B00F - R0012 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00F - R0013 - Home Base Store

No Asbestos

B00F - R0014 - Practical Activities - 1hb

No Asbestos

B00F - R0015 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0016 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0017 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0018 - Practical Activities - 1hb

No Asbestos

B00F - R0019 - Home Base Store

No Asbestos

B00F - R0020 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00F - R0021 - Home Base Store

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00F - R0022 - Practical Activities - 1hb

No Asbestos

B00F - R0023 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0024 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0025 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0026 - Practical Activities - 1hb

No Asbestos

B00F - R0027 - Home Base Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00G - R0001 - Home Base

No Asbestos

B00G - R0002 - Home Base Store

No Asbestos

B00G - R0003 - Practical Activities/Movement - 1hb

No Asbestos

B00G - R0004 - Withdrawal Space - 2hb

No Asbestos

B00G - R0005 - Home Base

No Asbestos

B00G - R0006 - Home Base Store

No Asbestos

B00G - R0007 - Practical Activities/Movement - 1hb

No Asbestos

B00G - R0008 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00H - R0001 - Home Base

No Asbestos

B00H - R0002 - Home Base Store

No Asbestos

B00H - R0003 - Practical Activities/Movement - 1hb

No Asbestos

B00H - R0004 - Withdrawal Space - 2hb

No Asbestos

B00H - R0005 - Home Base

No Asbestos

B00H - R0006 - Practical Activities/Movement - 1hb

No Asbestos

B00H - R0007 - Home Base Store

No Asbestos

B00H - R0008 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00I - R0001 - Home Base

No Asbestos

B00I - R0002 - Home Base Store

No Asbestos

B00I - R0003 - Practical Activities/Movement - 1hb

No Asbestos

B00I - R0004 - Withdrawal Space - 2hb

No Asbestos

B00I - R0005 - Home Base

No Asbestos

B00I - R0006 - Practical Activities/Movement - 1hb

No Asbestos

B00I - R0007 - Home Base Store

No Asbestos

B00I - R0008 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 603 - D10184 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 31/01/2002

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 603 - D10490 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 16/11/2006

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 603 - D11128 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 31/01/2002

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D11389 - Learning Unit - Standard With P.A.A. : Placement Date - 22/12/2008

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 750 - D11420 - Learning Unit - ESL : Placement Date - 9/01/2009

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Esl

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017