

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Bogangar Public School (4632)


Region : North Coast

State Electorate : Tweed

Local Government Area : Tweed

Initial Survey : Noel Arnold & Associates : 27 - May - 2008

Register Issue Date : 23 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration - 2003 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00A - R0001 - Entry Vestibule

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0002 - Clerical Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0003 - Sick Bay

No Asbestos

B00A - R0004 - Toilets - Boys/Girls

No Asbestos

B00A - R0005 - Security Store

No Asbestos

B00A - R0006 - Staff Toilet

No Asbestos

B00A - R0007 - Staff Toilet

No Asbestos

B00A - R0008 - Staff Toilet

No Asbestos

B00A - R0009 - Staff Room Annexe

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0011 - General Assistant/Bulk Store

No Asbestos

B00A - R0012 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0013 - Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0014 - Interview

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0015 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0016 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0017 - Practical Activities - 1hb

No Asbestos

B00A - R0018 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0019 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0020 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0021 - Practical Activities - 1hb

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00A - R0022 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0023 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0024 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0025 - Movement

No Asbestos

B00A - R0026 - Staff Kitchen

No Asbestos

B00A - R0027 - Staff Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Communal Facilities - 2003 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00B - R0001 - Main Switch Board

No Asbestos

B00B - R0002 - Sports Store

No Asbestos

B00B - R0003 - Hall Chair Store

No Asbestos

B00B - R0004 - Garden Store

No Asbestos

B00B - R0005 - Movement

No Asbestos

B00B - R0006 - Toilets - Boys

No Asbestos

B00B - R0007 - Toilets - Boys/Girls

No Asbestos

B00B - R0008 - Cleaning Distributed Store

No Asbestos

B00B - R0009 - Communal Space

No Asbestos

B00B - R0010 - Movement

No Asbestos

B00B - R0011 - Toilets - Girls

No Asbestos

B00B - R0012 - Plant

No Asbestos

B00B - R0013 - Cleaning Distributed Store

No Asbestos

B00B - R0014 - P.E. Store

No Asbestos

B00B - R0015 - Communal/Performance Store

No Asbestos

B00B - R0016 - General Assistant/Bulk Store

No Asbestos

B00B - R0017 - Canteen

No Asbestos

B00B - R0018 - Canteen Office/Store

No Asbestos

B00B - R0019 - Movement

No Asbestos

B00B - R0020 - Raised Platform

No Asbestos

B00B - R0021 - Movement

No Asbestos

B00B - R0022 - Movement

No Asbestos

B00B - R0023 - Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00B - R0026 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Library - 2003 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00C - R0001 - Toilets - Girls

No Asbestos

B00C - R0002 - Toilets - Boys

No Asbestos

B00C - R0003 - Kiln Room

No Asbestos

B00C - R0004 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0005 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0006 - Practical Activities - 1hb

No Asbestos

B00C - R0007 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0008 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0009 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0010 - Practical Activities - 1hb

No Asbestos

B00C - R0011 - Reading Area

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0012 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0013 - Communications Cupboard

No Asbestos

B00C - R0014 - K.L.A. Store

No Asbestos

B00C - R0015 - Staff Toilet

No Asbestos

B00C - R0016 - Movement

No Asbestos

B00C - R0017 - Cleaning Distributed Store

No Asbestos

B00C - R0018 - Distribution Board

No Asbestos

Note: No inspection of live electrical installation.

B00C - R0019 - Distribution Board

No Asbestos

Note: No inspection of live electrical installation.

B00C - R0020 - Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning - 2003 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00D - R0001 - Cleaning Distributed Store

No Asbestos

B00D - R0002 - Special Programs Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0003 - Special Programs Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0005 - Practical Activities - 1hb

No Asbestos

B00D - R0006 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0007 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0008 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0009 - Practical Activities - 1hb

No Asbestos

B00D - R0010 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0011 - Toilets - Boys

No Asbestos

B00D - R0012 - Toilets - Girls

No Asbestos

B00D - R0013 - Toilets - Boys/Girls

No Asbestos

B00D - R0016 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0017 - Practical Activities - 1hb

No Asbestos

B00D - R0018 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0019 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0020 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0021 - Practical Activities - 1hb

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00D - R0022 - Home Base Store						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00D - R0023 - Distribution Board						
No Asbestos			Note: No inspection of live electrical installation.			
B00D - R0024 - Movement						
No Asbestos						
B00D - R0025 - General Storeroom						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning - 2006 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00E - R0001 - External Movement

No Asbestos

B00E - R0002 - Practical Activities - 1hb

No Asbestos

B00E - R0003 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0005 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0007 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0008 - Practical Activities - 1hb

No Asbestos

B00E - R0009 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning/Other - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00F - R0001 - Special Programs Room

No Asbestos

B00F - R0002 - Special Programs Store

No Asbestos

B00F - R0003 - Cleaning Distributed Store

No Asbestos

B00F - R0004 - Practical Activities - 1hb

No Asbestos

B00F - R0005 - Home Base Store

No Asbestos

B00F - R0006 - Home Base

No Asbestos

B00F - R0007 - Withdrawal Space - 2hb

No Asbestos

B00F - R0008 - Home Base

No Asbestos

B00F - R0009 - Home Base Store

No Asbestos

B00F - R0010 - Practical Activities - 1hb

No Asbestos

B00F - R0011 - Garden Store

No Asbestos

B00F - R0012 - General Assistant/Bulk Store

No Asbestos

B00F - R0013 - Sports Store

No Asbestos

B00F - R0014 - External Movement

No Asbestos

B00F - R0015 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017