



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B001 - General Learning - 1959 - Timber (Timber)****Exterior**

Eaves Linings	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	5265/B001/Eaves Linings/S4			<b>Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)</b>		
Sunhood (Louvers)	Flat AC Sheeting	1m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	<b>Assumed Asbestos - Height Restriction</b>					
Ceiling Voids	Non Accessible Area - Height Restriction					
Underfloor Voids	Non Accessible Area - Area inaccessible					

**Interior****B001 - R0001 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	78m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	5265/B001/R0001/Ceiling Structures/Linings/S1			<b>Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)</b>		
Floor Coverings Res/Textile	Vinyl Sheet					<b>No Asbestos Detected</b>
	5265/B001/R0001/Floor Coverings Res/Textile/S2					

**B001 - R0006 - External Movement**

Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	5265/B001/R0001/Ceiling Structures/Linings/S1			<b>Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)</b>		

**B001 - R0007 - General Storeroom**

No Asbestos

**B001 - R0008 - Interview**

No Asbestos

**B001 - R0009 - Home Base**

No Asbestos

**B001 - R0010 - Home Base**

No Asbestos

**B001 - R0011 - Home Base**

No Asbestos

**B001 - R0012 - Home Base**

No Asbestos

**B001 - R0013 - Withdrawal Space - 1hb**

No Asbestos

**B001 - R0014 - Staff Room Annexe**

No Asbestos

**B001 - R0015 - External Movement**

No Asbestos

**B001 - R0016 - Deputy Principal**

No Asbestos

**B001 - R0017 - General Storeroom**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B004 - Pupil Facilities - 1966 - Timber (Timber)**

**Exterior**

Ceiling Voids	Non Accessible Area - Height Restriction
Underfloor Voids	Non Accessible Area - Area inaccessible

**Interior**

**B004 - R0001 - Drinking Facilities**

No Asbestos

**B004 - R0002 - Drinking Facilities**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B005 - Railway Carriage - 1966 - Steel (Steel)**

**Exterior**

Ceiling Voids	Non Accessible Area - Height Restriction
Underfloor Voids	Non Accessible Area - Area inaccessible

**Interior**

**B005 - R0001 - Railway Carriage**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B007 - General Learning - 1966 - Brick/Veneer (Brick/Veneer)****Exterior**

Eaves Linings	Flat AC Sheeting	26m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	5265/B001/R0001/Ceiling Structures/Linings/S1				<b>Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)</b>	
Ceiling Voids	Non Accessible Area - Height Restriction					
Underfloor Voids	Non Accessible Area - Area inaccessible					

**Interior****B007 - R0001 - Home Base Store**

No Asbestos

**B007 - R0002 - No Access**

No Asbestos

**B007 - R0003 - Home Base**

No Asbestos

**B007 - R0004 - Home Base**

No Asbestos

**B007 - R0005 - Movement**

No Asbestos

**B007 - R0006 - Personal Effects Storage**

No Asbestos

**B007 - R0007 - Home Base Store**

No Asbestos

**B007 - R0010 - General Storeroom**

No Asbestos

**B007 - R0011 - Home Base**

No Asbestos

**B007 - R0012 - Home Base Store**

No Asbestos

**B007 - R0013 - Personal Effects Storage**

No Asbestos

**B007 - R0014 - Home Base Store**

No Asbestos

**B007 - R0015 - Home Base**

No Asbestos

**B007 - R0016 - Movement**

No Asbestos

**B007 - R0017 - Movement**

No Asbestos

**B007 - R0018 - Special Education Support Centre**

No Asbestos

**B007 - R0019 - Deputy Principal**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B008 - Library/Administration - 1966 - Brick/Veneer (Brick/Veneer)****Exterior**

Eaves Linings	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	5265/B001/R0001/Ceiling Structures/Linings/S1					<b>Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)</b>
Ceiling Voids	Non Accessible Area - Height Restriction					
Underfloor Voids	Non Accessible Area - Area inaccessible					

**Interior****B008 - R0004 - Home Base Store**

No Asbestos

**B008 - R0005 - General Storeroom**

No Asbestos

**B008 - R0006 - Movement**

No Asbestos

**B008 - R0007 - Home Base**

No Asbestos

**B008 - R0008 - Home Base Store**

No Asbestos

**B008 - R0009 - General Storeroom**

No Asbestos

**B008 - R0010 - Movement**

No Asbestos

**B008 - R0011 - Home Base**

No Asbestos

**B008 - R0012 - Home Base**

No Asbestos

**B008 - R0013 - Home Base Store**

No Asbestos

**B008 - R0014 - General Storeroom**

No Asbestos

**B008 - R0015 - Home Base Store**

No Asbestos

**B008 - R0016 - Home Base**

No Asbestos

**B008 - R0025 - Movement**

No Asbestos

**B008 - R0026 - Home Base**

No Asbestos

**B008 - R0027 - Withdrawal Space - 1hb**

No Asbestos

**B008 - R0028 - Home Base Store**

No Asbestos

**B008 - R0029 - Practical Activities - 1hb**

No Asbestos

**B008 - R0030 - Home Base**

No Asbestos

**B008 - R0031 - Home Base Store**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B008 - R0032 - Withdrawal Space - 1hb</b>						
No Asbestos						
<b>B008 - R0033 - External Movement</b>						
No Asbestos						
<b>B008 - R0034 - Home Base</b>						
No Asbestos						
<b>B008 - R0035 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B008 - R0036 - Home Base Store</b>						
No Asbestos						
<b>B008 - R0037 - Deputy Principal - Type 1</b>						
No Asbestos						
<b>B008 - R9001 - General Storeroom</b>						
Packing to supports	Flat AC Sheeting	20Unit(s)	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
5265/B008/R9001/Packing to supports/S3				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B009 - Pupil Facilities - 2000 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior****B009 - R0001 - Toilets - Boys**

No Asbestos

**B009 - R0002 - Toilets - Girls**

No Asbestos

**B009 - R0003 - Staff Toilet**

No Asbestos

**B009 - R0004 - Staff Toilet**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B010 - General Learning - 2004 - Fibre Cement Clad (Fibre Cement Clad)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior****B010 - R0001 - External Movement**

No Asbestos

**B010 - R0002 - Practical Activities - 1hb**

No Asbestos

**B010 - R0003 - Home Base Store**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B010 - R0004 - Home Base**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B010 - R0005 - Withdrawal Space - 2hb**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B010 - R0006 - Home Base**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B010 - R0007 - Home Base Store**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B010 - R0008 - Practical Activities - 1hb**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B011 - Administration - 2010 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior****B011 - R0001 - External Movement**

No Asbestos

**B011 - R0002 - Entry Vestibule**

No Asbestos

**B011 - R0003 - Clerical Office**

No Asbestos

**B011 - R0004 - Clerical Office**

No Asbestos

**B011 - R0005 - General Storeroom**

No Asbestos

**B011 - R0006 - Sick Bay**

No Asbestos

**B011 - R0007 - Access Shower/Toilet/Change**

No Asbestos

**B011 - R0008 - Clerical/Printing**

No Asbestos

**B011 - R0009 - General Storeroom**

No Asbestos

**B011 - R0010 - Cleaning Distributed Store**

No Asbestos

**B011 - R0011 - Movement**

No Asbestos

**B011 - R0012 - Staff Room**

No Asbestos

**B011 - R0013 - Staff Room Annexe**

No Asbestos

**B011 - R0014 - Movement**

No Asbestos

**B011 - R0015 - Staff Toilet**

No Asbestos

**B011 - R0016 - Staff Toilet**

No Asbestos

**B011 - R0017 - Staff Toilet**

No Asbestos

**B011 - R0018 - Movement**

No Asbestos

**B011 - R0019 - Deputy Principal - Type 1**

No Asbestos

**B011 - R0020 - Deputy Principal - Type 1**

No Asbestos

**B011 - R0021 - Principal**

No Asbestos

**B011 - R0022 - Interview**

No Asbestos

**B011 - R0023 - External Movement**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B012 - Library - 2010 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior****B012 - R0001 - Reading Area**

No Asbestos

**B012 - R0002 - Communications Room**

No Asbestos

**B012 - R0003 - Library Office/Workroom**

No Asbestos

**B012 - R0004 - Special Programs Room - Type 2**

No Asbestos

**B012 - R0005 - Special Programs Room - Type 2**

No Asbestos

**B012 - R0006 - K.L.A. Store**

No Asbestos

**B012 - R0007 - K.L.A. Store**

No Asbestos

**B012 - R0008 - Toilet - Lobby**

No Asbestos

**B012 - R0009 - Cleaning Distributed Store**

No Asbestos

**B012 - R0010 - Staff Toilet**

No Asbestos

**B012 - R0011 - External Movement**

No Asbestos

**B012 - R0012 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B013 - Communal Facilities - 2010 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior****B013 - R0001 - Communal Space**

No Asbestos

**B013 - R0002 - Movement**

No Asbestos

**B013 - R0003 - Movement**

No Asbestos

**B013 - R0004 - Ramp**

No Asbestos

**B013 - R0005 - Communal/Performance Store**

No Asbestos

**B013 - R0006 - General Storeroom**

No Asbestos

**B013 - R0007 - Hall Chair Store**

No Asbestos

**B013 - R0008 - Toilet - Lobby**

No Asbestos

**B013 - R0009 - Toilets - Girls**

No Asbestos

**B013 - R0010 - Cleaning Distributed Store**

No Asbestos

**B013 - R0011 - Sound Cupboard**

No Asbestos

**B013 - R0012 - Toilet - Lobby**

No Asbestos

**B013 - R0013 - Toilets - Boys**

No Asbestos

**B013 - R0014 - External Movement**

No Asbestos

**B013 - R0015 - Toilets-Unisex**

No Asbestos

**B013 - R0016 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B013 - R0017 - P.E. Store**

No Asbestos

**B013 - R0018 - Ramp**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B014 - Pupil Facilities - 2011 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior****B014 - R0001 - Toilets - Girls/Disabled Cubicle**

No Asbestos

**B014 - R0002 - Access Shower/Toilet/Change**

No Asbestos

**B014 - R0003 - Toilets - Boys/Disabled Cubicle**

No Asbestos

**B014 - R0004 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B014 - R0005 - Other**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B015 - General Learning - 2011 - Fibre Cement Clad (Fibre Cement Clad)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior****B015 - R0001 - External Movement**

No Asbestos

**B015 - R0002 - Practical Activities - 1hb**

No Asbestos

**B015 - R0003 - Home Base**

No Asbestos

**B015 - R0004 - Home Base Store**

No Asbestos

**B015 - R0005 - Withdrawal Space - 2hb**

No Asbestos

**B015 - R0006 - Home Base**

No Asbestos

**B015 - R0007 - Home Base Store**

No Asbestos

**B015 - R0008 - Practical Activities - 1hb**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B016 - Pupil Facilities - 2011 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior****B016 - R0001 - Canteen Office/Store**

No Asbestos

**B016 - R0002 - Canteen**

No Asbestos

**B016 - R0003 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B017 - Electrical Services - 2011 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B017 - R0001 - Main Switch Board**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B018 - Pupil Facilities/Other - 2005 - Metal Shed (Metal Shed)**

**Exterior**

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

**Interior**

**B018 - R0001 - Sports Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B019 - Building Services/Other - 2010 - Steel (Steel)**

**Exterior**

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

**Interior**

**B019 - R0001 - Garden Store**

No Asbestos

**B019 - R0002 - Garden Store**

No Asbestos

**B019 - R0003 - Garden Store**

No Asbestos

**B019 - R0004 - Garden Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

## Demountables

**Demountable details as per the AMS records as of 15 Feb 2017.**

### OS 602 - D10561 - Learning Unit - Standard With P.A.A. : Placement Date - 12/08/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

#### Exterior

No Asbestos Found.

#### Interior

##### R1 - Learning space/withdrawal/entry

No Asbestos Found.

##### R2 - Home Base Store

No Asbestos Found.

### OS 601 - D10844 - Learning Unit - Standard/Withdrawal : Placement Date - 2/05/2006

#### Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

#### Interior

##### R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

##### R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

##### R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2
---------	---------------	------------------	-------

### OS 601 - D13893 - Learning Unit - Standard/Withdrawal : Placement Date - 17/07/2007

#### Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

#### Interior

##### R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

##### R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

##### R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2
---------	---------------	------------------	-------

### OS 601 - D14010 - Learning Unit - Standard/Withdrawal : Placement Date - 30/06/1995

#### Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>Interior</b>						
<b>R1 - Entry</b>						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
<b>R2 - General Learning Space</b>						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
<b>R3 - Store</b>						
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2
<b>OS 603 - D14557 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 11/11/2008</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
No Asbestos Found.						
<b>R2 - Home Base Store</b>						
No Asbestos Found.						
<b>OS 601 - D15708 - Learning Unit - Standard/Withdrawal : Placement Date - 15/10/1997</b>						
<b>Exterior</b>						
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
<b>Interior</b>						
<b>R1 - Entry</b>						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
<b>R2 - General Learning Space</b>						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
<b>R3 - Store</b>						
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Listing of Electronic Attachments as of 22/03/2017***

**There are no asbestos related file attachment(s) for this school.**

2017