


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Budawang School (5749)
Region : Illawarra and South East
State Electorate : South Coast
Local Government Area : Shoalhaven

Initial Survey : Noel Arnold & Associates : 07 - May - 2008
Reviewed By : Grencap-NAA : 20 - Jun - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/Support Unit - 1985 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
Eaves Linings	Flat AC Sheeting 5749/B00A/Eaves Linings/S2					No Asbestos Detected
In-fill-panel	Flat AC Sheeting 5749/B00A/In-fill-panel/S3	3m2	South side, under windows	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting 5749/B00A/Eaves Linings/S2					No Asbestos Detected
Ceiling void	No Asbestos Found					
Window	Putty 5749/B00A/Window/S4					No Asbestos Detected

Interior**B00A - R0001 - Cleaning Distributed Store**

No Asbestos

B00A - R0002 - Toilets - Girls

No Asbestos

B00A - R0005 - Principal

No Asbestos

B00A - R0006 - Movement

No Asbestos

B00A - R0007 - General Storeroom

No Asbestos

B00A - R0008 - Clerical Office

No Asbestos

B00A - R0009 - Communal Space

No Asbestos

B00A - R0010 - Duplicating Workroom

Floor Coverings Res/Textile	Vinyl Tiles 5749/B00A/R0011/Floor Coverings Res/Textile/S1	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
-----------------------------	---	-----	------------	--------------------	---------	--

B00A - R0011 - Laundry - S

Floor Coverings Res/Textile	Vinyl Tiles 5749/B00A/R0011/Floor Coverings Res/Textile/S1	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
-----------------------------	---	-----	------------	--------------------	---------	--

B00A - R0012 - Movement

No Asbestos

B00A - R0013 - Toilet - S

No Asbestos

B00A - R0014 - Staff Kitchen

Floor Coverings Res/Textile	No Asbestos Found					
-----------------------------	-------------------	--	--	--	--	--

B00A - R0015 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 5749/B00A/Eaves Linings/S2					No Asbestos Detected
----------------------------	--	--	--	--	--	-----------------------------

B00A - R0016 - Toilet - S

No Asbestos

B00A - R0018 - Movement

No Asbestos

B00A - R0019 - Home Base Store - S

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00A - R0022 - Home Base Store - S

No Asbestos

B00A - R0023 - Garden Store

Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
-----------------------------	-------------	-----	------------	--------------------	---------	--------------------

5749/B00A/R0011/Floor Coverings Res/Textile/S1

Chrysotile (white asbestos)**B00A - R0024 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting					
	5749/B00A/Eaves Linings/S2					

No Asbestos Detected

Electrical Backing Board	Resinous Board	1Unit	North	Good Condition (1)	Low (1)	Low Priority (2-3)
--------------------------	----------------	-------	-------	--------------------	---------	--------------------

5749/B00A/R0024/Electrical Backing Board/S5

Chrysotile (white asbestos)**B00A - R0025 - Plant**

Ceiling Structures/Linings	Flat AC Sheeting					
	5749/B00A/Eaves Linings/S2					

No Asbestos Detected**B00A - R0026 - Movement**

No Asbestos

B00A - R0027 - Home Base - S

No Asbestos

B00A - R0028 - Movement

No Asbestos

B00A - R0029 - Movement

No Asbestos

B00A - R0030 - Clerical Office

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning - 2008 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor void	No Asbestos Found
Lower infill - north	No Asbestos Found

Interior

B00C - R0001 - External Movement

Ceiling Structures/Linings	No Asbestos Found
----------------------------	-------------------

B00C - R0002 - Disabled Toilet

Wall Linings Internal	No Asbestos Found
-----------------------	-------------------

B00C - R0003 - Home Base/Practical Activities - M

No Asbestos

B00C - R0004 - Craft Store

No Asbestos

B00C - R0005 - Home Base/Practical Activities - M

No Asbestos

B00C - R0006 - Staff Room

No Asbestos

B00C - R0007 - Staff Toilet

Wall Linings Internal	No Asbestos Found
-----------------------	-------------------

B00C - R0008 - Craft Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Other - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible
Ceiling Voids	No Asbestos Found

Interior

B00D - R0001 - Special Programs Store

No Asbestos

B00D - R0002 - Storage area

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

NS 120 - D10294 - Learning Unit - Single Primary H/Cap PAA : Placement Date - 28/04/2014

Exterior

No Asbestos Found.

Interior

R1 - Home Base-I.O.

No Asbestos Found.

R2 - Toilets-Disabled

No Asbestos Found.

R3 - Home Base Store-I.O.

No Asbestos Found.

R4 - Practical Activity Area

No Asbestos Found.

R5 - Entry

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017