


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Balmain Public School (7404)
Region : Sydney
State Electorate : Balmain
Local Government Area : Leichhardt

Initial Survey : Noel Arnold & Associates : 30 - May - 2008
Reviewed By : AECOM : 29 - Oct - 2014



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning/Administration - 1876 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior**B00A - R0001 - Cleaning Distributed Store**

No Asbestos

B00A - R0002 - Duplicating Workroom

No Asbestos

B00A - R0003 - Movement

No Asbestos

B00A - R0004 - Movement

No Asbestos

B00A - R0005 - Principal

No Asbestos

B00A - R0006 - Movement

No Asbestos

B00A - R0007 - Clerical Office

No Asbestos

B00A - R0013 - Home Base

Wall Linings Internal	Flat AC Sheeting	12m2	South facing, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
7404/B00A/R0019/Wall Linings Internal/S1					Chrysotile (white asbestos)	

B00A - R0014 - Personal Effects Storage

No Asbestos

B00A - R0015 - Sports Store

No Asbestos

B00A - R0016 - Movement

No Asbestos

B00A - R0017 - Movement

No Asbestos

B00A - R0020 - Stairs

No Asbestos

B00A - R0021 - Movement

Wall Linings Internal	Flat AC Sheeting	47m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
7404/B00A/R0019/Wall Linings Internal/S1					Chrysotile (white asbestos)	

B00A - R0022 - Staff Room

No Asbestos

B00A - R0023 - Staff Kitchen

No Asbestos

B00A - R0024 - Special Programs Room

Wall Linings Internal	Flat AC Sheeting	12m2	South facing, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
7404/B00A/R0019/Wall Linings Internal/S1					Chrysotile (white asbestos)	

B00A - R0025 - Reading Area

Wall Linings Internal	Flat AC Sheeting	20m2	South facing, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
7404/B00A/R0019/Wall Linings Internal/S1					Chrysotile (white asbestos)	

B00A - R0026 - Stairs

No Asbestos

B00A - R1001 - Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
	No Asbestos					
	B00A - R1002 - Practical Activities - 1hb					
	No Asbestos					
	B00A - R1003 - Security Store					
	No Asbestos					
	B00A - R1004 - Interview					
	No Asbestos					
	B00A - R1005 - Movement					
	No Asbestos					
	B00A - R1006 - Staff Room Annexe					
	No Asbestos					
	B00A - R1007 - Home Base					
	No Asbestos					
	B00A - R1008 - Home Base					
	No Asbestos					
	B00A - R1009 - Reading Area					
	No Asbestos					
	B00A - R1011 - Personal Effects Storage					
	No Asbestos					
	B00A - R1014 - Movement					
	No Asbestos					
	B00A - R1018 - Stairs					
	No Asbestos					
	B00A - R1019 - Movement					
	No Asbestos					
	B00A - R1020 - Practical Activities/Movement - 2hb					
	No Asbestos					
	B00A - R1021 - Toilet - Lobby					
	No Asbestos					
	B00A - R1022 - Staff Toilet					
	No Asbestos					
	B00A - R1023 - Staff Toilet					
	No Asbestos					
	B00A - R1024 - Staff Toilet					
	No Asbestos					
	B00A - R1025 - Stairs					
	No Asbestos					
	B00A - R1026 - Home Base					
	No Asbestos					
	B00A - R1027 - Practical Activities - 1hb					
	No Asbestos					
	B00A - R2001 - Movement					
	No Asbestos					
	B00A - R2002 - Handwashing Facilities					
	No Asbestos					
	B00A - R2003 - General Storeroom					
	No Asbestos					
	B00A - R2004 - Practical Activities - 1hb					
	No Asbestos					
	B00A - R2005 - Home Base					
	No Asbestos					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R2006 - Home Base						
No Asbestos						
B00A - R2007 - Home Base						
No Asbestos						
B00A - R2008 - Personal Effects Storage						
No Asbestos						
B00A - R2009 - Toilets - Boys/Girls						
No Asbestos						
B00A - R2010 - Toilets - Boys/Girls						
No Asbestos						
B00A - R2011 - Movement						
No Asbestos						
B00A - R2012 - Special Programs Room						
No Asbestos						
B00A - R2015 - Home Base						
No Asbestos						
B00A - R2016 - Stairs						
No Asbestos						
B00A - R2017 - Movement						
No Asbestos						
B00A - R2018 - Stairs						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Communal Facilities/Other-After School Care - 1910 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior**B00B - R0001 - Movement**

No Asbestos

B00B - R0002 - Movement

No Asbestos

B00B - R0003 - Movement

Floor Coverings Res/Textile	Vinyl Tiles					
		7404/B00B/R0003/Floor Coverings Res/Textile/S4				No Asbestos Detected

B00B - R0005 - Home Base

No Asbestos

B00B - R0006 - Movement

Floor Coverings Res/Textile	Vinyl Tiles					
		7404/B00B/R0006/Floor Coverings Res/Textile/S3				No Asbestos Detected

B00B - R0007 - Movement

No Asbestos

B00B - R0008 - Raised Platform

No Asbestos

B00B - R0009 - Communal Space

No Asbestos

B00B - R0010 - Movement

No Asbestos

B00B - R0011 - Stairs

No Asbestos

B00B - R1001 - Movement

No Asbestos

B00B - R1002 - Home Base

Floor Coverings Res/Textile	Vinyl Sheet					
		7404/B00B/R1002/Floor Coverings Res/Textile/S5				No Asbestos Detected

B00B - R1004 - Home Base Store

No Asbestos

B00B - R1005 - Stairs

No Asbestos

B00B - R1006 - Home Base

No Asbestos

B00B - R1007 - Practical Activities

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Pupil Facilities/Other-After School Care - 1926 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Non Accessible Area - Area inaccessible. No designated entry was found.

Interior**B00C - R0001 - Drinking Facilities**

Wall Linings Internal	Flat AC Sheeting 7404/B00C/R0001/Wall Linings Internal/S7	No Asbestos Detected
-----------------------	--	-----------------------------

B00C - R0002 - Canteen

No Asbestos

B00C - R0003 - Movement

No Asbestos

B00C - R0004 - Canteen Office/Store

No Asbestos

B00C - R0005 - Other-Community Use

No Asbestos

B00C - R0006 - Movement

Floor Coverings Res/Textile	Vinyl Tiles 7404/B00C/R0006/Floor Coverings Res/Textile/S6	No Asbestos Detected
-----------------------------	---	-----------------------------

B00C - R0007 - Drinking Facilities

No Asbestos

B00C - R0008 - Stairs

No Asbestos

B00C - R1001 - Raised Platform

No Asbestos

B00C - R1002 - Home Base

Floor Coverings Res/Textile	Vinyl Tiles 7404/B00C/R0006/Floor Coverings Res/Textile/S6	No Asbestos Detected
-----------------------------	---	-----------------------------

B00C - R1003 - Movement

Floor Coverings Res/Textile	Vinyl Tiles 7404/B00C/R0006/Floor Coverings Res/Textile/S6	No Asbestos Detected
-----------------------------	---	-----------------------------

B00C - R1004 - Stairs

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Pupil Facilities - 1940 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior**B00E - R0003 - Garden Store**

No Asbestos

B00E - R0004 - Cleaning Distributed Store

No Asbestos

B00E - R0005 - Toilets - Boys

No Asbestos

B00E - R0006 - Toilet - Lobby

No Asbestos

B00E - R0007 - Toilet - Lobby

No Asbestos

B00E - R0008 - Toilets - Girls

No Asbestos

B00E - R0009 - Staff Toilet

No Asbestos

B00E - R0010 - Garden Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Other - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00G - R0001 - General Assistant/Bulk Store

No Asbestos

B00G - R0002 - Garden Store

No Asbestos

B00G - R0003 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00H - R0001 - Special Programs Room - Type 2

No Asbestos

B00H - R0002 - Special Programs Room - Type 2

No Asbestos

B00H - R0003 - Special Programs Store

No Asbestos

B00H - R0004 - Practical Activities - 1hb

No Asbestos

B00H - R0005 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 600 - D13371 - Learning Unit - Small : Placement Date - 10/06/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - General Learning Space

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017