

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Bondi Public School (7407)
Region : Sydney
State Electorate : Vacluse
Local Government Area : Waverley

Initial Survey : Noel Arnold & Associates : 29 - Mar - 2008
Reviewed By : Parsons Brinckerhoff : 28 - Feb - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning/Administration - 1916 - Brick/Block (Brick/Block)**Exterior**

Gable Verge Lining	Flat AC Sheeting	50m	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - No access due to height restrictions						
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00A - R0001 - Movement**

No Asbestos

B00A - R0002 - Movement

No Asbestos

B00A - R0003 - Movement

Floor Coverings Res/Textile	Vinyl Tiles	11m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
7407/B00A/R0022/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)	

B00A - R0004 - Movement

No Asbestos

B00A - R0005 - No Access

Floor Coverings Res/Textile	Vinyl Tiles	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
7407/B00A/R0022/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)	

B00A - R0006 - Shower/Change

Floor Coverings Res/Textile	Vinyl Tiles	3m2	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
7407/B00A/R0022/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)	

B00A - R0007 - Toilets - Boys/Girls

Floor Coverings Res/Textile	Vinyl Tiles	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
7407/B00A/R0022/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)	

B00A - R0008 - Security Store

Floor Coverings Res/Textile	Vinyl Tiles	11m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
7407/B00A/R0022/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)	

B00A - R0009 - Special Programs Room

No Asbestos

B00A - R0010 - Movement

No Asbestos

B00A - R0011 - Library Office/Workroom

No Asbestos

B00A - R0012 - Reading Area

No Asbestos

B00A - R0013 - Communications Room

No Asbestos

B00A - R0014 - Reading Area

No Asbestos

B00A - R0015 - Duplicating Workroom

No Asbestos

B00A - R0016 - Clerical Office

No Asbestos

B00A - R0017 - Principal

No Asbestos

B00A - R0019 - Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
B00A - R0020 - Movement						
No Asbestos						
B00A - R0021 - Sick Bay						
No Asbestos						
B00A - R0022 - Main Switch Board						
Floor Coverings Res/Textile	Vinyl Tiles	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
7407/B00A/R0022/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)	
B00A - R0023 - Movement						
No Asbestos						
B00A - R0024 - Cleaning Distributed Store						
No Asbestos						
B00A - R0025 - Movement						
No Asbestos						
B00A - R0027 - Interview						
No Asbestos						
B00A - R0028 - Movement						
No Asbestos						
B00A - R0029 - General Storeroom						
No Asbestos						
B00A - R0030 - Canteen Office/Store						
Floor Coverings Res/Textile	Vinyl Tiles	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
7407/B00A/R0022/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)	
B00A - R0031 - Canteen						
Floor Coverings Res/Textile	Vinyl Tiles	21m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
7407/B00A/R0022/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)	
B00A - R0032 - Staff Toilet						
Floor Coverings Res/Textile	Vinyl Tiles	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
7407/B00A/R0022/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)	
B00A - R0033 - No Access						
No Asbestos						
B00A - R0034 - Stairs						
No Asbestos						
B00A - R0035 - Stairs						
No Asbestos						
B00A - R0036 - Staff Toilet						
No Asbestos						
B00A - R0037 - Toilet - Lobby						
No Asbestos						
B00A - R0038 - Entry Vestibule						
No Asbestos						
B00A - R0039 - Clerical Office						
No Asbestos						
B00A - R1001 - Cleaning Distributed Store						
No Asbestos						
B00A - R1003 - Toilets - Boys/Girls						
Floor Coverings Res/Textile	Vinyl Tiles	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
7407/B00A/R0022/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R1005 - Home Base						
No Asbestos						
B00A - R1006 - Home Base						
No Asbestos						
B00A - R1007 - Home Base						
No Asbestos						
B00A - R1008 - Home Base						
No Asbestos						
B00A - R1009 - Home Base						
No Asbestos						
B00A - R1010 - General Storeroom						
Floor Coverings Res/Textile	Vinyl Tiles	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
7407/B00A/R0022/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)	
B00A - R1011 - Special Programs Room						
No Asbestos						
B00A - R1012 - Staff Room Annexe						
No Asbestos						
B00A - R1013 - Home Base						
No Asbestos						
B00A - R1014 - General Storeroom						
Floor Coverings Res/Textile	Vinyl Tiles	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
7407/B00A/R0022/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)	
B00A - R1015 - Stairs						
No Asbestos						
B00A - R1016 - Stairs						
No Asbestos						
B00A - R1017 - Movement						
No Asbestos						
B00A - R1018 - Toilet - Lobby						
No Asbestos						
B00A - R1019 - Toilets - Boys/Girls						
No Asbestos						
B00A - R1020 - Toilets - Boys/Girls						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning/Other-Community Use - 1882 - Sandstone (Sandstone)**Exterior**

Gable Verge Lining	Flat AC Sheeting	40m	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - No access due to height restriction						
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00B - R0001 - Practical Activities - 1hb**

Floor Coverings Res/Textile	Vinyl Tiles	52m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
7407/B00B/R0001/Floor Coverings Res/Textile/S7					Chrysotile (white asbestos)	

B00B - R0002 - Duplicating Workroom

No Asbestos

B00B - R0004 - Movement

Wall Linings Internal	Flat AC Sheeting	1m2	North facing, South facing, East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
7407/B00B/R0007/Wall Linings Internal/S6					Chrysotile (white asbestos)	

Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
7407/B00B/R0007/Wall Linings Internal/S6					Chrysotile (white asbestos)	

B00B - R0005 - Staff Room

No Asbestos

B00B - R0006 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting	2m2	South facing, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
7407/B00B/R0007/Wall Linings Internal/S6					Chrysotile (white asbestos)	

B00B - R0007 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting	2m2	North facing, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
7407/B00B/R0007/Wall Linings Internal/S6					Chrysotile (white asbestos)	

B00B - R0008 - Movement

No Asbestos

B00B - R0009 - Raised Platform

No Asbestos

B00B - R0010 - Communal Space

No Asbestos

B00B - R0011 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	40m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - No access due to height restriction						

B00B - R0012 - Clerical Office/Workroom

No Asbestos

B00B - R0013 - General Storeroom

No Asbestos

B00B - R0014 - Home Base

No Asbestos

B00B - R0015 - Cleaning Distributed Store

No Asbestos

B00B - R0016 - Stairs

No Asbestos

B00B - R0017 - Stairs

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
B00B - R0018 - Toilet - E						
No Asbestos						
B00B - R0019 - No Access						
No Asbestos						
B00B - R1001 - Home Base						
No Asbestos						
B00B - R1002 - Staff Room Annexe						
No Asbestos						
B00B - R1003 - Home Base						
No Asbestos						
B00B - R1004 - Toilets - Boys/Girls						
No Asbestos						
B00B - R1005 - General Storeroom						
Floor Coverings Res/Textile	Vinyl Tiles	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
7407/B00B/R1005/Floor Coverings Res/Textile/S9					Chrysotile (white asbestos)	
B00B - R1006 - Special Programs Room						
No Asbestos						
B00B - R1007 - Home Base						
No Asbestos						
B00B - R1008 - Withdrawal Space - 1hb						
No Asbestos						
B00B - R1009 - Movement						
No Asbestos						
B00B - R1010 - Home Base						
No Asbestos						
B00B - R1011 - Personal Effects Storage						
No Asbestos						
B00B - R1012 - Home Base						
Chalk Board	Compressed AC Sheet	3m2	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
7407/B00B/R1012/Chalk Board/S8					Chrysotile (white asbestos)	
B00B - R1013 - Stairs						
No Asbestos						
B00B - R1014 - Stairs						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Other-Community Use - 1928 - Brick/Block (Brick/Block)

Exterior

Gable Verge Lining	Flat AC Sheeting	40m	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - No access due to height restriction						
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00C - R0001 - Out Of School Hours Care Centre

No Asbestos

B00C - R0004 - General Storeroom

No Asbestos

B00C - R0005 - Cleaning Distributed Store

No Asbestos

B00C - R0007 - Movement

No Asbestos

B00C - R0008 - Movement

No Asbestos

B00C - R0009 - Stairs

No Asbestos

B00C - R0011 - Other-After School Care

No Asbestos

B00C - R0012 - Movement

No Asbestos

B00C - R0013 - Other

No Asbestos

B00C - R0014 - Practical Activities

No Asbestos

B00C - R0015 - Home Base

No Asbestos

B00C - R1002 - No Access

No Asbestos

B00C - R1005 - Stairs

No Asbestos

B00C - R1007 - Movement

No Asbestos

B00C - R1008 - Home Base

No Asbestos

B00C - R1009 - Home Base

No Asbestos

B00C - R1010 - Practical Activities/Movement - 2hb

No Asbestos

B00C - R1011 - External Movement

No Asbestos

B00C - R2003 - General Storeroom

Floor Coverings Res/Textile	Vinyl Sheet					
7407/B00C/R2003/Floor Coverings Res/Textile/S10					No Asbestos Detected	

B00C - R2005 - Movement

No Asbestos

B00C - R2006 - Stairs

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00C - R2007 - Home Base

No Asbestos

B00C - R2008 - Home Base

No Asbestos

B00C - R2009 - Practical Activities/Movement - 2hb

No Asbestos

B00C - R2010 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00D - General Learning - 1912 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior**B00D - M0001 - Other - D.E.T. Admin**

No Asbestos

B00D - M0002 - Other - D.E.T. Admin

No Asbestos

B00D - M0004 - Movement

No Asbestos

B00D - M0005 - Movement

No Asbestos

B00D - M0006 - Toilet - Lobby

No Asbestos

B00D - M0007 - Staff Toilet

No Asbestos

B00D - M0008 - Staff Toilet

No Asbestos

B00D - M0009 - Toilet - Lobby

No Asbestos

B00D - R0001 - Home Base

No Asbestos

B00D - R0002 - Security Store

No Asbestos

B00D - R0003 - Home Base

No Asbestos

B00D - R0004 - Home Base

No Asbestos

B00D - R0005 - Movement

No Asbestos

B00D - R0006 - Movement

No Asbestos

B00D - R0008 - Other - D.E.T. Admin

No Asbestos

B00D - R0009 - Other - D.E.T. Admin

No Asbestos

B00D - R0010 - Other - D.E.T. Admin

No Asbestos

B00D - R0011 - Home Base

No Asbestos

B00D - R0014 - Other - D.E.T. Admin

No Asbestos

B00D - R0015 - Other - D.E.T. Admin

No Asbestos

B00D - R0016 - Other - D.E.T. Admin

No Asbestos

B00D - R0017 - Stairs

No Asbestos

B00D - R0018 - Stairs

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result
						No Asbestos
	B00D - R0020 - Movement					No Asbestos
	B00D - R0021 - Disabled Toilet					No Asbestos
	B00D - R0022 - Movement					No Asbestos
	B00D - R0023 - Staff Kitchen					No Asbestos
	B00D - R1001 - Other - D.E.T. Admin					No Asbestos
	B00D - R1002 - Other - D.E.T. Admin					No Asbestos
	B00D - R1003 - Other - D.E.T. Admin					No Asbestos
	B00D - R1004 - Other - D.E.T. Admin					No Asbestos
	B00D - R1005 - Other - D.E.T. Admin					No Asbestos
	B00D - R1006 - Other - D.E.T. Admin					No Asbestos
	B00D - R1007 - Other - D.E.T. Admin					No Asbestos
	B00D - R1008 - Other - D.E.T. Admin					No Asbestos
	B00D - R1009 - Other - D.E.T. Admin					No Asbestos
	B00D - R1010 - Other - D.E.T. Admin					No Asbestos
	B00D - R1011 - Other - D.E.T. Admin					No Asbestos
	B00D - R1012 - Stairs					No Asbestos
	B00D - R1013 - Stairs					No Asbestos
	B00D - R1014 - Practical Activities					No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Pupil Facilities - 1910 - Brick/Block (Brick/Block)

Exterior

No Asbestos

Interior

B00E - R0007 - Other-Community Use

No Asbestos

B00E - R0008 - Other-Community Use

No Asbestos

B00E - R0014 - Special Programs Room

No Asbestos

B00E - R0015 - Special Programs Room

No Asbestos

B00E - R0016 - Special Programs Room

No Asbestos

B00E - R0017 - Movement

No Asbestos

B00E - R0018 - Handwashing Facilities

No Asbestos

B00E - R0019 - Staff Toilet

No Asbestos

B00E - R0020 - Staff Toilet

No Asbestos

B00E - R0021 - Special Programs Store

No Asbestos

B00E - R0022 - Staff Room Annexe

No Asbestos

B00E - R0023 - Special Programs Room

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Pupil Facilities - 1928 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting 7407/B00F/Eaves Linings/S11					No Asbestos Detected
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00F - R0001 - Toilets - Boys**

Ceiling Structures/Linings	Flat AC Sheeting 7407/B00G/R0002/Ceiling Structures/Linings/S2	30m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet 7407/B00F/R0002/Partition Walls (Cubicles)/S3	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)

B00F - R0002 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting 7407/B00G/R0002/Ceiling Structures/Linings/S2	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet 7407/B00F/R0002/Partition Walls (Cubicles)/S3	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Pupil Facilities - 1928 - Brick/Veneer (Brick/Veneer)**Exterior**

Eaves Linings	Flat AC Sheeting	20m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	7407/B00G/R0002/Ceiling Structures/Linings/S2					Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00G - R0001 - Drinking Facilities**

Ceiling Structures/Linings	Flat AC Sheeting	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	7407/B00G/R0002/Ceiling Structures/Linings/S2					Chrysotile (white asbestos)

B00G - R0002 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	32m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	7407/B00G/R0002/Ceiling Structures/Linings/S2					Chrysotile (white asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Pupil Facilities - 1928 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting 7407/B00F/Eaves Linings/S11					No Asbestos Detected
Gable Verge Lining	Flat AC Sheeting 7407/B00H/Gable Verge Lining/S12	20m	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00H - R0002 - Staff Toilet**

Ceiling Structures/Linings	Flat AC Sheeting 7407/B00G/R0002/Ceiling Structures/Linings/S2	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	---	-----	--------------	--------------------	---------	--

B00H - R0003 - Drinking Facilities

Ceiling Structures/Linings	Flat AC Sheeting 7407/B00G/R0002/Ceiling Structures/Linings/S2	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	---	------	--------------	--------------------	---------	--

B00H - R0004 - Toilets - Boys

No Asbestos

B00H - R0005 - Toilets - Girls

No Asbestos

Ceiling Structures/Linings	Flat AC Sheeting 7407/B00H/R0005/Ceiling Structures/Linings/S13	22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	--	------	------------	--------------------	---------	--

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - Pupil Facilities/Building Services - 1916 - Brick/Block (Brick/Block)**Exterior**

Gable Verge Lining	Flat AC Sheeting	20m	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	7407/B00H/Gable Verge Lining/S12					Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00J - R0001 - Toilets - Boys**

Ceiling Structures/Linings	Flat AC Sheeting	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	7407/B00G/R0002/Ceiling Structures/Linings/S2					Chrysotile (white asbestos)

B00J - R0003 - Toilets - Boys/Girls

Ceiling Structures/Linings	Flat AC Sheeting	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	7407/B00G/R0002/Ceiling Structures/Linings/S2					Chrysotile (white asbestos)

Partition Walls (Cubicles)	Compressed AC Sheet	16m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	7407/B00J/R0003/Partition Walls (Cubicles)/S4					Chrysotile (white asbestos)

B00J - R0004 - General Assistant/Bulk Store

Ceiling Structures/Linings	Flat AC Sheeting	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	7407/B00G/R0002/Ceiling Structures/Linings/S2					Chrysotile (white asbestos)

B00J - R0006 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	15m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	7407/B00G/R0002/Ceiling Structures/Linings/S2					Chrysotile (white asbestos)

B00J - R0007 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	7407/B00G/R0002/Ceiling Structures/Linings/S2					Chrysotile (white asbestos)

B00J - R0008 - Handwashing Facilities

No Asbestos						
Eaves	Flat AC Sheeting	NA	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	7407/B00J/R0008/Eaves/S14					Chrysotile (white asbestos)

B00J - R0009 - Toilets - Boys

No Asbestos						
Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	7407/B00J/R0009/Ceiling Structures/Linings/S15					

B00J - R0010 - External Movement

No Asbestos

B00J - R0011 - External Movement

No Asbestos

B00J - R0012 - External Movement

No Asbestos

B00J - R0013 - External Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Other - 2006 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00K - R0001 - Plant

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Pupil Facilities/Communal Facilities - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00L - R0001 - Communal Space

No Asbestos

B00L - R0002 - Raised Platform

No Asbestos

B00L - R0003 - Movement

No Asbestos

B00L - R0004 - Ramp

No Asbestos

B00L - R0005 - Movement

No Asbestos

B00L - R0006 - Toilet - Lobby

No Asbestos

B00L - R0007 - Toilets - Boys

No Asbestos

B00L - R0008 - P.E. Store

No Asbestos

B00L - R0009 - Movement

No Asbestos

B00L - R0010 - Hall Chair Store

No Asbestos

B00L - R0011 - Communal/Performance Store

No Asbestos

B00L - R0012 - Sound Cupboard

No Asbestos

B00L - R0013 - Toilet - P

No Asbestos

B00L - R0014 - Plant

No Asbestos

B00L - R0015 - Toilet - Lobby

No Asbestos

B00L - R0016 - Toilets - Girls

No Asbestos

B00L - R0017 - Cleaning Distributed Store

No Asbestos

B00L - R0018 - Main Switch Board

No Asbestos

B00L - R0019 - External Movement

No Asbestos

B00L - R0020 - External Movement

No Asbestos

B00L - R0021 - Covered Outdoor Learning Area

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017