


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Bourke Street Public School (7408)  
**Region :** Sydney  
**State Electorate :** Newtown  
**Local Government Area :** Sydney

**Initial Survey :** Noel Arnold & Associates : 23 - Feb - 2008  
**Reviewed By :** Grencap-NAA : 28 - Sep - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - General Learning/Administration - 1880 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting 7408/B00A/Eaves Linings/S28					No Asbestos Detected
Entrance Arch	Pointing 7408/B00A/Entrance Arch/S19					No Asbestos Detected
Ceiling Voids	Non Accessible Area - Height Restriction					
Underfloor Voids	Non Accessible Area - Visible from access hatch in R0034 only, no safe access					

**Interior**

**B00A - R0001 - Home Base**

No Asbestos

**B00A - R0002 - Security Store**

No Asbestos

**B00A - R0003 - Home Base**

No Asbestos

**B00A - R0006 - Movement**

No Asbestos

**B00A - R0007 - Movement**

No Asbestos

**B00A - R0008 - External Movement**

No Asbestos

**B00A - R0009 - Duplicating Workroom**

Floor Coverings Res/Textile	Vinyl Tiles	19m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	7408/B00A/R0009/Floor Coverings Res/Textile/S6					Chrysotile (white asbestos)

Adhesive to Vinyl Tiles	Adhesive 7408/B00A/R0009/Adhesive to Vinyl Tiles/S20					No Asbestos Detected
-------------------------	---	--	--	--	--	----------------------

**B00A - R0010 - Movement**

No Asbestos

**B00A - R0011 - Entry Vestibule**

No Asbestos

**B00A - R0012 - Clerical Office/Workroom**

No Asbestos

**B00A - R0013 - External Movement**

No Asbestos

**B00A - R0014 - Movement**

No Asbestos

**B00A - R0015 - Communal Space**

No Asbestos

**B00A - R0018 - Cleaning Distributed Store**

No Asbestos

**B00A - R0019 - Home Base**

No Asbestos

**B00A - R0020 - Home Base**

No Asbestos

**B00A - R0023 - Staff Toilet**

Floor Coverings Res/Textile	Vinyl Tiles 7408/B00A/R0023/Floor Coverings Res/Textile/S7					No Asbestos Detected
-----------------------------	---	--	--	--	--	----------------------

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Adhesive to Vinyl Tiles	Adhesive					
	7408/B00A/R0023/Adhesive to Vinyl Tiles/S21					<b>No Asbestos Detected</b>
<b>B00A - R0024 - Staff Room</b>						
No Asbestos						
<b>B00A - R0025 - External Movement</b>						
No Asbestos						
<b>B00A - R0026 - External Movement</b>						
No Asbestos						
<b>B00A - R0027 - External Movement</b>						
No Asbestos						
<b>B00A - R0028 - External Movement</b>						
No Asbestos						
<b>B00A - R0029 - External Movement</b>						
No Asbestos						
<b>B00A - R0031 - Library Office/Workroom</b>						
No Asbestos						
<b>B00A - R0032 - External Movement</b>						
No Asbestos						
<b>B00A - R0033 - External Movement</b>						
No Asbestos						
<b>B00A - R0034 - Interview/Office - Type 3</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	7408/B00A/R0023/Floor Coverings Res/Textile/S7					<b>No Asbestos Detected</b>
Adhesive to Vinyl Tiles	Adhesive					
	7408/B00A/R0023/Adhesive to Vinyl Tiles/S21					<b>No Asbestos Detected</b>
<b>B00A - R0035 - Library Office/Workroom</b>						
No Asbestos						
<b>B00A - R0036 - Communal Space</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - General Learning/Administration - 1923 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting 7408/B00B/Eaves Linings/S27					<b>No Asbestos Detected</b>
Eaves Linings	No Asbestos Found					
Underfloor Voids	Non Accessible Area - Area inaccessible					
Ceiling Voids	Non Accessible Area - Area inaccessible Height Restriction					

**Interior**

**B00B - R0001 - Interview**

No Asbestos

**B00B - R0002 - Movement**

No Asbestos

**B00B - R0004 - HB**

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 7408/B00B/R0030/Floor Coverings Res/Textile/S8	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>
Adhesive to Vinyl Tiles	Adhesive 7408/B00B/R0030/Adhesive to Vinyl Tiles/S9					<b>No Asbestos Detected</b>

**B00B - R0007 - Cleaning Distributed Store**

Wall Linings Internal	Flat AC Sheeting 7408/B00B/R0007/Wall Linings Internal/S4	6m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>

**B00B - R0008 - General Storeroom**

Wall Linings Internal	Flat AC Sheeting 7408/B00B/R0007/Wall Linings Internal/S4	6m2	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Vinyl Sheet 7408/B00B/R0008/Floor Coverings Res/Textile/S16					<b>No Asbestos Detected</b>
Adhesive to Hessian-backed Sheet Vinyl	Adhesive 7408/B00B/R0008/Adhesive to Hessian					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Millboard 7408/B00B/R0008/Floor Coverings Res/Textile/S18					<b>No Asbestos Detected</b>

**B00B - R0009 - Movement**

Electrical Mounting Board	Resinous Board <b>Assumed Asbestos - Electrical Hazard. Board appears of recent manufacture, not visible behind metal pane at the</b>	1Unit	West facing	Good Condition (1)	Medium (2)	Low Priority (2-3)
Floor Coverings Res/Textile	Vinyl Sheet 7408/B00B/R0009/Floor Coverings Res/Textile/S12					<b>No Asbestos Detected</b>
Adhesive to Sheet Vnyl	Adhesive 7408/B00B/R0009/Adhesive to Sheet Vnyl/S13					<b>No Asbestos Detected</b>

**B00B - R0010 - General Storeroom**

No Asbestos

**B00B - R0011 - Staff Room Annexe**

No Asbestos

**B00B - R0013 - Staff Toilet**

No Asbestos

**B00B - R0014 - Staff Toilet**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00B - R0015 - HB</b>						
No Asbestos						
<b>B00B - R0016 - External Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting					
	7408/B00B/R0016/Ceiling Structures/Linings/S26					<b>No Asbestos Detected</b>
<b>B00B - R0017 - Cleaning Distributed Store</b>						
No Asbestos						
<b>B00B - R0018 - Movement</b>						
No Asbestos						
<b>B00B - R0019 - HB</b>						
No Asbestos						
<b>B00B - R0020 - N/A</b>						
No Asbestos						
<b>B00B - R0022 - N/A</b>						
No Asbestos						
<b>B00B - R0023 - Other</b>						
Partition Walls (Cubicles)	Compressed AC Sheet					
	7408/B00B/R0023/Partition Walls (Cubicles)/S15					<b>No Asbestos Detected</b>
<b>B00B - R0024 - Other</b>						
Floor Coverings Res/Textile	Vinyl Tiles	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	7408/B00B/R0024/Floor Coverings Res/Textile/S5					<b>Chrysotile (white asbestos)</b>
Adhesive to Vinyl Tiles	Adhesive					
	7408/B00B/R0024/Adhesive to Vinyl Tiles/S14					<b>No Asbestos Detected</b>
<b>B00B - R0025 - Stairs</b>						
No Asbestos						
<b>B00B - R0026 - Stairs</b>						
No Asbestos						
<b>B00B - R0027 - PAA</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	15m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	7408/B00B/R0030/Floor Coverings Res/Textile/S8					<b>Chrysotile (white asbestos)</b>
Adhesive to Vinyl Tiles	Adhesive					
	7408/B00B/R0030/Adhesive to Vinyl Tiles/S9					<b>No Asbestos Detected</b>
<b>B00B - R0028 - Withdrawal Space - 1hb</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	7408/B00B/R0030/Floor Coverings Res/Textile/S8					<b>Chrysotile (white asbestos)</b>
Adhesive to Vinyl Tiles	Adhesive					
	7408/B00B/R0030/Adhesive to Vinyl Tiles/S9					<b>No Asbestos Detected</b>
<b>B00B - R0029 - HB</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	40m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	7408/B00B/R0030/Floor Coverings Res/Textile/S8					<b>Chrysotile (white asbestos)</b>
Adhesive to Vinyl Tiles	Adhesive					
	7408/B00B/R0030/Adhesive to Vinyl Tiles/S9					<b>No Asbestos Detected</b>
<b>B00B - R0030 - Withdrawal Space - 1hb</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	7408/B00B/R0030/Floor Coverings Res/Textile/S8					<b>Chrysotile (white asbestos)</b>
Adhesive to Vinyl Tiles	Adhesive					
	7408/B00B/R0030/Adhesive to Vinyl Tiles/S9					<b>No Asbestos Detected</b>
<b>B00B - R0031 - Duplicating Workroom</b>						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00B - R0032 - Withdrawal - M</b>						
No Asbestos						
<b>B00B - R0033 - Practical Activities</b>						
No Asbestos						
<b>B00B - R0034 - Home Base</b>						
No Asbestos						
<b>B00B - R0035 - Practical Activities/Movement - 1hb</b>						
No Asbestos						
<b>B00B - R0036 - Home Base</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 7408/B00B/R0030/Floor Coverings Res/Textile/S8	65m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Adhesive to Vinyl Tiles	Adhesive 7408/B00B/R0030/Adhesive to Vinyl Tiles/S9					<b>No Asbestos Detected</b>
<b>B00B - R0037 - Home Base</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 7408/B00B/R0030/Floor Coverings Res/Textile/S8	64m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Adhesive to Vinyl Tiles	Adhesive 7408/B00B/R0030/Adhesive to Vinyl Tiles/S9					<b>No Asbestos Detected</b>
<b>B00B - R0038 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00B - R1003 - HB</b>						
No Asbestos						
<b>B00B - R1004 - HB</b>						
No Asbestos						
<b>B00B - R1006 - General Storeroom</b>						
No Asbestos						
<b>B00B - R1008 - HB</b>						
No Asbestos						
<b>B00B - R1009 - Security Store</b>						
Floor Coverings Res/Textile	Hessian-backed sheeting 7408/B00B/R1009/Floor Coverings Res/Textile/S10					<b>No Asbestos Detected</b>
Adhesive to Hessian-backed Sheeting	Adhesive 7408/B00B/R1009/Adhesive to Hessian					<b>No Asbestos Detected</b>
<b>B00B - R1011 - Movement</b>						
No Asbestos						
<b>B00B - R1012 - Stairs</b>						
No Asbestos						
<b>B00B - R1013 - Stairs</b>						
No Asbestos						
<b>B00B - R1015 - PAA</b>						
No Asbestos						
<b>B00B - R1016 - Home Base Store</b>						
No Asbestos						
<b>B00B - R1017 - PAA</b>						
No Asbestos						
<b>B00B - R1018 - Home Base Store</b>						
No Asbestos						
<b>B00B - R1019 - Withdrawal Space - 1hb</b>						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00B - R1020 - Movement</b>						
No Asbestos						
<b>B00B - R1021 - PAA</b>						
No Asbestos						
<b>B00B - R1022 - Withdrawal Space - 1hb</b>						
No Asbestos						
<b>B00B - R1023 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00B - R1024 - Home Base</b>						
No Asbestos						
<b>B00B - R1025 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00B - R1026 - Home Base</b>						
No Asbestos						
<b>B00B - R1027 - Home Base</b>						
No Asbestos						
<b>B00B - R1028 - Practical Activities - 1hb</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - Pupil Facilities - 1883 - Timber (Timber)****Exterior**

Ceiling Voids - Raked Ceiling	Non Accessible Area - Extreme Access Issue - No Access Point into ceiling void identified					
Eaves Linings	Flat AC Sheeting 7408/B00C/Eaves Linings/S25					<b>No Asbestos Detected</b>
Underfloor Voids	Non Accessible Area - Area inaccessible					
Ceiling Voids - Raked Ceiling	Non Accessible Area - Height Restriction - Extreme Access Issue - No Access Point into ceiling void identified					

**Interior****B00C - R0001 - Movement**

Floor Coverings Res/Textile	Vinyl Sheet 7408/B00C/R0001/Floor Coverings Res/Textile/S1					<b>No Asbestos Detected</b>
-----------------------------	---	--	--	--	--	-----------------------------

**B00C - R0002 - Canteen**

Floor Coverings Res/Textile	Vinyl Sheet 7408/B00C/R0001/Floor Coverings Res/Textile/S1					<b>No Asbestos Detected</b>
-----------------------------	---	--	--	--	--	-----------------------------

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - Other-Community Use - 1950 - Timber (Timber)****Exterior**

Eaves Linings	Flat AC Sheeting	50m2	North facing, South facing, East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - Height Restriction - Height Restriction</b>						
Ceiling Voids - Raked Ceiling	Non Accessible Area - Height Restriction - Height Restriction					
Underfloor Voids	Non Accessible Area - Area inaccessible					

**Interior****B00D - R0001 - Other-Community Use**

Safe	Encapsulated Insulation material within unit	1Unit	East	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - Internal insulation inaccessible</b>						
Chalk Board	Resinous Board 7408/B00D/R0001/Chalk Board/S23					<b>No Asbestos Detected</b>

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - Other-Community Use - 1883 - Brick/Veneer (Brick/Veneer)****Exterior**

Eaves Linings	Flat AC Sheeting	20m2	North facing, South facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - Height Restriction - Height Restriction</b>						
Ceiling Voids	Non Accessible Area - Height Restriction - Height Restriction					
Underfloor Voids	Non Accessible Area - Area inaccessible					

**Interior****B00E - R0002 - External Movement**

No Asbestos

**B00E - R0003 - Movement**

Electrical Backing Board	Encapsulated Insulation material within unit	1Unit	West	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - Electrical Hazard</b>						

**B00E - R0004 - General Assistant/Bulk Store**

Wall Linings Internal	Flat AC Sheeting 7408/B00E/R0006/Wall Linings Internal/S24					<b>No Asbestos Detected</b>
Ceiling Structures/Linings	Flat AC Sheeting 7408/B00E/R0006/Wall Linings Internal/S24					<b>No Asbestos Detected</b>

**B00E - R0005 - General Storeroom**

Wall Linings Internal	Flat AC Sheeting 7408/B00E/R0006/Wall Linings Internal/S24					<b>No Asbestos Detected</b>
Ceiling Structures/Linings	Flat AC Sheeting 7408/B00E/R0006/Wall Linings Internal/S24					<b>No Asbestos Detected</b>

**B00E - R0006 - Garden Store**

Wall Linings Internal	Flat AC Sheeting 7408/B00E/R0006/Wall Linings Internal/S24					<b>No Asbestos Detected</b>
Ceiling Structures/Linings	Flat AC Sheeting 7408/B00E/R0006/Wall Linings Internal/S24					<b>No Asbestos Detected</b>

**B00E - R0007 - General Storeroom**

Wall Linings Internal	Flat AC Sheeting 7408/B00E/R1004/Wall Linings Internal/S3	3m2	South, upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Chrysotile (white asbestos)</b>						

**B00E - R0008 - Stairs**

Wall Linings Internal	Flat AC Sheeting 7408/B00E/R1004/Wall Linings Internal/S3	5m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Chrysotile (white asbestos)</b>						

**B00E - R0009 - Home Base/Practical Activities**

No Asbestos

**B00E - R0010 - Communications Room**

Wall Linings Internal	Flat AC Sheeting 7408/B00E/R1004/Wall Linings Internal/S3	5m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Chrysotile (white asbestos)</b>						

**B00E - R1001 - Staff Toilet**

Floor Coverings Res/Textile	Vinyl Tiles 7408/B00E/R0001/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>
-----------------------------	---	--	--	--	--	-----------------------------

**B00E - R1003 - Staff Toilet**

Floor Coverings Res/Textile	Vinyl Tiles 7408/B00E/R0001/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>
-----------------------------	---	--	--	--	--	-----------------------------

**B00E - R1004 - Movement**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Wall Linings Internal	Flat AC Sheeting	2m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
7408/B00E/R1004/Wall Linings Internal/S3					Chrysotile (white asbestos)	
<b>B00E - R1006 - Stairs</b>						
Wall Linings Internal	Flat AC Sheeting	10m2	South facing, East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
7408/B00E/R1004/Wall Linings Internal/S3					Chrysotile (white asbestos)	
<b>B00E - R1007 - Staff Room</b>						
No Asbestos						
<b>B00E - R1008 - Staff Kitchen</b>						
No Asbestos						
<b>B00E - R1009 - Other</b>						
No Asbestos						
<b>B00E - R1010 - Other</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - Pupil Facilities - 1883 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	No Asbestos Found					
Ceiling Voids	Non Accessible Area - Area inaccessible					
Underfloor Voids	Non Accessible Area - Area inaccessible					

**Interior**

**B00F - R0001 - Drinking Facilities**

No Asbestos

**B00F - R0002 - Toilets - Girls**

Partition Walls (Cubicles)	Compressed AC Sheet	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
7408/B00F/R0003/Partition Walls (Cubicles)/S22				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00F - R0003 - Toilets - Boys**

Partition Walls (Cubicles)	Compressed AC Sheet	12m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
7408/B00F/R0003/Partition Walls (Cubicles)/S22				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00F - R0004 - Drinking Facilities**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - Pupil Facilities - 1883 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids	Non Accessible Area - Area inaccessible
Eaves Linings	No Asbestos Found
Underfloor Voids	Non Accessible Area - Area inaccessible

**Interior****B00G - R0001 - Drinking Facilities**

No Asbestos

**B00G - R0002 - Toilets - Boys**

Partition Walls (Cubicles)	Corrugated AC Sheeting	10m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
7408/B00F/R0003/Partition Walls (Cubicles)/S22				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00G - R0003 - Toilets - Girls**

Partition Walls (Cubicles)	Compressed AC Sheet	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
7408/B00F/R0003/Partition Walls (Cubicles)/S22				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00G - R0004 - Drinking Facilities**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Demountables***

**There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017