

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Ballina High School (8195)
Region : North Coast
State Electorate : Ballina
Local Government Area : Ballina

Initial Survey : Noel Arnold & Associates : 11 - Jun - 2008
Reviewed By : Parsons Brinckerhoff : 08 - Oct - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/General Learning - 1966 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	200m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8195/B00A/Eaves Linings/S22			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00A - R0001 - Ancillary Staff (18.4 m2)**

No Asbestos

B00A - R0002 - Administration - Clerical (15 m2)

No Asbestos

B00A - R0003 - Administration - Clerical (11.95 m2)

No Asbestos

B00A - R0006 - Public Entry (20.3 m2)

No Asbestos

B00A - R0007 - Leading Teacher (14.25 m2)

No Asbestos

B00A - R0008 - General Storeroom (3.17 m2)

No Asbestos

B00A - R0009 - Administration - Clerical (19 m2)

No Asbestos

B00A - R0010 - Principal Office (30.68 m2)

Ceiling Structures/Linings Vermiculite
 8195/B00A/R0045/Ceiling Structures/Linings/S4 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00A - R0011 - Administration - Clerical (6.97 m2)

Ceiling Structures/Linings Vermiculite
 8195/B00A/R0045/Ceiling Structures/Linings/S4 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00A - R0012 - General Storeroom (6.56 m2)

No Asbestos

B00A - R0013 - Movement (30.3 m2)

No Asbestos

B00A - R0014 - Deputy Principal Office (18.41 m2)

Ceiling Structures/Linings Vermiculite
 8195/B00A/R0045/Ceiling Structures/Linings/S4 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00A - R0015 - Distribution Board Cupboard (0.48 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0017 - Pupil Entry (12.56 m2)

No Asbestos

B00A - R0018 - Cleaning Store - Distributed (4.17 m2)

No Asbestos

B00A - R0019 - Movement (5.83 m2)

No Asbestos

B00A - R0020 - Interview/Office - Type 1 (23.53 m2)

No Asbestos

B00A - R0022 - Toilets-Girls (49.64 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Partition Walls (Cubicles)	Compressed AC Sheet	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8195/B00A/R0022/Partition Walls (Cubicles)/S6					Chrysotile (white asbestos)	
B00A - R0023 - Resources Store (24.31 m2)						
No Asbestos						
B00A - R0024 - Toilets-Boys (59.55 m2)						
Partition Walls (Cubicles)	Compressed AC Sheet	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8195/B00A/R0022/Partition Walls (Cubicles)/S6					Chrysotile (white asbestos)	
B00A - R0025 - General Storeroom (7.59 m2)						
No Asbestos						
B00A - R0026 - Kiln Space (5.1 m2)						
No Asbestos						
B00A - R0029 - Cleaning Store - Distributed (3.08 m2)						
No Asbestos						
B00A - R0030 - Movement (6.74 m2)						
No Asbestos						
B00A - R0032 - Movement (33.03 m2)						
Ceiling Structures/Linings	Vermiculite					
8195/B00A/R0045/Ceiling Structures/Linings/S4					Limited Samples Taken	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R0038 - Resources Store (11.16 m2)						
No Asbestos						
B00A - R0039 - No Access (4.44 m2)						
No Asbestos						
B00A - R0040 - Movement (2.86 m2)						
No Asbestos						
B00A - R0041 - Preparation (27.01 m2)						
Ceiling Structures/Linings	Vermiculite					
8195/B00A/R0045/Ceiling Structures/Linings/S4					Limited Samples Taken	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R0042 - Laboratory L.S. (161.58 m2)						
Ceiling Structures/Linings	Vermiculite					
8195/B00A/R0045/Ceiling Structures/Linings/S4					Limited Samples Taken	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R0043 - Laboratory L.S. (108.09 m2)						
Ceiling Structures/Linings	Vermiculite					
8195/B00A/R0045/Ceiling Structures/Linings/S4					Limited Samples Taken	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R0044 - Distribution Board Cupboard (0.37 m2)				Note: No inspection of live electrical installation.		
No Asbestos						
B00A - R0045 - Movement (19.39 m2)						
Ceiling Structures/Linings	Vermiculite					
8195/B00A/R0045/Ceiling Structures/Linings/S4					Limited Samples Taken	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R0046 - Stairs (1.95 m2)						
No Asbestos						
B00A - R0047 - Stairs (6.64 m2)						
No Asbestos						
B00A - R0048 - Stairs (8.05 m2)						
No Asbestos						
B00A - R0049 - Movement (8.62 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result
	No Asbestos					
	B00A - R0050 - Movement (14.98 m2)					
	No Asbestos					
	B00A - R0051 - Movement (16.32 m2)					
	No Asbestos					
	B00A - R0052 - Movement (10.54 m2)					
	No Asbestos					
	B00A - R0053 - Movement (217.6 m2)					
	Ceiling Structures/Linings	No Asbestos Found				
	B00A - R0054 - Staff - Toilet (1.39 m2)					
	No Asbestos					
	B00A - R0055 - Toilet - Lobby (3.18 m2)					
	No Asbestos					
	B00A - R0056 - Movement (2.48 m2)					
	No Asbestos					
	B00A - R0057 - Toilet - Lobby (6.38 m2)					
	No Asbestos					
	B00A - R0058 - Staff - Toilet (2 m2)					
	No Asbestos					
	B00A - R0059 - Staff - Toilet (1.39 m2)					
	No Asbestos					
	B00A - R1001 - Cleaning Store - Distributed (1.47 m2)					
	No Asbestos					
	B00A - R1002 - Staff - Toilet (4.14 m2)					
	No Asbestos					
	B00A - R1003 - Movement (189.41 m2)					
	No Asbestos					
	B00A - R1004 - Art Learning Space (60.04 m2)					
	No Asbestos					
	B00A - R1005 - Resources Store (10.74 m2)					
	No Asbestos					
	B00A - R1006 - Kiln Space (22.55 m2)					
	No Asbestos					
	B00A - R1007 - Workshop (53.29 m2)					
	No Asbestos					
	B00A - R1008 - Resources Store (5.21 m2)					
	No Asbestos					
	B00A - R1009 - Art Learning Space (53 m2)					
	No Asbestos					
	B00A - R1010 - Resources Store (6.27 m2)					
	No Asbestos					
	B00A - R1011 - General Learning Space (54.24 m2)					
	No Asbestos					
	B00A - R1012 - Resources Store (7.45 m2)					
	No Asbestos					
	B00A - R1013 - Duplicating Workroom (52.62 m2)					
	No Asbestos					
	B00A - R1014 - Clinic - Girls (21.98 m2)					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
B00A - R1016 - Clinic - Boys (21.47 m2)						
No Asbestos						
B00A - R1017 - Clinic-Toilets (3.67 m2)						
No Asbestos						
B00A - R1018 - Commonroom (125.82 m2)						
No Asbestos						
B00A - R1019 - Staff - Toilet (8.13 m2)						
No Asbestos						
B00A - R1020 - Staff - Toilet (8.18 m2)						
No Asbestos						
B00A - R1021 - Staff Study (35.87 m2)						
No Asbestos						
B00A - R1022 - Resources Store (23.32 m2)						
No Asbestos						
B00A - R1023 - Stairs (5.98 m2)						
No Asbestos						
B00A - R1024 - Movement (5.06 m2)						
No Asbestos						
B00A - R1025 - Stairs (10.28 m2)						
No Asbestos						
B00A - R1026 - Stairs (14.91 m2)						
No Asbestos						
B00A - R1027 - No Access (0.85 m2)						
No Asbestos						
B00A - R1028 - Toilet - Lobby (1.62 m2)						
No Asbestos						
B00A - R1029 - Staff - Toilet (2.04 m2)						
Boxing around toilet cistern	Flat AC Sheeting	2m2	South	Some Damage - Unsealed (3)	Medium (2)	Medium Priority (4-5)
8195/B00A/R1029/Boxing around toilet cistern/S27					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning/Staff Facilities - 1915 - Concrete (Concrete)

Exterior

Ceiling Voids	No Asbestos Found					
Underfloor Voids	Debris	90m2	Throughout	Poor Condition - Extensive Damage (4)	Medium (2)	High Priority (6-8)
	8195/B00C/Underfloor Voids/S23			Chrysotile (white asbestos) , Amosite (brown asbestos)		

Interior

B00C - R0006 - Resources Store (13.12 m2)

No Asbestos

B00C - R0007 - General Learning Space (44.39 m2)

No Asbestos

B00C - R0008 - Movement (21.56 m2)

No Asbestos

B00C - R0009 - Study Space (25.6 m2)

No Asbestos

B00C - R0010 - Movement (1.81 m2)

No Asbestos

B00C - R0011 - Staff Study (17.6 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning - 1966 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	160m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8195/B00E/Eaves Linings/S24					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Underfloor Voids	No Asbestos Found					
Ceiling Voids	No Asbestos Found					

Interior**B00E - R0001 - General Learning Space (45.59 m2)**

No Asbestos

B00E - R0002 - Staff Shower (2.75 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8195/B00E/R1001/Ceiling Structures/Linings/S2					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00E - R0003 - Staff Study (33.94 m2)

No Asbestos

B00E - R0004 - Resources Store (10.68 m2)

No Asbestos

B00E - R0005 - Staff Shower (2.14 m2)

No Asbestos

B00E - R0006 - General Learning Space (52.92 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8195/B00E/R1001/Ceiling Structures/Linings/S2					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00E - R0007 - Performance Workspace (65.99 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8195/B00E/R1001/Ceiling Structures/Linings/S2					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00E - R0008 - Toilets-Girls (35.21 m2)

Partition Walls (Cubicles)	Compressed AC Sheet	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8195/B00E/R0008/Partition Walls (Cubicles)/S1					Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8195/B00E/R1001/Ceiling Structures/Linings/S2					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00E - R0009 - Cleaning Store - Distributed (3.79 m2)

No Asbestos

B00E - R0010 - General Storeroom (28.39 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8195/B00E/R1001/Ceiling Structures/Linings/S2					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00E - R0011 - Distribution Board Cupboard (0.61 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00E - R0012 - Movement (306.87 m2)

No Asbestos

B00E - R0013 - Laboratory L.S. (86.46 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8195/B00E/R1001/Ceiling Structures/Linings/S2					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00E - R0014 - Preparation (28.57 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Ceiling Structures/Linings	Vermiculite					
	8195/B00E/R1001/Ceiling Structures/Linings/S2					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R0015 - Preparation (10.17 m2)						
Ceiling Structures/Linings	Vermiculite					
	8195/B00E/R1001/Ceiling Structures/Linings/S2					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R0016 - Laboratory L.S. (86.32 m2)						
Ceiling Structures/Linings	Vermiculite					
	8195/B00E/R1001/Ceiling Structures/Linings/S2					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R0017 - General Learning Space (52.25 m2)						
No Asbestos						
B00E - R0018 - Stairs (16.04 m2)						
Ceiling Structures/Linings	Vermiculite					
	8195/B00E/R1001/Ceiling Structures/Linings/S2					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R0019 - Stairs (12.32 m2)						
Ceiling Structures/Linings	Vermiculite					
	8195/B00E/R1001/Ceiling Structures/Linings/S2					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R1001 - Staff Study (13.91 m2)						
Ceiling Structures/Linings	Vermiculite					
	8195/B00E/R1001/Ceiling Structures/Linings/S2					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R1002 - Staff Study (49.1 m2)						
Ceiling Structures/Linings	Vermiculite					
	8195/B00E/R1001/Ceiling Structures/Linings/S2					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R1003 - General Learning Space (45.45 m2)						
Ceiling Structures/Linings	Vermiculite					
	8195/B00E/R1001/Ceiling Structures/Linings/S2					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R1004 - Movement (263.3 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	263m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8195/B00E/R1004/Ceiling Structures/Linings/S3					Chrysotile (white asbestos) , Amosite (brown asbestos)
B00E - R1005 - General Learning Space (53.13 m2)						
No Asbestos						
B00E - R1006 - Resources Store (3.08 m2)						
Ceiling Structures/Linings	Vermiculite					
	8195/B00E/R1001/Ceiling Structures/Linings/S2					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R1007 - Staff Study (66.06 m2)						
Ceiling Structures/Linings	Vermiculite					
	8195/B00E/R1001/Ceiling Structures/Linings/S2					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R1008 - Resources Store (9.09 m2)						
Ceiling Structures/Linings	Vermiculite					
	8195/B00E/R1001/Ceiling Structures/Linings/S2					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R1009 - Resources Store (6.77 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite	8195/B00E/R1001/Ceiling Structures/Linings/S2				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R1010 - Resources Store (6.75 m2)						
Ceiling Structures/Linings	Vermiculite	8195/B00E/R1001/Ceiling Structures/Linings/S2				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R1011 - General Learning Space (67.81 m2)						
Ceiling Structures/Linings	Vermiculite	8195/B00E/R1001/Ceiling Structures/Linings/S2				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R1012 - General Learning Space (53.34 m2)						
Ceiling Structures/Linings	Vermiculite	8195/B00E/R1001/Ceiling Structures/Linings/S2				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R1013 - Distribution Board Cupboard (0.48 m2)						
					Note: No inspection of live electrical installation.	
No Asbestos						
B00E - R1015 - Cleaning Store - Distributed (6.21 m2)						
Ceiling Structures/Linings	Vermiculite	8195/B00E/R1001/Ceiling Structures/Linings/S2				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R1016 - Computer Learning Space (39.01 m2)						
Ceiling Structures/Linings	Vermiculite	8195/B00E/R1001/Ceiling Structures/Linings/S2				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R1017 - General Learning Space (52.63 m2)						
Ceiling Structures/Linings	Vermiculite	8195/B00E/R1001/Ceiling Structures/Linings/S2				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R1018 - General Learning Space (52.78 m2)						
Ceiling Structures/Linings	Vermiculite	8195/B00E/R1001/Ceiling Structures/Linings/S2				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R1019 - General Learning Space (52.78 m2)						
Ceiling Structures/Linings	Vermiculite	8195/B00E/R1001/Ceiling Structures/Linings/S2				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R1020 - Stairs (15.66 m2)						
Ceiling Structures/Linings	Vermiculite	8195/B00E/R1001/Ceiling Structures/Linings/S2				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R1021 - Stairs (18.64 m2)						
Ceiling Structures/Linings	Vermiculite	8195/B00E/R1001/Ceiling Structures/Linings/S2				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R1022 - Staff - Toilet (1.8 m2)						
Ceiling Structures/Linings	Vermiculite	8195/B00E/R1022/Ceiling Structures/Linings/S28				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R1023 - Toilet - Lobby (4.12 m2)						
Ceiling Structures/Linings	Vermiculite	8195/B00E/R1023/Ceiling Structures/Linings/S29				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Multi Purpose Facilities/Music - 1975 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior**B00H - R0001 - Cleaning Supplies Store (16.41 m2)**

No Asbestos

B00H - R0002 - Staff Study (24.93 m2)

No Asbestos

B00H - R0003 - Movement (16.7 m2)

No Asbestos

B00H - R0004 - Music Learning Space (82.25 m2)

No Asbestos

B00H - R0005 - Music Store (15.61 m2)

No Asbestos

B00H - R0006 - Music Learning Space (95.27 m2)

No Asbestos

B00H - R0008 - Resources Store (0.74 m2)

No Asbestos

B00H - R0009 - Distribution Board Cupboard (1.13 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00H - R0010 - Multi-Purpose Space (630.21 m2)

No Asbestos

B00H - R0011 - Stage (64.22 m2)

No Asbestos

B00H - R0013 - Office/Store (4.32 m2)

Floor Coverings Res/Textile	Vinyl Tiles
-----------------------------	-------------

8195/B00H/R0012/Floor Coverings Res/Textile/S7

No Asbestos Detected**B00H - R0014 - Staff - Toilet (2.26 m2)**

No Asbestos

B00H - R0015 - General Storeroom (6 m2)

Floor Coverings Res/Textile	Vinyl Tiles
-----------------------------	-------------

8195/B00H/R0012/Floor Coverings Res/Textile/S7

No Asbestos Detected**B00H - R0016 - Sport Equipment Store (65.15 m2)**

No Asbestos

B00H - R0017 - Toilets-Girls (15.7 m2)

No Asbestos

B00H - R0018 - Shower/Change (60.72 m2)

No Asbestos

B00H - R0019 - Shower/Change (9.86 m2)

No Asbestos

B00H - R0020 - Toilets-Boys (15.62 m2)

No Asbestos

B00H - R0021 - Staff Shower (9.56 m2)

No Asbestos

B00H - R0022 - Shower/Change (62.91 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00H - R0024 - Shower/Change (12.39 m2)						
No Asbestos						
B00H - R0025 - Shower/Change (12.1 m2)						
No Asbestos						
B00H - R0026 - Movement (57.22 m2)						
No Asbestos						
B00H - R0027 - Chair Store (7.63 m2)						
No Asbestos						
B00H - R0028 - Movement (4.7 m2)						
No Asbestos						
B00H - R0029 - Movement (4.56 m2)						
No Asbestos						
B00H - R0030 - Movement (9.52 m2)						
No Asbestos						
B00H - R0031 - Movement (38.48 m2)						
No Asbestos						
B00H - R0032 - Student Canteen (44.38 m2)						
No Asbestos						
B00H - R0033 - Other (4.16 m2)						
No Asbestos						
B00H - R0034 - Student Canteen (122.02 m2)						
No Asbestos						
B00H - R0035 - Performance Workshop (57.71 m2)						
No Asbestos						
B00H - R0036 - External Movement (26.16 m2)						
No Asbestos						
B00H - R0037 - Outdoor Learning Area (285.99 m2)						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Library/Science Learning - 1973 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior**B00L - M1001 - Seminar (14.79 m2)**

No Asbestos

B00L - M1002 - Study Space (68.39 m2)

No Asbestos

B00L - M1003 - Seminar (39.78 m2)

No Asbestos

B00L - M1004 - Stairs (2.97 m2)

No Asbestos

B00L - M1005 - Stairs (3.02 m2)

No Asbestos

B00L - R0001 - Laboratory L.S. (91.19 m2)

Floor Coverings Res/Textile	Vinyl Tiles	8195/B00L/R0005/Floor Coverings Res/Textile/S8	No Asbestos Detected
Ceiling Structures/Linings	Vermiculite	8195/B00L/R1004/Ceiling Structures/Linings/S5	Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>

B00L - R0004 - Chemical Store (17.29 m2)

Floor Coverings Res/Textile	Vinyl Tiles	8195/B00L/R0005/Floor Coverings Res/Textile/S8	No Asbestos Detected
Ceiling Structures/Linings	Vermiculite	8195/B00L/R1004/Ceiling Structures/Linings/S5	Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>

B00L - R0005 - Movement (40.52 m2)

Floor Coverings Res/Textile	Vinyl Tiles	8195/B00L/R0005/Floor Coverings Res/Textile/S8	No Asbestos Detected
-----------------------------	-------------	--	-----------------------------

B00L - R0006 - Laboratory L.S. (91.1 m2)

Floor Coverings Res/Textile	Vinyl Tiles	8195/B00L/R0005/Floor Coverings Res/Textile/S8	No Asbestos Detected
Ceiling Structures/Linings	Vermiculite	8195/B00L/R1004/Ceiling Structures/Linings/S5	Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>

B00L - R0009 - Laboratory L.S. (91.1 m2)

No Asbestos

B00L - R0010 - Cleaning Store - Distributed (7.9 m2)

No Asbestos

B00L - R0011 - Distribution Board Cupboard (0.52 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00L - R0012 - General Storeroom (8.65 m2)

No Asbestos

B00L - R0013 - Distribution Board Cupboard (1.17 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00L - R0014 - Stairs (7.8 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
B00L - R0015 - Movement (43.14 m2)						
No Asbestos						
B00L - R0016 - Staff Study (48.51 m2)						
No Asbestos						
B00L - R0017 - General Learning Space - Type 10 (91.51 m2)						
No Asbestos						
B00L - R0018 - Preparation - Science (48.52 m2)						
No Asbestos						
B00L - R1004 - Main Area (325.17 m2)						
Ceiling Structures/Linings	Vermiculite		8195/B00L/R1004/Ceiling Structures/Linings/S5			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00L - R1005 - Seminar (10.95 m2)						
No Asbestos						
B00L - R1006 - Cleaning Store - Distributed (5.05 m2)						
No Asbestos						
B00L - R1007 - Distribution Board Cupboard (0.43 m2)						
						Note: No inspection of live electrical installation.
No Asbestos						
B00L - R1008 - Cleaning Store - Distributed (0.29 m2)						
No Asbestos						
B00L - R1009 - Audio Visual Workroom (28.7 m2)						
No Asbestos						
B00L - R1010 - Resources Store (12.79 m2)						
No Asbestos						
B00L - R1011 - Workroom (17.63 m2)						
No Asbestos						
B00L - R1012 - Seminar (71.79 m2)						
No Asbestos						
B00L - R1013 - Seminar (11.56 m2)						
No Asbestos						
B00L - R1014 - Seminar (13.34 m2)						
No Asbestos						
B00L - R1015 - Plant Space (6.27 m2)						
No Asbestos						
B00L - R1016 - Plant Space (4.28 m2)						
No Asbestos						
B00L - R1017 - Movement (11.41 m2)						
No Asbestos						
B00L - R1018 - Seminar (14.31 m2)						
No Asbestos						
B00L - R1019 - Stairs (0.76 m2)						
No Asbestos						
B00L - R1020 - Stairs (0.76 m2)						
No Asbestos						
B00L - R1021 - Stairs (17.04 m2)						
No Asbestos						
B00L - R1022 - Movement (43.59 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00L - R1023 - Movement (3.17 m2)

No Asbestos

B00L - R1024 - Toilet - Lobby (1.54 m2)

No Asbestos

B00L - R1025 - Staff - Toilet (1.22 m2)

No Asbestos

B00L - R1026 - Toilet - Lobby (1.53 m2)

No Asbestos

B00L - R1027 - Staff - Toilet (1.23 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - General Learning - 1931 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	No Asbestos Found
Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00M - R0001 - General Learning Space (48.6 m2)

No Asbestos

B00M - R0002 - General Learning Space (48.37 m2)

No Asbestos

B00M - R0003 - Seminar (12.33 m2)

No Asbestos

B00M - R0004 - No Access (8.26 m2)

No Asbestos

B00M - R0005 - Resources Store (5.5 m2)

No Asbestos

B00M - R0006 - Movement (5.46 m2)

No Asbestos

B00M - R0007 - Resources Store (2.75 m2)

No Asbestos

B00M - R0008 - General Learning Space (48.63 m2)

No Asbestos

B00M - R0009 - General Learning Space (48.3 m2)

No Asbestos

B00M - R0010 - General Learning Space (48.6 m2)

No Asbestos

B00M - R0011 - Movement (62.81 m2)

No Asbestos

B00M - R0012 - Stairs (4.35 m2)

No Asbestos

B00M - R0013 - External Movement (1.91 m2)

No Asbestos

B00M - R0014 - Movement (4.17 m2)

No Asbestos

B00M - R1001 - General Learning Space (50.33 m2)

Decorative Coating	Vermiculite 8195/B00M/R1001/Decorative Coating/S30
--------------------	---

Limited Samples Taken

Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00M - R1002 - General Learning Space (49.25 m2)

Ceiling Structures/Linings	Flat AC Sheeting 8195/B00M/R1002/Ceiling Structures/Linings/S31
----------------------------	--

No Asbestos Detected

B00M - R1003 - General Learning Space (49.45 m2)

No Asbestos

B00M - R1004 - Staff Study (29.71 m2)

No Asbestos

B00M - R1005 - General Learning Space (77.84 m2)

Ceiling Structures/Linings	Flat AC Sheeting 8195/B00M/R1005/Ceiling Structures/Linings/S32
----------------------------	--

No Asbestos Detected

B00M - R1006 - Interview/Office - Type 1 (15.35 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00M - R1007 - Resources Store (4.44 m2)

No Asbestos

B00M - R1008 - Movement (59.11 m2)

No Asbestos

B00M - R1009 - Resources Store (8.32 m2)

No Asbestos

B00M - R1010 - Stairs (11.17 m2)

No Asbestos

B00M - R1011 - External Movement (5.27 m2)

Throughout

No Asbestos Found

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00S - General Learning - 1959 - Timber (Timber)

Exterior

Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	90m2	North and South	Good Condition (1)	Low (1)	Low Priority (2-3)
	8195/B00S/Eaves Linings/S25					Chrysotile (white asbestos) , Amosite (brown asbestos)
Gable Ends	Flat AC Sheeting	20m2	East and West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8195/B00S/Gable Ends/S26					Chrysotile (white asbestos) , Amosite (brown asbestos)

Interior

B00S - R0001 - Chair Store (58.87 m2)

Ceiling Structures/Linings	Flat AC Sheeting	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8195/B00S/R0001/Ceiling Structures/Linings/S33					Chrysotile (white asbestos) , Amosite (brown asbestos)
Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	8195/B00S/R0001/Wall Linings Internal/S34					

B00S - R0002 - General Assistants (26.21 m2)

Ceiling Structures/Linings	Flat AC Sheeting	6m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	8195/B00S/R0002/Ceiling Structures/Linings/S35					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00S - R0003 - General Assistants (20.85 m2)

Ceiling Structures/Linings	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8195/B00S/R0003/Ceiling Structures/Linings/S36					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00S - R0004 - General Assistants (6.54 m2)

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8195/B00S/R0004/Ceiling Structures/Linings/S37					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00S - R0005 - Garden Store Room (1 m2)

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8195/B00S/R0005/Ceiling Structures/Linings/S38					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00S - R0006 - Garden Store Room (59.23 m2)

Ceiling Structures/Linings	Flat AC Sheeting	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8195/B00S/R0006/Ceiling Structures/Linings/S39					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00S - R0007 - General Storeroom (28.71 m2)

Ceiling Structures/Linings	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8195/B00S/R0007/Ceiling Structures/Linings/S40					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00S - R0008 - Sport Equipment Store (88.1 m2)

Ceiling Structures/Linings	Flat AC Sheeting	100m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8195/B00S/R0008/Ceiling Structures/Linings/S41					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00S - R0009 - Sport Equipment Store (6.58 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8195/B00S/R0009/Ceiling Structures/Linings/S42				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00S - R0010 - No Access (1 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8195/B00S/R0010/Ceiling Structures/Linings/S43				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00S - R0011 - Sport Equipment Store (20.98 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	50m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8195/B00S/R0011/Ceiling Structures/Linings/S44				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00S - R0012 - Sport Equipment Store (26.08 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8195/B00S/R0012/Ceiling Structures/Linings/S45				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00S - R0013 - Darkroom Space (28.43 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8195/B00S/R0013/Ceiling Structures/Linings/S46				Chrysotile (white asbestos) , Amosite (brown asbestos)		
Wall Linings Internal	Flat AC Sheeting					
8195/B00S/R0013/Wall Linings Internal/S47				No Asbestos Detected		
B00S - R0014 - Movement (44.4 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	44m2	Throughout	Poor Condition - Extensive Damage (4)	High (3)	High Priority (6-8)
8195/B00S/R0014/Ceiling Structures/Linings/S48				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
B00S - R0015 - Movement (1.56 m2)						
No Asbestos						
B00S - R0016 - Movement (1.56 m2)						
No Asbestos						
B00S - R0017 - Movement (5.37 m2)						
No Asbestos						
B00S - R1001 - Resources Store (9.82 m2)						
No Asbestos						
B00S - R1002 - General Learning Space (59.29 m2)						
No Asbestos						
B00S - R1003 - General Learning Space (55.42 m2)						
No Asbestos						
B00S - R1004 - General Learning Space (55.78 m2)						
No Asbestos						
B00S - R1005 - General Learning Space (49.86 m2)						
No Asbestos						
B00S - R1006 - General Learning Space (53 m2)						
No Asbestos						
B00S - R1010 - Movement (81.7 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	90m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8195/B00S/R1010/Ceiling Structures/Linings/S49				Chrysotile (white asbestos) , Amosite (brown asbestos)		

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00S - R1011 - Movement (8.77 m2)

Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8195/B00S/R1011/Ceiling Structures/Linings/S50				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		

B00S - R1012 - Movement (1.56 m2)

Ceiling Structures/Linings	No Asbestos Found					
----------------------------	-------------------	--	--	--	--	--

B00S - R1013 - Movement (1.56 m2)

Ceiling Structures/Linings	No Asbestos Found					
----------------------------	-------------------	--	--	--	--	--

B00S - R1014 - Staff Study (28.71 m2)

No Asbestos						
-------------	--	--	--	--	--	--

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00T - Technological & Applied Studies - 1966 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior**B00T - R0002 - Distribution Board Cupboard (0.48 m2)**

Note: No inspection of live electrical installation.

No Asbestos

B00T - R0003 - Workshop Area (167.94 m2)

No Asbestos

B00T - R0004 - Materials Store (31.57 m2)

No Asbestos

B00T - R0007 - Resource/Project Store (12.85 m2)

Decorative Coating	Vermiculite 8195/B00T/R0007/Decorative Coating/S11	Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>		

B00T - R0008 - Dust Extraction Space (6.34 m2)

Decorative Coating	Vermiculite 8195/B00T/R0008/Decorative Coating/S12	Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>		

B00T - R0011 - Materials Technology L.S. (78.58 m2)

Decorative Coating	Vermiculite 8195/B00T/R0011/Decorative Coating/S15	Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>		

B00T - R0012 - Metal Technology Bay (41.97 m2)

Decorative Coating	Vermiculite 8195/B00T/R0012/Decorative Coating/S16	Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>		

B00T - R0013 - Welding Area (18.41 m2)

Decorative Coating	Vermiculite 8195/B00T/R0013/Decorative Coating/S17	Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>		

B00T - R0014 - Materials Technology L.S. (71.67 m2)

Decorative Coating	Vermiculite 8195/B00T/R0014/Decorative Coating/S18	Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>		

B00T - R0015 - Main Switchroom (10.14 m2)

No Asbestos

B00T - R0016 - Materials Store (9.17 m2)

No Asbestos

B00T - R0017 - Cleaning Store - Distributed (9.07 m2)

No Asbestos

B00T - R0018 - Movement (92.4 m2)

No Asbestos

B00T - R0019 - Movement (28.33 m2)

No Asbestos

B00T - R0021 - Stairs (9.17 m2)

No Asbestos

B00T - R0022 - Stairs (10.08 m2)

No Asbestos

B00T - R0024 - Movement (4.57 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
B00T - R0025 - Lift (2.1 m2)						
No Asbestos						
B00T - R0026 - Seminar (9.68 m2)						
No Asbestos						
B00T - R0027 - Careers Advisers Office (21.97 m2)						
Decorative Coating	Vermiculite					
	8195/B00T/R0027/Decorative Coating/S19					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00T - R0028 - Movement (43.47 m2)						
No Asbestos						
B00T - R0034 - General Learning Space (76.71 m2)						
No Asbestos						
B00T - R0035 - Workshop Area (134.87 m2)						
No Asbestos						
B00T - R1001 - Distribution Board Cupboard (1.06 m2)					Note: No inspection of live electrical installation.	
No Asbestos						
B00T - R1002 - Staff Study (38.8 m2)						
No Asbestos						
B00T - R1005 - Food Technology L.S. (104.63 m2)						
No Asbestos						
B00T - R1006 - Laundry (15.45 m2)						
No Asbestos						
B00T - R1007 - Pantry (5.08 m2)						
No Asbestos						
B00T - R1010 - Food Technology L.S. (78.75 m2)						
No Asbestos						
B00T - R1012 - Computer Learning Space (63.79 m2)						
No Asbestos						
B00T - R1013 - Resources Store (3.89 m2)						
No Asbestos						
B00T - R1014 - Materials Technology L.S. (64.3 m2)						
No Asbestos						
B00T - R1015 - Resources Store (8.28 m2)						
No Asbestos						
B00T - R1017 - Materials Technology L.S. (51.62 m2)						
No Asbestos						
B00T - R1020 - Movement (195.82 m2)						
No Asbestos						
B00T - R1021 - Computer Learning Space (77.18 m2)						
No Asbestos						
B00T - R1022 - Stairs (20.17 m2)						
No Asbestos						
B00T - R1023 - Stairs (18.37 m2)						
No Asbestos						
B00T - R1024 - Computer Resource (11.17 m2)						
No Asbestos						
B00T - R1025 - Shower/Change (13.84 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00T - R1026 - Preparation - Materials (26.06 m2)

No Asbestos

B00T - R1027 - Movement (4.57 m2)

No Asbestos

B00T - R1028 - Lift (2.1 m2)

No Asbestos

B00T - R1029 - Movement (7.08 m2)

No Asbestos

B00T - R1030 - Toilet - Lobby (1.97 m2)

Decorative Coating Vermiculite
8195/B00T/R1030/Decorative Coating/S20

Limited Samples Taken

Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00T - R1031 - Staff - Toilet (1.96 m2)

No Asbestos

B00T - R1032 - Staff - Toilet (1.94 m2)

No Asbestos

B00T - R1033 - Toilet - Lobby (1.95 m2)

Decorative Coating Vermiculite
8195/B00T/R1033/Decorative Coating/S21

Limited Samples Taken

Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00U - Building Services - 1999 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00U - R0001 - Garden Store Room (35.34 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00V - General Learning - 2007 - Steel (Steel)

Exterior

Ceiling voids No Asbestos Found

Underfloor Voids No Asbestos Found

Interior

B00V - R0001 - Aboriginal Resource Centre (63.69 m2)

No Asbestos

B00V - R0002 - External Movement (5.28 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00W - General Learning/Technological - 2008 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior**B00W - R0001 - Workshop (152.35 m2)**

No Asbestos

B00W - R0002 - Store (5.17 m2)

No Asbestos

B00W - R0003 - Toilets-Disabled (5.17 m2)

No Asbestos

B00W - R0004 - Distribution Board Cupboard (2.29 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00W - R0005 - Plant (2.13 m2)

No Asbestos

B00W - R0006 - Kitchen - Type 1 (108.85 m2)

No Asbestos

B00W - R0007 - Materials Store - Type 1 (14.48 m2)

No Asbestos

B00W - R0008 - Pantry (13.88 m2)

No Asbestos

B00W - R0009 - Preparation (14.48 m2)

No Asbestos

B00W - R0010 - Distribution Board Cupboard (0.81 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00W - R0011 - Covered Outdoor Space (31.45 m2)

No Asbestos

B00W - R0013 - Covered Area (96.75 m2)

No Asbestos

B00W - R0014 - Materials Store (1.12 m2)

No Asbestos

B00W - R0015 - Materials Store (1.18 m2)

No Asbestos

B00W - R0016 - Materials Store (1.47 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00X - General Learning - 2008 - Concrete (Concrete)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior**B00X - R0001 - External Movement (4.39 m2)**

No Asbestos

B00X - R0002 - Movement (14.05 m2)

No Asbestos

B00X - R0003 - General Learning Space (51.45 m2)

No Asbestos

B00X - R0004 - Practical Activities (32.43 m2)

No Asbestos

B00X - R0005 - Staff Kitchen (4.69 m2)

No Asbestos

B00X - R0006 - Staff - Toilet (4.23 m2)

No Asbestos

B00X - R0007 - G.L.S. Store (2.18 m2)

No Asbestos

B00X - R0008 - Movement (5.94 m2)

No Asbestos

B00X - R0009 - General Learning Space (88.01 m2)

No Asbestos

B00X - R0010 - Stairs (2.18 m2)

No Asbestos

B00X - R1001 - Commonroom (63.24 m2)

No Asbestos

B00X - R1002 - Practical Activities (19.81 m2)

No Asbestos

B00X - R1003 - Stairs (4.41 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

BTAS - Technological & Applied Studies - 1985 - Steel Framed (Steel Framed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

BTAS - R0003 - Workshop Area (64 m2)

No Asbestos

BTAS - R0004 - Growing/Breeding (30.9 m2)

No Asbestos

BTAS - R0005 - Covered Area (8.82 m2)

No Asbestos

BTAS - R0006 - Workshop Area (110.69 m2)

No Asbestos

BTAS - R0007 - Growing/Breeding (72.53 m2)

No Asbestos

BTAS - R0008 - Sport Equipment Store (6.58 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Build+1 - Block W

Exterior

No Asbestos

Interior

Build+1 - Room+1 - all Rooms

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Build+2 - Blue Building

Exterior

No Asbestos

Interior

Build+2 - Room+1 - Room 1

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017