

# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Birrong Boys High School (8213)  
**Region :** South Western Sydney  
**State Electorate :** Bankstown  
**Local Government Area :** Bankstown

**Initial Survey :** Noel Arnold & Associates : 11 - Mar - 2008  
**Reviewed By :** Parsons Brinckerhoff : 11 - Sep - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - General Learning/Science Learning - 1958 - Concrete Framed (Concrete Framed)****Exterior**

Gable Verge Lining	Flat AC Sheeting	20m	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - No Access Due To Height</b>						
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Non Accessible Area - No Access Gate Welded					

**Interior****B00A - R0001 - Laboratory L.S. (93 m2)**

No Asbestos

**B00A - R0002 - Preparation - Science (24.09 m2)**

No Asbestos

**B00A - R0003 - Apparatus Store (13.86 m2)**

No Asbestos

**B00A - R0004 - General Learning Space (42.26 m2)**

No Asbestos

**B00A - R0005 - Interview/Office - Type 1 (17.64 m2)**

No Asbestos

**B00A - R0006 - Cleaning Store - Distributed (3.69 m2)**

No Asbestos

**B00A - R0007 - Computer Learning Space (41.92 m2)**

No Asbestos

**B00A - R0008 - Preparation - Science (18.76 m2)**

No Asbestos

**B00A - R0009 - General Storeroom (18.73 m2)**

No Asbestos

**B00A - R0010 - Laboratory L.S. (93.47 m2)**

No Asbestos

**B00A - R0011 - Movement (42.84 m2)**

No Asbestos

**B00A - R0012 - Movement (26.97 m2)**

No Asbestos

**B00A - R0013 - Archive Store (18.57 m2)**

No Asbestos

**B00A - R0014 - Staff - Toilet (6.83 m2)**

No Asbestos

**B00A - R0015 - Movement (24.12 m2)**

No Asbestos

**B00A - R0016 - Stairs (3.18 m2)**

No Asbestos

**B00A - R0017 - External Movement (2.86 m2)**

No Asbestos

**B00A - R0018 - External Movement (3 m2)**

No Asbestos

**B00A - R0019 - External Movement (2.95 m2)**

No Asbestos

**B00A - R0020 - External Movement (2.95 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

**B00A - R0021 - Printing/Photocopying (3.63 m2)**

No Asbestos

**B00A - R1001 - General Learning Space (64.8 m2)**

No Asbestos

**B00A - R1002 - General Learning Space (65.27 m2)**

No Asbestos

**B00A - R1003 - General Learning Space (65.34 m2)**

No Asbestos

**B00A - R1004 - General Learning Space (51.91 m2)**

No Asbestos

**B00A - R1005 - General Learning Space (51.91 m2)**

No Asbestos

**B00A - R1006 - Computer Learning Space (65.07 m2)**

No Asbestos

**B00A - R1007 - Movement (60.35 m2)**

No Asbestos

**B00A - R1008 - Resources Store (18.76 m2)**

No Asbestos

**B00A - R1009 - Movement (20.8 m2)**

No Asbestos

**B00A - R1010 - Resources Store (18.61 m2)**

No Asbestos

**B00A - R1011 - Stairs (13.49 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - General Learning/Staff Facilities - 1959 - Concrete Framed (Concrete Framed)****Exterior**

Gable Verge Lining	Flat AC Sheeting	20m	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - No Access Due To Height</b>						
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Flat AC Sheeting Debris	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8213/B00B/Underfloor Voids/S17				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Underfloor Voids	Packing To Stumps Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8213/B00B/Underfloor Voids/S18				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**Interior****B00B - R0001 - Staff - Toilet (6.85 m2)**

No Asbestos

**B00B - R0002 - Movement (21.43 m2)**

No Asbestos

**B00B - R0004 - Staff Kitchen (9.17 m2)**

No Asbestos

**B00B - R0006 - Resources Store (10.45 m2)**

No Asbestos

**B00B - R0007 - General Learning Space (64.33 m2)**

No Asbestos

**B00B - R0008 - Movement (15.41 m2)**

No Asbestos

**B00B - R0010 - Distribution Board Cupboard (1.1 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B00B - R0011 - Cleaning Store - Distributed (1.09 m2)**

No Asbestos

**B00B - R0012 - Stairs (3.22 m2)**

No Asbestos

**B00B - R0013 - Stairs (6.04 m2)**

No Asbestos

**B00B - R0014 - External Movement (3.95 m2)**

No Asbestos

**B00B - R0015 - External Movement (3.99 m2)**

No Asbestos

**B00B - R0017 - Commonroom (112.81 m2)**

No Asbestos

**B00B - R0018 - Movement (28.16 m2)**

Infills Below Window Flat AC Sheeting  
8213/B00B/R0018/Infills Below Window/S19

**No Asbestos Detected****B00B - R0019 - Movement (20.37 m2)**

Wall Linings Internal Flat AC Sheeting  
8213/B00B/R0019/Wall Linings Internal/S20

**No Asbestos Detected****B00B - R0020 - Staff Study (37.94 m2)**

No Asbestos

**B00B - R0021 - Tea Room (5.02 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No						Test Result
No Asbestos						
<b>B00B - R1002 - Movement (14.89 m2)</b>						
No Asbestos						
<b>B00B - R1005 - General Learning Space (51.98 m2)</b>						
No Asbestos						
<b>B00B - R1006 - General Learning Space (65.41 m2)</b>						
No Asbestos						
<b>B00B - R1007 - General Learning Space (66.08 m2)</b>						
No Asbestos						
<b>B00B - R1008 - Cleaning Store - Distributed (1.18 m2)</b>						
No Asbestos						
<b>B00B - R1009 - Cleaning Store - Distributed (1.18 m2)</b>						
No Asbestos						
<b>B00B - R1010 - Deputy Principal Office (15.83 m2)</b>						
No Asbestos						
<b>B00B - R1011 - Movement (70.22 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	72m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8213/B00B/R1011/Floor Coverings Res/Textile/S16						<b>Chrysotile (white asbestos)</b>
<b>B00B - R1012 - Stairs (13.57 m2)</b>						
No Asbestos						
<b>B00B - R1013 - Stairs (18.24 m2)</b>						
No Asbestos						
<b>B00B - R1014 - Tea Room (8.04 m2)</b>						
No Asbestos						
<b>B00B - R1015 - Staff Study (16.87 m2)</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - General Learning - 1959 - Concrete Framed (Concrete Framed)****Exterior**

Gable Verge Lining	Flat AC Sheeting	20m	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - No Access Due To Height</b>						
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Non Accessible Area - No Access Gate Welded					

**Interior****B00C - R0002 - General Storeroom (3.82 m2)**

No Asbestos

**B00C - R0003 - Movement (37.99 m2)**

No Asbestos

**B00C - R0004 - Staff - Toilet (6.81 m2)**

No Asbestos

**B00C - R0005 - General Learning Space (64.47 m2)**

No Asbestos

**B00C - R0006 - General Learning Space (65.09 m2)**

No Asbestos

**B00C - R0007 - General Learning Space (78.41 m2)**

No Asbestos

**B00C - R0008 - Resources Store (3.13 m2)**

No Asbestos

**B00C - R0009 - General Storeroom (3.13 m2)**

No Asbestos

**B00C - R0010 - Movement (54.66 m2)**

No Asbestos

**B00C - R0011 - Sport Equipment Store (9.1 m2)**

No Asbestos

**B00C - R0012 - Tea Room (9.13 m2)**

No Asbestos

**B00C - R0013 - Movement (2.96 m2)**

No Asbestos

**B00C - R0014 - General Learning Space (81.45 m2)**

No Asbestos

**B00C - R0015 - Resources Store (7.61 m2)**

No Asbestos

**B00C - R0016 - Cleaning Supplies Store (4.56 m2)**

No Asbestos

**B00C - R0017 - Movement (31.82 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	32m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8213/B00C/R1007/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	

**B00C - R0018 - Stairs (3.35 m2)**

No Asbestos

**B00C - R0019 - External Movement (2.96 m2)**

No Asbestos

**B00C - R0020 - External Movement (2.88 m2)**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00C - R0021 - Cleaning Store - Distributed (2.09 m2)</b>						
No Asbestos						
<b>B00C - R0022 - Other-Vacant (1 m2)</b>						
No Asbestos						
<b>B00C - R1001 - Resources Store (19.38 m2)</b>						
No Asbestos						
<b>B00C - R1002 - Movement (20.59 m2)</b>						
No Asbestos						
<b>B00C - R1004 - General Learning Space (65.32 m2)</b>						
No Asbestos						
<b>B00C - R1005 - General Learning Space (65.25 m2)</b>						
No Asbestos						
<b>B00C - R1006 - General Learning Space (51.91 m2)</b>						
No Asbestos						
<b>B00C - R1007 - Movement (48.87 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	50m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8213/B00C/R1007/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	
<b>B00C - R1008 - General Storeroom (19.12 m2)</b>						
No Asbestos						
<b>B00C - R1009 - General Storeroom (2.94 m2)</b>						
No Asbestos						
<b>B00C - R1010 - Cleaning Store - Distributed (2.96 m2)</b>						
No Asbestos						
<b>B00C - R1011 - Seminar (91.96 m2)</b>						
No Asbestos						
<b>B00C - R1012 - General Storeroom (6.12 m2)</b>						
No Asbestos						
<b>B00C - R1013 - Movement (38.22 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	39m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8213/B00C/R1007/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	
<b>B00C - R1014 - Stairs (13.5 m2)</b>						
No Asbestos						
<b>B00C - R1015 - Tea Room (6.52 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8213/B00C/R1015/Floor Coverings Res/Textile/S21					<b>Chrysotile (white asbestos)</b>	
<b>B00C - R1016 - Staff Study (18.74 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8213/B00C/R1016/Floor Coverings Res/Textile/S22					<b>Chrysotile (white asbestos)</b>	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - Administration/General Learning - 1958 - Concrete Framed (Concrete Framed)****Exterior**

Gable Verge Lining	Flat AC Sheeting	20m	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - No Access Due To Height</b>						
Eaves Linings	Flat AC Sheeting	80m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - No Access Due To Height</b>						
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Debris Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8213/B00D/Underfloor Voids/S23					<b>Chrysotile (white asbestos)</b>
Underfloor Voids	Packing To Stumps Flat AC Sheeting					<b>No Asbestos Detected</b>
	8213/B00D/Underfloor Voids/S24					

**Interior****B00D - R0030 - External Movement (14.11 m2)**

No Asbestos

**B00D - R0031 - Public Reception (26.06 m2)**

No Asbestos

**B00D - R0032 - Clinic - Boys (10.28 m2)**

No Asbestos

**B00D - R0033 - Movement (37.35 m2)**

No Asbestos

**B00D - R0034 - Deputy Principal Office (20.72 m2)**

No Asbestos

**B00D - R0035 - Leading Teacher (14.02 m2)**

No Asbestos

**B00D - R0036 - Deputy Principal Office (20.94 m2)**

No Asbestos

**B00D - R0037 - Principal Office (21.13 m2)**

No Asbestos

**B00D - R0038 - General Storeroom (6.35 m2)**

No Asbestos

**B00D - R0039 - Interview/Meeting (25.78 m2)**

No Asbestos

**B00D - R0040 - Staff Kitchen (5.55 m2)**

No Asbestos

**B00D - R0041 - General Storeroom (5.56 m2)**

No Asbestos

**B00D - R0042 - Staff - Toilet (11.43 m2)**

No Asbestos

**B00D - R0043 - General Storeroom (8.55 m2)**

No Asbestos

**B00D - R0044 - Office/Store (8.55 m2)**

No Asbestos

**B00D - R0045 - Staff - Toilet (5.51 m2)**

No Asbestos

**B00D - R0046 - Printing/Photocopying (14.89 m2)**

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00D - R0047 - Ancillary Staff (7.91 m2)</b>						
No Asbestos						
<b>B00D - R0048 - Communications Cupboard (5.56 m2)</b>						
No Asbestos						
<b>B00D - R0049 - Student Reception (3.98 m2)</b>						
No Asbestos						
<b>B00D - R0050 - Administration - Clerical (51.14 m2)</b>						
No Asbestos						
<b>B00D - R0051 - External Movement (10.4 m2)</b>						
No Asbestos						
<b>B00D - R1001 - Archive Store (9.13 m2)</b>						
No Asbestos						
<b>B00D - R1002 - General Learning Space (52.06 m2)</b>						
No Asbestos						
<b>B00D - R1004 - Office/Store (17.1 m2)</b>						
No Asbestos						
<b>B00D - R1005 - General Storeroom (7.41 m2)</b>						
No Asbestos						
<b>B00D - R1006 - General Learning Space (52.06 m2)</b>						
No Asbestos						
<b>B00D - R1007 - Computer Learning Space (52.13 m2)</b>						
No Asbestos						
<b>B00D - R1008 - General Storeroom (9.14 m2)</b>						
No Asbestos						
<b>B00D - R1009 - Movement (47.35 m2)</b>						
No Asbestos						
<b>B00D - R1010 - General Learning Space (52.35 m2)</b>						
No Asbestos						
<b>B00D - R1011 - Interview/Office - Type 1 (21.75 m2)</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00E - General Learning - 1966 - Brick/Block (Brick/Block)</b>						
<b>Exterior</b>						
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Non Accessible Area - No Access Gate Welded					
<b>Interior</b>						
<b>B00E - R0001 - General Storeroom (11.57 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8213/B00E/R0007/Ceiling Structures/Linings/S2					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R0002 - Distribution Board Cupboard (1.78 m2)</b> <span style="float: right;">Note: No inspection of live electrical installation.</span>						
Ceiling Structures/Linings	Vermiculite 8213/B00E/R0007/Ceiling Structures/Linings/S2					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R0004 - Sport Equipment Store (4.62 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8213/B00E/R0007/Ceiling Structures/Linings/S2					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R0005 - General Learning Space (64.3 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8213/B00E/R0007/Ceiling Structures/Linings/S2					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R0006 - Resources Store (8.11 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8213/B00E/R0007/Ceiling Structures/Linings/S2					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R0007 - Movement (55.63 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8213/B00E/R0007/Ceiling Structures/Linings/S2					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R0008 - Machine Storage (17.81 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8213/B00E/R0007/Ceiling Structures/Linings/S2					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R0010 - Staff Study (13.56 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8213/B00E/R0007/Ceiling Structures/Linings/S2					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R0011 - Tea Room (2.95 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8213/B00E/R0007/Ceiling Structures/Linings/S2					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R1003 - General Storeroom (22.17 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8213/B00E/R0007/Ceiling Structures/Linings/S2					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles 8213/B00E/R1003/Floor Coverings Res/Textile/S11	22m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
<i>Chrysotile (white asbestos)</i>						
<b>B00E - R1004 - Resources Store (4.67 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8213/B00E/R0007/Ceiling Structures/Linings/S2					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R1005 - General Learning Space (50.26 m2)</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite					
	8213/B00E/R0007/Ceiling Structures/Linings/S2					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R1006 - Resources Store (8.01 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8213/B00E/R0007/Ceiling Structures/Linings/S2					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R1007 - Movement (52.34 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8213/B00E/R0007/Ceiling Structures/Linings/S2					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00E - R1009 - Distribution Board Cupboard (1.71 m2)</b>						
					Note: No inspection of live electrical installation.	
Ceiling Structures/Linings	Vermiculite					
	8213/B00E/R1010/Ceiling Structures/Linings/S25					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Electrical Backing Board	Resinous Board	1m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	8213/B00E/R1009/Electrical Backing Board/S26					Chrysotile (white asbestos)
<b>B00E - R1010 - Movement (11.52 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8213/B00E/R1010/Ceiling Structures/Linings/S25					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - Science Learning/General Learning - 1966 - Brick/Block (Brick/Block)****Exterior**

Gable Verge Lining	Flat AC Sheeting	20m	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - No Access Due To Height</b>						
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior****B00F - M0001 - Staff - Toilet (5.2 m2)**

Ceiling Structures/Linings	Vermiculite					
	8213/B00F/R0006/Ceiling Structures/Linings/S4					Limited Samples Taken
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

Partition Walls (Cubicles)	Compressed AC Sheet	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8213/B00F/M0001/Partition Walls (Cubicles)/S10					Chrysotile (white asbestos)

**B00F - M0002 - Movement (6.31 m2)**

Ceiling Structures/Linings	Vermiculite					
	8213/B00F/R0006/Ceiling Structures/Linings/S4					Limited Samples Taken
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00F - R0003 - Movement (21.18 m2)**

Ceiling Structures/Linings	Vermiculite					
	8213/B00F/R0006/Ceiling Structures/Linings/S4					Limited Samples Taken
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00F - R0004 - Staff Study (25.53 m2)**

Ceiling Structures/Linings	Vermiculite					
	8213/B00F/R0006/Ceiling Structures/Linings/S4					Limited Samples Taken
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00F - R0005 - Laboratory L.S. (89.37 m2)**

Ceiling Structures/Linings	Vermiculite					
	8213/B00F/R0006/Ceiling Structures/Linings/S4					Limited Samples Taken
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00F - R0008 - Apparatus Store (25.7 m2)**

Ceiling Structures/Linings	Vermiculite					
	8213/B00F/R0006/Ceiling Structures/Linings/S4					Limited Samples Taken
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00F - R0009 - Movement (46.52 m2)**

Ceiling Structures/Linings	Vermiculite					
	8213/B00F/R0006/Ceiling Structures/Linings/S4					Limited Samples Taken
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00F - R0010 - Stairs (3.76 m2)**

Ceiling Structures/Linings	Vermiculite					
	8213/B00F/R0006/Ceiling Structures/Linings/S4					Limited Samples Taken
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00F - R0011 - Seminar (38 m2)**

Ceiling Structures/Linings	Vermiculite					
	8213/B00F/R0006/Ceiling Structures/Linings/S4					Limited Samples Taken
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00F - R1001 - Movement (16.53 m2)**

Ceiling Structures/Linings	Vermiculite					
	8213/B00F/R0006/Ceiling Structures/Linings/S4					Limited Samples Taken
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00F - R1002 - Office/Store (21.28 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite	8213/B00F/R0006/Ceiling Structures/Linings/S4				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00F - R1004 - Staff Study (25.13 m2)</b>						
Ceiling Structures/Linings	Vermiculite	8213/B00F/R0006/Ceiling Structures/Linings/S4				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00F - R1005 - General Learning Space (51.19 m2)</b>						
Ceiling Structures/Linings	Vermiculite	8213/B00F/R0006/Ceiling Structures/Linings/S4				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00F - R1006 - General Storeroom (4.41 m2)</b>						
Ceiling Structures/Linings	Vermiculite	8213/B00F/R0006/Ceiling Structures/Linings/S4				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00F - R1008 - Office/Store (4.64 m2)</b>						
Ceiling Structures/Linings	Vermiculite	8213/B00F/R0006/Ceiling Structures/Linings/S4				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00F - R1010 - Movement (55.94 m2)</b>						
Ceiling Structures/Linings	Vermiculite	8213/B00F/R0006/Ceiling Structures/Linings/S4				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00F - R1011 - Stairs (4.05 m2)</b>						
Ceiling Structures/Linings	Vermiculite	8213/B00F/R0006/Ceiling Structures/Linings/S4				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00F - R1012 - Tea Room (3.26 m2)</b>						
Ceiling Structures/Linings	Vermiculite	8213/B00F/R0006/Ceiling Structures/Linings/S4				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00F - R1013 - Staff Shower (33.19 m2)</b>						
Ceiling Structures/Linings	Vermiculite	8213/B00F/R0006/Ceiling Structures/Linings/S4				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00F - R1014 - Staff Study (20.3 m2)</b>						
Ceiling Structures/Linings	Vermiculite	8213/B00F/R0006/Ceiling Structures/Linings/S4				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00F - R1015 - Tea Room (4.99 m2)</b>						
Ceiling Structures/Linings	Vermiculite	8213/B00F/R0006/Ceiling Structures/Linings/S4				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - Music/Science Learning/Art - 1966 - Brick/Block (Brick/Block)****Exterior**

Gable Verge Lining	Flat AC Sheeting	20m	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - No Access Due To Height</b>						
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior****B00G - R0001 - Sport Equipment Store (20.1 m2)**

Ceiling Structures/Linings	Vermiculite	8213/B00G/R0013/Ceiling Structures/Linings/S6				<b>Limited Samples Taken</b>	
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>							

**B00G - R0002 - Movement (20.44 m2)**

Ceiling Structures/Linings	Vermiculite	8213/B00G/R0013/Ceiling Structures/Linings/S6				<b>Limited Samples Taken</b>	
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>							

**B00G - R0005 - Covered Area (134.22 m2)**

No Asbestos

**B00G - R0006 - Laboratory L.S. (91.11 m2)**

Ceiling Structures/Linings	Vermiculite	8213/B00G/R0013/Ceiling Structures/Linings/S6				<b>Limited Samples Taken</b>	
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>							

Hot Metal Workbench	Compressed AC Sheet	3m2	South-west Demonstration Bench	Minimal Damage (2)	Low (1)	Low Priority (2-3)
8213/B00G/R0006/Hot Metal Workbench/S8						<b>Chrysotile (white asbestos)</b>

**B00G - R0009 - Laboratory L.S. (90.68 m2)**

Ceiling Structures/Linings	Vermiculite	8213/B00G/R0013/Ceiling Structures/Linings/S6				<b>Limited Samples Taken</b>	
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>							

**B00G - R0010 - General Storeroom (21.79 m2)**

Ceiling Structures/Linings	Vermiculite	8213/B00G/R0013/Ceiling Structures/Linings/S6				<b>Limited Samples Taken</b>	
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>							

Floor Coverings Res/Textile	Vinyl Tiles	22m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8213/B00G/R0016/Floor Coverings Res/Textile/S5						<b>Chrysotile (white asbestos)</b>

**B00G - R0011 - Distribution Board Cupboard (0.74 m2)**

Note: No inspection of live electrical installation.

Floor Coverings Res/Textile	Vinyl Tiles	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8213/B00G/R0016/Floor Coverings Res/Textile/S5						<b>Chrysotile (white asbestos)</b>

**B00G - R0012 - Movement (54.81 m2)**

Ceiling Structures/Linings	Vermiculite	8213/B00G/R0013/Ceiling Structures/Linings/S6				<b>Limited Samples Taken</b>	
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>							

Floor Coverings Res/Textile	Vinyl Tiles	55m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8213/B00G/R0016/Floor Coverings Res/Textile/S5						<b>Chrysotile (white asbestos)</b>

**B00G - R0013 - Chemical Store (13.79 m2)**

Ceiling Structures/Linings	Vermiculite	8213/B00G/R0013/Ceiling Structures/Linings/S6				<b>Limited Samples Taken</b>	
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>							

**B00G - R0014 - Cleaning Store - Distributed (0.54 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite					
	8213/B00G/R0013/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00G - R0015 - General Storeroom (3.78 m2)</b>						
No Asbestos						
<b>B00G - R0017 - Stairs (4.16 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8213/B00G/R0013/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00G - R0018 - Preparation - Science (38.74 m2)</b>						
No Asbestos						
<b>B00G - R0019 - Movement (19.98 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8213/B00G/R0013/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00G - R0020 - Stairs (0.37 m2)</b>						
No Asbestos						
<b>B00G - R0021 - Movement (6.21 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8213/B00G/R0013/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00G - R0022 - Stairs (0.37 m2)</b>						
No Asbestos						
<b>B00G - R0023 - Staff Shower (5.32 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8213/B00G/R0013/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00G - R1001 - Dark Room (20.13 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8213/B00G/R0013/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00G - R1004 - Movement (16.59 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8213/B00G/R0013/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00G - R1005 - Multi Media Workshop (38.75 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8213/B00G/R0013/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00G - R1006 - General Storeroom (9.51 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8213/B00G/R0013/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00G - R1009 - General Storeroom (3.72 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8213/B00G/R0013/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00G - R1010 - Art Learning Space (51.55 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8213/B00G/R0013/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles	51m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8213/B00G/R0016/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00G - R1011 - Resources Store (7.82 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8213/B00G/R0013/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00G - R1012 - Workshop (26.04 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8213/B00G/R0013/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00G - R1013 - Art Learning Space (64.58 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8213/B00G/R0013/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles	65m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8213/B00G/R0016/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)
<b>B00G - R1014 - Project Store - Type 1 (5.86 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8213/B00G/R0013/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8213/B00G/R0016/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)
<b>B00G - R1015 - Resources Store (5.84 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8213/B00G/R0013/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8213/B00G/R0016/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)
<b>B00G - R1016 - Materials Store (1.81 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8213/B00G/R0013/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00G - R1017 - Distribution Board Cupboard (0.75 m2)</b>					Note: No inspection of live electrical installation.	
No Asbestos						
<b>B00G - R1018 - Movement (104.02 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8213/B00G/R0013/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00G - R1019 - Independent Learning Space (13.89 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8213/B00G/R0013/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00G - R1020 - Cleaning Store - Distributed (0.54 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8213/B00G/R0013/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00G - R1021 - Stairs (7.73 m2)</b>						
No Asbestos						
<b>B00G - R1022 - Stairs (8.74 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8213/B00G/R0013/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00G - R1023 - Fitness Laboratory (90.84 m2)</b>						



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
<b>B00G - R1024 - Movement (16.62 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8213/B00G/R0013/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00G - R1025 - Movement (6.08 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8213/B00G/R0013/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00G - R1026 - Staff - Toilet (5.38 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8213/B00G/R0013/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00G - R2001 - Sport Equipment Store (20.1 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8213/B00G/R0013/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Partition Walls (Cubicles)	Compressed AC Sheet	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8213/B00G/M0001/Partition Walls (Cubicles)/S9					Chrysotile (white asbestos)
<b>B00G - R2002 - Movement (16.83 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8213/B00G/R0013/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00G - R2003 - Art Learning Space (64.42 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8213/B00G/R0013/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles	66m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8213/B00G/R0016/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)
<b>B00G - R2004 - Kiln Space (12.64 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8213/B00G/R0013/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles	13m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8213/B00G/R0016/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)
<b>B00G - R2005 - Design L.S. (12.43 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8213/B00G/R0013/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles	13m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8213/B00G/R0016/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)
<b>B00G - R2006 - Office/Store (12.39 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8213/B00G/R0013/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles	13m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8213/B00G/R0016/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)
<b>B00G - R2007 - Resources Store (12.36 m2)</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite 8213/B00G/R0013/Ceiling Structures/Linings/S6					Limited Samples Taken <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
Floor Coverings Res/Textile	Vinyl Tiles 8213/B00G/R0016/Floor Coverings Res/Textile/S5	13m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00G - R2010 - Music Learning Space (51.12 m2)</b>						
No Asbestos						
<b>B00G - R2011 - Music Store (5.98 m2)</b>						
No Asbestos						
<b>B00G - R2012 - Practice/Seminar (51.19 m2)</b>						
No Asbestos						
<b>B00G - R2013 - Music Learning Space (50.48 m2)</b>						
No Asbestos						
<b>B00G - R2014 - Resources Store (8.62 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8213/B00G/R0013/Ceiling Structures/Linings/S6					Limited Samples Taken <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
<b>B00G - R2015 - Distribution Board Cupboard (0.73 m2)</b>						
No Asbestos						
<b>B00G - R2016 - General Storeroom (5.01 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8213/B00G/R0013/Ceiling Structures/Linings/S6					Limited Samples Taken <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
<b>B00G - R2017 - Cleaning Store - Distributed (0.54 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8213/B00G/R0013/Ceiling Structures/Linings/S6					Limited Samples Taken <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
<b>B00G - R2018 - Movement (103.7 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8213/B00G/R0013/Ceiling Structures/Linings/S6					Limited Samples Taken <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
<b>B00G - R2019 - Stairs (3.94 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8213/B00G/R0013/Ceiling Structures/Linings/S6					Limited Samples Taken <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
<b>B00G - R2020 - Stairs (4.14 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8213/B00G/R0013/Ceiling Structures/Linings/S6					Limited Samples Taken <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
<b>B00G - R2021 - Careers Advisers Office (31.71 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8213/B00G/R0013/Ceiling Structures/Linings/S6					Limited Samples Taken <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - Library - 1981 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting	100m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	8213/B00H/Eaves Linings/S27					<b>Chrysotile (white asbestos)</b>
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior****B00H - R0001 - External Movement (21.84 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	21m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8213/B00H/R0001/Ceiling Structures/Linings/S28					<b>Chrysotile (white asbestos)</b>

**B00H - R0002 - Main Entry (11.42 m2)**

No Asbestos

**B00H - R0004 - Librarian (14.26 m2)**

No Asbestos

**B00H - R0005 - Audio Visual Workroom (33.97 m2)**

No Asbestos

**B00H - R0006 - Distribution Board Cupboard (0.76 m2)**

Note: No inspection of live electrical installation.

Electrical Mounting Board	Resinous Board					
	8213/B00H/R0006/Electrical Mounting Board/S29					<b>No Asbestos Detected</b>

**B00H - R0007 - Senior Study (10.76 m2)**

No Asbestos

**B00H - R0008 - Office/Store (10.82 m2)**

No Asbestos

**B00H - R0009 - Interview/Office - Type 1 (10.52 m2)**

No Asbestos

**B00H - R0010 - Staff - Toilet (4.12 m2)**

No Asbestos

**B00H - R0011 - Staff - Toilet (4.07 m2)**

No Asbestos

**B00H - R0012 - Main Area (322.4 m2)**

No Asbestos

**B00H - R0013 - External Stairs (5.76 m2)**

No Asbestos

**B00H - R0014 - Library Administration (28.7 m2)**

No Asbestos

**B00H - R0015 - Tea Room (5.34 m2)**

No Asbestos

**B00H - R9001 - Covered Area (278.52 m2)**

No Asbestos

**B00H - R9002 - Stairs (6.25 m2)**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B001 - Multi Purpose Facilities/Pupil Facilities - 1978 - Brick/Block (Brick/Block)****Exterior**

Gable Verge Lining	Flat AC Sheeting	60m	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	8213/B001/Gable Verge Lining/S30					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior****B001 - M0001 - Plant (6.64 m2)**

No Asbestos

**B001 - M0002 - Plant (6.5 m2)**

Electrical Mounting Board	Resinous Board	1Unit	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	8213/B001/M0002/Electrical Mounting Board/S31					<b>Chrysotile (white asbestos)</b>

**B001 - R0001 - Student Canteen (58.99 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	59m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8213/B001/R0001/Floor Coverings Res/Textile/S14					<b>Chrysotile (white asbestos)</b>

Ceiling Structures/Linings	Flat AC Sheeting	59m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8213/B001/R0003/Ceiling Structures/Linings/S15					<b>Chrysotile (white asbestos)</b>

**B001 - R0002 - Office/Store (3.54 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8213/B001/R0001/Floor Coverings Res/Textile/S14					<b>Chrysotile (white asbestos)</b>

Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8213/B001/R0003/Ceiling Structures/Linings/S15					<b>Chrysotile (white asbestos)</b>

**B001 - R0003 - Staff - Toilet (2.32 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8213/B001/R0001/Floor Coverings Res/Textile/S14					<b>Chrysotile (white asbestos)</b>

Ceiling Structures/Linings	Flat AC Sheeting	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8213/B001/R0003/Ceiling Structures/Linings/S15					<b>Chrysotile (white asbestos)</b>

**B001 - R0004 - Covered Area (64.64 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	63m2	All surfaces	Some Damage / Unsealed (3)	Medium (2)	Low Priority (2-3)
	8213/B001/R0004/Ceiling Structures/Linings/S13					<b>Chrysotile (white asbestos)</b>

**B001 - R0006 - Chair Store (42.64 m2)**

No Asbestos

**B001 - R0007 - Toilets-Boys (7.67 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8213/B001/R0003/Ceiling Structures/Linings/S15					<b>Chrysotile (white asbestos)</b>

**B001 - R0008 - General Storeroom (8.74 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8213/B001/R0001/Floor Coverings Res/Textile/S14					<b>Chrysotile (white asbestos)</b>

Ceiling Structures/Linings	Flat AC Sheeting	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8213/B001/R0003/Ceiling Structures/Linings/S15					<b>Chrysotile (white asbestos)</b>

**B001 - R0009 - Change (32.6 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Ceiling Structures/Linings	Flat AC Sheeting	34m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8213/B001/R0003/Ceiling Structures/Linings/S15				<b>Chrysotile (white asbestos)</b>		
<b>B001 - R0011 - Movement (2.31 m2)</b>						
No Asbestos						
<b>B001 - R0012 - Stage (52.92 m2)</b>						
No Asbestos						
<b>B001 - R0013 - Movement (2.33 m2)</b>						
No Asbestos						
<b>B001 - R0014 - Change (32.64 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	34m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8213/B001/R0003/Ceiling Structures/Linings/S15				<b>Chrysotile (white asbestos)</b>		
<b>B001 - R0015 - Staff Shower (8.74 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8213/B001/R0001/Floor Coverings Res/Textile/S14				<b>Chrysotile (white asbestos)</b>		
Ceiling Structures/Linings	Flat AC Sheeting	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8213/B001/R0003/Ceiling Structures/Linings/S15				<b>Chrysotile (white asbestos)</b>		
<b>B001 - R0016 - Toilets-Girls (7.75 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8213/B001/R0003/Ceiling Structures/Linings/S15				<b>Chrysotile (white asbestos)</b>		
<b>B001 - R0017 - Cleaning Store - Distributed (1.38 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8213/B001/R0017/Ceiling Structures/Linings/S32				<b>Chrysotile (white asbestos)</b>		
<b>B001 - R0019 - Sport Equipment Store (21.62 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	22m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8213/B001/R0003/Ceiling Structures/Linings/S15				<b>Chrysotile (white asbestos)</b>		
<b>B001 - R0020 - External Movement (7.11 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8213/B001/R0017/Ceiling Structures/Linings/S32				<b>Chrysotile (white asbestos)</b>		
<b>B001 - R0021 - Distribution Board Cupboard (1.08 m2)</b>				Note: No inspection of live electrical installation.		
No Asbestos						
<b>B001 - R0022 - External Movement (7.03 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8213/B001/R0017/Ceiling Structures/Linings/S32				<b>Chrysotile (white asbestos)</b>		
<b>B001 - R0023 - External Movement (1.78 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8213/B001/R0017/Ceiling Structures/Linings/S32				<b>Chrysotile (white asbestos)</b>		
<b>B001 - R0024 - External Movement (1.77 m2)</b>						
Ceiling Structures/Linings	Fibre Cement Casting (Monocrete)	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8213/B001/R0017/Ceiling Structures/Linings/S32				<b>Chrysotile (white asbestos)</b>		
<b>B001 - R0025 - Multi-Purpose Space (462.38 m2)</b>						
No Asbestos						
<b>B001 - R0026 - Movement (18.34 m2)</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8213/B001/R0017/Ceiling Structures/Linings/S32					Chrysotile (white asbestos)	
<b>B001 - R0027 - Movement (18.69 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8213/B001/R0017/Ceiling Structures/Linings/S32					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00J - Technological & Applied Studies - 1957 - Brick/Block (Brick/Block)****Exterior**

Gable Verge Lining	Flat AC Sheeting	20m	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	8213/B00J/Gable Verge Lining/S33				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
Underfloor Voids	No Asbestos Found					
Ceiling Voids	Flat AC Sheeting	NA	Old FCS Ceiling Lining	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8213/B00J/Ceiling Voids/S41				<b>Chrysotile (white asbestos)</b>	

**Interior****B00J - R0002 - Materials Store (16.77 m2)**

No Asbestos

**B00J - R0003 - Dust Extraction Space (4.12 m2)**

No Asbestos

**B00J - R0004 - Materials Store (13.78 m2)**

No Asbestos

**B00J - R0005 - Movement (16.6 m2)**

No Asbestos

**B00J - R0006 - Wood Technology L.S. (130.87 m2)**

No Asbestos

**B00J - R0007 - Materials Store (6.11 m2)**

No Asbestos

**B00J - R0008 - Resources Store (6.12 m2)**

No Asbestos

**B00J - R0010 - Resources Store (6.11 m2)**

No Asbestos

**B00J - R0011 - General Learning Space (51.98 m2)**

No Asbestos

**B00J - R0012 - Resources Store (6.12 m2)**

No Asbestos

**B00J - R0015 - Movement (33.15 m2)**

Wall Linings Internal	Flat AC Sheeting					
	8213/B00J/R0015/Wall Linings Internal/S12				<b>No Asbestos Detected</b>	

**B00J - R0016 - Staff - Toilet (5.29 m2)**

No Asbestos

**B00J - R0017 - Cleaning Store - Distributed (1.53 m2)**

No Asbestos

**B00J - R0018 - Resources Store (2.58 m2)**

No Asbestos

**B00J - R0019 - Staff Study (16.31 m2)**

No Asbestos

**B00J - R0020 - Tea Room (2.08 m2)**

No Asbestos

**B00J - R0021 - General Learning Space (51.47 m2)**

No Asbestos

**B00J - R0022 - Handwashing Facilities (0.55 m2)**

No Asbestos

**B00J - R0023 - Wood Technology L.S. (74.75 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	<b>Sample No</b>					<b>Test Result</b>

No Asbestos

**B00J - R0024 - Handwashing Facilities (0.56 m2)**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00K - Technological & Applied Studies - 1957 - Brick/Block (Brick/Block)****Exterior**

Gable Verge Lining	Flat AC Sheeting	20m	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	8213/B00K/Gable Verge Lining/S34			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Ceiling Voids	Flat AC Sheeting Debris	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8213/B00K/Ceiling Voids/S35			<b>Chrysotile (white asbestos)</b>		
Ceiling Voids	Flat AC Sheeting Roof Lining	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8213/B00K/Ceiling Voids/S36			<b>Chrysotile (white asbestos)</b>		
Underfloor Voids	No Asbestos Found					

**Interior****B00K - R0002 - Resources Store (12.67 m2)**

No Asbestos

**B00K - R0003 - Welding Area (25.45 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	26m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8213/B00K/R0003/Ceiling Structures/Linings/S37			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00K - R0005 - General Storeroom (12.57 m2)**

No Asbestos

**B00K - R0006 - Movement (12.24 m2)**

No Asbestos

**B00K - R0009 - Main Switchroom (12.5 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	13m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8213/B00K/R0009/Ceiling Structures/Linings/S38			<b>Chrysotile (white asbestos)</b>		

**B00K - R0010 - Materials Store (21.65 m2)**

No Asbestos

**B00K - R0011 - Preparation - Materials (20.77 m2)**

No Asbestos

**B00K - R0012 - Food Technology L.S. (117.9 m2)**

No Asbestos

**B00K - R0013 - Class Tools Storage (11.63 m2)**

No Asbestos

**B00K - R0014 - Laundry (8.4 m2)**

No Asbestos

**B00K - R0015 - Pantry (20.29 m2)**

No Asbestos

**B00K - R0016 - Metal Technology L.S. (63.7 m2)**

No Asbestos

**B00K - R0017 - Handwashing Facilities (0.57 m2)**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00L - Building Services - 1957 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting 8213/B00L/Eaves Linings/S39					<b>No Asbestos Detected</b>
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior**

**B00L - R0002 - General Storeroom (18.29 m2)**

No Asbestos

**B00L - R0003 - General Storeroom (18.74 m2)**

No Asbestos

**B00L - R0004 - General Assistants (43.94 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00M - Pupil Facilities - 1960 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting 8213/B00M/Eaves Linings/S40					<b>No Asbestos Detected</b>
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior**

**B00M - R0001 - Toilets-Boys (81.35 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00Z - Building Services - 2000 - Brick/Block (Brick/Block)**

**Exterior**

No Asbestos

**Interior**

**B00Z - R0001 - Plant (5.74 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Demountables***

**There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017