

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Bass High School (8223)
Region : South Western Sydney
State Electorate : Bankstown
Local Government Area : Bankstown

Initial Survey : Noel Arnold & Associates : 04 - Apr - 2008
Reviewed By : Greencap-NAA : 13 - Aug - 2014



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/General Learning/Support Unit - 1959 - Concrete Framed (Concrete Framed)

Exterior

Eaves Linings	Flat AC Sheeting	14m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
---------------	------------------	------	--------------	--------------------	---------	--------------------

Assumed Asbestos - Inaccessible - Height restricted.

Underfloor Voids	No Asbestos Found
------------------	-------------------

Ceiling Voids	No Asbestos Found
---------------	-------------------

Infil panels	Flat AC Sheeting 8223/B00A/R1014/In-fill-panel/S4					No Asbestos Detected
--------------	--	--	--	--	--	-----------------------------

Interior

B00A - R0001 - Cleaning Store - Distributed (0.87 m2)

Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	-----	------------	--------------------	---------	--------------------

8223/B00A/R0001/Ceiling Structures/Linings/S19 **Chrysotile (white asbestos) , Amosite (brown asbestos)**

B00A - R0002 - Resources Store (0.89 m2)

Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	-----	------------	--------------------	---------	--------------------

8223/B00A/R0001/Ceiling Structures/Linings/S19 **Chrysotile (white asbestos) , Amosite (brown asbestos)**

B00A - R0003 - Staff - Toilet (8.54 m2)

No Asbestos

B00A - R0004 - Resources Store (3.79 m2)

No Asbestos

B00A - R0005 - Staff Study (18.58 m2)

Floor Coverings Res/Textile	Millboard					
	8223/B00A/R0005/Floor Coverings Res/Textile/S21					No Asbestos Detected

B00A - R0006 - Special Learning Space (52.13 m2)

No Asbestos

B00A - R0007 - Special Learning Space (51.98 m2)

No Asbestos

B00A - R0008 - Special Learning Space (51.91 m2)

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	52.05m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8223/B00A/R0008/Floor Coverings Res/Textile/S22					Chrysotile (white asbestos)

Floor Coverings Res/Textile	Vinyl tile adhesive					
	8223/B00A/R0008/Floor Coverings Res/Textile/S23					No Asbestos Detected

B00A - R0009 - General Learning Space (51.84 m2)

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	52.27m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8223/B00A/R0008/Floor Coverings Res/Textile/S22					Chrysotile (white asbestos)

Floor Coverings Res/Textile	Vinyl tile adhesive					
	8223/B00A/R0008/Floor Coverings Res/Textile/S23					No Asbestos Detected

B00A - R0011 - Deputy Principal Office (12.57 m2)

No Asbestos

B00A - R0014 - Staff Study (15.87 m2)

No Asbestos

B00A - R0016 - Principal Office (17.61 m2)

No Asbestos

B00A - R0017 - Staff - Toilet (3.45 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
B00A - R0022 - Distribution Board Cupboard (0.85 m2)						
Note: No inspection of live electrical installation.						
Ceiling Structures/Linings	Flat AC Sheeting	1.11m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
8223/B00A/R0001/Ceiling Structures/Linings/S19				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00A - R0025 - Secure Storeroom (8.25 m2)						
No Asbestos						
B00A - R0026 - Staff - Toilet (6.03 m2)						
No Asbestos						
B00A - R0027 - Staff - Toilet (6.19 m2)						
No Asbestos						
B00A - R0028 - Deputy Principal Office (12.6 m2)						
No Asbestos						
B00A - R0030 - Stairs (6.38 m2)						
No Asbestos						
B00A - R0031 - External Movement (13.88 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					
8223/B00A/R0031/Ceiling Structures/Linings/S24				No Asbestos Detected		
B00A - R0032 - Archive Store (2.61 m2)						
No Asbestos						
B00A - R0033 - Public Reception (27.24 m2)						
No Asbestos						
B00A - R0035 - Student Waiting (26.3 m2)						
No Asbestos						
B00A - R0036 - Leading Teacher (9.62 m2)						
No Asbestos						
B00A - R0037 - Deputy Principal Office (9.72 m2)						
No Asbestos						
B00A - R0038 - Clinic - Boys (8.39 m2)						
No Asbestos						
B00A - R0039 - Interview/Office - Type 1 (10.61 m2)						
No Asbestos						
B00A - R0040 - Movement (77.14 m2)						
No Asbestos						
B00A - R0041 - External Movement (233.69 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	24m2	North east	Minimal Damage (2)	Low (1)	Low Priority (2-3)
8223/B00A/R0001/Ceiling Structures/Linings/S19				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00A - R0042 - Administration - Clerical (35.17 m2)						
No Asbestos						
B00A - R0043 - Tea Room (2.42 m2)						
No Asbestos						
B00A - R1001 - Cleaning Store - Distributed (0.99 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8223/B00A/R0001/Ceiling Structures/Linings/S19				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00A - R1002 - Resources Store (0.97 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8223/B00A/R0001/Ceiling Structures/Linings/S19				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00A - R1003 - General Learning Space (52.2 m2)						
Floor Coverings Res/Textile	Millboard					
8223/B00A/R0005/Floor Coverings Res/Textile/S21				No Asbestos Detected		
B00A - R1004 - General Learning Space (51.98 m2)						
No Asbestos						
B00A - R1005 - General Learning Space (52.2 m2)						
No Asbestos						
B00A - R1006 - General Learning Space (51.98 m2)						
No Asbestos						
B00A - R1007 - Multi Media Workshop (24.2 m2)						
Wall Linings Internal	Infill panel					
8223/B00A/R1014/In-fill-panel/S4				No Asbestos Detected		
Wall Linings Internal	Flat AC Sheeting	10m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
8223/B00A/R0001/Ceiling Structures/Linings/S19				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00A - R1008 - Dark Room (27.04 m2)						
In-fill-panel	Flat AC Sheeting					
8223/B00A/R1014/In-fill-panel/S4				No Asbestos Detected		
B00A - R1009 - Art Learning Space (64.02 m2)						
In-fill-panel	Flat AC Sheeting					
8223/B00A/R1014/In-fill-panel/S4				No Asbestos Detected		
B00A - R1010 - General Storeroom (1.03 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8223/B00A/R0001/Ceiling Structures/Linings/S19				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00A - R1011 - Project Store - Type 1 (38.15 m2)						
Floor Coverings Res/Textile	Vinyl Tiles					
8223/B00A/R1011/Floor Coverings Res/Textile/S5				No Asbestos Detected		
B00A - R1012 - Distribution Board Cupboard (0.84 m2)						
				Note: No inspection of live electrical installation.		
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
8223/B00A/R0001/Ceiling Structures/Linings/S19				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00A - R1013 - Art Learning Space (65.67 m2)						
No Asbestos						
B00A - R1014 - Movement (85.93 m2)						
In-fill-panel	Flat AC Sheeting					
8223/B00A/R1014/In-fill-panel/S4				No Asbestos Detected		
B00A - R1015 - Stairs (16.37 m2)						
No Asbestos						
B00A - R1016 - Movement (44.62 m2)						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00B - Technological & Applied Studies/Staff Facilities - 1958 - Concrete Framed (Concrete Framed)

Exterior

Eaves Linings	Flat AC Sheeting	20m2	Northeast, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - No access hight restricted.						
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00B - R0001 - Cleaning Store - Distributed (0.83 m2)

No Asbestos

B00B - R0003 - Staff - Toilet (6.67 m2)

No Asbestos

B00B - R0006 - Main Switchroom (4.05 m2)

No Asbestos

B00B - R0012 - Distribution Board Cupboard (1.03 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00B - R0014 - Food Technology L.S. (63.68 m2)

No Asbestos

B00B - R0016 - External Movement (3.51 m2)

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	-----	------------	--------------------	---------	--------------------

8223/B00C/R0027/Ceiling Structures/Linings/S10

Chrysotile (white asbestos) , Amosite (brown asbestos)

B00B - R0017 - Stairs (2.28 m2)

No Asbestos

B00B - R0018 - Movement (5.88 m2)

No Asbestos

B00B - R0019 - Staff Kitchen (11.25 m2)

No Asbestos

B00B - R0020 - Commonroom (74.38 m2)

No Asbestos

B00B - R0021 - Movement (37.31 m2)

No Asbestos

B00B - R0022 - Seminar (25.35 m2)

No Asbestos

B00B - R0023 - Food Technology L.S. (90.51 m2)

No Asbestos

B00B - R0024 - Plant (0.48 m2)

No Asbestos

B00B - R0025 - Laundry (4.24 m2)

No Asbestos

B00B - R0026 - Pantry (7.56 m2)

No Asbestos

B00B - R0027 - Preparation - Materials (24.59 m2)

No Asbestos

B00B - R0028 - Archive Store (3.54 m2)

No Asbestos

B00B - R0029 - Student Reception (13.37 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00B - R0030 - Movement (27.84 m2)						
No Asbestos						
B00B - R1001 - Resources Store (18.23 m2)						
No Asbestos						
B00B - R1008 - General Learning Space (78.3 m2)						
No Asbestos						
B00B - R1009 - Distribution Board Cupboard (0.84 m2)				Note: No inspection of live electrical installation.		
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
8223/B00C/R0027/Ceiling Structures/Linings/S10				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00B - R1010 - Design/Technology L.S. (65.05 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	65.33m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8223/B00B/R1012/Floor Coverings Res/Textile/S25				Chrysotile (white asbestos)		
Floor Coverings Res/Textile	Vinyl tile adhesive					
8223/B00B/R1012/Floor Coverings Res/Textile/S26				No Asbestos Detected		
B00B - R1011 - Resources Store (11.5 m2)						
No Asbestos						
B00B - R1012 - General Storeroom (12.6 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	6.3m2	South	Minimal Damage (2)	Low (1)	Low Priority (2-3)
8223/B00B/R1012/Floor Coverings Res/Textile/S25				Chrysotile (white asbestos)		
Floor Coverings Res/Textile	Vinyl tile adhesive					
8223/B00B/R1012/Floor Coverings Res/Textile/S26				No Asbestos Detected		
B00B - R1013 - Movement (75.94 m2)						
No Asbestos						
B00B - R1014 - Stairs (15.65 m2)						
No Asbestos						
B00B - R1015 - Staff Study (23.74 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	23.74m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8223/B00B/R1012/Floor Coverings Res/Textile/S25				Chrysotile (white asbestos)		
Floor Coverings Res/Textile	Adhesive under tile under carpet					
8223/B00B/R1012/Floor Coverings Res/Textile/S26				No Asbestos Detected		
B00B - R1016 - Tea Room (1.65 m2)						
No Asbestos						
B00B - R1017 - Staff Study (35.53 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	35.53m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8223/B00B/R1012/Floor Coverings Res/Textile/S25				Chrysotile (white asbestos)		
Floor Coverings Res/Textile	Adhesive undee vinyl tile under carpet					
8223/B00B/R1012/Floor Coverings Res/Textile/S26				No Asbestos Detected		
B00B - R1018 - Tea Room (2.79 m2)						
No Asbestos						
B00B - R1019 - General Learning Space (65.18 m2)						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Student Services/General Learning - 1958 - Concrete Framed (Concrete Framed)

Exterior

Eaves Linings	Flat AC Sheeting	20m2	Southwest , southeast, northeast & northwest first floor	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Inaccessible - Height restricted.						
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00C - R0001 - Cleaning Store - Distributed (0.83 m2)

No Asbestos

B00C - R0002 - Movement (45.58 m2)

No Asbestos

B00C - R0003 - Staff - Toilet (6.63 m2)

No Asbestos

B00C - R0004 - Staff Study (24.66 m2)

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	8223/B00C/R0015/Floor Coverings Res/Textile/S11				No Asbestos Detected
-----------------------------	---	---	--	--	--	-----------------------------

B00C - R0005 - Apparatus Store (16.11 m2)

Floor Coverings Res/Textile	Vinyl Tiles	8223/B00C/R0015/Floor Coverings Res/Textile/S11				No Asbestos Detected
-----------------------------	-------------	---	--	--	--	-----------------------------

B00C - R0006 - Preparation - Science (26.2 m2)

Floor Coverings Res/Textile	Vinyl Tiles	8223/B00C/R0015/Floor Coverings Res/Textile/S11				No Asbestos Detected
-----------------------------	-------------	---	--	--	--	-----------------------------

B00C - R0007 - Distribution Board Cupboard (0.73 m2)

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting	0.76m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
8223/B00C/R0027/Ceiling Structures/Linings/S10				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00C - R0008 - Laboratory L.S. (86.99 m2)

No Asbestos

B00C - R0009 - Movement (36.56 m2)

No Asbestos

B00C - R0010 - Sport Equipment Store (8.43 m2)

Ceiling Structures/Linings	Flat AC Sheeting	4m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
8223/B00C/R0027/Ceiling Structures/Linings/S10				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00C - R0011 - Sport Equipment Store (4.5 m2)

No Asbestos

B00C - R0012 - Student Canteen (37.69 m2)

No Asbestos

B00C - R0013 - General Storeroom (2.92 m2)

No Asbestos

B00C - R0014 - Staff - Toilet (1.46 m2)

No Asbestos

B00C - R0015 - Pantry (4.38 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles					
	8223/B00C/R0015/Floor Coverings Res/Textile/S11					No Asbestos Detected
B00C - R0016 - Covered Area (262.86 m2)						
Infill panels	Compressed AC Sheet					
	8223/B00C/R0032/Ceiling Structures/Linings/S27					No Asbestos Detected
B00C - R0017 - Food Technology L.S. (104.76 m2)						
No Asbestos						
B00C - R0019 - Movement (30.99 m2)						
No Asbestos						
B00C - R0021 - Staff - Toilet (6.61 m2)						
No Asbestos						
B00C - R0022 - Cleaning Store - Distributed (0.81 m2)						
No Asbestos						
B00C - R0024 - External Movement (76.76 m2)						
No Asbestos						
B00C - R0025 - External Movement (4.27 m2)						
No Asbestos						
B00C - R0026 - External Movement (3.5 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					
	8223/B00C/R0032/Ceiling Structures/Linings/S27					No Asbestos Detected
B00C - R0027 - External Movement (1.76 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8223/B00C/R0027/Ceiling Structures/Linings/S10					Chrysotile (white asbestos) , Amosite (brown asbestos)
B00C - R0029 - Stairs (2.91 m2)						
No Asbestos						
B00C - R0030 - Stairs (2.54 m2)						
No Asbestos						
B00C - R0031 - Lift (2.09 m2)						
No Asbestos						
B00C - R0032 - External Movement (3.35 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					
	8223/B00C/R0032/Ceiling Structures/Linings/S27					No Asbestos Detected
B00C - R0033 - Toilets-Disabled (10.01 m2)						
No Asbestos						
B00C - R0034 - External Movement (13.13 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					
	8223/B00C/R0032/Ceiling Structures/Linings/S27					No Asbestos Detected
Internal eaves lining	Flat AC Sheeting	2m2	North	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8223/B00C/R0027/Ceiling Structures/Linings/S10					Chrysotile (white asbestos) , Amosite (brown asbestos)
B00C - R0035 - External Movement (4.24 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					
	8223/B00C/R0032/Ceiling Structures/Linings/S27					No Asbestos Detected
B00C - R0036 - Staff Study (21.14 m2)						
No Asbestos						
B00C - R0037 - Tea Room (3.63 m2)						
No Asbestos						
B00C - R0038 - Movement (43.6 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
B00C - R0039 - Resources Store (2.76 m2)						
Recently Modified Space Requires Inspection						
B00C - R1001 - Sport Equipment Store (18.16 m2)						
No Asbestos						
B00C - R1002 - Computer Learning Space (51.91 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8223/B00C/R1002/Floor Coverings Res/Textile/S28	51.76m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive under brown vinyl tile under carpet 8223/B00C/R1002/Floor Coverings Res/Textile/S29					No Asbestos Detected
B00C - R1003 - System Administrators Office (6.05 m2)						
No Asbestos						
B00C - R1004 - Art Learning Space (78.59 m2)						
Floor Coverings Res/Textile	Vinyl Tiles 8223/B00C/R1002/Floor Coverings Res/Textile/S28	78.23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive under vinyl tiles 8223/B00C/R1002/Floor Coverings Res/Textile/S29					No Asbestos Detected
B00C - R1005 - Resources Store (6.12 m2)						
No Asbestos						
B00C - R1006 - General Learning Space (65.18 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8223/B00C/R1002/Floor Coverings Res/Textile/S28	65.35m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive under tile under carpet 8223/B00C/R1002/Floor Coverings Res/Textile/S29					No Asbestos Detected
B00C - R1007 - General Learning Space (51.98 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8223/B00C/R1002/Floor Coverings Res/Textile/S28	52.12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive under tile under carpet 8223/B00C/R1002/Floor Coverings Res/Textile/S29					No Asbestos Detected
B00C - R1008 - Distribution Board Cupboard (0.48 m2)						
Note: No inspection of live electrical installation.						
Floor Coverings Res/Textile	Vinyl Tiles 8223/B00C/R0015/Floor Coverings Res/Textile/S11					No Asbestos Detected
B00C - R1009 - Resources Store (16.23 m2)						
Floor Coverings Res/Textile	Vinyl Tiles 8223/B00C/R1017/Floor Coverings Res/Textile/S2	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00C - R1010 - Staff Study (21.63 m2)						
No Asbestos						
B00C - R1011 - General Learning Space (51.84 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8223/B00C/R1002/Floor Coverings Res/Textile/S28	51.98m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive under tiles under carpet 8223/B00C/R1002/Floor Coverings Res/Textile/S29					No Asbestos Detected
B00C - R1012 - General Learning Space (51.7 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8223/B00C/R1002/Floor Coverings Res/Textile/S28	51.25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive under tiles under carpet. 8223/B00C/R1002/Floor Coverings Res/Textile/S29					No Asbestos Detected
B00C - R1013 - General Learning Space (52.2 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8223/B00C/R1002/Floor Coverings Res/Textile/S28	51.25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Fume Cupboard	Adhesive under tiles under carpet. 8223/B00C/R1002/Floor Coverings Res/Textile/S29					No Asbestos Detected
B00C - R1014 - General Storeroom (5.76 m2)						
Floor Coverings Res/Textile	Vinyl Tiles 8223/B00C/R1017/Floor Coverings Res/Textile/S2	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00C - R1015 - Staff Study (18.65 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8223/B00C/R1017/Floor Coverings Res/Textile/S2	18.56m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8223/B00C/R1002/Floor Coverings Res/Textile/S28	18.56m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00C - R1016 - Resources Store (18.88 m2)						
No Asbestos						
B00C - R1018 - Stairs (15.54 m2)						
No Asbestos						
B00C - R1019 - Stairs (15.41 m2)						
No Asbestos						
B00C - R1020 - Tea Room (4.24 m2)						
Floor Coverings Res/Textile	Vinyl Tiles 8223/B00C/R1002/Floor Coverings Res/Textile/S28	4.24m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Floor Coverings Res/Textile	Adhesive under tiles. 8223/B00C/R1002/Floor Coverings Res/Textile/S29					No Asbestos Detected
B00C - R1021 - Resources Store (6.89 m2)						
No Asbestos						
B00C - R1022 - Movement (160.99 m2)						
No Asbestos						
B00C - Room+1 - Movement, West Adjacent CR0002						
Ceiling Structures/Linings	Flat AC Sheeting 8223/B00A/R0001/Ceiling Structures/Linings/S19	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
B00C - Room+2 - Movement, West Adjacent CR0023						
Ceiling Structures/Linings	Flat AC Sheeting 8223/B00A/R0001/Ceiling Structures/Linings/S19	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00D - Science Learning/General Learning - 1959 - Concrete Framed (Concrete Framed)**Exterior**

Eaves Linings	Flat AC Sheeting	16m2	West, Northeast & Southeast	Good Condition (1)	Low (1)	Low Priority (2-3)
---------------	------------------	------	-----------------------------	--------------------	---------	--------------------

Assumed Asbestos - Inaccessible - Height restricted.

Ceiling Voids	No Asbestos Found
---------------	-------------------

Underfloor Voids	No Asbestos Found
------------------	-------------------

Interior**B00D - R0001 - Cleaning Supplies Store (0.81 m2)**

No Asbestos

B00D - R0002 - Resources Store (0.85 m2)

Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	-----	------------	--------------------	---------	--------------------

8223/B00D/R0002/Ceiling Structures/Linings/S20

Chrysotile (white asbestos) , Amosite (brown asbestos)**B00D - R0003 - Cleaning Store - Distributed (0.87 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
----------------------------	------------------	-----	------------	----------------------------	---------	-----------------------

8223/B00D/R0002/Ceiling Structures/Linings/S20

Chrysotile (white asbestos) , Amosite (brown asbestos)**B00D - R0004 - Movement (51.54 m2)**

No Asbestos

B00D - R0008 - Laboratory L.S. (91.62 m2)

No Asbestos

B00D - R0010 - Archive Store (7.06 m2)

No Asbestos

B00D - R0013 - External Movement (4.29 m2)

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
----------------------------	------------------	-----	------------	--------------------	---------	--------------------

8223/B00D/R0002/Ceiling Structures/Linings/S20

Chrysotile (white asbestos) , Amosite (brown asbestos)**B00D - R0014 - External Movement (4.21 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	-----	------------	--------------------	---------	--------------------

8223/B00D/R0002/Ceiling Structures/Linings/S20

Chrysotile (white asbestos) , Amosite (brown asbestos)**B00D - R0015 - Stairs (6.54 m2)**

No Asbestos

B00D - R0016 - Laboratory L.S. (93.63 m2)

No Asbestos

B00D - R0017 - Preparation - Science (21.05 m2)

No Asbestos

B00D - R0018 - Chemical Store (11.72 m2)

No Asbestos

B00D - R0019 - Distribution Board Cupboard (0.63 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0020 - Staff Study (24.36 m2)

No Asbestos

B00D - R0021 - Movement (36.98 m2)

No Asbestos

B00D - R1001 - Resources Store (18.75 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
B00D - R1002 - General Storeroom (0.87 m2)						
No Asbestos						
B00D - R1003 - Cleaning Store - Distributed (0.94 m2)						
No Asbestos						
B00D - R1004 - Office/Store (19.39 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	8223/B00D/R1005/Floor Coverings Res/Textile/S30					No Asbestos Detected
Floor Coverings Res/Textile	Adhesive under tile under carpet.					
	8223/B00D/R1005/Floor Coverings Res/Textile/S31					No Asbestos Detected
B00D - R1005 - Distribution Board Cupboard (1.05 m2)					Note: No inspection of live electrical installation.	
Floor Coverings Res/Textile	Vinyl Tiles					
	8223/B00D/R1005/Floor Coverings Res/Textile/S30					No Asbestos Detected
Floor Coverings Res/Textile	Adhesive under tiles.					
	8223/B00D/R1005/Floor Coverings Res/Textile/S31					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting	1.05m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8223/B00D/R0002/Ceiling Structures/Linings/S20					Chrysotile (white asbestos) , Amosite (brown asbestos)
B00D - R1006 - Resources Store (2.8 m2)						
Floor Coverings Res/Textile	Vinyl Tiles					
	8223/B00D/R1005/Floor Coverings Res/Textile/S30					No Asbestos Detected
Floor Coverings Res/Textile	Adhesive under tiles					
	8223/B00D/R1005/Floor Coverings Res/Textile/S31					No Asbestos Detected
B00D - R1007 - General Learning Space (38.77 m2)						
No Asbestos						
B00D - R1008 - Resources Store (12.4 m2)						
No Asbestos						
B00D - R1009 - Staff Study (25.38 m2)						
No Asbestos						
B00D - R1010 - General Learning Space (65.27 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	8223/B00D/R1005/Floor Coverings Res/Textile/S30					No Asbestos Detected
Floor Coverings Res/Textile	Adhesive under tiles under carpet					
	8223/B00D/R1005/Floor Coverings Res/Textile/S31					No Asbestos Detected
B00D - R1011 - General Learning Space (52.05 m2)						
No Asbestos						
B00D - R1012 - General Storeroom (6.19 m2)						
Floor Coverings Res/Textile	Vinyl Tiles					
	8223/B00D/R1005/Floor Coverings Res/Textile/S30					No Asbestos Detected
Floor Coverings Res/Textile	Adhesive under tile					
	8223/B00D/R1005/Floor Coverings Res/Textile/S31					No Asbestos Detected
B00D - R1013 - Cleaning Store - Distributed (2.99 m2)						
No Asbestos						
B00D - R1014 - Movement (82.01 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00D - R1015 - Stairs (18.24 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning/Science Learning - 1959 - Concrete Framed (Concrete Framed)**Exterior**

Eaves Linings	Flat AC Sheeting	16m2	North & South first floor eaves.	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Inaccessible - Height restricted.						
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00E - R0001 - Laboratory L.S. (96.44 m2)**

No Asbestos

B00E - R0002 - Preparation - Science (38.39 m2)

No Asbestos

B00E - R0003 - Laboratory L.S. (91.48 m2)

No Asbestos

B00E - R0004 - General Learning Space (50.47 m2)

No Asbestos

B00E - R0005 - Printing/Photocopying (25.74 m2)

Floor Coverings Res/Textile	Vinyl Tiles					
		8223/B00E/R0005/Floor Coverings Res/Textile/S6				No Asbestos Detected

B00E - R0006 - Distribution Board Cupboard (1.05 m2)

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
		8223/B00A/R0001/Ceiling Structures/Linings/S19				Chrysotile (white asbestos) , Amosite (brown asbestos)

B00E - R0007 - Archive Store (11.56 m2)

Floor Coverings Res/Textile	Vinyl Tiles					
		8223/B00E/R0005/Floor Coverings Res/Textile/S6				No Asbestos Detected

B00E - R0008 - Movement (68.86 m2)

No Asbestos

B00E - R1001 - Movement (2.94 m2)

No Asbestos

B00E - R1002 - General Learning Space (65.56 m2)

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
		8223/B00D/R1005/Floor Coverings Res/Textile/S30				No Asbestos Detected

Floor Coverings Res/Textile	Adhesive under tile under carpet.					
		8223/B00D/R1005/Floor Coverings Res/Textile/S31				No Asbestos Detected

B00E - R1003 - Resources Store (6.05 m2)

No Asbestos

B00E - R1004 - Resources Store (6.09 m2)

Floor Coverings Res/Textile	Millboard					
		8223/B00A/R0005/Floor Coverings Res/Textile/S21				No Asbestos Detected

Floor Coverings Res/Textile	Vinyl Tiles					
		8223/B00D/R1005/Floor Coverings Res/Textile/S30				No Asbestos Detected

Floor Coverings Res/Textile	Adhesive under tiles.					
		8223/B00D/R1005/Floor Coverings Res/Textile/S31				No Asbestos Detected

B00E - R1005 - General Learning Space (64.96 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00E - R1006 - General Learning Space (51.98 m2)

No Asbestos

B00E - R1007 - General Learning Space (52.06 m2)

No Asbestos

B00E - R1008 - General Learning Space (52.13 m2)

No Asbestos

B00E - R1009 - Distribution Board Cupboard (1.04 m2)

Note: No inspection of live electrical installation.

Floor Coverings Res/Textile	Vinyl Tiles					
	8223/B00D/R1005/Floor Coverings Res/Textile/S30					No Asbestos Detected

Floor Coverings Res/Textile	Adhesive under tiles.					
	8223/B00D/R1005/Floor Coverings Res/Textile/S31					No Asbestos Detected

Ceiling Structures/Linings	Flat AC Sheeting	0.98m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8223/B00A/R0001/Ceiling Structures/Linings/S19					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00E - R1010 - Resources Store (12.06 m2)

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	8223/B00E/R0005/Floor Coverings Res/Textile/S6					No Asbestos Detected

B00E - R1011 - Movement (71.44 m2)

No Asbestos

B00E - Room+1 - Movement Southeast of E

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Music/Computer Learning - 1959 - Concrete Framed (Concrete Framed)**Exterior**

Eaves Linings	Flat AC Sheeting	56m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
---------------	------------------	------	------------	--------------------	---------	--------------------

Assumed Asbestos - No access , height restricted.

Ceiling Voids	No Asbestos Found
---------------	-------------------

Underfloor Voids	No Asbestos Found
------------------	-------------------

Interior**B00F - R0001 - Movement (6.06 m2)**

No Asbestos

B00F - R0002 - Toilets-Boys (5.8 m2)

Toilet cistern	Compressed AC Sheet	8223/B00F/R0002/Toilet cistern/S32	No Asbestos Detected
----------------	---------------------	------------------------------------	-----------------------------

B00F - R0003 - Resources Store (18.68 m2)

No Asbestos

B00F - R0005 - Movement (6.09 m2)

No Asbestos

B00F - R0006 - Computer Learning Space (25.32 m2)

No Asbestos

B00F - R0007 - Distribution Board Cupboard (0.54 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00F - R0008 - Music Store (15.12 m2)

No Asbestos

B00F - R0009 - Music Learning Space (78.42 m2)

No Asbestos

B00F - R0010 - External Movement (10.45 m2)

No Asbestos

B00F - R0011 - External Movement (1.65 m2)

No Asbestos

B00F - R0012 - General Learning Space (64.92 m2)

Office partition	Compressed AC Sheet	8223/B00F/R0013/Office partition/S33	No Asbestos Detected
------------------	---------------------	--------------------------------------	-----------------------------

B00F - R0013 - Tea Room (3.03 m2)

Office partition	Compressed AC Sheet	8223/B00F/R0013/Office partition/S33	No Asbestos Detected
------------------	---------------------	--------------------------------------	-----------------------------

Floor Coverings Res/Textile	Vinyl Tiles	8223/B00D/R0009/Floor Coverings Res/Textile/S8	No Asbestos Detected
-----------------------------	-------------	--	-----------------------------

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Technological & Applied Studies - 1958 - Concrete Framed (Concrete Framed)**Exterior**

Eaves Linings	Flat AC Sheeting	82m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8223/B00G/Eaves Linings/S34				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					
Infill panels	Flat AC Sheeting	3m2	Western side southern end	Good Condition (1)	Low (1)	Low Priority (2-3)
	8223/B00G/Eaves Linings/S34				Chrysotile (white asbestos) , Amosite (brown asbestos)	

Interior**B00G - R0001 - Movement (6.07 m2)**

No Asbestos

B00G - R0003 - Materials Store (10.4 m2)

No Asbestos

B00G - R0004 - Materials Store (10.53 m2)

No Asbestos

B00G - R0007 - Movement (2.79 m2)

No Asbestos

B00G - R0009 - Resources Store (11.11 m2)

No Asbestos

B00G - R0010 - Dust Extraction Space (3.36 m2)

No Asbestos

B00G - R0011 - External Movement (2.42 m2)

No Asbestos

B00G - R0012 - External Movement (9.87 m2)

Ceiling Structures/Linings Flat AC Sheeting
8223/B00C/R0032/Ceiling Structures/Linings/S27

No Asbestos Detected**B00G - R0013 - Wood Technology L.S. (77.82 m2)**

No Asbestos

B00G - R0014 - Handwashing Facilities (0.6 m2)

No Asbestos

B00G - R0015 - Metal Technology L.S. (72.13 m2)

No Asbestos

B00G - R0016 - Handwashing Facilities (0.61 m2)

No Asbestos

B00G - R0017 - Metal Technology Bay (10.59 m2)

Ceiling Structures/Linings	Flat AC Sheeting	10.59m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8223/B00C/R0027/Ceiling Structures/Linings/S10				Chrysotile (white asbestos) , Amosite (brown asbestos)	

Wall Linings Internal Flat AC Sheeting
8223/B00C/R0032/Ceiling Structures/Linings/S27

No Asbestos Detected**B00G - R0018 - Materials Store (3.07 m2)**

Wall Linings Internal Flat AC Sheeting
8223/B00C/R0032/Ceiling Structures/Linings/S27

No Asbestos Detected**B00G - R0019 - Project Store - Type 1 (6.93 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Ceiling Structures/Linings	Flat AC Sheeting	6.93m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8223/B00C/R0027/Ceiling Structures/Linings/S10			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Wall Linings Internal	Flat AC Sheeting	10m2	North	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8223/B00C/R0027/Ceiling Structures/Linings/S10			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	8223/B00C/R0032/Ceiling Structures/Linings/S27					

B00G - R0020 - Metal Technology L.S. (71.57 m2)

No Asbestos

B00G - R0021 - Handwashing Facilities (0.47 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Pupil Facilities - 1958 - Concrete Framed (Concrete Framed)**Exterior**

Eaves Linings	Compressed AC	5m2	North, northeast & southwest	Some Damage / Unsealed (3)	Medium (2)	Low Priority (2-3)
	8223/B00H/Eaves Linings/S35				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Voids	Non Accessible Area - No ceiling void opening sighted.					
Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	41m2	Throughout except North, NE & SW	Good Condition (1)	Low (1)	Low Priority (2-3)
	8223/B00G/Eaves Linings/S34				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Roof	Black membrane					No Asbestos Detected
	8223/B00H/Roof/S36					

Interior**B00H - R0001 - General Assistants (19.09 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	19.07m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8223/B00C/R0027/Ceiling Structures/Linings/S10				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00H - R0003 - Change (29.45 m2)

Ceiling Structures/Linings	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8223/B00C/R0027/Ceiling Structures/Linings/S10				Chrysotile (white asbestos) , Amosite (brown asbestos)	

Partition Walls (Cubicles)	Compressed AC Sheet	26m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8223/B00H/R0003/Partition Walls (Cubicles)/S18				Chrysotile (white asbestos)	

B00H - R0005 - Toilets-Girls (37.55 m2)

Ceiling Structures/Linings	Flat AC Sheeting	37.55m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8223/B00C/R0027/Ceiling Structures/Linings/S10				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00H - R0006 - Toilets-Girls (41.88 m2)

Ceiling Structures/Linings	Encapsulated Insulation material within unit	41.88m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8223/B00C/R0027/Ceiling Structures/Linings/S10				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00H - R0007 - Change (29.58 m2)

Ceiling Structures/Linings	Flat AC Sheeting	29.58m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8223/B00C/R0027/Ceiling Structures/Linings/S10				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00H - R0008 - Plant (0.51 m2)

Ceiling Structures/Linings	Flat AC Sheeting	0.51m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8223/B00C/R0027/Ceiling Structures/Linings/S10				Chrysotile (white asbestos) , Amosite (brown asbestos)	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - Multi Purpose Facilities - 1966 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	Non Accessible Area - Ceiling void inaccessible - Height restricted.

Interior

B00I - M0001 - Movement (4.18 m2)						
No Asbestos						
B00I - M0003 - Movement (4.3 m2)						
No Asbestos						
B00I - M0005 - Stairs (4.94 m2)						
No Asbestos						
B00I - M0006 - Stairs (4.75 m2)						
No Asbestos						
B00I - M0007 - Change (5.98 m2)						
No Asbestos						
B00I - M0008 - Toilets-Boys (2.16 m2)						
No Asbestos						
B00I - M0009 - Change (6.31 m2)						
No Asbestos						
B00I - M0010 - Toilets-Girls (2.16 m2)						
No Asbestos						
B00I - R0001 - Multi-Purpose Space (458.19 m2)						
No Asbestos						
B00I - R0002 - Stage (96.56 m2)						
No Asbestos						
B00I - R0003 - Movement (2.23 m2)						
No Asbestos						
B00I - R0004 - Movement (2 m2)						
No Asbestos						
B00I - R0005 - Movement (21.09 m2)						
No Asbestos						
B00I - R0006 - Distribution Board Cupboard (0.62 m2)					Note: No inspection of live electrical installation.	
No Asbestos						
B00I - R0007 - Toilets-Boys (8.45 m2)						
No Asbestos						
B00I - R0008 - Toilets-Girls (6.38 m2)						
No Asbestos						
B00I - R0009 - Staff Kitchen (15.92 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8223/B00I/R0009/Floor Coverings Res/Textile/S14					Chrysotile (white asbestos)	
B00I - R0010 - External Movement (7.37 m2)						
No Asbestos						
B00I - R0011 - External Movement (5.04 m2)						
No Asbestos						
B00I - R0012 - External Movement (3.77 m2)						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00I - R0013 - External Movement (3.75 m2)						
No Asbestos						
B00I - R0014 - External Movement (4.99 m2)						
No Asbestos						
B00I - R0015 - Stairs (3 m2)						
No Asbestos						
B00I - R0016 - Stairs (2.92 m2)						
No Asbestos						
B00I - R9001 - Movement (3.36 m2)						
No Asbestos						
B00I - R9002 - Chair Store (80.04 m2)						
No Asbestos						
B00I - R9003 - Movement (3.36 m2)						
No Asbestos						
B00I - R9004 - Stairs (1.53 m2)						
No Asbestos						
B00I - R9005 - Stairs (1.51 m2)						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - Pupil Facilities - 1958 - Concrete Framed (Concrete Framed)**Exterior**

Eaves Linings	Flat AC Sheeting 8223/B00G/Eaves Linings/S34	29m2	East, South & Southwest	Good Condition (1)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Voids	Non Accessible Area - No visible access to ceiling void					
Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting 8223/B00C/R0032/Ceiling Structures/Linings/S27					No Asbestos Detected

Interior**B00J - R0004 - Laundry (9.11 m2)**

Ceiling Structures/Linings	Flat AC Sheeting 8223/B00C/R0027/Ceiling Structures/Linings/S10	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos) , Amosite (brown asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles 8223/B00C/R1017/Floor Coverings Res/Textile/S2	8m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos)	

B00J - R0005 - Staff Shower (9.22 m2)

Ceiling Structures/Linings	Flat AC Sheeting 8223/B00C/R0027/Ceiling Structures/Linings/S10	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos) , Amosite (brown asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles 8223/B00C/R1017/Floor Coverings Res/Textile/S2	7m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos)	

B00J - R0006 - Sport Equipment Store (19.03 m2)

Ceiling Structures/Linings	Flat AC Sheeting 8223/B00C/R0027/Ceiling Structures/Linings/S10	20m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00J - R0007 - Change (27.82 m2)

No Asbestos

B00J - R0008 - Toilets-Boys (38.25 m2)

Wall Linings Internal	Flat AC Sheeting 8223/B00C/R0032/Ceiling Structures/Linings/S27					No Asbestos Detected
-----------------------	--	--	--	--	--	-----------------------------

B00J - R0009 - Toilets-Boys (42.16 m2)

Wall Linings Internal	Flat AC Sheeting 8223/B00C/R0032/Ceiling Structures/Linings/S27					No Asbestos Detected
-----------------------	--	--	--	--	--	-----------------------------

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Library - 1975 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior**B00K - M1001 - Plant (23.3 m2)**

Electrical motor, part of Air Con	Gaskets	1Unit	Eastern side of southern wall	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Asbestos material totally encased.						

B00K - M1002 - Plant (24.48 m2)

No Asbestos

B00K - R0001 - Main Entry (14.92 m2)

Ceiling Structures/Linings	Vermiculite	8223/B00K/R0001/Ceiling Structures/Linings/S12			Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

B00K - R0002 - Movement (33.39 m2)

Ceiling Structures/Linings	Vermiculite	8223/B00K/R0001/Ceiling Structures/Linings/S12			Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

B00K - R0003 - Careers Advisers Office (16.28 m2)

Ceiling Structures/Linings	Vermiculite	8223/B00K/R0001/Ceiling Structures/Linings/S12			Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

B00K - R0004 - Staff - Toilet (3.89 m2)

Ceiling Structures/Linings	Vermiculite	8223/B00K/R0001/Ceiling Structures/Linings/S12			Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

B00K - R0005 - Multi Media Workshop (49.85 m2)

Ceiling Structures/Linings	Vermiculite	8223/B00K/R0001/Ceiling Structures/Linings/S12			Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

B00K - R0006 - General Storeroom (7.09 m2)

Floor Coverings Res/Textile	Vinyl Tiles	8223/B00K/R0006/Floor Coverings Res/Textile/S13			No Asbestos Detected	
Safe.	Encapsulated Insulation material within unit	24m2	South east adjacent eastern wall	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Cannot sample, asbestos encased in						

B00K - R0008 - Distribution Board Cupboard (0.84 m2)

Note: No inspection of live electrical installation.

Floor Coverings Res/Textile	Vinyl Tiles	8223/B00K/R0006/Floor Coverings Res/Textile/S13			No Asbestos Detected	
-----------------------------	-------------	---	--	--	-----------------------------	--

B00K - R0009 - Cleaning Store - Distributed (4.67 m2)

No Asbestos

B00K - R0010 - Resources Store (2.8 m2)

Floor Coverings Res/Textile	Vinyl Tiles	8223/B00K/R0006/Floor Coverings Res/Textile/S13			No Asbestos Detected	
-----------------------------	-------------	---	--	--	-----------------------------	--

B00K - R0011 - Staff - Toilet (3.89 m2)

Ceiling Structures/Linings	Vermiculite	8223/B00K/R0001/Ceiling Structures/Linings/S12			Limited Samples Taken	
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00K - R0012 - Library Administration (50.3 m2)						
Ceiling Structures/Linings	Vermiculite		8223/B00K/R0001/Ceiling Structures/Linings/S12			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00K - R0013 - External Movement (19.85 m2)						
No Asbestos						
B00K - R0014 - Stairs (1.26 m2)						
Ceiling Structures/Linings	Vermiculite		8223/B00K/R0001/Ceiling Structures/Linings/S12			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00K - R0015 - Stairs (0.71 m2)						
Ceiling Structures/Linings	Vermiculite		8223/B00K/R0001/Ceiling Structures/Linings/S12			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00K - R0016 - Lift (1.65 m2)						
Ceiling Structures/Linings	Vermiculite		8223/B00K/R0001/Ceiling Structures/Linings/S12			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00K - R0018 - Tiered Learning Area (11.09 m2)						
Ceiling Structures/Linings	Vermiculite		8223/B00K/R0001/Ceiling Structures/Linings/S12			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00K - R0019 - Main Area (203.89 m2)						
Ceiling Structures/Linings	Vermiculite		8223/B00K/R0001/Ceiling Structures/Linings/S12			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00K - R0020 - Stairs (5.01 m2)						
Ceiling Structures/Linings	Vermiculite		8223/B00K/R0001/Ceiling Structures/Linings/S12			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00K - R0021 - Stairs (5.13 m2)						
Ceiling Structures/Linings	Vermiculite		8223/B00K/R0001/Ceiling Structures/Linings/S12			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00K - R0022 - Movement (3.38 m2)						
No Asbestos						
B00K - R1001 - General Storeroom (1.18 m2)						
No Asbestos						
B00K - R1004 - Leading Teacher (16.24 m2)						
Ceiling Structures/Linings	Vermiculite		8223/B00K/R0001/Ceiling Structures/Linings/S12			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00K - R1006 - Distribution Board Cupboard (1.38 m2)						
					Note: No inspection of live electrical installation.	
Floor Coverings Res/Textile	Vinyl Tiles		8223/B00K/R0006/Floor Coverings Res/Textile/S13			No Asbestos Detected
B00K - R1013 - Stairs (3.83 m2)						
Ceiling Structures/Linings	Vermiculite		8223/B00K/R0001/Ceiling Structures/Linings/S12			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00K - R1014 - Stairs (3.88 m2)						
Ceiling Structures/Linings	Vermiculite		8223/B00K/R0001/Ceiling Structures/Linings/S12			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00K - R1015 - Stairs (1.24 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
		8223/B00K/R0001/Ceiling Structures/Linings/S12				
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00K - R1016 - Stairs (1.28 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
		8223/B00K/R0001/Ceiling Structures/Linings/S12				
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00K - R1017 - Study Space (57.95 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
		8223/B00K/R0001/Ceiling Structures/Linings/S12				
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00K - R1018 - Independent Learning Space (74.18 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
		8223/B00K/R0001/Ceiling Structures/Linings/S12				
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00K - R1019 - Seminar (33.08 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
		8223/B00K/R0001/Ceiling Structures/Linings/S12				
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00K - R1020 - Stairs (3.87 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
		8223/B00K/R0001/Ceiling Structures/Linings/S12				
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00K - R1021 - Movement (4.28 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
		8223/B00K/R0001/Ceiling Structures/Linings/S12				
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00K - R1022 - Independent Learning Space (86.95 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
		8223/B00K/R0001/Ceiling Structures/Linings/S12				
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00K - R1023 - Movement (14.84 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
		8223/B00K/R0001/Ceiling Structures/Linings/S12				
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00K - R1024 - Stairs (3.83 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
		8223/B00K/R0001/Ceiling Structures/Linings/S12				
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00K - R1025 - Movement (2.69 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
		8223/B00K/R0001/Ceiling Structures/Linings/S12				
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00K - R1026 - Ancillary Staff (10.2 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
		8223/B00K/R0001/Ceiling Structures/Linings/S12				
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00K - Room+1 - Movement Block A-K						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - Physical Education - 2004 - Steel (Steel)

Exterior

Ceiling Voids - Raked Ceiling No Asbestos Found

Underfloor Voids - Slab on Ground No Asbestos Found

Underfloor Voids - Slab on Ground No Asbestos Found

Interior

B00M - R0001 - Sport Equipment Store (20.43 m2)

No Asbestos

B00M - R0002 - Sport Equipment Store (20.29 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00N - Building Services - 2007 - Steel (Steel)

Exterior

Ceiling Voids - Raked Ceiling No Asbestos Found

Underfloor Voids - Slab on Ground No Asbestos Found

Interior

B00N - R0001 - Machine Storage (80 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B000 - Agricultural Science - 2008 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids - Raked Ceiling No Asbestos Found

Underfloor Voids - Slab on Ground No Asbestos Found

Interior

B000 - R0001 - Staff - Toilet (8.03 m2)

No Asbestos

B000 - R0002 - First Aid (6.73 m2)

Sink pad Resinous Membrane
8223/B000/R0002/Sink pad/S37 **No Asbestos Detected**

B000 - R0004 - Covered Area (24.16 m2)

No Asbestos

B000 - R0005 - Covered Area (47.78 m2)

No Asbestos

B000 - R0006 - General Learning Space (65.24 m2)

No Asbestos

B000 - R0007 - Fitness Laboratory (75.71 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00P - Agricultural Science - 2008 - Steel (Steel)

Exterior

Ceiling Voids - Raked Ceiling No Asbestos Found

Underfloor Voids - Slab on Ground No Asbestos Found

Interior

B00P - R0001 - Machine Storage (48.22 m2)

No Asbestos

B00P - R0002 - L.P.G. Store (4.94 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00Q - Performance Learning/General Learning - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found
Eaves Linings	No Asbestos Found

Interior

B00Q - R0001 - General Learning Space (60.97 m2)

No Asbestos

B00Q - R0002 - General Learning Space (60.89 m2)

No Asbestos

B00Q - R0003 - Movement Studio (104.21 m2)

No Asbestos

B00Q - R0004 - Staff Study (19.45 m2)

No Asbestos

B00Q - R0005 - Sport Equipment Store (19.24 m2)

No Asbestos

B00Q - R0006 - Change (24 m2)

No Asbestos

B00Q - R0007 - Change (27.13 m2)

No Asbestos

B00Q - R0008 - Sport Equipment Store (11.67 m2)

No Asbestos

B00Q - R0009 - Control Room (12.95 m2)

No Asbestos

B00Q - R0010 - Performance Store (16.36 m2)

No Asbestos

B00Q - R0011 - Main Switchroom (6.28 m2)

No Asbestos

B00Q - R0012 - Movement Studio (130.48 m2)

No Asbestos

B00Q - R0013 - External Movement (99.4 m2)

No Asbestos

B00Q - R0014 - Access Student Shower/Toilet/Change (6.54 m2)

No Asbestos

B00Q - R0015 - Performance Workshop (31.86 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00Y - Building Services - 2000 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Flat Roof	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00Y - R0001 - Plant (1.27 m2)

Electrical Mounting Board	Compressed AC Sheet	3Unit	East	Good Condition (1)	Low (1)	Low Priority (2-3)
8223/B00Y/R0001/Electrical Mounting Board/S38					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00Z - Building Services - 2000 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Flat Roof	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00Z - R0001 - Plant (5.44 m2)

Flat AC debris.	Corrugated AC Sheeting	0.1m2	Mid east on ground surface.	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5)
8223/B00Y/R0001/Electrical Mounting Board/S38					Chrysotile (white asbestos)	
Gas meter gaskets	Encapsulated Insulation material within unit	1Unit	Southeast	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Gas meter assumed "old" has analog						
Disused gas pipe gaskets.	Encapsulated Insulation material within unit	4Unit	North	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Pipe & some machinery still intact.						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Build+1 - North playground awning

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

Build+1 - Room+1 - Added Room

Ceiling Structures/Linings	No Asbestos Found
----------------------------	-------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Build+2 - SW Block K Awning

Exterior

No Asbestos

Interior

Build+2 - Room+1 - Interior

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 601 - D10672 - Learning Unit - Standard/Withdrawal : Placement Date - 24/11/2009

Exterior

No Asbestos Found.

Interior

R1 - Entry

No Asbestos Found.

R2 - General Learning Space

No Asbestos Found.

R3 - Store

No Asbestos Found.

OS 601 - D14104 - Learning Unit - Standard/Withdrawal : Placement Date - 6/01/2012

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2
---------	---------------	------------------	-------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017