

# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Blacktown Boys High School (8244)  
**Region :** Western Sydney  
**State Electorate :** Blacktown  
**Local Government Area :** Blacktown

**Initial Survey :** Noel Arnold & Associates : 21 - Apr - 2008  
**Reviewed By :** Greencap-NAA : 10 - Jun - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - Various - 1956 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
---------------	------------------	------	------------	--------------------	---------	--------------------

**Assumed Asbestos - Height Restriction**

Ceiling Voids - Raked Ceiling	Non Accessible Area - Area inaccessible					
Underfloor Voids	No Asbestos Found					

**Interior**

**B00A - R0001 - Laboratory L.S. (100.5 m2)**

Flue Pipe	Fibre Cement Pipe	6m	South East Corner	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00A/R0001/Flue Pipe/S32					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00A - R0002 - Preparation (23.61 m2)**

No Asbestos

**B00A - R0003 - General Storeroom (13.47 m2)**

No Asbestos

**B00A - R0004 - General Learning Space (42.67 m2)**

Flue Pipe	Fibre Cement Pipe	6m	North East Corner	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00A/R0001/Flue Pipe/S32					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00A - R0005 - Distribution Board Cupboard (0.15 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B00A - R0006 - General Storeroom (22.13 m2)**

No Asbestos

**B00A - R0007 - Movement (79.51 m2)**

Floor Coverings Res/Textile	Vinyl Tiles					
	8244/B00A/R0007/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>

**B00A - R0008 - Tiered Learning Area (42.83 m2)**

Flue Pipe	Fibre Cement Pipe	2m	South East Corner	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00A/R0001/Flue Pipe/S32					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00A - R0009 - Preparation (23.65 m2)**

Flue Pipe	Fibre Cement Pipe	6m	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00A/R0001/Flue Pipe/S32					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00A - R0010 - Staff Study (13.46 m2)**

No Asbestos

**B00A - R0011 - Laboratory L.S. (101.25 m2)**

Flue Pipe	Fibre Cement Pipe	1m	North East Corner	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00A/R0001/Flue Pipe/S32					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00A - R0012 - Commonroom (93.13 m2)**

No Asbestos

**B00A - R0013 - Administration - Clerical (12.18 m2)**

No Asbestos

**B00A - R0014 - Staff Kitchen (5.85 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
<b>B00A - R0015 - Staff - Toilet (7.54 m2)</b>						
No Asbestos						
<b>B00A - R0016 - Staff - Toilet (4.03 m2)</b>						
No Asbestos						
<b>B00A - R0017 - Duplicating Workroom (25.5 m2)</b>						
No Asbestos						
<b>B00A - R0018 - Security Store (12.08 m2)</b>						
No Asbestos						
<b>B00A - R0019 - Administration - Clerical (12.75 m2)</b>						
No Asbestos						
<b>B00A - R0020 - Principal Office (25.21 m2)</b>						
No Asbestos						
<b>B00A - R0021 - Movement (6.12 m2)</b>						
No Asbestos						
<b>B00A - R0022 - Movement (40.52 m2)</b>						
No Asbestos						
<b>B00A - R0023 - Interview/Office - Type 1 (12.36 m2)</b>						
No Asbestos						
<b>B00A - R0024 - Staff - Toilet (2.55 m2)</b>						
No Asbestos						
<b>B00A - R0025 - Distribution Board Cupboard (2.82 m2)</b>						
					Note: No inspection of live electrical installation.	
No Asbestos						
<b>B00A - R0026 - Ancillary Staff (21.47 m2)</b>						
No Asbestos						
<b>B00A - R0027 - Entry (8.99 m2)</b>						
No Asbestos						
<b>B00A - R0028 - Librarian (12.61 m2)</b>						
No Asbestos						
<b>B00A - R0029 - Audio Visual Workroom (41.2 m2)</b>						
No Asbestos						
<b>B00A - R0030 - Workroom (42.71 m2)</b>						
No Asbestos						
<b>B00A - R0031 - Main Area (420.17 m2)</b>						
No Asbestos						
<b>B00A - R0032 - Main Switchroom (5.98 m2)</b>						
Flooring	Compressed AC Sheet					No Asbestos Detected
	8244/B00A/R0032/Flooring/S31					
<b>B00A - R0033 - Seminar (11.49 m2)</b>						
No Asbestos						
<b>B00A - R0034 - Seminar (11.56 m2)</b>						
No Asbestos						
<b>B00A - R0035 - Seminar (11.76 m2)</b>						
No Asbestos						
<b>B00A - R0036 - Movement (69.51 m2)</b>						
No Asbestos						
<b>B00A - R0037 - Administration - Clerical (37.76 m2)</b>						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00A - R0038 - Clinic-Toilets (3.1 m2)</b>						
No Asbestos						
<b>B00A - R0039 - Clinic - Boys (15.13 m2)</b>						
No Asbestos						
<b>B00A - R0040 - Deputy Principal Office (18.61 m2)</b>						
No Asbestos						
<b>B00A - R0041 - Administration - Clerical (12.92 m2)</b>						
No Asbestos						
<b>B00A - R0042 - General Storeroom (2.09 m2)</b>						
No Asbestos						
<b>B00A - R0043 - Movement (43.78 m2)</b>						
No Asbestos						
<b>B00A - R0044 - General Learning Space (52.45 m2)</b>						
Floor Coverings Res/Textile	Vinyl Sheet					
	8244/B00A/R0052/Floor Coverings Res/Textile/S29					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Adhesive					
	8244/B00A/R0052/Floor Coverings Res/Textile/S30					<b>No Asbestos Detected</b>
<b>B00A - R0045 - Distribution Board Cupboard (0.15 m2)</b>						
					Note: No inspection of live electrical installation.	
No Asbestos						
<b>B00A - R0046 - General Storeroom (2.32 m2)</b>						
No Asbestos						
<b>B00A - R0047 - General Storeroom (7.28 m2)</b>						
No Asbestos						
<b>B00A - R0048 - General Storeroom (4.9 m2)</b>						
No Asbestos						
<b>B00A - R0049 - Staff Study (65.91 m2)</b>						
Floor Coverings Res/Textile	Adhesive					
	8244/B00A/R0052/Floor Coverings Res/Textile/S30					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Vinyl Sheet					
	8244/B00A/R0052/Floor Coverings Res/Textile/S29					<b>No Asbestos Detected</b>
<b>B00A - R0050 - General Learning Space (65.91 m2)</b>						
Floor Coverings Res/Textile	Adhesive					
	8244/B00A/R0052/Floor Coverings Res/Textile/S30					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Vinyl Sheet					
	8244/B00A/R0052/Floor Coverings Res/Textile/S29					<b>No Asbestos Detected</b>
<b>B00A - R0051 - General Learning Space (65.91 m2)</b>						
Floor Coverings Res/Textile	Adhesive					
	8244/B00A/R0052/Floor Coverings Res/Textile/S30					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Vinyl Sheet					
	8244/B00A/R0052/Floor Coverings Res/Textile/S29					<b>No Asbestos Detected</b>
<b>B00A - R0052 - Computer Learning Space (52.08 m2)</b>						
Floor Coverings Res/Textile	Vinyl Sheet					
	8244/B00A/R0052/Floor Coverings Res/Textile/S29					<b>No Asbestos Detected</b>

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Adhesive					
	8244/B00A/R0052/Floor Coverings Res/Textile/S30					<b>No Asbestos Detected</b>
<b>B00A - R0053 - General Storeroom (2.4 m2)</b>						
No Asbestos						
<b>B00A - R0054 - Cleaning Store - Distributed (2.04 m2)</b>						
No Asbestos						
<b>B00A - R0055 - Computer Resource (18.73 m2)</b>						
No Asbestos						
<b>B00A - R0056 - Computer Store (3.83 m2)</b>						
No Asbestos						
<b>B00A - R0057 - Computer Learning Space (70.25 m2)</b>						
No Asbestos						
<b>B00A - R0058 - Movement (163.16 m2)</b>						
No Asbestos						
<b>B00A - R0059 - General Storeroom (8.71 m2)</b>						
No Asbestos						
<b>B00A - R0060 - Stairs (3.57 m2)</b>						
No Asbestos						
<b>B00A - R0061 - Stairs (3.57 m2)</b>						
No Asbestos						
<b>B00A - R0062 - Stairs (3.89 m2)</b>						
No Asbestos						
<b>B00A - R1001 - General Learning Space (52.58 m2)</b>						
No Asbestos						
<b>B00A - R1002 - General Learning Space (52.23 m2)</b>						
No Asbestos						
<b>B00A - R1004 - General Storeroom (25.6 m2)</b>						
No Asbestos						
<b>B00A - R1005 - Staff Study (17.33 m2)</b>						
No Asbestos						
<b>B00A - R1006 - General Storeroom (8.17 m2)</b>						
No Asbestos						
<b>B00A - R1007 - Distribution Board Cupboard (0.15 m2)</b>						
					Note: No inspection of live electrical installation.	
No Asbestos						
<b>B00A - R1008 - General Storeroom (3.96 m2)</b>						
Floor Coverings Res/Textile	Adhesive					
	8244/B00A/R1015/Floor Coverings Res/Textile/S34					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00A/R1015/Floor Coverings Res/Textile/S33					<b>Chrysotile (white asbestos)</b>
<b>B00A - R1009 - General Learning Space (51.87 m2)</b>						
No Asbestos						
<b>B00A - R1010 - General Learning Space (52.58 m2)</b>						
No Asbestos						
<b>B00A - R1011 - General Learning Space (52.58 m2)</b>						
No Asbestos						
<b>B00A - R1012 - Movement (114.76 m2)</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles					
	8244/B00A/R1012/Floor Coverings Res/Textile/S1					<b>No Asbestos Detected</b>
<b>B00A - R1013 - General Learning Space (69.65 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	70m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00A/R1013/Floor Coverings Res/Textile/S35					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive					
	8244/B00A/R1013/Floor Coverings Res/Textile/S36					<b>No Asbestos Detected</b>
<b>B00A - R1014 - Interview/Office - Type 1 (18.42 m2)</b>						
Floor Coverings Res/Textile	Adhesive					
	8244/B00A/R1013/Floor Coverings Res/Textile/S36					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00A/R1013/Floor Coverings Res/Textile/S35					<b>Chrysotile (white asbestos)</b>
<b>B00A - R1015 - General Storeroom (3.74 m2)</b>						
Floor Coverings Res/Textile	Adhesive					
	8244/B00A/R1015/Floor Coverings Res/Textile/S34					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00A/R1015/Floor Coverings Res/Textile/S33					<b>Chrysotile (white asbestos)</b>
<b>B00A - R1016 - Cleaning Store - Distributed (2.04 m2)</b>						
No Asbestos						
<b>B00A - R1017 - Movement (61.36 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	62m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00A/R1015/Floor Coverings Res/Textile/S33					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive					
	8244/B00A/R1015/Floor Coverings Res/Textile/S34					<b>No Asbestos Detected</b>
<b>B00A - R1018 - General Learning Space (52.44 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	53m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00A/R1013/Floor Coverings Res/Textile/S35					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive					
	8244/B00A/R1015/Floor Coverings Res/Textile/S34					<b>No Asbestos Detected</b>
<b>B00A - R1019 - General Learning Space (52.44 m2)</b>						
Floor Coverings Res/Textile	Adhesive					
	8244/B00A/R1015/Floor Coverings Res/Textile/S34					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	53m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00A/R1013/Floor Coverings Res/Textile/S35					<b>Chrysotile (white asbestos)</b>
<b>B00A - R1020 - Staff Study (69.09 m2)</b>						
Floor Coverings Res/Textile	Adhesive					
	8244/B00A/R1013/Floor Coverings Res/Textile/S36					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	70m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00A/R1013/Floor Coverings Res/Textile/S35					<b>Chrysotile (white asbestos)</b>
<b>B00A - R1021 - General Learning Space (69.85 m2)</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8244/B00A/R1015/Floor Coverings Res/Textile/S33	70m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive 8244/B00A/R1015/Floor Coverings Res/Textile/S34					<b>No Asbestos Detected</b>
<b>B00A - R1022 - Music Learning Space (52.45 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8244/B00A/R1015/Floor Coverings Res/Textile/S33	53m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive 8244/B00A/R1015/Floor Coverings Res/Textile/S34					<b>No Asbestos Detected</b>
<b>B00A - R1023 - Movement (44.51 m2)</b>						
Floor Coverings Res/Textile	Adhesive 8244/B00A/R1015/Floor Coverings Res/Textile/S34					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8244/B00A/R1015/Floor Coverings Res/Textile/S33	45m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00A - R1024 - Cleaning Store - Distributed (2.04 m2)</b>						
No Asbestos						
<b>B00A - R1025 - General Storeroom (3.83 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles 8244/B00A/R1015/Floor Coverings Res/Textile/S33	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive 8244/B00A/R1015/Floor Coverings Res/Textile/S34					<b>No Asbestos Detected</b>
<b>B00A - R1026 - Staff Study (18.73 m2)</b>						
Floor Coverings Res/Textile	Adhesive 8244/B00A/R1015/Floor Coverings Res/Textile/S34					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8244/B00A/R1015/Floor Coverings Res/Textile/S33	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00A - R1027 - Music Learning Space (70.25 m2)</b>						
Floor Coverings Res/Textile	Adhesive 8244/B00A/R1015/Floor Coverings Res/Textile/S34					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8244/B00A/R1015/Floor Coverings Res/Textile/S33	71m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00A - R1028 - Stairs (13.48 m2)</b>						
No Asbestos						
<b>B00A - R1029 - Stairs (13.35 m2)</b>						
No Asbestos						
<b>B00A - R1030 - Stairs (13.8 m2)</b>						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

**B00B - Pupil Facilities - 1956 - Concrete (Concrete)**

**Exterior**

Eaves Linings	Flat AC Sheeting	30m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00B/R0004/Ceiling Structures/Linings/S28			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Ceiling Voids - Raked Ceiling	Non Accessible Area - Area inaccessible					
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					

**Interior**

**B00B - R0001 - Staff - Toilet (1.63 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00B/R0004/Ceiling Structures/Linings/S28			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00B - R0002 - Ancillary Staff (3.95 m2)**

Floor Coverings Res/Textile	Vinyl Tiles 8244/B00B/R0002/Floor Coverings Res/Textile/S18 <b>No Asbestos Detected</b>					
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00B/R0004/Ceiling Structures/Linings/S28			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00B - R0003 - General Storeroom (3.44 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00B/R0004/Ceiling Structures/Linings/S28			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Floor Coverings Res/Textile	Vinyl Tiles 8244/B00B/R0002/Floor Coverings Res/Textile/S18 <b>No Asbestos Detected</b>					

**B00B - R0004 - Student Canteen (40.11 m2)**

Floor Coverings Res/Textile	Vinyl Tiles 8244/B00B/R0002/Floor Coverings Res/Textile/S18 <b>No Asbestos Detected</b>					
Ceiling Structures/Linings	Flat AC Sheeting	41m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00B/R0004/Ceiling Structures/Linings/S28			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00B - R0005 - Maintenance Bulk Store (11.19 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00B/R0004/Ceiling Structures/Linings/S28			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00B - R0006 - Sport Equipment Store (27.88 m2)**

Wall Linings Internal	Flat AC Sheeting 8244/B00B/R0006/Wall Linings Internal/S15 <b>No Asbestos Detected</b>					
Ceiling Structures/Linings	Flat AC Sheeting	28m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00B/R0004/Ceiling Structures/Linings/S28			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00B - R0007 - Movement (236.06 m2)**



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Ceiling Structures/Linings	Flat AC Sheeting	236m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8244/B00B/R0004/Ceiling Structures/Linings/S28				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00B - R0008 - General Storeroom (37.96 m2)</b>						
No Asbestos						
<b>B00B - R0009 - Movement (49.36 m2)</b>						
Ceiling Structures/Linings	Compressed AC Sheet	5m2	Entrance	Good Condition (1)	Low (1)	Low Priority (2-3)
8244/B00B/R0004/Ceiling Structures/Linings/S28				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00B - R0010 - Cleaning Store - Distributed (4.76 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8244/B00B/R0004/Ceiling Structures/Linings/S28				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00B - R0012 - General Storeroom (3.15 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8244/B00B/R0004/Ceiling Structures/Linings/S28				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00B - R0013 - Shower/Change (95.37 m2)</b>						
Wall Linings Internal	Flat AC Sheeting					<b>No Asbestos Detected</b>
8244/B00B/R0013/Wall Linings Internal/S17						
Ceiling Structures/Linings	Flat AC Sheeting	96m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8244/B00B/R0004/Ceiling Structures/Linings/S28				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00B - R0014 - Toilets - Boys (126 m2)</b>						
Partition Walls (Cubicles)	Compressed AC Sheet					<b>No Asbestos Detected</b>
8244/B00B/R0014/Partition Walls (Cubicles)/S16						
Ceiling Structures/Linings	Flat AC Sheeting	126m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8244/B00B/R0004/Ceiling Structures/Linings/S28				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - Technological & Applied Studies - 1956 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00C/R0009/High level fill panel/S24			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Underfloor Voids	No Asbestos Found					
Ceiling Voids - Raked Ceiling	Non Accessible Area - Area inaccessible					

**Interior**

**B00C - M0001 - Resource/Project Store (16.25 m2)**

No Asbestos

**B00C - M0002 - Resource/Project Store (14.61 m2)**

No Asbestos

**B00C - R0001 - Computer Learning Space (52.73 m2)**

Wall Linings Internal	Flat AC Sheeting	15m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00C/R0009/High level fill panel/S24			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00C - R0002 - Computer Store (6.5 m2)**

High level fill panel	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00C/R0009/High level fill panel/S24			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00C - R0003 - Materials Store (6.5 m2)**

High level fill panel	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00C/R0009/High level fill panel/S24			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00C - R0004 - Resource/Project Store (12.18 m2)**

High level fill panel	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00C/R0009/High level fill panel/S24			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00C - R0005 - Design L.S. (52.73 m2)**

High level fill panel	Flat AC Sheeting	40m2	East and West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00C/R0009/High level fill panel/S24			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00C - R0006 - Materials Store (15.67 m2)**

High level fill panel	Flat AC Sheeting	40m2	East and West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00C/R0009/High level fill panel/S24			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00C - R0007 - Materials Technology L.S. (76 m2)**

High level fill panel	Flat AC Sheeting	40m2	East and West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00C/R0009/High level fill panel/S24			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00C - R0008 - Welding Area (25.93 m2)**

High level fill panel	Flat AC Sheeting	20m2	East and West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00C/R0009/High level fill panel/S24			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00C - R0009 - Materials Technology L.S. (76.01 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
High level fill panel	Flat AC Sheeting	20m2	East and West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00C/R0009/High level fill panel/S24			Chrysotile (white asbestos) , Amosite (brown asbestos)		
<b>B00C - R0010 - Materials Store (14.94 m2)</b>						
Stored Furnace	Encapsulated Insulation material within unit	1Unit	Shelving	Minimal Damage (2)	Medium (2)	Medium Priority (4-5)
	8244/B00C/R0010/Stored Furnace/S23			Chrysotile (white asbestos) , Amosite (brown asbestos)		
High level fill panel	Flat AC Sheeting	NA	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Height Restriction					
<b>B00C - R0011 - Materials Store (10.22 m2)</b>						
Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	8244/B00C/R0036/Wall Linings Internal/S6					
<b>B00C - R0012 - Resource/Project Store (1.72 m2)</b>						
No Asbestos						
<b>B00C - R0013 - Materials Technology L.S. (84.77 m2)</b>						
Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	8244/B00C/R0036/Wall Linings Internal/S6					
<b>B00C - R0014 - Materials Technology L.S. (89.29 m2)</b>						
No Asbestos						
<b>B00C - R0015 - Materials Store (8.68 m2)</b>						
No Asbestos						
<b>B00C - R0016 - Staff Study (18.65 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00C/R0016/Floor Coverings Res/Textile/S25			Chrysotile (white asbestos)		
Floor Coverings Res/Textile	Adhesive					No Asbestos Detected
	8244/B00C/R0016/Floor Coverings Res/Textile/S26					
<b>B00C - R0017 - Staff - Toilet (5.48 m2)</b>						
High level fill panel	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00C/R0009/High level fill panel/S24			Chrysotile (white asbestos) , Amosite (brown asbestos)		
<b>B00C - R0018 - Cleaning Store - Distributed (1.02 m2)</b>						
No Asbestos						
<b>B00C - R0019 - Staff Study (25.69 m2)</b>						
Floor Coverings Res/Textile	Adhesive					No Asbestos Detected
	8244/B00C/R0016/Floor Coverings Res/Textile/S26					
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	26m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00C/R0016/Floor Coverings Res/Textile/S25			Chrysotile (white asbestos)		
<b>B00C - R0020 - Materials Technology L.S. (72.14 m2)</b>						
No Asbestos						
<b>B00C - R0021 - Materials Store (7.1 m2)</b>						
No Asbestos						
<b>B00C - R0022 - Movement (113.68 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	2m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00C/R0022/Ceiling Structures/Linings/S4			Chrysotile (white asbestos) , Amosite (brown asbestos)		
<b>B00C - R0024 - Movement (2.02 m2)</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
<b>B00C - R0029 - Sport Equipment Store (21.9 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8244/B00C/R0029/Ceiling Structures/Linings/S10					<b>Chrysotile (white asbestos)</b>	
<b>B00C - R0030 - Cleaning Store - Distributed (5.97 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8244/B00C/R0030/Floor Coverings Res/Textile/S20					<b>Chrysotile (white asbestos)</b>	
Floor Coverings Res/Textile	Adesive					
8244/B00C/R0030/Floor Coverings Res/Textile/S21					<b>No Asbestos Detected</b>	
Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8244/B00C/R0030/Ceiling Structures/Linings/S22					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
<b>B00C - R0033 - Movement (2.02 m2)</b>						
No Asbestos						
<b>B00C - R0034 - Distribution Board Cupboard (0.25 m2)</b>						
Note: No inspection of live electrical installation.						
Electrical Backing Board	Resinous Board	2Unit	West	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - Electrical Hazard</b>						
<b>B00C - R0035 - Dust Extraction Space (6.71 m2)</b>						
Flooring	Compressed AC Sheet					
8244/B00C/R0036/Floor Coverings Res/Textile/S7					<b>No Asbestos Detected</b>	
<b>B00C - R0036 - Dust Extraction Space (7.2 m2)</b>						
Wall Linings Internal	Flat AC Sheeting					
8244/B00C/R0036/Wall Linings Internal/S6					<b>No Asbestos Detected</b>	
Flooring	Compressed AC Sheet					
8244/B00C/R0036/Floor Coverings Res/Textile/S7					<b>No Asbestos Detected</b>	
<b>B00C - R0037 - External Movement (18.29 m2)</b>						
No Asbestos						
<b>B00C - R0038 - Laundry (2.91 m2)</b>						
No Asbestos						
<b>B00C - R0039 - Preparation (20.5 m2)</b>						
No Asbestos						
<b>B00C - R0040 - Food Technology L.S. (111.45 m2)</b>						
No Asbestos						
<b>B00C - R0041 - General Learning Space (41.33 m2)</b>						
No Asbestos						
<b>B00C - R0042 - Movement (24.91 m2)</b>						
Floor Coverings Res/Textile	Adesive					
8244/B00C/R0030/Floor Coverings Res/Textile/S21					<b>No Asbestos Detected</b>	
Floor Coverings Res/Textile	Vinyl Tiles	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8244/B00C/R0030/Floor Coverings Res/Textile/S20					<b>Chrysotile (white asbestos)</b>	
Ceiling Structures/Linings	Vermiculite					
8244/B00C/R0032/Ceiling Structures/Linings/S8					<b>Limited Samples Taken</b>	
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						
<b>B00C - R0043 - Toilets-Boys (1.59 m2)</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8244/B00C/R0030/Ceiling Structures/Linings/S22				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00C - R0044 - Shower (43.97 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	44m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8244/B00C/R0030/Ceiling Structures/Linings/S22				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00C - R0045 - Movement (6.3 m2)</b>						
No Asbestos						
<b>B00C - R0046 - Plant (3.06 m2)</b>						
Flue Pipe	Fibre Cement Pipe	6m	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
8244/B00C/R0046/Flue Pipe/S19				<b>Chrysotile (white asbestos)</b>		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - Performing Arts - 1960 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00D/R0015/Ceiling Structures/Linings/S13				Chrysotile (white asbestos)	
Ceiling Voids - Raked Ceiling	Non Accessible Area - Area inaccessible					
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					

**Interior****B00D - M0001 - Control Room (20.73 m2)**

No Asbestos

**B00D - M0002 - Performing Arts Store (20.73 m2)**

No Asbestos

**B00D - R0001 - Cleaning Supplies Store (6.76 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00D/R0006/Floor Coverings Res/Textile/S37				Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive 8244/B00D/R0006/Floor Coverings Res/Textile/S38					No Asbestos Detected

**B00D - R0002 - Toilets-Girls (1.76 m2)**

No Asbestos

**B00D - R0003 - Performing Arts Changeroom (43.67 m2)**

No Asbestos

**B00D - R0004 - Performing Arts Changeroom (43.57 m2)**

No Asbestos

**B00D - R0005 - Toilets-Boys (1.76 m2)**

No Asbestos

**B00D - R0006 - Cleaning Supplies Store (6.79 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00D/R0006/Floor Coverings Res/Textile/S37				Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Adhesive 8244/B00D/R0006/Floor Coverings Res/Textile/S38					No Asbestos Detected

**B00D - R0007 - Movement (5.28 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00D/R0007/Ceiling Structures/Linings/S14				Chrysotile (white asbestos)	

**B00D - R0008 - Performing Arts Store (14.06 m2)**

No Asbestos

**B00D - R0009 - Cleaning Store - Distributed (0.63 m2)**

No Asbestos

**B00D - R0010 - Stage (94.73 m2)**

No Asbestos

**B00D - R0011 - Performing Arts Chair Store (13.01 m2)**

No Asbestos

**B00D - R0012 - Movement (5.28 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8244/B00D/R0007/Ceiling Structures/Linings/S14					Chrysotile (white asbestos)	
<b>B00D - R0013 - Movement (29.72 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8244/B00D/R0015/Ceiling Structures/Linings/S13					Chrysotile (white asbestos)	
<b>B00D - R0014 - Multi-Purpose Space (392.39 m2)</b>						
No Asbestos						
<b>B00D - R0015 - Movement (29.72 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8244/B00D/R0015/Ceiling Structures/Linings/S13					Chrysotile (white asbestos)	
<b>B00D - R0016 - Staff Kitchen (8.8 m2)</b>						
No Asbestos						
<b>B00D - R0017 - Toilets-Boys (8.12 m2)</b>						
No Asbestos						
<b>B00D - R0018 - Movement (22.21 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8244/B00D/R0015/Ceiling Structures/Linings/S13					Chrysotile (white asbestos)	
<b>B00D - R0019 - Toilets-Girls (5.61 m2)</b>						
No Asbestos						
<b>B00D - R0020 - Performing Arts Chair Store (11.34 m2)</b>						
No Asbestos						
<b>B00D - R9001 - General Assistants (47.3 m2)</b>						
No Asbestos						
<b>B00D - R9002 - General Storeroom (11.18 m2)</b>						
No Asbestos						
<b>B00D - R9003 - Maintenance Bulk Store (46.98 m2)</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00I - Building Services - 2009 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

**Interior**

**B00I - R0001 - Machine Storage (72.09 m2)**

No Asbestos

**B00I - R0002 - External Movement (85.01 m2)**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00K - Art/General Learning - 1972 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

**Interior****B00K - R0001 - Kiln Space (22.08 m2)**

Ceiling Structures/Linings	Vermiculite 8244/B00K/R0005/Ceiling Structures/Linings/S12	<b>Limited Samples Taken</b>				
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00K - R0002 - Darkroom Space (10.47 m2)**

Ceiling Structures/Linings	Vermiculite 8244/B00K/R0005/Ceiling Structures/Linings/S12	<b>Limited Samples Taken</b>				
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

Floor Coverings Res/Textile	Vinyl Tiles	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8244/B00K/R0005/Floor Coverings Res/Textile/S11						<b>Chrysotile (white asbestos)</b>

Floor Coverings Res/Textile	Adhesive 8244/B00K/R0009/Floor Coverings Res/Textile/S27	<b>No Asbestos Detected</b>				
-----------------------------	---	-----------------------------	--	--	--	--

**B00K - R0003 - Cleaning Store - Distributed (6.3 m2)**

No Asbestos

**B00K - R0004 - Distribution Board Cupboard (0.72 m2)**

Note: No inspection of live electrical installation.

Electrical Mounting Board	Resinous Board	2m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - Electrical Hazard</b>						

**B00K - R0005 - Toilets-Boys (22.81 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	5m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
8244/B00K/R0005/Floor Coverings Res/Textile/S11						<b>Chrysotile (white asbestos)</b>

Ceiling Structures/Linings	Vermiculite 8244/B00K/R0005/Ceiling Structures/Linings/S12	<b>Limited Samples Taken</b>				
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

Floor Coverings Res/Textile	Adhesive 8244/B00K/R0009/Floor Coverings Res/Textile/S27	<b>No Asbestos Detected</b>				
-----------------------------	---	-----------------------------	--	--	--	--

**B00K - R0006 - General Storeroom (4.16 m2)**

Ceiling Structures/Linings	Vermiculite 8244/B00K/R0005/Ceiling Structures/Linings/S12	<b>Limited Samples Taken</b>				
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8244/B00K/R0005/Floor Coverings Res/Textile/S11						<b>Chrysotile (white asbestos)</b>

Floor Coverings Res/Textile	Adhesive 8244/B00K/R0009/Floor Coverings Res/Textile/S27	<b>No Asbestos Detected</b>				
-----------------------------	---	-----------------------------	--	--	--	--

**B00K - R0007 - Staff Study (21.08 m2)**

Ceiling Structures/Linings	Vermiculite 8244/B00K/R0005/Ceiling Structures/Linings/S12	<b>Limited Samples Taken</b>				
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00K - R0008 - Computer Resource (26 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite 8244/B00K/R0005/Ceiling Structures/Linings/S12				Limited Samples Taken <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>	
Floor Coverings Res/Textile	Vinyl Tiles 8244/B00K/R0005/Floor Coverings Res/Textile/S11	26m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive 8244/B00K/R0009/Floor Coverings Res/Textile/S27				No Asbestos Detected	
<b>B00K - R0009 - Resources Store (9.85 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8244/B00K/R0005/Ceiling Structures/Linings/S12				Limited Samples Taken <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>	
Floor Coverings Res/Textile	Vinyl Tiles 8244/B00K/R0005/Floor Coverings Res/Textile/S11	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive 8244/B00K/R0009/Floor Coverings Res/Textile/S27				No Asbestos Detected	
<b>B00K - R0010 - Machine Storage (9.85 m2)</b>						
No Asbestos						
<b>B00K - R0011 - Art Learning Space (52.08 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8244/B00K/R0005/Ceiling Structures/Linings/S12				Limited Samples Taken <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>	
Floor Coverings Res/Textile	Vinyl Tiles 8244/B00K/R0005/Floor Coverings Res/Textile/S11	53m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive 8244/B00K/R0009/Floor Coverings Res/Textile/S27				No Asbestos Detected	
<b>B00K - R0012 - Laboratory L.S. (92.13 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8244/B00K/R0005/Ceiling Structures/Linings/S12				Limited Samples Taken <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>	
<b>B00K - R0013 - Commonroom (28.53 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8244/B00K/R0005/Ceiling Structures/Linings/S12				Limited Samples Taken <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>	
<b>B00K - R0014 - Preparation (9.83 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8244/B00K/R0005/Ceiling Structures/Linings/S12				Limited Samples Taken <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>	
<b>B00K - R0015 - Laboratory L.S. (99.62 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8244/B00K/R0005/Ceiling Structures/Linings/S12				Limited Samples Taken <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>	
<b>B00K - R0016 - Cleaning Store - Distributed (1.4 m2)</b>						
No Asbestos						
<b>B00K - R0017 - Chemical Store (25.64 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8244/B00K/R0005/Ceiling Structures/Linings/S12				Limited Samples Taken <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Adhesive					
	8244/B00K/R0009/Floor Coverings Res/Textile/S27					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Vinyl Tiles	26m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00K/R0005/Floor Coverings Res/Textile/S11					<b>Chrysotile (white asbestos)</b>
<b>B00K - R0018 - Staff Study (25.5 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8244/B00K/R0005/Ceiling Structures/Linings/S12					<b>Limited Samples Taken</b>
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						
Floor Coverings Res/Textile	Vinyl Tiles	26m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00K/R0005/Floor Coverings Res/Textile/S11					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive	26m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00K/R0005/Floor Coverings Res/Textile/S11					<b>Chrysotile (white asbestos)</b>
<b>B00K - R0019 - Movement (7.51 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8244/B00K/R0005/Ceiling Structures/Linings/S12					<b>Limited Samples Taken</b>
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						
<b>B00K - R0020 - Distribution Board Cupboard (0.9 m2)</b>				Note: No inspection of live electrical installation.		
Electrical Mounting Board	Resinous Board	1Unit	North	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - Electrical Hazard</b>						
<b>B00K - R0021 - Cleaning Store - Distributed (7.24 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8244/B00K/R0005/Ceiling Structures/Linings/S12					<b>Limited Samples Taken</b>
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00K/R0005/Floor Coverings Res/Textile/S11					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive					
	8244/B00K/R0009/Floor Coverings Res/Textile/S27					<b>No Asbestos Detected</b>
<b>B00K - R0022 - Staff - Toilet (4.87 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8244/B00K/R0005/Ceiling Structures/Linings/S12					<b>Limited Samples Taken</b>
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						
<b>B00K - R0023 - General Storeroom (16.74 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8244/B00K/R0005/Ceiling Structures/Linings/S12					<b>Limited Samples Taken</b>
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						
Floor Coverings Res/Textile	Adhesive					
	8244/B00K/R0009/Floor Coverings Res/Textile/S27					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Vinyl Tiles	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00K/R0005/Floor Coverings Res/Textile/S11					<b>Chrysotile (white asbestos)</b>
<b>B00K - R0024 - Bulk Store (12.17 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8244/B00K/R0005/Ceiling Structures/Linings/S12					<b>Limited Samples Taken</b>
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						
<b>B00K - R0025 - Laboratory L.S. (99.63 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8244/B00K/R0005/Ceiling Structures/Linings/S12					<b>Limited Samples Taken</b>
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00K - R0026 - Apparatus Store (9.85 m2)</b>						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8244/B00K/R0005/Ceiling Structures/Linings/S12					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
<b>B00K - R0027 - Preparation (28.53 m2)</b>						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8244/B00K/R0005/Ceiling Structures/Linings/S12					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
<b>B00K - R0028 - Resources Store (6.22 m2)</b>						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8244/B00K/R0005/Ceiling Structures/Linings/S12					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00K/R0005/Floor Coverings Res/Textile/S11					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive					No Asbestos Detected
	8244/B00K/R0009/Floor Coverings Res/Textile/S27					
<b>B00K - R0029 - General Storeroom (5.95 m2)</b>						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8244/B00K/R0005/Ceiling Structures/Linings/S12					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00K/R0005/Floor Coverings Res/Textile/S11					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive					No Asbestos Detected
	8244/B00K/R0009/Floor Coverings Res/Textile/S27					
<b>B00K - R0030 - Art Learning Space (58.62 m2)</b>						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8244/B00K/R0005/Ceiling Structures/Linings/S12					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
Floor Coverings Res/Textile	Vinyl Tiles	59m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00K/R0005/Floor Coverings Res/Textile/S11					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive					No Asbestos Detected
	8244/B00K/R0009/Floor Coverings Res/Textile/S27					
<b>B00K - R0031 - Art Learning Space (59 m2)</b>						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8244/B00K/R0005/Ceiling Structures/Linings/S12					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
<b>B00K - R0032 - Movement (243.74 m2)</b>						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8244/B00K/R0005/Ceiling Structures/Linings/S12					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
<b>B00K - R0033 - Stairs (5.4 m2)</b>						
No Asbestos						
<b>B00K - R0034 - Stairs (1.33 m2)</b>						
No Asbestos						
<b>B00K - R0035 - Movement (1.33 m2)</b>						
No Asbestos						
<b>B00K - R0036 - Movement (1.33 m2)</b>						
No Asbestos						
<b>B00K - R1001 - General Learning Space (46.42 m2)</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite 8244/B00K/R0005/Ceiling Structures/Linings/S12					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Adhesive 8244/B00K/R0009/Floor Coverings Res/Textile/S27					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles 8244/B00K/R0005/Floor Coverings Res/Textile/S11	46m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00K - R1002 - Cleaning Store - Distributed (1.4 m2)</b>						
No Asbestos						
<b>B00K - R1003 - Distribution Board Cupboard (0.72 m2)</b>						
				Note: No inspection of live electrical installation.		
Electrical Mounting Board	Resinous Board	1m2	East	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Assumed Asbestos - Electrical Hazard</b>
<b>B00K - R1004 - Interview/Office - Type 1 (11.83 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8244/B00K/R0005/Ceiling Structures/Linings/S12					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Adhesive 8244/B00K/R0009/Floor Coverings Res/Textile/S27					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles 8244/B00K/R0005/Floor Coverings Res/Textile/S11	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00K - R1005 - Staff Study (19.84 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8244/B00K/R0005/Ceiling Structures/Linings/S12					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Adhesive 8244/B00K/R0009/Floor Coverings Res/Textile/S27					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles 8244/B00K/R0005/Floor Coverings Res/Textile/S11	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00K - R1006 - Art Learning Space (51.93 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles 8244/B00K/R0005/Floor Coverings Res/Textile/S11	52m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Vermiculite 8244/B00K/R0005/Ceiling Structures/Linings/S12					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Adhesive 8244/B00K/R0009/Floor Coverings Res/Textile/S27					No Asbestos Detected
<b>B00K - R1007 - Resources Store (5.02 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles 8244/B00K/R0005/Floor Coverings Res/Textile/S11	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Vermiculite 8244/B00K/R0005/Ceiling Structures/Linings/S12					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Adhesive 8244/B00K/R0009/Floor Coverings Res/Textile/S27					No Asbestos Detected
<b>B00K - R1008 - General Learning Space (59.11 m2)</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite 8244/B00K/R0005/Ceiling Structures/Linings/S12				Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>	
Floor Coverings Res/Textile	Adhesive 8244/B00K/R0009/Floor Coverings Res/Textile/S27				No Asbestos Detected	
Floor Coverings Res/Textile	Vinyl Tiles 8244/B00K/R0005/Floor Coverings Res/Textile/S11	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00K - R1009 - General Storeroom (5.95 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles 8244/B00K/R0005/Floor Coverings Res/Textile/S11	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Vermiculite 8244/B00K/R0005/Ceiling Structures/Linings/S12				Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>	
Floor Coverings Res/Textile	Adhesive 8244/B00K/R0009/Floor Coverings Res/Textile/S27				No Asbestos Detected	
<b>B00K - R1010 - General Storeroom (6.22 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles 8244/B00K/R0005/Floor Coverings Res/Textile/S11	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Vermiculite 8244/B00K/R0005/Ceiling Structures/Linings/S12				Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>	
Floor Coverings Res/Textile	Adhesive 8244/B00K/R0009/Floor Coverings Res/Textile/S27				No Asbestos Detected	
<b>B00K - R1011 - General Learning Space (51.85 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8244/B00K/R0005/Ceiling Structures/Linings/S12				Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>	
Floor Coverings Res/Textile	Adhesive 8244/B00K/R0009/Floor Coverings Res/Textile/S27				No Asbestos Detected	
Floor Coverings Res/Textile	Vinyl Tiles 8244/B00K/R0005/Floor Coverings Res/Textile/S11	52m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00K - R1012 - General Learning Space (51.86 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8244/B00K/R0005/Ceiling Structures/Linings/S12				Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>	
Floor Coverings Res/Textile	Adhesive 8244/B00K/R0009/Floor Coverings Res/Textile/S27				No Asbestos Detected	
Floor Coverings Res/Textile	Vinyl Tiles 8244/B00K/R0005/Floor Coverings Res/Textile/S11	52m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00K - R1013 - General Learning Space (51.86 m2)</b>						
Ceiling Structures/Linings	Vermiculite 8244/B00K/R0005/Ceiling Structures/Linings/S12				Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>	
Floor Coverings Res/Textile	Adhesive 8244/B00K/R0009/Floor Coverings Res/Textile/S27				No Asbestos Detected	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles	52m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8244/B00K/R0005/Floor Coverings Res/Textile/S11					<b>Chrysotile (white asbestos)</b>	
<b>B00K - R1014 - General Storeroom (5.95 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8244/B00K/R0005/Floor Coverings Res/Textile/S11					<b>Chrysotile (white asbestos)</b>	
Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
8244/B00K/R0005/Ceiling Structures/Linings/S12					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>	
Floor Coverings Res/Textile	Adhesive					<b>No Asbestos Detected</b>
8244/B00K/R0009/Floor Coverings Res/Textile/S27						
<b>B00K - R1015 - General Storeroom (6.23 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8244/B00K/R0005/Floor Coverings Res/Textile/S11					<b>Chrysotile (white asbestos)</b>	
Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
8244/B00K/R0005/Ceiling Structures/Linings/S12					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>	
Floor Coverings Res/Textile	Adhesive					<b>No Asbestos Detected</b>
8244/B00K/R0009/Floor Coverings Res/Textile/S27						
<b>B00K - R1016 - General Learning Space (59.48 m2)</b>						
Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
8244/B00K/R0005/Ceiling Structures/Linings/S12					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>	
Floor Coverings Res/Textile	Adhesive					<b>No Asbestos Detected</b>
8244/B00K/R0009/Floor Coverings Res/Textile/S27						
Floor Coverings Res/Textile	Vinyl Tiles	59m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8244/B00K/R0005/Floor Coverings Res/Textile/S11					<b>Chrysotile (white asbestos)</b>	
<b>B00K - R1017 - Staff Study (52.15 m2)</b>						
Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
8244/B00K/R0005/Ceiling Structures/Linings/S12					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>	
Floor Coverings Res/Textile	Adhesive					<b>No Asbestos Detected</b>
8244/B00K/R0009/Floor Coverings Res/Textile/S27						
Floor Coverings Res/Textile	Vinyl Tiles	52m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8244/B00K/R0005/Floor Coverings Res/Textile/S11					<b>Chrysotile (white asbestos)</b>	
<b>B00K - R1018 - Cleaning Store - Distributed (7.24 m2)</b>						
Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
8244/B00K/R0005/Ceiling Structures/Linings/S12					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>	
Floor Coverings Res/Textile	Adhesive					<b>No Asbestos Detected</b>
8244/B00K/R0009/Floor Coverings Res/Textile/S27						
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8244/B00K/R0005/Floor Coverings Res/Textile/S11					<b>Chrysotile (white asbestos)</b>	
<b>B00K - R1019 - Staff - Toilet (4.87 m2)</b>						
Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
8244/B00K/R0005/Ceiling Structures/Linings/S12					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00K - R1020 - Movement (7.51 m2)</b>						
No Asbestos						
<b>B00K - R1021 - Distribution Board Cupboard (0.9 m2)</b>					Note: No inspection of live electrical installation.	
Electrical Mounting Board	Resinous Board	NA	North	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - Electrical Hazard</b>						
<b>B00K - R1022 - General Storeroom (8.9 m2)</b>						
No Asbestos						
<b>B00K - R1023 - Study Space (16.77 m2)</b>						
Floor Coverings Res/Textile	Adhesive					<b>No Asbestos Detected</b>
	8244/B00K/R0009/Floor Coverings Res/Textile/S27					
Floor Coverings Res/Textile	Vinyl Tiles	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00K/R0005/Floor Coverings Res/Textile/S11					<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
	8244/B00K/R0005/Ceiling Structures/Linings/S12					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
<b>B00K - R1024 - General Learning Space (59.11 m2)</b>						
Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
	8244/B00K/R0005/Ceiling Structures/Linings/S12					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
Floor Coverings Res/Textile	Adhesive					<b>No Asbestos Detected</b>
	8244/B00K/R0009/Floor Coverings Res/Textile/S27					
Floor Coverings Res/Textile	Vinyl Tiles	59m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00K/R0005/Floor Coverings Res/Textile/S11					<b>Chrysotile (white asbestos)</b>
<b>B00K - R1025 - General Learning Space (51.86 m2)</b>						
Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
	8244/B00K/R0005/Ceiling Structures/Linings/S12					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
Floor Coverings Res/Textile	Adhesive					<b>No Asbestos Detected</b>
	8244/B00K/R0009/Floor Coverings Res/Textile/S27					
Floor Coverings Res/Textile	Vinyl Tiles	52m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00K/R0005/Floor Coverings Res/Textile/S11					<b>Chrysotile (white asbestos)</b>
<b>B00K - R1026 - General Learning Space (52.22 m2)</b>						
Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
	8244/B00K/R0005/Ceiling Structures/Linings/S12					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
Floor Coverings Res/Textile	Adhesive					<b>No Asbestos Detected</b>
	8244/B00K/R0009/Floor Coverings Res/Textile/S27					
Floor Coverings Res/Textile	Vinyl Tiles	52m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8244/B00K/R0005/Floor Coverings Res/Textile/S11					<b>Chrysotile (white asbestos)</b>
<b>B00K - R1027 - General Storeroom (12.33 m2)</b>						
Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
	8244/B00K/R0005/Ceiling Structures/Linings/S12					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
Floor Coverings Res/Textile	Adhesive					<b>No Asbestos Detected</b>
	8244/B00K/R0009/Floor Coverings Res/Textile/S27					



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Floor Coverings Res/Textile	Vinyl Tiles	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8244/B00K/R0005/Floor Coverings Res/Textile/S11				Chrysotile (white asbestos)		
<b>B00K - R1028 - Study Space (22.73 m2)</b>						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
8244/B00K/R0005/Ceiling Structures/Linings/S12				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		
Floor Coverings Res/Textile	Adhesive					No Asbestos Detected
8244/B00K/R0009/Floor Coverings Res/Textile/S27						
Floor Coverings Res/Textile	Vinyl Tiles	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8244/B00K/R0005/Floor Coverings Res/Textile/S11				Chrysotile (white asbestos)		
<b>B00K - R1029 - Interview/Office - Type 1 (12.36 m2)</b>						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
8244/B00K/R0005/Ceiling Structures/Linings/S12				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		
Floor Coverings Res/Textile	Adhesive					No Asbestos Detected
8244/B00K/R0009/Floor Coverings Res/Textile/S27						
Floor Coverings Res/Textile	Vinyl Tiles	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8244/B00K/R0005/Floor Coverings Res/Textile/S11				Chrysotile (white asbestos)		
<b>B00K - R1030 - Movement (2.46 m2)</b>						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
8244/B00K/R0005/Ceiling Structures/Linings/S12				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		
Floor Coverings Res/Textile	Vinyl Tiles	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8244/B00K/R0005/Floor Coverings Res/Textile/S11				Chrysotile (white asbestos)		
Floor Coverings Res/Textile	Adhesive					No Asbestos Detected
8244/B00K/R0009/Floor Coverings Res/Textile/S27						
<b>B00K - R1031 - General Learning Space (38.08 m2)</b>						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
8244/B00K/R0005/Ceiling Structures/Linings/S12				Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works		
Floor Coverings Res/Textile	Adhesive					No Asbestos Detected
8244/B00K/R0009/Floor Coverings Res/Textile/S27						
Floor Coverings Res/Textile	Vinyl Tiles	38m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8244/B00K/R0005/Floor Coverings Res/Textile/S11				Chrysotile (white asbestos)		
<b>B00K - R1032 - Movement (227.74 m2)</b>						
No Asbestos						
<b>B00K - R1033 - Cleaning Store - Distributed (1.4 m2)</b>						
No Asbestos						
<b>B00K - R1034 - Stairs (6.91 m2)</b>						
No Asbestos						
<b>B00K - R1035 - Stairs (7.09 m2)</b>						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Demountables***

**There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Listing of Electronic Attachments as of 22/03/2017***

**Available Asbestos Related Electronic Files**

8244\_ASB\_010713\_AMP.pdf

\* Note : Refer to AMS for details of the attachment(s).

2017