


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Bellingen High School (8258)  
**Region :** North Coast  
**State Electorate :** Oxley  
**Local Government Area :** Bellingen

**Initial Survey :** Noel Arnold & Associates : 20 - May - 2008  
**Reviewed By :** Parsons Brinckerhoff : 08 - Oct - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - Library/Computer Learning - 1991 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior****B00A - R0001 - Toilets-Boys (42.47 m2)**

No Asbestos

**B00A - R0002 - External Movement (87.58 m2)**

No Asbestos

**B00A - R0003 - Entry (10.61 m2)**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B00A - R0004 - Main Area (252.37 m2)**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B00A - R0005 - General Learning Space (50.99 m2)**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B00A - R0006 - Senior Seminar (12.68 m2)**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B00A - R0007 - Senior Study (12.83 m2)**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B00A - R0008 - Senior Study (12.68 m2)**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B00A - R0009 - Audio Visual Workroom (25.4 m2)**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B00A - R0010 - Workroom (28.92 m2)**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B00A - R0011 - Librarian (9.96 m2)**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B00A - R0012 - Toilets-Girls (42.39 m2)**

No Asbestos

**B00A - R0013 - External Movement (61.15 m2)**

No Asbestos

**B00A - R0014 - External Stairs (7.18 m2)**

No Asbestos

**B00A - R9001 - Main Switchroom (8.64 m2)**

No Asbestos

**B00A - R9002 - Resources Store (11.15 m2)**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B00A - R9003 - Computer Learning Space (61.94 m2)**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B00A - R9004 - Computer Store (18.22 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R9005 - General Storeroom (8.06 m2)**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R9006 - Tiered Learning Area (68.64 m2)**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R9007 - Resources Store (2.19 m2)**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R9008 - Plant Space (15.54 m2)**

No Asbestos

**B00A - R9009 - External Movement (121.97 m2)**

No Asbestos

**B00A - R9010 - External Stairs (6.43 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - General Learning - 1991 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior****B00B - R0001 - Staff Study (18.18 m2)**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00B - R0002 - General Learning Space (48.76 m2)**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00B - R0003 - General Learning Space (40.08 m2)**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00B - R0004 - Distribution Board Cupboard (1.58 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B00B - R0005 - Resources Store (21.87 m2)**

No Asbestos

**B00B - R0006 - General Learning Space (48.16 m2)**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00B - R0007 - Cleaning Store - Distributed (3.39 m2)**

No Asbestos

**B00B - R0008 - External Movement (97.12 m2)**

No Asbestos

**B00B - R0009 - Staff Study (39.55 m2)**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00B - R0012 - External Movement (17.01 m2)**

No Asbestos

**B00B - R0013 - Toilet - Lobby (1.93 m2)**

No Asbestos

**B00B - R0014 - Staff - Toilet (2.77 m2)**

No Asbestos

**B00B - R0015 - Staff - Toilet (2.86 m2)**

No Asbestos

**B00B - R0016 - Toilet - Lobby (1.98 m2)**

No Asbestos

**B00B - R0017 - External Stairs (2.03 m2)**

No Asbestos

**B00B - R0018 - External Stairs (0.73 m2)**

No Asbestos

**B00B - R1002 - General Learning Space (48.75 m2)**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00B - R1003 - General Learning Space (40.19 m2)**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00B - R1004 - General Storeroom (1.78 m2)**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00B - R1005 - General Learning Space (52.17 m2)</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found						
<b>B00B - R1006 - Resources Store (20.38 m2)</b>						
No Asbestos						
<b>B00B - R1007 - Cleaning Store - Distributed (3.07 m2)</b>						
No Asbestos						
<b>B00B - R1008 - Movement (7.31 m2)</b>						
No Asbestos						
<b>B00B - R1009 - Movement (55.33 m2)</b>						
No Asbestos						
<b>B00B - R1010 - External Movement (15.41 m2)</b>						
No Asbestos						
<b>B00B - R1011 - Senior Study (41.25 m2)</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found						
<b>B00B - R1013 - Movement (14.7 m2)</b>						
No Asbestos						
<b>B00B - R1014 - Senior Study (29.75 m2)</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found						
<b>B00B - R1015 - Stairs (3.36 m2)</b>						
No Asbestos						
<b>B00B - R1016 - Stairs (4.42 m2)</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - Music - 1991 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior****B00C - R0001 - Practice/Seminar (25.46 m2)**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00C - R0002 - Music Learning Space (78.6 m2)**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00C - R0003 - Resources Store (25.21 m2)**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00C - R0004 - Cleaning Store - Distributed (2.51 m2)**

No Asbestos

**B00C - R0005 - Distribution Board Cupboard (2.23 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B00C - R0006 - Music Store (22.84 m2)**

No Asbestos

**B00C - R0007 - General Learning Space (41.11 m2)**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00C - R0009 - External Movement (89.12 m2)**

No Asbestos

**B00C - R0010 - Practice/Seminar (23.91 m2)**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00C - R0011 - External Movement (11.23 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00D - Technological & Applied Studies - 1991 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior****B00D - R0001 - Art Outdoor Area (81.86 m2)**

No Asbestos

**B00D - R0002 - Art Learning Space (62.11 m2)**

No Asbestos

**B00D - R0003 - Darkroom Space (27.3 m2)**

No Asbestos

**B00D - R0004 - Distribution Board Cupboard (0.99 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B00D - R0005 - Resources Store (14.24 m2)**

No Asbestos

**B00D - R0006 - Resources Store (22.62 m2)**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B00D - R0007 - Resources Store (7.21 m2)**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B00D - R0008 - Art Learning Space (61.4 m2)**

No Asbestos

**B00D - R0009 - Staff Study (20.68 m2)**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B00D - R0010 - General Storeroom (21.24 m2)**

No Asbestos

**B00D - R0013 - External Movement (105.29 m2)**

No Asbestos

**B00D - R0014 - External Stairs (2.42 m2)**

No Asbestos

**B00D - R0015 - Covered Area (51.97 m2)**

No Asbestos

**B00D - R0016 - Workshop (61.18 m2)**

No Asbestos

**B00D - R0017 - Kiln Space (13.87 m2)**

No Asbestos

**B00D - R0018 - External Movement (107.43 m2)**

No Asbestos

**B00D - R1001 - Staff Study (19.04 m2)**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B00D - R1002 - Food Technology L.S. (104.63 m2)**

No Asbestos

**B00D - R1003 - Movement (8.07 m2)**

No Asbestos

**B00D - R1004 - Cleaning Store - Distributed (3.45 m2)**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00D - R1005 - Distribution Board Cupboard (0.93 m2)</b>				Note: No inspection of live electrical installation.		
No Asbestos						
<b>B00D - R1006 - Preparation (20.77 m2)</b>						
No Asbestos						
<b>B00D - R1007 - Seminar/Technology Space (12.02 m2)</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found						
<b>B00D - R1008 - Food Technology L.S. (107.61 m2)</b>						
No Asbestos						
<b>B00D - R1010 - Movement (52.22 m2)</b>						
No Asbestos						
<b>B00D - R1011 - Materials Technology L.S. (75.06 m2)</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found						
<b>B00D - R1012 - Resources Store (12.59 m2)</b>						
No Asbestos						
<b>B00D - R1013 - Laundry (6.42 m2)</b>						
No Asbestos						
<b>B00D - R1014 - Stairs (4.39 m2)</b>						
No Asbestos						
<b>B00D - R1015 - External Movement (46.88 m2)</b>						
No Asbestos						
<b>B00D - R1016 - Toilets-Disabled (5.28 m2)</b>						
No Asbestos						
<b>B00D - R1017 - Food/Research Space (53.5 m2)</b>						
No Asbestos						
<b>B00D - R1018 - Store (13.7 m2)</b>						
No Asbestos						

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00E - Technological & Applied Studies - 1991 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior****B00E - M0001 - Resources Store (25.89 m2)**

No Asbestos

**B00E - R0001 - Materials Technology L.S. (103.48 m2)**

No Asbestos

**B00E - R0002 - Wood Technology Bay (35.19 m2)**

No Asbestos

**B00E - R0003 - Materials Technology L.S. (107.16 m2)**

No Asbestos

**B00E - R0004 - Dust Extraction Space (9.12 m2)**

No Asbestos

**B00E - R0005 - Metal Technology Bay (34.8 m2)**

No Asbestos

**B00E - R0006 - Materials Technology L.S. (89.95 m2)**

No Asbestos

**B00E - R0007 - Workshop (57.68 m2)**

No Asbestos

**B00E - R0008 - Welding Area (12.92 m2)**

No Asbestos

**B00E - R0009 - Welding Area (3.68 m2)**

No Asbestos

**B00E - R0010 - Welding Store (2.79 m2)**

No Asbestos

**B00E - R0011 - General Storeroom (1.3 m2)**

No Asbestos

**B00E - R0012 - L.P.G. Store (1.49 m2)**

No Asbestos

**B00E - R0013 - Distribution Board Cupboard (2.36 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B00E - R0014 - Movement (53.66 m2)**

No Asbestos

**B00E - R0015 - Staff Study (22.72 m2)**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00E - R0016 - Materials Store (31.29 m2)**

No Asbestos

**B00E - R0017 - Design L.S. (56.27 m2)**

No Asbestos

**B00E - R0018 - Seminar/Technology Space (26.14 m2)**

No Asbestos

**B00E - R0019 - Movement (17.23 m2)**

No Asbestos

**B00E - R0020 - Toilets-Disabled (11.19 m2)**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00E - R0021 - Cleaning Store - Distributed (4.07 m2)</b>						
No Asbestos						
<b>B00E - R0022 - External Movement (3.32 m2)</b>						
No Asbestos						
<b>B00E - R0023 - External Movement (34.93 m2)</b>						
No Asbestos						
<b>B00E - R0024 - Movement (11.22 m2)</b>						
No Asbestos						
<b>B00E - R0025 - External Movement (36.76 m2)</b>						
No Asbestos						
<b>B00E - R0026 - External Stairs (2.06 m2)</b>						
No Asbestos						
<b>B00E - R0027 - Stairs (1.1 m2)</b>						
No Asbestos						
<b>B00E - R0028 - Stairs (1.32 m2)</b>						
No Asbestos						
<b>B00E - R0029 - Stairs (0.62 m2)</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - General Learning/Computer Learning - 1915 - Timber (Timber)****Exterior**

Eaves Linings	Flat AC Sheeting	60m2	East & West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8258/B00F/Eaves Linings/S7				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
Underfloor Void	Debris / AC Sheeting	>5m2	Throughout	Poor Condition - Extensive Damage (4)	Medium (2)	High Priority (6-8)
	8258/B00F/Underfloor Void/S8				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
Ceiling Void	No Asbestos Found					

**Interior****B00F - R0001 - Staff Study (21.4 m2)**

No Asbestos

**B00F - R0002 - General Learning Space (64.1 m2)**

No Asbestos

**B00F - R0003 - Resources Store (20.75 m2)**

No Asbestos

**B00F - R0004 - General Learning Space (47.45 m2)**

No Asbestos

**B00F - R0005 - General Learning Space (41.22 m2)**

No Asbestos

**B00F - R0006 - Staff Study (40.48 m2)**

No Asbestos

**B00F - R0007 - General Learning Space (52.8 m2)**

No Asbestos

**B00F - R0008 - General Learning Space (57.34 m2)**

No Asbestos

**B00F - R0009 - Staff Study (42.83 m2)**

No Asbestos

**B00F - R0010 - Staff Study (7.86 m2)**

No Asbestos

**B00F - R0011 - Cleaning Store - Distributed (1.98 m2)**

No Asbestos

**B00F - R0012 - Resources Store (7.18 m2)**

No Asbestos

**B00F - R0013 - Seminar Room (22.22 m2)**

No Asbestos

**B00F - R0014 - General Learning Space (53.38 m2)**

No Asbestos

**B00F - R0015 - General Learning Space (53.54 m2)**

No Asbestos

**B00F - R0016 - Seminar Room (22.29 m2)**

No Asbestos

**B00F - R0017 - General Learning Space (53.39 m2)**

No Asbestos

**B00F - R0018 - General Learning Space (53.46 m2)**

No Asbestos

**B00F - R0019 - Study Space (22.27 m2)**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
No Asbestos						
<b>B00F - R0022 - External Movement (284.56 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	285m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8258/B00F/R0022/Ceiling Structures/Linings/S15				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00F - R0023 - Resources Store (5.1 m2)</b>						
No Asbestos						
<b>B00F - R0024 - Toilet - Lobby (1.92 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8258/B00F/R0024/Ceiling Structures/Linings/S16				<b>Chrysotile (white asbestos)</b>		
Wall Linings Internal	Flat AC Sheeting	15m2	Throughout	Some Damage - Unsealed (3)	Medium (2)	Medium Priority (4-5)
8258/B00F/R0024/Wall Linings Internal/S17				<b>Chrysotile (white asbestos)</b>		
<b>B00F - R0025 - Staff - Toilet (2.15 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8258/B00F/R0025/Ceiling Structures/Linings/S18				<b>Chrysotile (white asbestos)</b>		
Wall Linings Internal	Flat AC Sheeting	10m2	Throughout	Some Damage - Unsealed (3)	Medium (2)	Medium Priority (4-5)
8258/B00F/R0025/Wall Linings Internal/S19				<b>Chrysotile (white asbestos)</b>		
<b>B00F - R0026 - Toilet - Lobby (2.74 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8258/B00F/R0026/Ceiling Structures/Linings/S20				<b>Chrysotile (white asbestos)</b>		
Wall Linings Internal	Flat AC Sheeting	20m2	Throughout	Some Damage - Unsealed (3)	Medium (2)	Medium Priority (4-5)
8258/B00F/R0026/Wall Linings Internal/S21				<b>Chrysotile (white asbestos)</b>		
<b>B00F - R0027 - Staff - Toilet (1.26 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8258/B00F/R0027/Ceiling Structures/Linings/S22				<b>Chrysotile (white asbestos)</b>		
Wall Linings Internal	Flat AC Sheeting	10m2	Throughout	Some Damage - Unsealed (3)	Medium (2)	Medium Priority (4-5)
8258/B00F/R0027/Wall Linings Internal/S23				<b>Chrysotile (white asbestos)</b>		
<b>B00F - R0028 - External Movement (11.64 m2)</b>						
No Asbestos						
<b>B00F - R0029 - External Stairs (4.33 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8258/B00F/R0029/Ceiling Structures/Linings/S24				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00F - R9001 - Bulk Store (21.59 m2)</b>						
No Asbestos						
<b>B00F - R9002 - Sport Equipment Store (8.63 m2)</b>						
No Asbestos						
<b>B00F - R9003 - Performing Arts Store (21.75 m2)</b>						
No Asbestos						
<b>B00F - R9004 - External Movement (7.27 m2)</b>						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - Science Learning - 1973 - Brick/Block (Brick/Block)****Exterior**

Gable Ends	Flat AC Sheeting 8258/B00G/Gable Ends/S10	10m2	Throughout Upper Roof	Some Damage - Unsealed (3)	Medium (2)	Medium Priority (4-5) <b>Chrysotile (white asbestos)</b>
Gable Verge Lining	Flat AC Sheeting 8258/B00G/Gable Verge Lining/S11	4m2	Throughout	Some Damage - Unsealed (3)	Medium (2)	Medium Priority (4-5) <b>Chrysotile (white asbestos)</b>
Ceiling Void	AC Sheeting Debris 8258/B00G/Ceiling Void/S9	<1m2	Throughout	Poor Condition - Extensive Damage (4)	Medium (2)	High Priority (6-8) <b>Chrysotile (white asbestos)</b>
Underfloor Void	No Asbestos Found					

**Interior****B00G - R0001 - Serviced Learning Space (58.57 m2)**

Ceiling Structures/Linings	Vermiculite 8258/B00G/R0003/Ceiling Structures/Linings/S5	<b>Limited Samples Taken</b>				
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00G - R0002 - Preparation (43.92 m2)**

Ceiling Structures/Linings	Vermiculite 8258/B00G/R0003/Ceiling Structures/Linings/S5	<b>Limited Samples Taken</b>				
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00G - R0003 - Cleaning Store - Distributed (13.5 m2)**

Ceiling Structures/Linings	Vermiculite 8258/B00G/R0003/Ceiling Structures/Linings/S5	<b>Limited Samples Taken</b>				
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00G - R0004 - Cleaning Store - Distributed (0.58 m2)**

Ceiling Structures/Linings	Vermiculite 8258/B00G/R0003/Ceiling Structures/Linings/S5	<b>Limited Samples Taken</b>				
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00G - R0005 - Distribution Board Cupboard (0.85 m2)**

No Asbestos	Note: No inspection of live electrical installation.				
-------------	--	--	--	--	--

**B00G - R0006 - Apparatus Store (24.77 m2)**

Ceiling Structures/Linings	Vermiculite 8258/B00G/R0003/Ceiling Structures/Linings/S5	<b>Limited Samples Taken</b>				
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00G - R0010 - Stairs (9.26 m2)**

No Asbestos

**B00G - R0011 - Stairs (4.89 m2)**

No Asbestos

**B00G - R0012 - Science Laboratory (55.45 m2)**

No Asbestos

**B00G - R0013 - General Learning Space (35.76 m2)**

No Asbestos

**B00G - R0014 - Science Laboratory (55.24 m2)**

No Asbestos

**B00G - R0015 - General Learning Space (36.17 m2)**

No Asbestos

**B00G - R0016 - External Stairs (6.58 m2)**

No Asbestos

**B00G - R0017 - External Movement (141.12 m2)**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No						Test Result
<b>B00G - R1001 - Staff Study (59.47 m2)</b>						
No Asbestos						
<b>B00G - R1002 - Movement (16.78 m2)</b>						
No Asbestos						
<b>B00G - R1003 - Movement (13.31 m2)</b>						
No Asbestos						
<b>B00G - R1005 - Distribution Board Cupboard (0.66 m2)</b>						Note: No inspection of live electrical installation.
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
8258/B00G/R1005/Ceiling Structures/Linings/S4						<b>Chrysotile (white asbestos)</b>
<b>B00G - R1006 - Cleaning Store - Distributed (2.36 m2)</b>						
No Asbestos						
<b>B00G - R1008 - Preparation (31.11 m2)</b>						
No Asbestos						
<b>B00G - R1009 - Plant (0.89 m2)</b>						
No Asbestos						
<b>B00G - R1012 - External Movement (19.37 m2)</b>						
No Asbestos						
<b>B00G - R1013 - External Movement (18.61 m2)</b>						
No Asbestos						
<b>B00G - R1014 - Toilet - Lobby (1.79 m2)</b>						
No Asbestos						
<b>B00G - R1015 - Staff - Toilet (1.22 m2)</b>						
No Asbestos						
<b>B00G - R1016 - Staff - Toilet (1.21 m2)</b>						
No Asbestos						
<b>B00G - R1017 - Toilet - Lobby (1.77 m2)</b>						
No Asbestos						
<b>B00G - R1018 - Stairs (14.52 m2)</b>						
No Asbestos						
<b>B00G - R1019 - Science Laboratory (64.66 m2)</b>						
No Asbestos						
<b>B00G - R1020 - General Learning Space (33.34 m2)</b>						
No Asbestos						
<b>B00G - R1021 - Science Laboratory (64.74 m2)</b>						
No Asbestos						
<b>B00G - R1022 - General Learning Space (33.35 m2)</b>						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - Technological & Applied Studies - 1999 - Metal Shed (Metal Shed)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00H - R0001 - Materials Store (51.72 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00I - Agricultural Science - 1999 - Metal Shed (Metal Shed)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00I - R0001 - Machine Storage (43.36 m2)**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00J - Agricultural Science/Other - 2008 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00J - R0001 - Animal Space (6.41 m2)**

No Asbestos

**B00J - R0002 - External Movement (2.43 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00K - Other - 2009 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00K - R0001 - Gymnasium (105.34 m2)**

No Asbestos

**B00K - R0002 - General Storeroom (26.53 m2)**

No Asbestos

**B00K - R0003 - External Movement (45.99 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00L - Agricultural Science - 2011 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

**Interior**

**B00L - R0001 - Agriculture Covered Area (24.29 m2)**

No Asbestos

**B00L - R0002 - Tiered Learning Area (20.65 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00M - Music - 1990 - Steel (Steel)****Exterior**

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

**Interior****B00M - R0001 - External Movement (20.72 m2)**

No Asbestos

**B00M - R0002 - Office/Store (8.25 m2)**

No Asbestos

**B00M - R0003 - Practice/Seminar (12.59 m2)**

No Asbestos

**B00M - R0004 - Practice/Seminar (9.94 m2)**

No Asbestos

**B00M - R0005 - Practice/Seminar (9.19 m2)**

No Asbestos

**B00M - R0006 - Music Store (15.03 m2)**

No Asbestos

**B00M - R0007 - Practice/Seminar (12.32 m2)**

No Asbestos

**B00M - R0008 - Practice/Seminar (8.77 m2)**

No Asbestos

**B00M - R0009 - Practice/Seminar (8.96 m2)**

No Asbestos

**B00M - R0010 - Practice/Seminar (10.07 m2)**

No Asbestos

**B00M - R0011 - Practice/Seminar (8.96 m2)**

No Asbestos

**B00M - R0012 - Kitchen - Type 2 (7.1 m2)**

No Asbestos

**B00M - R0013 - Movement (14.8 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B0AD - Administration - 1956 - Timber (Timber)****Exterior**

Eaves Linings	Flat AC Sheeting	20m2	North & South	Good Condition (1)	Low (1)	Low Priority (2-3)
	8258/B0AD/Eaves Linings/S12				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
Underfloor Voids	AC Sheeting Debris	<1m2	Throughout	Poor Condition - Extensive Damage (4)	Medium (2)	High Priority (6-8)
	8258/B0AD/Underfloor Voids/S13				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
Ceiling Void	No Asbestos Found					

**Interior****B0AD - R0001 - Clinic - Girls (13.24 m2)**

No Asbestos

**B0AD - R0003 - Duplicating Workroom (22.01 m2)**

No Asbestos

**B0AD - R0004 - Staff Study (14.36 m2)**

No Asbestos

**B0AD - R0005 - External Movement (85.28 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	86m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8258/B0AD/R0005/Ceiling Structures/Linings/S25				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	

**B0AD - R0007 - Commonroom (76.54 m2)**

No Asbestos

**B0AD - R0008 - Cleaning Store - Distributed (2.77 m2)**

No Asbestos

**B0AD - R0010 - Interview/Office - Type 1 (16.71 m2)**

No Asbestos

**B0AD - R0011 - Ancillary Staff (18.07 m2)**

No Asbestos

**B0AD - R0012 - Movement (8.39 m2)**

No Asbestos

**B0AD - R0013 - Interview/Office - Type 1 (12.87 m2)**

No Asbestos

**B0AD - R0014 - Interview/Office - Type 1 (12.77 m2)**

No Asbestos

**B0AD - R0015 - Deputy Principal Office (7.58 m2)**

No Asbestos

**B0AD - R0016 - Deputy Principal Office (18.25 m2)**

No Asbestos

**B0AD - R0017 - Movement (16.17 m2)**

No Asbestos

**B0AD - R0018 - External Movement (4.87 m2)**

Wall Linings Internal	Flat AC Sheeting					<b>No Asbestos Detected</b>
	8258/B0AD/R0018/Wall Linings Internal/S27					
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8258/B0AD/R0018/Ceiling Structures/Linings/S26				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	

**B0AD - R0019 - Administration - Clerical (56.15 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
<b>B0AD - R0020 - Staff Shower (4.06 m2)</b>						
Wall Linings Internal	Flat AC Sheeting	5m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
8258/B0AD/R0021/Wall Linings Internal/S1					<b>Chrysotile (white asbestos)</b>	
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8258/B0AD/R0020/Ceiling Structures/Linings/S28					<b>Chrysotile (white asbestos)</b>	
<b>B0AD - R0021 - Staff - Toilet (1.68 m2)</b>						
Wall Linings Internal	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8258/B0AD/R0021/Wall Linings Internal/S1					<b>Chrysotile (white asbestos)</b>	
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8258/B0AD/R0021/Ceiling Structures/Linings/S29					<b>Chrysotile (white asbestos)</b>	
<b>B0AD - R0022 - Movement (2.25 m2)</b>						
No Asbestos						
<b>B0AD - R0023 - Principal Office (30.4 m2)</b>						
No Asbestos						
<b>B0AD - R0024 - Interview/Office - Type 1 (12.8 m2)</b>						
No Asbestos						
<b>B0AD - R0025 - General Storeroom (16.29 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting					
8258/B0AD/R0025/Ceiling Structures/Linings/S30					<b>No Asbestos Detected</b>	
<b>B0AD - R0026 - Public Entry (20.43 m2)</b>						
No Asbestos						
<b>B0AD - R0027 - External Movement (9.95 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8258/B0AD/R0027/Ceiling Structures/Linings/S31					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
<b>B0AD - R0028 - Clinic - Boys (11.82 m2)</b>						
No Asbestos						
<b>B0AD - R0029 - Movement (27.63 m2)</b>						
No Asbestos						
<b>B0AD - R0030 - General Storeroom (0.97 m2)</b>						
No Asbestos						
<b>B0AD - R0031 - Other (4.87 m2)</b>						
No Asbestos						
<b>B0AD - R0032 - Staff Study (14.4 m2)</b>						
No Asbestos						
<b>B0AD - R0033 - Toilet - Lobby (2.48 m2)</b>						
No Asbestos						
<b>B0AD - R0034 - Staff - Toilet (2.26 m2)</b>						
No Asbestos						
<b>B0AD - R0035 - Toilet - Lobby (4.17 m2)</b>						
No Asbestos						
<b>B0AD - R0036 - Staff - Toilet (2.05 m2)</b>						
No Asbestos						
<b>B0AD - R0037 - Staff - Toilet (2.05 m2)</b>						
No Asbestos						
<b>B0AD - R9001 - General Assistants (80.91 m2)</b>						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B0AG - Agricultural Science - 1999 - Fibre Cement Clad (Fibre Cement Clad)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior****B0AG - R0001 - Machine Storage (20.05 m2)**

No Asbestos

**B0AG - R0002 - Class Tools Storage (39.88 m2)**

No Asbestos

**B0AG - R0003 - General Storeroom (18.13 m2)**

No Asbestos

**B0AG - R0004 - Animal Space (26.35 m2)**

No Asbestos

**B0AG - R0005 - External Movement (14.31 m2)**

No Asbestos

**B0AG - R0006 - Animal Space (6.3 m2)**

No Asbestos

**B0AG - R0007 - Movement (4.97 m2)**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**BOSP - Technological & Applied Studies - 1999 - Metal Shed (Metal Shed)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**BOSP - R0001 - Materials Store (52.38 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B0WS - Technological & Applied Studies - 1961 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B0WS - R0003 - External Movement (15.1 m2)**

No Asbestos

**B0WS - R0004 - External Movement (18.25 m2)**

No Asbestos

**B0WS - R0005 - Craft Store (34.1 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**BMPU - Multi Purpose Facilities - 1992 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior****BMPU - R0001 - Toilets-Boys (13.54 m2)**

No Asbestos

**BMPU - R0004 - Multi-Purpose Space (461.97 m2)**

No Asbestos

**BMPU - R0005 - Stage (91.94 m2)**

No Asbestos

**BMPU - R0006 - Movement (0.8 m2)**

No Asbestos

**BMPU - R0007 - Movement (0.76 m2)**

No Asbestos

**BMPU - R0008 - Student Canteen (45.37 m2)**

No Asbestos

**BMPU - R0009 - General Storeroom (5.84 m2)**

No Asbestos

**BMPU - R0010 - Toilets-Disabled (4.61 m2)**

No Asbestos

**BMPU - R0011 - Toilets-Girls (18.39 m2)**

No Asbestos

**BMPU - R0012 - Distribution Board Cupboard (1.43 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**BMPU - R0013 - Cleaning Store - Distributed (2.02 m2)**

No Asbestos

**BMPU - R0014 - Sport Equipment Store (34.59 m2)**

No Asbestos

**BMPU - R0015 - Movement (25.74 m2)**

No Asbestos

**BMPU - R0016 - External Movement (112.2 m2)**

No Asbestos

**BMPU - R0017 - External Movement (214.19 m2)**

No Asbestos

**BMPU - R0018 - Staff Study (16.98 m2)**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**BMPU - R0019 - Stairs (18.52 m2)**

No Asbestos

**BMPU - R0020 - Stairs (18.52 m2)**

No Asbestos

**BMPU - R0021 - Stairs (1.7 m2)**

No Asbestos

**BMPU - R0022 - Stairs (1.7 m2)**

No Asbestos

**BMPU - R9001 - General Storeroom (11.18 m2)**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>BMPU - R9002 - Shower/Change (36.53 m2)</b>						
No Asbestos						
<b>BMPU - R9003 - Sport Equipment Store (18.08 m2)</b>						
No Asbestos						
<b>BMPU - R9004 - Shower/Change (36.58 m2)</b>						
No Asbestos						
<b>BMPU - R9005 - General Storeroom (26.26 m2)</b>						
No Asbestos						
<b>BMPU - R9006 - External Movement (102.8 m2)</b>						
No Asbestos						
<b>BMPU - R9007 - External Stairs (11.86 m2)</b>						
No Asbestos						
<b>BMPU - R9008 - External Stairs (11.68 m2)</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**BTAS - Technological & Applied Studies - 1961 - Timber (Timber)**

**Exterior**

Wall Cladding	Flat AC Sheeting 8258/BTAS/Wall Cladding/S3					No Asbestos Detected
Eaves Linings	Flat AC Sheeting 8258/BTAS/Eaves Linings/S14					No Asbestos Detected
Ceiling Voids	No Asbestos Found					
Underfloor Void	No Asbestos Found					

**Interior**

**BTAS - R0001 - General Storeroom (46.94 m2)**

Wall Linings Internal	Flat AC Sheeting 8258/BTAS/R0001/Wall Linings Internal/S2					No Asbestos Detected
-----------------------	--	--	--	--	--	----------------------

**BTAS - R0002 - External Movement (6.14 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

***Demountables***

**There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017