

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Banora Point High School (8282)
Region : North Coast
State Electorate : Tweed
Local Government Area : Tweed

Initial Survey : Noel Arnold & Associates : 27 - May - 2008
Register Issue Date : 24 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration - 2004 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00A - R0001 - Deputy Principal Office**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0002 - Deputy Principal Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0003 - Student Reception

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0004 - Interview/Office - Type 2

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0006 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0007 - Clinic - Girls

No Asbestos

B00A - R0008 - Access Student Shower/Toilet - Type 2

No Asbestos

B00A - R0009 - Clinic - Boys

No Asbestos

B00A - R0010 - Interview/Office - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0011 - Administration - Executive

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0012 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0013 - Administration - Clerical

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0014 - Visitors Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0015 - Public Reception

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0016 - Interview/Meeting

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0018 - Tea Room

No Asbestos

B00A - R0019 - Principal Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0020 - Security Store

No Asbestos

B00A - R0021 - Staff - Toilet

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
B00A - R0022 - Staff - Toilet						
No Asbestos						
B00A - R0023 - External Movement						
No Asbestos						
B00A - R0024 - External Stairs						
No Asbestos						
B00A - R1001 - General Learning Space - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00A - R1002 - Shared Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00A - R1003 - General Learning Space - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00A - R1004 - Cleaning Store - Distributed						
No Asbestos						
B00A - R1005 - G.L.S. Store						
No Asbestos						
B00A - R1006 - General Learning Space - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00A - R1007 - General Learning Space - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00A - R1008 - Seminar - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00A - R1009 - General Learning Space - Type 2						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00A - R1010 - Practical Activity Area						
No Asbestos						
B00A - R1011 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B00A - R1012 - External Stairs						
No Asbestos						
B00A - R1013 - External Movement						
No Asbestos						
B00A - R1014 - External Movement						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Library/General Learning - 2004 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00B - R0001 - Toilets-Boys

No Asbestos

B00B - R0002 - G.L.S. Store

No Asbestos

B00B - R0003 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0004 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0005 - Seminar - Type 1

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0006 - Special Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0007 - Special Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0008 - G.L.S. Store

No Asbestos

B00B - R0009 - General Learning Space - Type 2

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0011 - Special Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0012 - Access Student Shower/Toilet - Type 2

No Asbestos

B00B - R0013 - Student Laundry - Type 2

No Asbestos

B00B - R0014 - Access Student Shower/Toilet - Type 2

No Asbestos

B00B - R0015 - Access Student Shower/Toilet - Type 2

No Asbestos

B00B - R0016 - General Storeroom

No Asbestos

B00B - R0017 - Cleaning Store - Distributed

No Asbestos

B00B - R0018 - Main Switchroom

No Asbestos

B00B - R0019 - Distribution Board Cupboard

No Asbestos

Note: No inspection of live electrical installation.

B00B - R0020 - Distribution Board Cupboard

No Asbestos

Note: No inspection of live electrical installation.

B00B - R0022 - External Movement

No Asbestos

B00B - R0023 - Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
B00B - R0024 - Lift						
No Asbestos						
B00B - R0026 - Practical Activities Area - 2 G.L.S.						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00B - R0027 - General Learning Space - S/P						
No Asbestos						
B00B - R0028 - Movement						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00B - R0029 - General Learning Space - S/P						
No Asbestos						
B00B - R0030 - Movement						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00B - R0031 - External Movement						
No Asbestos						
B00B - R0032 - External Movement						
No Asbestos						
B00B - R0033 - External Movement						
No Asbestos						
B00B - R0034 - External Movement						
No Asbestos						
B00B - R1001 - Access Staff Shower/Toilet						
No Asbestos						
B00B - R1002 - Staff - Toilet						
No Asbestos						
B00B - R1003 - Careers Advisers Office						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00B - R1004 - Seminar - Type 3						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00B - R1005 - Seminar - Type 3						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00B - R1006 - Seminar - Type 3						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00B - R1007 - Main Entry						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00B - R1008 - Library Administration						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00B - R1009 - Main Area						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00B - R1010 - System Administrators Office						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00B - R1011 - Communication Space						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00B - R1012 - Computer Store						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00B - R1013 - Computer Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00B - R1014 - General Learning Space - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00B - R1015 - Distribution Board Cupboard				Note: No inspection of live electrical installation.		
No Asbestos						
B00B - R1016 - Distribution Board Cupboard				Note: No inspection of live electrical installation.		
No Asbestos						
B00B - R1017 - External Movement						
No Asbestos						
B00B - R1018 - Movement						
No Asbestos						
B00B - R1019 - Lift						
No Asbestos						
B00B - R1020 - External Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning/Science Learning - 2004 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00C - R0001 - Seminar - Type 2**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0002 - Botany/Zoology

No Asbestos

B00C - R0003 - General Learning Space - Type 3

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0004 - General Learning Space - Type 3

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0005 - Science Laboratory

No Asbestos

B00C - R0006 - Chemical Store

No Asbestos

B00C - R0007 - Apparatus Store

No Asbestos

B00C - R0008 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0009 - Apparatus Storage

No Asbestos

B00C - R0010 - Preparation - Science

No Asbestos

B00C - R0011 - General Learning Space - Type 3

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0012 - General Learning Space - Type 3

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0014 - Cleaning Store - Distributed

No Asbestos

B00C - R0015 - Toilets-Girls

No Asbestos

B00C - R0016 - External Movement

No Asbestos

B00C - R0017 - External Stairs

No Asbestos

B00C - R0018 - Science Laboratory

No Asbestos

B00C - R0019 - Science Laboratory

No Asbestos

B00C - R1001 - Interview/Meeting

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R1002 - Interview/Meeting

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R1003 - Staff - Toilet

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00C - R1004 - Staff - Toilet

No Asbestos

B00C - R1005 - Staff - Toilet

No Asbestos

B00C - R1006 - Staff - Toilet

No Asbestos

B00C - R1007 - General Storeroom

No Asbestos

B00C - R1008 - Access Staff Shower/Toilet

No Asbestos

B00C - R1009 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00C - R1010 - Preparation/Printing

No Asbestos

B00C - R1011 - Interview/Meeting

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R1012 - Interview/Meeting

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R1013 - Movement

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R1014 - Staff Study

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R1015 - Staff Lounge

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R1016 - Staff Study

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R1017 - External Movement

No Asbestos

B00C - R1018 - External Stairs

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning/Visual Arts Learning Unit - 2004 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00E - R0001 - Project Store - Type 3

No Asbestos

B00E - R0002 - Visual Arts Store

No Asbestos

B00E - R0003 - Visual Arts Workshop

No Asbestos

B00E - R0004 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00E - R0005 - Cleaning Store - Distributed

No Asbestos

B00E - R0006 - Visual Arts Store

No Asbestos

B00E - R0007 - Project Store - Type 3

No Asbestos

B00E - R0008 - Visual Arts Workshop

No Asbestos

B00E - R0009 - General Learning Space - Type 5

No Asbestos

B00E - R0010 - General Learning Space - Type 4

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0011 - Dark Room

No Asbestos

B00E - R0012 - General Learning Space - Type 4

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0013 - General Learning Space - Type 5

No Asbestos

B00E - R0014 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning/Outdoor Covered Workshop - 2004 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00F - R0001 - General Learning Space - Type 9**

No Asbestos

B00F - R0002 - General Learning Space - Type 9

No Asbestos

B00F - R0003 - Resource/Project Store

No Asbestos

B00F - R0004 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00F - R0005 - General Learning Space - Type 8

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0006 - General Learning Space - Type 9

No Asbestos

B00F - R0007 - Materials Workshop - Type 2

No Asbestos

B00F - R0008 - Dust Extraction Space

No Asbestos

B00F - R0009 - Materials Workshop - Type 2

No Asbestos

B00F - R0010 - Materials Store

No Asbestos

B00F - R0011 - Kiln Space

No Asbestos

B00F - R0012 - Pottery Store

No Asbestos

B00F - R0013 - Welding Area

No Asbestos

B00F - R0014 - L.P.G. Store

No Asbestos

B00F - R0015 - Outdoor Workshop

No Asbestos

B00F - R0016 - External Movement

No Asbestos

B00F - R0017 - External Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00G - General Learning - 2004 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00G - R0001 - General Learning Space - Type 7**

No Asbestos

B00G - R0002 - Materials Store - Type 1

No Asbestos

B00G - R0003 - General Learning Space - Type 6

No Asbestos

B00G - R0004 - Kitchen - Type 1

No Asbestos

B00G - R0005 - Preparation - Materials

No Asbestos

B00G - R0006 - Pantry

No Asbestos

B00G - R0007 - Laundry

No Asbestos

B00G - R0008 - Kitchen - Type 1

No Asbestos

B00G - R0009 - General Learning Space - Type 7

No Asbestos

B00G - R0010 - Materials Store - Type 1

No Asbestos

B00G - R0011 - General Learning Space - Type 6

No Asbestos

B00G - R0012 - Cleaning Store - Distributed

No Asbestos

B00G - R0013 - Seminar - Type 2Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00G - R0014 - Distribution Board Cupboard**

No Asbestos

Note: No inspection of live electrical installation.

B00G - R0015 - Distribution Board Cupboard

No Asbestos

Note: No inspection of live electrical installation.

B00G - R0016 - External Movement

No Asbestos

B00G - R0017 - External Stairs

No Asbestos

B00G - R1001 - General Learning Space - Type 2Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00G - R1002 - Shared Learning Space**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00G - R1003 - General Learning Space - Type 1**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00G - R1004 - General Learning Space - Type 1**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00G - R1005 - General Learning Space - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00G - R1006 - Seminar - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00G - R1007 - General Learning Space - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00G - R1008 - General Learning Space - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00G - R1009 - G.L.S. Store						
No Asbestos						
B00G - R1010 - Cleaning Store - Distributed						
No Asbestos						
B00G - R1011 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B00G - R1012 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B00G - R1013 - Practical Activity Area						
No Asbestos						
B00G - R1014 - External Movement						
No Asbestos						
B00G - R1015 - External Stairs						
No Asbestos						
B00G - R1016 - External Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Pupil Facilities - 2004 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00H - R0001 - Office/Store

No Asbestos

B00H - R0002 - Student Canteen

No Asbestos

B00H - R0003 - Change

No Asbestos

B00H - R0004 - Change

No Asbestos

B00H - R0005 - Change

No Asbestos

B00H - R0006 - Change

No Asbestos

B00H - R0007 - Change

No Asbestos

B00H - R0008 - Change

No Asbestos

B00H - R0009 - Toilets-Girls

No Asbestos

B00H - R0010 - Toilets-Boys

No Asbestos

B00H - R0012 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00H - R0013 - Covered Outdoor Space

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00I - Movement Complex - 2004 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00I - R0001 - Gymnasium**

No Asbestos

B00I - R0002 - Stage

No Asbestos

B00I - R0003 - First Aid

No Asbestos

B00I - R0004 - Toilets-Disabled

No Asbestos

B00I - R0005 - Staff Change

No Asbestos

B00I - R0006 - External Movement

No Asbestos

B00I - R0007 - Control RoomVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00I - R0008 - Chair Store**

No Asbestos

B00I - R0009 - Sport Equipment Store

No Asbestos

B00I - R0010 - Plant

No Asbestos

B00I - R0011 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00I - R0012 - Maintenance Bulk Store

No Asbestos

B00I - R0013 - Cleaning Supplies Store

No Asbestos

B00I - R0014 - Movement Studio

No Asbestos

B00I - R0015 - Cleaning Store - Distributed

No Asbestos

B00I - R0016 - Sport Equipment Store

No Asbestos

B00I - R0017 - Store

No Asbestos

B00I - R0018 - Movement Studio Store

No Asbestos

B00I - R0019 - Lift

No Asbestos

B00I - R0020 - External Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - Performance/Fitness Learning Unit - 2004 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00J - R0001 - Change

No Asbestos

B00J - R0002 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R0003 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R0004 - Fitness Store

No Asbestos

B00J - R0005 - Seminar - Type 2

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R0006 - Fitness Laboratory

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R0007 - Change

No Asbestos

B00J - R0008 - Cleaning Store - Distributed

No Asbestos

B00J - R0009 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00J - R0010 - External Movement

No Asbestos

B00J - R1001 - Performance Workshop

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R1002 - Practice/Seminar

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R1003 - Music Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R1004 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R1005 - General Learning Space - Type 1

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R1006 - Archive Store

No Asbestos

B00J - R1007 - Archive Store

No Asbestos

B00J - R1008 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00J - R1009 - External Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017