

Asbestos Register

(Hazardous Materials and Risk Assessment)



School : Brisbane Water Secondary College Woy Woy Campus (8374)
Region : Hunter/Central Coast
State Electorate : Gosford
Local Government Area : Gosford

Initial Survey : Noel Arnold & Associates : 21 - Mar - 2008
Reviewed By : AECOM : 29 - Jun - 2016

8374 - Brisbane Water Secondary College Woy Woy Campus
Site Plan (11412)



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Technological & Applied Studies/Art - 1961 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Packing to Floor Joists	Non Accessible Area - Area inaccessible					
Eaves Linings	Compressed AC Sheet 8374/B00A/Eaves Linings/S6					No Asbestos Detected

Interior

B00A - R0003 - Art Learning Space (58.16 m2)

No Asbestos

B00A - R0004 - Workshop (50.08 m2)

No Asbestos

B00A - R0005 - Kiln Space (7.55 m2)

No Asbestos

B00A - R0006 - Art Learning Space (59.03 m2)

No Asbestos

B00A - R0010 - Laundry (9.42 m2)

No Asbestos

B00A - R0016 - Food Technology L.S. (102.88 m2)

No Asbestos

B00A - R0017 - Resources Store (21.4 m2)

No Asbestos

B00A - R0018 - Staff Study (24.09 m2)

No Asbestos

B00A - R0019 - Resources Store (6.32 m2)

No Asbestos

B00A - R0020 - Computer Learning Space (18.3 m2)

No Asbestos

B00A - R0021 - Senior Study (45.49 m2)

No Asbestos

B00A - R0022 - Design/Technology L.S. (58.67 m2)

No Asbestos

B00A - R0023 - Resources Store (26.08 m2)

No Asbestos

B00A - R0025 - Main Switchroom (6.51 m2)

No Asbestos

B00A - R0026 - External Movement (68.09 m2)

Panel above door	Compressed AC Sheet 8374/B00A/R0026/Panel above door/S4					No Asbestos Detected
Panel between Movements from Block A to Block E	Compressed AC Sheet 8374/B00A/R0026/Panel between Movements from Block A to Block E/S7	2m2	Above window	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

B00A - R0029 - Food Technology L.S. (113.94 m2)

No Asbestos

B00A - R0030 - Class Tools Storage (14.13 m2)

No Asbestos

B00A - R0031 - Plant (0.99 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00A - R0032 - Preparation (20.34 m2)

No Asbestos

B00A - R0033 - Class Tools Storage (9.39 m2)

No Asbestos

B00A - R0034 - Movement (164.11 m2)

No Asbestos

B00A - R0035 - Staff Study (25.5 m2)

No Asbestos

B00A - R0036 - Food Technology L.S. (52.08 m2)

No Asbestos

B00A - R0037 - Staff Study (34.89 m2)

No Asbestos

B00A - R0038 - Tea Room (1.7 m2)

No Asbestos

B00A - R0039 - Design/Technology L.S. (48.4 m2)

No Asbestos

B00A - R0040 - Design L.S. (62.99 m2)

No Asbestos

B00A - R0041 - Handwashing Facilities (4.31 m2)

No Asbestos

B00A - R0042 - External Movement (54.85 m2)

No Asbestos

B00A - R0043 - Chair Store (13.04 m2)

No Asbestos

B00A - R0044 - Outdoor Learning Area (39.19 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning/Music - 1961 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible Height Restriction					
Underfloor Voids - Packing to Floor Joists	Non Accessible Area - Area inaccessible no void entrance located.					
Eaves Linings	Compressed AC Sheet 8374/B00B/Eaves Linings/S28					No Asbestos Detected

Interior

B00B - R0001 - General Learning Space (39.44 m2)						
No Asbestos						
B00B - R0002 - General Learning Space (45.63 m2)						
No Asbestos						
B00B - R0003 - General Learning Space (45.49 m2)						
No Asbestos						
B00B - R0004 - General Learning Space (45.48 m2)						
No Asbestos						
B00B - R0005 - General Learning Space (45.62 m2)						
No Asbestos						
B00B - R0006 - General Learning Space (45.55 m2)						
No Asbestos						
B00B - R0008 - Practice/Seminar (25.46 m2)						
No Asbestos						
B00B - R0009 - Music Learning Space (71.19 m2)						
No Asbestos						
B00B - R0010 - Handwashing Facilities (3.36 m2)						
No Asbestos						
B00B - R0012 - Staff - Toilet (3.23 m2)						
Ceiling Structures/Linings	Compressed AC Sheet 8374/B00B/R0012/Ceiling Structures/Linings/S2					No Asbestos Detected
B00B - R0013 - Movement Studio (59.27 m2)						
No Asbestos						
B00B - R0014 - Practice/Seminar (25.57 m2)						
No Asbestos						
B00B - R0015 - Music Store (18.57 m2)						
No Asbestos						
B00B - R0016 - General Learning Space (45.63 m2)						
No Asbestos						
B00B - R0017 - General Learning Space (58.91 m2)						
No Asbestos						
B00B - R0019 - Resources Store (11.43 m2)						
No Asbestos						
B00B - R0020 - Distribution Board Cupboard (0.64 m2)						
No Asbestos						Note: No inspection of live electrical installation.
B00B - R0022 - Interview/Office - Type 1 (15.84 m2)						
No Asbestos						
B00B - R0023 - Resources Store (6.25 m2)						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00B - R0025 - Resources Store (5.01 m2)						
No Asbestos						
B00B - R0026 - Printing/Photocopying (23.15 m2)						
No Asbestos						
B00B - R0027 - Cleaning Store - Distributed (6.81 m2)						
No Asbestos						
B00B - R0028 - Movement (157.84 m2)						
No Asbestos						
B00B - R0029 - Movement (69.28 m2)						
No Asbestos						
B00B - R0030 - Garden Store Room (20.7 m2)						
No Asbestos						
Ceiling Structures/Linings	Compressed AC Sheet	21m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8374/B00B/R0030/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	
B00B - R0031 - External Movement (58.96 m2)						
No Asbestos						
B00B - R0033 - Staff Study (32.18 m2)						
No Asbestos						
B00B - R0034 - Tea Room (6.48 m2)						
No Asbestos						
B00B - R0035 - Fitness Laboratory (45.69 m2)						
No Asbestos						
B00B - R0037 - Practice/Seminar (17.36 m2)						
No Asbestos						
B00B - R0038 - Handwashing Facilities (1.24 m2)						
No Asbestos						
B00B - R0039 - Resources Store (7.85 m2)						
No Asbestos						
B00B - R0041 - General Storeroom (1.73 m2)						
No Asbestos						
B00B - R0042 - Dark Room (11.17 m2)						
No Asbestos						
B00B - R0043 - External Movement (14.88 m2)						
No Asbestos						
B00B - R0044 - Staff Study (32.18 m2)						
No Asbestos						
B00B - R0045 - Printing/Photocopying (13.04 m2)						
No Asbestos						
B00B - R0046 - Movement (1.19 m2)						
No Asbestos						
B00B - R0047 - Photographic Studio (2.28 m2)						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Performance Learning - 1961 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible no void entrance located.					
Underfloor Voids - Packing to Floor Joists	No Asbestos Found					
Eaves Linings	Compressed AC Sheet 8374/B00C/Eaves Linings/S3					No Asbestos Detected

Interior

B00C - R0002 - Distribution Board Cupboard (0.93 m2) Note: No inspection of live electrical installation.

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0004 - Chair Store (9 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0005 - Toilets-Boys (10.79 m2)

No Asbestos

B00C - R0006 - Toilets-Girls (10.71 m2)

No Asbestos

B00C - R0007 - Movement (49.74 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0008 - Plant (9.66 m2)

No Asbestos

B00C - R0009 - External Movement (14.65 m2)

No Asbestos

B00C - R0010 - Main Switchroom (8.11 m2)

No Asbestos

B00C - R0011 - Control Room (9.7 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0012 - Performance Store (26.83 m2)

No Asbestos

B00C - R0013 - Movement Studio (141.69 m2)

No Asbestos

B00C - R0014 - Stage (18.68 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0016 - Resources Store (8.49 m2)

No Asbestos

B00C - R0017 - External Movement (13.57 m2)

No Asbestos

B00C - R0018 - External Movement (13.68 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00D - General Learning/Science Learning - 1961 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible no void entrance located.					
Eaves Linings	Compressed AC Sheet	50m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Height Restriction 4.0m						
Underfloor Voids	Paper 8374/B00D/Underfloor Voids/S29					No Asbestos Detected

Interior

B00D - R0001 - Computer Learning Space (86.55 m2)

Ceiling Structures/Linings	Vermiculite 8374/B00D/R0019/Ceiling Structures/Linings/S22					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

B00D - R0005 - General Learning Space (52.66 m2)

Ceiling Structures/Linings	Vermiculite 8374/B00D/R0019/Ceiling Structures/Linings/S22					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

B00D - R0006 - General Learning Space (52.59 m2)

Ceiling Structures/Linings	Vermiculite 8374/B00D/R0019/Ceiling Structures/Linings/S22					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

B00D - R0007 - Staff - Toilet (3.61 m2)

Ceiling Structures/Linings	Vermiculite 8374/B00D/R0019/Ceiling Structures/Linings/S22					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

B00D - R0010 - Staff - Toilet (3.73 m2)

Ceiling Structures/Linings	Vermiculite 8374/B00D/R0019/Ceiling Structures/Linings/S22					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

B00D - R0011 - Resources Store (13.05 m2)

Ceiling Structures/Linings	Vermiculite 8374/B00D/R0019/Ceiling Structures/Linings/S22					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

Floor Coverings Res/Textile	Vinyl Sheet 8374/B00D/R0011/Floor Coverings Res/Textile/S23					No Asbestos Detected
-----------------------------	--	--	--	--	--	-----------------------------

B00D - R0012 - General Learning Space (52.81 m2)

Ceiling Structures/Linings	Vermiculite 8374/B00D/R0019/Ceiling Structures/Linings/S22					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

B00D - R0013 - General Learning Space (52.81 m2)

Ceiling Structures/Linings	Vermiculite 8374/B00D/R0019/Ceiling Structures/Linings/S22					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

B00D - R0014 - General Learning Space (52.88 m2)

Ceiling Structures/Linings	Vermiculite 8374/B00D/R0019/Ceiling Structures/Linings/S22					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

B00D - R0016 - Distribution Board Cupboard (0.92 m2)

Electrical Mounting Board	Resinous Board	2Unit	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
				Note: No inspection of live electrical installation.		
Assumed Asbestos - Electrical Hazard						

B00D - R0018 - Music Store (6.16 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite	8374/B00D/R0019/Ceiling Structures/Linings/S22				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R0019 - General Learning Space (52.81 m2)						
Ceiling Structures/Linings	Vermiculite	8374/B00D/R0019/Ceiling Structures/Linings/S22				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R0020 - General Storeroom (6.12 m2)						
Ceiling Structures/Linings	Vermiculite	8374/B00D/R0019/Ceiling Structures/Linings/S22				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R0021 - Computer Learning Space (53.1 m2)						
Ceiling Structures/Linings	Vermiculite	8374/B00D/R0019/Ceiling Structures/Linings/S22				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R0023 - External Movement (9.57 m2)						
Ceiling Structures/Linings	Compressed AC Sheet	8374/B00D/R0030/Ceiling Structures/Linings/S21				No Asbestos Detected
B00D - R0024 - Staff - Toilet (4.95 m2)						
Ceiling Structures/Linings	Vermiculite	8374/B00D/R0019/Ceiling Structures/Linings/S22				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R0025 - Staff - Toilet (4.95 m2)						
Ceiling Structures/Linings	Vermiculite	8374/B00D/R0019/Ceiling Structures/Linings/S22				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R0027 - Computer Store (4.77 m2)						
Ceiling Structures/Linings	Vermiculite	8374/B00D/R0019/Ceiling Structures/Linings/S22				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R0028 - Resources Store (19.26 m2)						
Ceiling Structures/Linings	Vermiculite	8374/B00D/R0019/Ceiling Structures/Linings/S22				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R0030 - External Movement (9.61 m2)						
Ceiling Structures/Linings	Compressed AC Sheet	8374/B00D/R0030/Ceiling Structures/Linings/S21				No Asbestos Detected
B00D - R0032 - External Movement (9.47 m2)						
Ceiling Structures/Linings	Compressed AC Sheet	8374/B00D/R0030/Ceiling Structures/Linings/S21				No Asbestos Detected
B00D - R0033 - Movement (54.02 m2)						
Ceiling Structures/Linings	Vermiculite	8374/B00D/R0019/Ceiling Structures/Linings/S22				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R0035 - Computer Resource (22.07 m2)						
No Asbestos						
B00D - R0036 - Multi Media Studio (17.23 m2)						
No Asbestos						
B00D - R0037 - Multi Media Studio (27.27 m2)						
No Asbestos						
B00D - R0038 - Multi Media Studio (3.55 m2)						
No Asbestos						
B00D - R0039 - Tea Room (2.32 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00D - R0040 - Staff Study (11.49 m2)

No Asbestos

B00D - R0041 - Plant (1.2 m2)

No Asbestos

B00D - R0042 - Staff Study (45.28 m2)

No Asbestos

B00D - R0043 - General Learning Space (40.52 m2)

No Asbestos

B00D - R0044 - Science Laboratory (44.99 m2)

No Asbestos

B00D - R0045 - Movement (125.2 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00E - Pupil Facilities - 1961 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
Eaves Linings	Compressed AC Sheet 8374/B00E/R0008/Ceiling Structures/Linings/S24	50m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	AC Fragments/Debris 8374/B00E/Ceiling Voids/S30					No Asbestos Detected

Interior

B00E - R0002 - Performance Store (44.36 m2)

Ceiling Structures/Linings	Compressed AC Sheet 8374/B00E/R0002/Ceiling Structures/Linings/S26	45m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
----------------------------	---	------	--------------	--------------------	---------	---

B00E - R0004 - Toilets-Boys (74.38 m2)

Ceiling Structures/Linings	Compressed AC Sheet 8374/B00E/R0002/Ceiling Structures/Linings/S26	76m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
Toilet partition	Compressed AC Sheet 8374/B00E/R0004/Toilet partition/S25	76m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

B00E - R0005 - Movement (177.64 m2)

Ceiling Structures/Linings	Compressed AC Sheet 8374/B00E/R0008/Ceiling Structures/Linings/S24	180m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
----------------------------	---	-------	--------------	--------------------	---------	---

B00E - R0007 - Staff - Toilet (4.65 m2)

Ceiling Structures/Linings	Compressed AC Sheet 8374/B00E/R0008/Ceiling Structures/Linings/S24	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
----------------------------	---	-----	--------------	--------------------	---------	---

B00E - R0008 - Office/Store (4.49 m2)

Ceiling Structures/Linings	Compressed AC Sheet 8374/B00E/R0008/Ceiling Structures/Linings/S24	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
----------------------------	---	-----	--------------	--------------------	---------	---

B00E - R0009 - Toilet - Lobby (4.12 m2)

Ceiling Structures/Linings	Compressed AC Sheet 8374/B00E/R0002/Ceiling Structures/Linings/S26	5m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
----------------------------	---	-----	--------------	--------------------	---------	---

B00E - R0010 - Cleaning Store - Distributed (7.54 m2)

Ceiling Structures/Linings	Compressed AC Sheet 8374/B00E/R0002/Ceiling Structures/Linings/S26	8m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
----------------------------	---	-----	--------------	--------------------	---------	---

B00E - R0011 - General Storeroom (7.56 m2)

Ceiling Structures/Linings	Compressed AC Sheet 8374/B00E/R0002/Ceiling Structures/Linings/S26	8m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
----------------------------	---	-----	--------------	--------------------	---------	---

B00E - R0012 - Toilets-Girls (69.14 m2)

8374 Brisbane Water Secondary College Woy Woy Campus

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Ceiling Structures/Linings	Compressed AC Sheet	70m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)
8374/B00E/R0002/Ceiling Structures/Linings/S26				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00E - R0013 - General Storeroom (9.57 m2)						
Ceiling Structures/Linings	Compressed AC Sheet	9m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)
8374/B00E/R0002/Ceiling Structures/Linings/S26				Chrysotile (white asbestos) , Amosite (brown asbestos)		
Flue from boiler	Fibre cement pipe and associated debris on boiler	1m2	All surfaces	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
8374/B00E/R0013/Flue from boiler/S27				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00E - R0015 - General Storeroom (5.15 m2)						
Ceiling Structures/Linings	Compressed AC Sheet	6m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)
8374/B00E/R0002/Ceiling Structures/Linings/S26				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00E - R0017 - General Storeroom (5.06 m2)						
Ceiling Structures/Linings	Compressed AC Sheet	6m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)
8374/B00E/R0002/Ceiling Structures/Linings/S26				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00E - R0018 - External Movement (193.87 m2)						
No Asbestos						
B00E - R0019 - External Movement (32.5 m2)						
Ceiling Structures/Linings	Compressed AC Sheet	29m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8374/B00E/R0008/Ceiling Structures/Linings/S24				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00E - R0020 - Student Canteen (63.04 m2)						
No Asbestos						
B00E - R0021 - Pantry (5.46 m2)						
No Asbestos						
B00E - R0022 - General Storeroom (5.32 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	5.32m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8374/B00E/R0002/Ceiling Structures/Linings/S26				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00E - R0023 - General Storeroom (28.03 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	28.03m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8374/B00E/R0002/Ceiling Structures/Linings/S26				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00E - R0024 - Cleaning Supplies Store (15.21 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	15.21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8374/B00E/R0002/Ceiling Structures/Linings/S26				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00E - R0025 - Machine Storage (25.84 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	25.84m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8374/B00E/R0002/Ceiling Structures/Linings/S26				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00E - R0026 - General Assistants (6 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8374/B00E/R0002/Ceiling Structures/Linings/S26				Chrysotile (white asbestos) , Amosite (brown asbestos)		

8374 Brisbane Water Secondary College Woy Woy Campus

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8374/B00E/R0002/Ceiling Structures/Linings/S26				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00E - R0027 - General Storeroom (23.86 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	23.86m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8374/B00E/R0002/Ceiling Structures/Linings/S26				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00E - R0028 - General Storeroom (5.38 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	5.38m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8374/B00E/R0002/Ceiling Structures/Linings/S26				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00E - R0029 - General Storeroom (4.96 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	4.96m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8374/B00E/R0002/Ceiling Structures/Linings/S26				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00E - R0030 - Toilet - Lobby (3.5 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	3.5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8374/B00E/R0002/Ceiling Structures/Linings/S26				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00E - R0031 - Cleaning Store - Distributed (5.22 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	5.22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8374/B00E/R0002/Ceiling Structures/Linings/S26				Chrysotile (white asbestos) , Amosite (brown asbestos)		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Science Learning/Library - 1973 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

Interior

B00G - M1001 - System Administrators Office (62.92 m2)

Ceiling Structures/Linings	Vermiculite 8374/B00G/R0002/Ceiling Structures/Linings/S12	Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>		

B00G - M1002 - Senior Study (76.71 m2)

No Asbestos

B00G - M1003 - Aboriginal Resource Centre (19.9 m2)

Ceiling Structures/Linings	Vermiculite 8374/B00G/R0002/Ceiling Structures/Linings/S12	Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>		

B00G - M1004 - Senior Study (18.61 m2)

Ceiling Structures/Linings	Vermiculite 8374/B00G/R0002/Ceiling Structures/Linings/S12	Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>		

B00G - M1005 - Stairs (2.25 m2)

No Asbestos

B00G - M1006 - Stairs (3.91 m2)

No Asbestos

B00G - R0001 - Laboratory L.S. (91.39 m2)

Ceiling Structures/Linings	Vermiculite 8374/B00G/R0002/Ceiling Structures/Linings/S12	Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>		

B00G - R0002 - Preparation - Science (47.79 m2)

Ceiling Structures/Linings	Vermiculite 8374/B00G/R0002/Ceiling Structures/Linings/S12	Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>		

Floor Coverings Res/Textile
Vinyl Tiles

8374/B00G/R0002/Floor Coverings Res/Textile/S13	No Asbestos Detected
---	----------------------

B00G - R0003 - Distribution Board Cupboard (0.37 m2)

Note: No inspection of live electrical installation.

Electrical Mounting Board	Resinous Board	1Unit	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
<i>Assumed Asbestos - Electrical Hazard</i>						

B00G - R0004 - Laboratory L.S. (89.1 m2)

Ceiling Structures/Linings	Vermiculite 8374/B00G/R0002/Ceiling Structures/Linings/S12	Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>		

B00G - R0005 - Staff - Toilet (4.43 m2)

Ceiling Structures/Linings	Vermiculite 8374/B00G/R0002/Ceiling Structures/Linings/S12	Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>		

B00G - R0006 - Staff - Toilet (4.38 m2)

Ceiling Structures/Linings	Vermiculite 8374/B00G/R0002/Ceiling Structures/Linings/S12	Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>		

B00G - R0008 - Resources Store (22.76 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
B00G - R0009 - Apparatus Store (32.49 m2)						
Ceiling Structures/Linings	Vermiculite		8374/B00G/R0002/Ceiling Structures/Linings/S12			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00G - R0010 - Chemical Store (11.51 m2)						
No Asbestos						
B00G - R0011 - Laboratory L.S. (91.63 m2)						
Ceiling Structures/Linings	Vermiculite		8374/B00G/R0002/Ceiling Structures/Linings/S12			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00G - R0012 - Movement (66.31 m2)						
Ceiling Structures/Linings	Vermiculite		8374/B00G/R0002/Ceiling Structures/Linings/S12			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles		8374/B00G/R0002/Floor Coverings Res/Textile/S13			No Asbestos Detected
Ceiling space hatch	Compressed AC Sheet		8374/B00G/R0012/Ceiling space hatch/S14			No Asbestos Detected
B00G - R0014 - Cleaning Store - Distributed (4.7 m2)						
No Asbestos						
B00G - R0015 - External Movement (6.3 m2)						
No Asbestos						
B00G - R0016 - Plant (15.07 m2)						
No Asbestos						
B00G - R0018 - Lift (2.09 m2)						
No Asbestos						
B00G - R0019 - Plant (5.55 m2)						
No Asbestos						
B00G - R0020 - Staff Study (37.19 m2)						
No Asbestos						
B00G - R0021 - Tea Room (3.07 m2)						
No Asbestos						
B00G - R0022 - Stairs (11.71 m2)						
No Asbestos						
B00G - R0023 - Movement (24.89 m2)						
No Asbestos						
B00G - R0024 - External Movement (5.41 m2)						
No Asbestos						
B00G - R1001 - Audio Visual Workroom (28.7 m2)						
Ceiling Structures/Linings	Vermiculite		8374/B00G/R0002/Ceiling Structures/Linings/S12			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00G - R1002 - General Storeroom (7.24 m2)						
Ceiling Structures/Linings	Vermiculite		8374/B00G/R0002/Ceiling Structures/Linings/S12			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles		8374/B00G/R0002/Floor Coverings Res/Textile/S13			No Asbestos Detected
B00G - R1003 - Library Administration (20.13 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No						Test Result
No Asbestos						
B00G - R1004 - Librarian (10.54 m2)						
No Asbestos						
B00G - R1005 - Staff - Toilet (3.07 m2)						
No Asbestos						
B00G - R1006 - Main Entry (38.76 m2)						
No Asbestos						
B00G - R1007 - Staff - Toilet (3.11 m2)						
No Asbestos						
B00G - R1008 - Main Area (345.15 m2)						
Ceiling Structures/Linings	Vermiculite					
		8374/B00G/R0002/Ceiling Structures/Linings/S12				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00G - R1009 - Seminar (12.87 m2)						
Ceiling Structures/Linings	Vermiculite					
		8374/B00G/R0002/Ceiling Structures/Linings/S12				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00G - R1010 - Seminar (12.85 m2)						
No Asbestos						
B00G - R1011 - Distribution Board Cupboard (0.7 m2)						Note: No inspection of live electrical installation.
No Asbestos						
B00G - R1012 - Cleaning Store - Distributed (1.88 m2)						
No Asbestos						
B00G - R1013 - Distribution Board Cupboard (0.7 m2)						Note: No inspection of live electrical installation.
Electrical Mounting Board	Resinous Board	1Unit	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Electrical Hazard						
B00G - R1014 - Office/Store (11.9 m2)						
Ceiling Structures/Linings	Vermiculite					
		8374/B00G/R0002/Ceiling Structures/Linings/S12				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00G - R1015 - Independent Learning Space (11.08 m2)						
No Asbestos						
B00G - R1016 - Independent Learning Space (11.66 m2)						
Ceiling Structures/Linings	Vermiculite					
		8374/B00G/R0002/Ceiling Structures/Linings/S12				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00G - R1017 - Movement (2.39 m2)						
No Asbestos						
B00G - R1018 - Movement (25.28 m2)						
No Asbestos						
B00G - R1020 - Stairs (1.73 m2)						
No Asbestos						
B00G - R1021 - Stairs (1.63 m2)						
No Asbestos						
B00G - R1022 - Stairs (16.75 m2)						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - Support Unit - 1965 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

Interior

B00I - R0007 - Distribution Board Cupboard (0.63 m2) Note: No inspection of live electrical installation.

Electrical Mounting Board	Resinous Board	3Unit	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
---------------------------	----------------	-------	--------------	--------------------	---------	--------------------

Assumed Asbestos - Electrical Hazard

B00I - R0011 - Toilets-Disabled (4.57 m2)

No Asbestos

B00I - R0012 - Resources Store (4.62 m2)

No Asbestos

B00I - R0017 - Interview/Office - Type 1 (15.91 m2)

No Asbestos

B00I - R0020 - Resources Store (5.28 m2)

No Asbestos

B00I - R0021 - Special Learning Space (54.23 m2)

No Asbestos

B00I - R0023 - Access Student Shower/Toilet/Change (21.15 m2)

No Asbestos

B00I - R0024 - Laundry (8.45 m2)

No Asbestos

B00I - R0025 - Special Learning Space (53.14 m2)

No Asbestos

B00I - R0026 - Resources Store (4.97 m2)

No Asbestos

B00I - R0027 - Careers Advisers Office (53.38 m2)

No Asbestos

B00I - R0029 - External Movement (28.23 m2)

Ceiling Structures/Linings	Compressed AC Sheet	25m2	Above window	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	---------------------	------	--------------	--------------------	---------	--------------------

8374/B00J/R1009/Ceiling Structures/Linings/S15

Chrysotile (white asbestos) , Amosite (brown asbestos)

B00I - R0030 - Practical Activities (38.72 m2)

No Asbestos

B00I - R0031 - Plant (0.72 m2)

No Asbestos

B00I - R0032 - External Movement (122.88 m2)

Ceiling Structures/Linings	Flat AC Sheeting	122.88m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	----------	------------	--------------------	---------	--------------------

8374/B00J/R1009/Ceiling Structures/Linings/S15

Chrysotile (white asbestos) , Amosite (brown asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - General Learning - 1965 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground Non Accessible Area
 - Area inaccessible

Ceiling Voids - Raked Ceiling No Asbestos Found

Interior

B00J - R0001 - General Learning Space (53.1 m2)

Ceiling Structures/Linings Vermiculite
 8374/B00J/R0006/Ceiling Structures/Linings/S18 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00J - R0002 - General Learning Space (52.66 m2)

Ceiling Structures/Linings Vermiculite
 8374/B00J/R0006/Ceiling Structures/Linings/S18 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00J - R0003 - Distribution Board Cupboard (0.64 m2)

Note: No inspection of live electrical installation.

Electrical Mounting Board Resinous Board 2Unit North facing Good Condition (1) Low (1) Low Priority (2-3)
Assumed Asbestos - Electrical Hazard

B00J - R0005 - General Learning Space (52.73 m2)

Ceiling Structures/Linings Vermiculite
 8374/B00J/R0006/Ceiling Structures/Linings/S18 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00J - R0006 - General Learning Space (52.66 m2)

Ceiling Structures/Linings Vermiculite
 8374/B00J/R0006/Ceiling Structures/Linings/S18 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00J - R0007 - Toilets-Girls (17.41 m2)

Toilet partition Compressed AC Sheet 10m2 All surfaces Good Condition (1) Low (1) Low Priority (2-3)
 8374/B00J/R1007/Toilet partition/S16 **Chrysotile (white asbestos)**

B00J - R0008 - General Storeroom (11.32 m2)

No Asbestos

B00J - R0010 - Staff Study (21.88 m2)

No Asbestos

B00J - R0011 - Tea Room (3.16 m2)

No Asbestos

B00J - R0012 - Stairs (3.54 m2)

No Asbestos

B00J - R0013 - External Movement (6.78 m2)

No Asbestos

B00J - R0014 - External Movement (52.69 m2)

No Asbestos

B00J - R0015 - External Movement (28.95 m2)

No Asbestos

B00J - R1001 - General Learning Space (52.95 m2)

No Asbestos

B00J - R1003 - Distribution Board Cupboard (0.65 m2)

Note: No inspection of live electrical installation.

Electrical Mounting Board Resinous Board 1Unit North facing Good Condition (1) Low (1) Low Priority (2-3)
Assumed Asbestos - Electrical Hazard

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling panel & associated debris to floor	Compressed AC Sheet	1m2	Above window	Some Damage / Unsealed (3)	Medium (2)	Low Priority (2-3)
8374/B00J/R1003/Ceiling panel & associated debris to floor/S17					Chrysotile (white asbestos)	
B00J - R1005 - General Learning Space (52.81 m2)						
No Asbestos						
B00J - R1006 - General Learning Space (52.66 m2)						
No Asbestos						
B00J - R1007 - Cleaning Store - Distributed (17.53 m2)						
Toilet partition	Compressed AC Sheet	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8374/B00J/R1007/Toilet partition/S16					Chrysotile (white asbestos)	
B00J - R1008 - Resources Store (10.84 m2)						
No Asbestos						
B00J - R1009 - External Movement (72.81 m2)						
Ceiling Structures/Linings	Compressed AC Sheet	74m2	Above window	Good Condition (1)	Low (1)	Low Priority (2-3)
8374/B00J/R1009/Ceiling Structures/Linings/S15					Chrysotile (white asbestos) , Amosite (brown asbestos)	
B00J - R1011 - External Stairs (16.64 m2)						
No Asbestos						
B00J - R1012 - Staff Study (52.73 m2)						
Recently Modified Space Requires Inspection						
B00J - R1013 - Staff Lounge (25.16 m2)						
Recently Modified Space Requires Inspection						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - Technological & Applied Studies - 1978 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Packing to Floor Joists	No Asbestos Found					
Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible no void entrance located.					
Awning to entrance	Compressed AC Sheet 8374/B00M/Awning to entrance/S9					No Asbestos Detected
Eaves Linings	Compressed AC Sheet	100m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Height Restriction 4.0m						

Interior

B00M - R0003 - General Storeroom (14.41 m2)

No Asbestos

B00M - R0004 - Metal Technology Bay (31.42 m2)

No Asbestos

B00M - R0007 - Class Tools Storage (3.56 m2)

Ceiling Structures/Linings	Compressed AC Sheet 8374/B00M/R0007/Ceiling Structures/Linings/S8					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

B00M - R0009 - Distribution Board Cupboard (1.15 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00M - R0010 - Materials Store (33.47 m2)

Ceiling Structures/Linings	Compressed AC Sheet 8374/B00M/R0015/Ceiling Structures/Linings/S10					No Asbestos Detected
----------------------------	---	--	--	--	--	----------------------

B00M - R0012 - Wood Technology Bay (30.49 m2)

No Asbestos

B00M - R0013 - Dust Extraction Space (6.48 m2)

No Asbestos

B00M - R0014 - Cleaning Store - Distributed (3.26 m2)

Ceiling Structures/Linings	Compressed AC Sheet 8374/B00M/R0015/Ceiling Structures/Linings/S10					No Asbestos Detected
----------------------------	---	--	--	--	--	----------------------

B00M - R0015 - Staff - Toilet (5.05 m2)

Ceiling Structures/Linings	Compressed AC Sheet 8374/B00M/R0015/Ceiling Structures/Linings/S10					No Asbestos Detected
----------------------------	---	--	--	--	--	----------------------

B00M - R0020 - Materials Technology L.S. (73.24 m2)

No Asbestos

B00M - R0021 - Outdoor Workshop (66 m2)

No Asbestos

B00M - R0022 - Welding Area (3.44 m2)

No Asbestos

B00M - R0023 - Welding Area (3.42 m2)

No Asbestos

B00M - R0024 - Materials Technology L.S. (85.4 m2)

No Asbestos

B00M - R0025 - Materials Technology L.S. (92.51 m2)

No Asbestos

B00M - R0026 - Materials Technology L.S. (86.12 m2)

No Asbestos

B00M - R0027 - Handwashing Facilities (3.32 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00M - R0028 - Materials Technology L.S. (86.4 m2)						
No Asbestos						
B00M - R0029 - Handwashing Facilities (3.31 m2)						
No Asbestos						
B00M - R0030 - Machine Storage (1.18 m2)						
No Asbestos						
B00M - R0031 - Materials Store (1.18 m2)						
No Asbestos						
B00M - R0032 - Project Store - Type 1 (1.18 m2)						
No Asbestos						
B00M - R0033 - Project Store - Type 1 (1.18 m2)						
No Asbestos						
B00M - R0034 - Project Store - Type 1 (1.18 m2)						
No Asbestos						
B00M - R0035 - Project Store - Type 1 (1.18 m2)						
No Asbestos						
B00M - R0036 - Movement (64.02 m2)						
No Asbestos						
B00M - R0037 - External Movement (45.22 m2)						
No Asbestos						
B00M - R0038 - External Movement (7.18 m2)						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00N - Multi Purpose Facilities - 1997 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible
Ceiling Voids	No Asbestos Found

Interior

B00N - M0001 - General Storeroom (5.57 m2)

No Asbestos

B00N - M0002 - General Storeroom (5.54 m2)

No Asbestos

B00N - R0001 - External Movement (170.5 m2)

No Asbestos

B00N - R0002 - Sport Equipment Store (24 m2)

No Asbestos

B00N - R0003 - Movement (3.66 m2)

No Asbestos

B00N - R0004 - Sport Equipment Store (22.11 m2)

No Asbestos

B00N - R0005 - Distribution Board Cupboard (2.14 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00N - R0009 - Stage (67.54 m2)

No Asbestos

B00N - R0013 - Cleaning Store - Distributed (4.04 m2)

No Asbestos

B00N - R0014 - Plant (0.32 m2)

No Asbestos

B00N - R0015 - Staff Kitchen (15.4 m2)

No Asbestos

B00N - R0016 - Sport Equipment Store (9.2 m2)

No Asbestos

B00N - R0017 - Staff - Toilet (7.89 m2)

No Asbestos

B00N - R0018 - General Storeroom (22.5 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00N - R0019 - Control Room (1.23 m2)

No Asbestos

B00N - R0020 - Multi-Purpose Space (483.84 m2)

No Asbestos

B00N - R0021 - Movement (17.15 m2)

No Asbestos

B00N - R0022 - Movement (15.12 m2)

No Asbestos

B00N - R0023 - Stairs (4.8 m2)

No Asbestos

B00N - R0024 - Stairs (5.62 m2)

No Asbestos

B00N - R0025 - Toilet - Lobby (5.2 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00N - R0026 - Toilets-Boys (12.31 m2)

No Asbestos

B00N - R0027 - Change (26.78 m2)

No Asbestos

B00N - R0028 - Toilet - Lobby (2.34 m2)

No Asbestos

B00N - R0029 - Toilets-Girls (15.2 m2)

No Asbestos

B00N - R0030 - Change (34.04 m2)

No Asbestos

B00N - R0031 - Chair Store (67.07 m2)

No Asbestos

B00N - R1001 - General Storeroom (78.43 m2)

No Asbestos

B00N - R1002 - Performance Store (20.92 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00N - R1003 - Stairs (5.5 m2)

No Asbestos

B00N - R1004 - Stairs (4.76 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B000 - Administration - 2005 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible
Ceiling Voids	No Asbestos Found

Interior

B000 - R0001 - Principal Office (19.06 m2)

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B000 - R0002 - External Movement (1.33 m2)

No Asbestos

B000 - R0003 - Movement (3.63 m2)

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B000 - R0004 - Archive Store (11.84 m2)

No Asbestos

B000 - R0005 - Staff - Toilet (5.25 m2)

No Asbestos

B000 - R0006 - Staff - Toilet (5.28 m2)

No Asbestos

B000 - R0009 - Interview/Meeting (18.07 m2)

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B000 - R0011 - Office/Store (11.9 m2)

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B000 - R0012 - Leading Teacher (11.9 m2)

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B000 - R0013 - Administration - Clerical (12.15 m2)

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B000 - R0014 - Clinic - Boys (12.94 m2)

No Asbestos

B000 - R0015 - Toilets-Disabled (4.99 m2)

No Asbestos

B000 - R0016 - Cleaning Store - Distributed (3.16 m2)

No Asbestos

B000 - R0017 - Clinic - Girls (12.41 m2)

No Asbestos

B000 - R0018 - Deputy Principal Office (13.11 m2)

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B000 - R0019 - Deputy Principal Office (13.1 m2)

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B000 - R0020 - Student Waiting (40.12 m2)

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B000 - R0021 - Distribution Board Cupboard (0.56 m2)

Note: No inspection of live electrical installation.

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B000 - R0023 - Staff Kitchen (5.58 m2)						
No Asbestos						
B000 - R0024 - Public Reception (32.03 m2)						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B000 - R0025 - Interview/Meeting (12.55 m2)						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B000 - R0026 - External Movement (91.79 m2)						
No Asbestos						
B000 - R0027 - Administration - Clerical (84.8 m2)						
No Asbestos						
B000 - R0028 - Principal Office (24.23 m2)						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00P - General Learning - 2010 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Packing to Floor Joists	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00P - R0001 - Movement (44.12 m2)

No Asbestos

B00P - R0002 - General Learning Space (46.8 m2)

No Asbestos

B00P - R0003 - General Learning Space (59.48 m2)

No Asbestos

B00P - R0004 - Access Student Shower/Toilet/Change (5.97 m2)

No Asbestos

B00P - R0005 - Distribution Board Cupboard (0.57 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00P - R0006 - Cleaning Store - Distributed (2.89 m2)

No Asbestos

B00P - R0007 - Movement (5.9 m2)

No Asbestos

B00P - R0008 - Other (82.48 m2)

No Asbestos

B00P - R0009 - Staff Study (72.83 m2)

No Asbestos

B00P - R0010 - External Movement (32.24 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00Q - Storage - 2013 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground Non Accessible Area
 - Area inaccessible

Ceiling Voids No Asbestos Found

Interior

B00Q - R0001 - Store (66.1 m2)

No Asbestos

B00Q - R0002 - Store (13.87 m2)

No Asbestos

B00Q - R0003 - Store (13.87 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00Z - Building Services - 1961 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids Requires Inspection

Underfloor Voids Requires Inspection

Interior

B00Z - R0001 - Plant (1.56 m2)

Recently Modified Space Requires Inspection

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

Available Asbestos Related Electronic Files

8374_ASB_010713_AMP.pdf

* Note : Refer to AMS for details of the attachment(s).

2017