


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Batemans Bay High School (8581)  
**Region :** Illawarra and South East  
**State Electorate :** Bega  
**Local Government Area :** Eurobodalla

**Initial Survey :** Noel Arnold & Associates : 07 - May - 2008  
**Register Issue Date :** 24 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

### B00A - General Learning/Multi Purpose Facilities - 1987 - Brick/Block (Brick/Block)

#### Exterior

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

#### Interior

##### B00A - R0001 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

##### B00A - R0002 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

##### B00A - R0003 - Cleaning Store - Distributed

No Asbestos

##### B00A - R0005 - Staff Study

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

##### B00A - R0008 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

##### B00A - R0009 - General Storeroom

No Asbestos

##### B00A - R0010 - Toilets-Girls

No Asbestos

##### B00A - R0011 - Toilets-Boys

No Asbestos

##### B00A - R0012 - Workroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

##### B00A - R0013 - Librarian

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

##### B00A - R0014 - Seminar

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

##### B00A - R0015 - Seminar

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

##### B00A - R0016 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

##### B00A - R0017 - General Storeroom

No Asbestos

##### B00A - R0018 - Main Area

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

##### B00A - R0019 - Audio Visual Workroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

##### B00A - R0020 - External Movement

No Asbestos

##### B00A - R0021 - General Storeroom

No Asbestos

##### B00A - R0022 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

##### B00A - R0023 - General Learning Space

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No						Test Result
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R0024 - General Learning Space</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R0025 - General Learning Space</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R0026 - Staff Study</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R0027 - Careers Advisers Office</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R0028 - Deputy Principal Office</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R0029 - Duplicating Workroom</b>						
No Asbestos						
<b>B00A - R0030 - General Storeroom</b>						
No Asbestos						
<b>B00A - R0031 - Interview/Office - Type 1</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R0032 - Principal Office</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R0033 - Public Entry</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R0034 - Interview/Meeting</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R0035 - Administration - Clerical</b>						
No Asbestos						
<b>B00A - R0036 - Staff - Toilet</b>						
No Asbestos						
<b>B00A - R0037 - Staff - Toilet</b>						
No Asbestos						
<b>B00A - R0038 - Clinic - Girls</b>						
No Asbestos						
<b>B00A - R0039 - Secure Storeroom</b>						
No Asbestos						
<b>B00A - R0040 - Administration - Clerical</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R0041 - Pupil Entry</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R0042 - External Movement</b>						
No Asbestos						
<b>B00A - R0043 - Distribution Board Cupboard</b>						Note: No inspection of live electrical installation.
No Asbestos						
<b>B00A - R0044 - Tiered Learning Area</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R0045 - Tiered Learning Store</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R0046 - Distribution Board Cupboard</b>				Note: No inspection of live electrical installation.		
No Asbestos						
<b>B00A - R0047 - Movement</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R0048 - Cleaning Store - Distributed</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R0049 - Multi-Purpose Space</b>						
No Asbestos						
<b>B00A - R0050 - Chair Store</b>						
No Asbestos						
<b>B00A - R0051 - Movement</b>						
No Asbestos						
<b>B00A - R0052 - Stage</b>						
No Asbestos						
<b>B00A - R0053 - Movement</b>						
No Asbestos						
<b>B00A - R0054 - Sport Equipment Store</b>						
No Asbestos						
<b>B00A - R0055 - Sport Equipment Store</b>						
No Asbestos						
<b>B00A - R0056 - Cleaning Supplies Store</b>						
No Asbestos						
<b>B00A - R0057 - Main Switchroom</b>						
No Asbestos						
<b>B00A - R0058 - Maintenance Bulk Store</b>						
No Asbestos						
<b>B00A - R0059 - Movement</b>						
No Asbestos						
<b>B00A - R0060 - Cleaning Store - Distributed</b>						
No Asbestos						
<b>B00A - R0061 - Sport Equipment Store</b>						
No Asbestos						
<b>B00A - R0062 - General Storeroom</b>						
No Asbestos						
<b>B00A - R0063 - External Movement</b>						
No Asbestos						
<b>B00A - R0064 - Toilets-Boys</b>						
No Asbestos						
<b>B00A - R0065 - Toilets-Girls</b>						
No Asbestos						
<b>B00A - R0066 - External Movement</b>						
No Asbestos						
<b>B00A - R0067 - External Movement</b>						
No Asbestos						
<b>B00A - R0068 - General Learning Space</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R0069 - Design L.S.</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R0070 - Resource/Project Store</b>						
No Asbestos						
<b>B00A - R0071 - Cleaning Store - Distributed</b>						
No Asbestos						
<b>B00A - R0072 - General Storeroom</b>						
No Asbestos						
<b>B00A - R0073 - Distribution Board Cupboard</b>					Note: No inspection of live electrical installation.	
No Asbestos						
<b>B00A - R0074 - Interview/Office - Type 1</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R0075 - Interview/Office - Type 1</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R0076 - Movement</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R0077 - Cleaning Store - Distributed</b>						
No Asbestos						
<b>B00A - R0078 - External Movement</b>						
No Asbestos						
<b>B00A - R0079 - External Movement</b>						
No Asbestos						
<b>B00A - R0080 - External Movement</b>						
No Asbestos						
<b>B00A - R0081 - External Movement</b>						
No Asbestos						
<b>B00A - R0082 - External Movement</b>						
No Asbestos						
<b>B00A - R0083 - Interview/Office - Type 1</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R0084 - General Storeroom</b>						
No Asbestos						
<b>B00A - R0085 - Covered Area</b>						
No Asbestos						
<b>B00A - R0086 - External Stairs</b>						
No Asbestos						
<b>B00A - R0089 - Stairs</b>						
No Asbestos						
<b>B00A - R0090 - Stairs</b>						
No Asbestos						
<b>B00A - R0092 - External Movement</b>						
No Asbestos						
<b>B00A - R0093 - Staff Study</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R0094 - Movement</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R0095 - Stairs</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R0096 - General Storeroom</b>						
No Asbestos						
<b>B00A - R0097 - Stairs</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R0098 - Lift</b>						
No Asbestos						
<b>B00A - R0099 - Stairs</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R0100 - General Storeroom</b>						
No Asbestos						
<b>B00A - R0101 - Stairs</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R0102 - Plant</b>						
No Asbestos						
<b>B00A - R0103 - Stairs</b>						
No Asbestos						
<b>B00A - R0104 - Stairs</b>						
No Asbestos						
<b>B00A - R0105 - Plant</b>						
No Asbestos						
<b>B00A - R0106 - Stairs</b>						
No Asbestos						
<b>B00A - R0107 - Stairs</b>						
No Asbestos						
<b>B00A - R0108 - External Movement</b>						
No Asbestos						
<b>B00A - R0109 - External Movement</b>						
No Asbestos						
<b>B00A - R0110 - External Movement</b>						
No Asbestos						
<b>B00A - R0111 - External Movement</b>						
No Asbestos						
<b>B00A - R1001 - General Learning Space</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R1002 - General Learning Space</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R1003 - Careers Advisers Office</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R1004 - Interview/Office - Type 1</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R1005 - General Learning Space</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No						Test Result
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R1006 - General Learning Space</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R1007 - Movement</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R1008 - General Storeroom</b>						
No Asbestos						
<b>B00A - R1009 - Staff Study</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R1010 - Staff - Toilet</b>						
No Asbestos						
<b>B00A - R1011 - Staff - Toilet</b>						
No Asbestos						
<b>B00A - R1012 - Cleaning Store - Distributed</b>						
No Asbestos						
<b>B00A - R1013 - Commonroom</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R1014 - External Movement</b>						
No Asbestos						
<b>B00A - R1015 - Seminar</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R1016 - Seminar</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R1017 - Senior Seminar</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R1018 - General Learning Space</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R1019 - General Learning Space</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R1020 - General Learning Space</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R1021 - Staff Study</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R1022 - Music Store</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R1023 - Music Learning Space</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R1024 - Practice/Seminar</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00A - R1025 - Distribution Board Cupboard</b>						
No Asbestos						Note: No inspection of live electrical installation.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00A - R1026 - Plant</b>						
No Asbestos						
<b>B00A - R1027 - Practice/Seminar</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found						
<b>B00A - R1028 - Music Learning Space</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found						
<b>B00A - R1031 - Shower/Change</b>						
No Asbestos						
<b>B00A - R1032 - Shower/Change</b>						
No Asbestos						
<b>B00A - R1033 - Shower/Change</b>						
No Asbestos						
<b>B00A - R1034 - Cleaning Store - Distributed</b>						
No Asbestos						
<b>B00A - R1035 - Shower/Change</b>						
No Asbestos						
<b>B00A - R1036 - Shower/Change</b>						
No Asbestos						
<b>B00A - R1037 - Shower/Change</b>						
No Asbestos						
<b>B00A - R1038 - Movement</b>						
No Asbestos						
<b>B00A - R1040 - Interview/Office - Type 1</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found						
<b>B00A - R1041 - Staff Study</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found						
<b>B00A - R1042 - Computer Learning Space</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found						
<b>B00A - R1043 - Computer Store</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found						
<b>B00A - R1044 - Computer Resource</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found						
<b>B00A - R1045 - General Learning Space</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found						
<b>B00A - R1046 - Staff Study</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found						
<b>B00A - R1047 - General Storeroom</b>						
No Asbestos						
<b>B00A - R1048 - Distribution Board Cupboard</b>					Note: No inspection of live electrical installation.	
No Asbestos						
<b>B00A - R1049 - Movement</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found						
<b>B00A - R1050 - External Movement</b>						
No Asbestos						



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00A - R1051 - External Movement</b>						
No Asbestos						
<b>B00A - R1052 - Stairs</b>						
No Asbestos						
<b>B00A - R1053 - External Stairs</b>						
No Asbestos						
<b>B00A - R1054 - Stairs</b>						
No Asbestos						
<b>B00A - R1055 - Stairs</b>						
No Asbestos						
<b>B00A - R1056 - Stairs</b>						
No Asbestos						
<b>B00A - R1057 - Lift</b>						
No Asbestos						
<b>B00A - R1058 - Stairs</b>						
No Asbestos						
<b>B00A - R1059 - Stairs</b>						
No Asbestos						
<b>B00A - R1060 - Stairs</b>						
No Asbestos						
<b>B00A - R1061 - Stairs</b>						
No Asbestos						
<b>B00A - R1062 - Staff Study</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found						
<b>B00A - R1063 - Movement</b>						
No Asbestos						
<b>B00A - R1064 - Staff Study</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - Pupil Facilities - 1987 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

**Interior****B00B - R0001 - Movement**

No Asbestos

**B00B - R0002 - Student Canteen**

No Asbestos

**B00B - R0003 - General Storeroom**

No Asbestos

**B00B - R0004 - Toilets-Disabled**

No Asbestos

**B00B - R0005 - General Assistants**

No Asbestos

**B00B - R0006 - Garden Store Room**

No Asbestos

**B00B - R0007 - External Movement**

No Asbestos

**B00B - R0008 - External Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00C - Technological & Applied Studies - 1987 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

**Interior****B00C - R0001 - Materials Store**

No Asbestos

**B00C - R0002 - Welding Area**

No Asbestos

**B00C - R0003 - Staff Study**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B00C - R0004 - Materials Technology L.S.**

No Asbestos

**B00C - R0005 - Wood Technology Bay**

No Asbestos

**B00C - R0006 - Materials Technology L.S.**

No Asbestos

**B00C - R0007 - Dust Extraction Space**

No Asbestos

**B00C - R0008 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

**B00C - R0009 - Workshop Area**

No Asbestos

**B00C - R0010 - Welding Area**

No Asbestos

**B00C - R0011 - Welding Store**

No Asbestos

**B00C - R0012 - General Storeroom**

Non Accessible

**B00C - R0013 - Materials Technology L.S.**

No Asbestos

**B00C - R0014 - Metal Technology Bay**

No Asbestos

**B00C - R0015 - Materials Technology L.S.**

No Asbestos

**B00C - R0018 - External Movement**

No Asbestos

**B00C - R0019 - Seminar/Technology Space**

No Asbestos

**B00C - R0020 - Toilets-Disabled**

No Asbestos

**B00C - R0021 - External Movement**

No Asbestos

**B00C - R0022 - External Movement**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - Art - 1987 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

**Interior****B00D - R0001 - External Movement**

No Asbestos

**B00D - R0002 - Cleaning Store - Distributed**

No Asbestos

**B00D - R0003 - Staff - Toilet**

No Asbestos

**B00D - R0004 - Staff - Toilet**

No Asbestos

**B00D - R0005 - General Storeroom**

No Asbestos

**B00D - R0006 - Art Learning Space**

No Asbestos

**B00D - R0007 - Movement**

No Asbestos

**B00D - R0008 - Staff Study**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00D - R0009 - Resources Store**

No Asbestos

**B00D - R0010 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

**B00D - R0011 - Art Learning Space**

No Asbestos

**B00D - R0012 - Workshop**

No Asbestos

**B00D - R0013 - Art Learning Space**

No Asbestos

**B00D - R0014 - Movement**

No Asbestos

**B00D - R0015 - Staff Study**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00D - R0016 - Bulk Store**

No Asbestos

**B00D - R0017 - External Movement**

No Asbestos

**B00D - R0018 - External Movement**

No Asbestos

**B00D - R0019 - External Movement**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - Technological & Applied Studies - 1987 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

**Interior****B00E - R0001 - Design L.S.**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00E - R0002 - Design L.S.**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00E - R0003 - Food Technology L.S.**

No Asbestos

**B00E - R0004 - Food/Research Space**

No Asbestos

**B00E - R0005 - Food Technology L.S.**

No Asbestos

**B00E - R0006 - Food/Research Space**

No Asbestos

**B00E - R0007 - Staff Study**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00E - R0008 - Laundry**

No Asbestos

**B00E - R0009 - External Movement**

No Asbestos

**B00E - R0010 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

**B00E - R0011 - External Movement**

No Asbestos

**B00E - R0012 - External Movement**

No Asbestos

# 2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - Science Learning - 1987 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

**Interior****B00F - R0001 - Laboratory L.S.**

No Asbestos

**B00F - R0002 - Preparation**

No Asbestos

**B00F - R0003 - Interview/Office - Type 1**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B00F - R0004 - Toilets-Boys**

No Asbestos

**B00F - R0005 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

**B00F - R0006 - Toilets-Girls**

No Asbestos

**B00F - R0007 - External Movement**

No Asbestos

**B00F - R0008 - Staff - Toilet**

No Asbestos

**B00F - R0009 - Staff - Toilet**

No Asbestos

**B00F - R0010 - Cleaning Store - Distributed**

No Asbestos

**B00F - R0011 - Toilets-Disabled**

No Asbestos

**B00F - R0012 - Laboratory L.S.**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B00F - R0013 - Preparation**

No Asbestos

**B00F - R0014 - Laboratory L.S.**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B00F - R0015 - Laboratory L.S.**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B00F - R0016 - Preparation**

No Asbestos

**B00F - R0017 - Laboratory L.S.**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B00F - R0018 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

**B00F - R0019 - Staff Study**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B00F - R0020 - Apparatus Store**

No Asbestos

**B00F - R0021 - Chemical Store**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

**B00F - R0022 - External Movement**

No Asbestos

**B00F - R0023 - External Movement**

No Asbestos

**B00F - R0024 - Covered Vehicle Area/Porte Cochere**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - Agricultural Science - 1987 - Timber (Timber)**

**Exterior**

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

**Interior**

**B00G - R0001 - Animal Space**

No Asbestos

**B00G - R0002 - Animal Space**

No Asbestos

**B00G - R0003 - Class Tools Storage**

No Asbestos

**B00G - R0004 - Machine Storage**

No Asbestos

**B00G - R0005 - Plant Space**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - Agricultural Science - 2004 - Metal Shed (Metal Shed)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00H - R0001 - Machine Storage**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00I - Agricultural Science - 2004 - Metal Shed (Metal Shed)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00I - R0001 - Machine Storage**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00J - Technological & Applied Studies - 2004 - Steel (Steel)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00J - R0001 - Workshop Area**

No Asbestos

**B00J - R0002 - Workshop Area**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

## Demountables

**Demountable details as per the AMS records as of 15 Feb 2017.**

### OS 601 - D10323 - Learning Unit - Standard/Withdrawal : Placement Date - 19/01/2017

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

#### Exterior

No Asbestos Found.

#### Interior

##### R1 - Entry

No Asbestos Found.

##### R2 - General Learning Space

No Asbestos Found.

##### R3 - Store

No Asbestos Found.

### OS 601 - D13487 - Learning Unit - Standard/Withdrawal : Placement Date - 27/05/1997

#### Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

#### Interior

##### R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

##### R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

##### R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2
---------	---------------	------------------	-------

### NS 111 - D15202 - Learning Unit - Double Secondary/Secure : Placement Date - 30/06/1995

#### Exterior

No Asbestos Found.

#### Interior

##### R1 - General Learning Space

No Asbestos Found.

##### R2 - General Learning Space

No Asbestos Found.

##### R3 - Entry

No Asbestos Found.

##### R4 - Secure Storeroom

No Asbestos Found.

##### R5 - Secure Storeroom

No Asbestos Found.

##### R6 - Entry

No Asbestos Found.

### OS 626 - D15492 - Double Learning Unit - H/Cap : Placement Date - 4/02/2008

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

#### Exterior

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Home Base-I.O.</b>						
No Asbestos Found.						
<b>OS 601 - D15775 - Learning Unit - Standard/Withdrawal : Placement Date - 3/05/2016</b>						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Entry</b>						
No Asbestos Found.						
<b>R2 - General Learning Space</b>						
No Asbestos Found.						
<b>R3 - Store</b>						
No Asbestos Found.						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Listing of Electronic Attachments as of 22/03/2017***

**Available Asbestos Related Electronic Files**

8581\_ASB\_211210\_AMP.pdf

\* Note : Refer to AMS for details of the attachment(s).

2017