


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Bossley Park High School (8582)
Region : South Western Sydney
State Electorate : Prospect
Local Government Area : Fairfield

Initial Survey : Noel Arnold & Associates : 29 - May - 2008
Reviewed By : Parsons Brinckerhoff : 25 - Nov - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning/Science Learning/Library - 1988 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting 8582/B00A/Eaves Linings/S2					No Asbestos Detected
Ceiling Voids	No Asbestos Found					

Interior

B00A - M0002 - Tiered Learning Area

No Asbestos

B00A - R0003 - Staff Study

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0004 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0006 - General Learning Space

In-fill-panel Flat AC Sheeting
8582/B00A/R0008/In-fill-panel/S3 No Asbestos Detected

B00A - R0007 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0008 - Study Space

In-fill-panel Flat AC Sheeting
8582/B00A/R0008/In-fill-panel/S3 No Asbestos Detected

B00A - R0009 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0011 - Main Area

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0013 - Librarian

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0014 - Seminar

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0015 - Seminar

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0016 - Audio Visual Workroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0017 - External Movement

No Asbestos

B00A - R0018 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0019 - Plant

No Asbestos

B00A - R0020 - General Storeroom

No Asbestos

B00A - R0021 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R0022 - Office/Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0023 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0024 - General Learning Space						
In-fill-panel	Flat AC Sheeting					
	8582/B00A/R0008/In-fill-panel/S3					No Asbestos Detected
B00A - R0026 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0027 - General Storeroom						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0028 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0029 - General Learning Space						
No Asbestos						
B00A - R0030 - External Movement						
In-fill-panel	Flat AC Sheeting					
	8582/B00A/R0008/In-fill-panel/S3					No Asbestos Detected
B00A - R0031 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0032 - Sport Equipment Store						
No Asbestos						
B00A - R0033 - External Movement						
In-fill-panel	Flat AC Sheeting					
	8582/B00A/R0008/In-fill-panel/S3					No Asbestos Detected
B00A - R0034 - Toilets-Boys						
No Asbestos						
B00A - R0035 - Toilets-Girls						
No Asbestos						
B00A - R0036 - Resources Store						
No Asbestos						
B00A - R0037 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B00A - R0038 - Staff - Toilet						
No Asbestos						
B00A - R0039 - General Storeroom						
No Asbestos						
B00A - R0040 - Staff - Toilet						
No Asbestos						
B00A - R0041 - Deputy Principal Office						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0042 - Cleaning Store - Distributed						
No Asbestos						
B00A - R0043 - External Movement						
In-fill-panel	Flat AC Sheeting					
	8582/B00A/R0008/In-fill-panel/S3					No Asbestos Detected
B00A - R0044 - Toilets-Disabled						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
B00A - R0045 - Administration - Clerical						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0046 - Leading Teacher						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0047 - Cleaning Store - Distributed						
No Asbestos						
B00A - R0048 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B00A - R0049 - Archive Store						
No Asbestos						
B00A - R0050 - External Movement						
In-fill-panel	Flat AC Sheeting					
	8582/B00A/R0008/In-fill-panel/S3					No Asbestos Detected
B00A - R0051 - Toilets-Girls						
In-fill-panel	Flat AC Sheeting					
	8582/B00A/R0008/In-fill-panel/S3					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting					
	8582/B00A/R0008/In-fill-panel/S3					No Asbestos Detected
B00A - R0052 - Toilets-Boys						
In-fill-panel	Flat AC Sheeting					
	8582/B00A/R0008/In-fill-panel/S3					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting					
	8582/B00A/R0008/In-fill-panel/S3					No Asbestos Detected
B00A - R0053 - Secure Storeroom						
No Asbestos						
B00A - R0055 - External Movement						
No Asbestos						
B00A - R0057 - Stairs						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0058 - Stairs						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0059 - Stairs						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0060 - Special Education Support Centre						
No Asbestos						
B00A - R0061 - Toilets-Disabled						
No Asbestos						
B00A - R0062 - Toilets-Disabled						
No Asbestos						
B00A - R0063 - Special Learning Space						
No Asbestos						
B00A - R0064 - Handwashing Facilities						
No Asbestos						
B00A - R0065 - Special Learning Space						
No Asbestos						
B00A - R0066 - Handwashing Facilities						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R0067 - Staff Study						
No Asbestos						
B00A - R0068 - Tea Room						
No Asbestos						
B00A - R0069 - Darkroom Space						
No Asbestos						
B00A - R0070 - General Storeroom						
No Asbestos						
B00A - R0071 - Dark Room						
No Asbestos						
B00A - R0072 - Tiered Learning Area						
No Asbestos						
B00A - R0073 - Staff Study						
No Asbestos						
B00A - R0074 - Tea Room						
No Asbestos						
B00A - R0075 - General Storeroom						
No Asbestos						
B00A - R0076 - Movement						
No Asbestos						
B00A - R0077 - Library Administration						
No Asbestos						
B00A - R0078 - Tea Room						
No Asbestos						
B00A - R1001 - General Learning Space						
Vinyl Tiles (Under Floor No Asbestos Found Covering/Carpet)						
B00A - R1002 - General Learning Space						
Vinyl Tiles (Under Floor No Asbestos Found Covering/Carpet)						
B00A - R1003 - Senior Study						
Vinyl Tiles (Under Floor No Asbestos Found Covering/Carpet)						
B00A - R1004 - General Learning Space						
Vinyl Tiles (Under Floor No Asbestos Found Covering/Carpet)						
B00A - R1005 - General Learning Space						
Vinyl Tiles (Under Floor No Asbestos Found Covering/Carpet)						
B00A - R1006 - General Learning Space						
Vinyl Tiles (Under Floor No Asbestos Found Covering/Carpet)						
B00A - R1007 - General Learning Space						
Vinyl Tiles (Under Floor No Asbestos Found Covering/Carpet)						
B00A - R1008 - Senior Study						
Vinyl Tiles (Under Floor No Asbestos Found Covering/Carpet)						
B00A - R1009 - General Learning Space						
Vinyl Tiles (Under Floor No Asbestos Found Covering/Carpet)						
B00A - R1010 - Staff - Toilet						
In-fill-panel Flat AC Sheeting 8582/B00A/R0008/In-fill-panel/S3						

No Asbestos Detected

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	8582/B00A/R0008/In-fill-panel/S3					
B00A - R1011 - Staff - Toilet						
In-fill-panel	Flat AC Sheeting					No Asbestos Detected
	8582/B00A/R0008/In-fill-panel/S3					
Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	8582/B00A/R0008/In-fill-panel/S3					
B00A - R1012 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R1013 - Interview/Office - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R1014 - Interview/Office - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R1015 - Computer Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R1016 - Independent Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R1017 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R1018 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R1019 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R1020 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R1021 - Leading Teacher						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R1022 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R1023 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R1024 - External Movement						
Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	8582/B00A/R0008/In-fill-panel/S3					
B00A - R1025 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R1026 - Staff Study						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R1027 - Resources Store						
No Asbestos						
B00A - R1029 - General Storeroom						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R1030 - Distribution Board Cupboard				Note: No inspection of live electrical installation.		
Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	8582/B00A/R0008/In-fill-panel/S3					
B00A - R1031 - Resources Store						
No Asbestos						
B00A - R1032 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R1034 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R1035 - Resources Store						
No Asbestos						
B00A - R1036 - Distribution Board Cupboard				Note: No inspection of live electrical installation.		
In-fill-panel	Flat AC Sheeting					No Asbestos Detected
	8582/B00A/R1036/In-fill-panel/S4					
B00A - R1037 - Cleaning Store - Distributed						
No Asbestos						
B00A - R1039 - Resources Store						
No Asbestos						
B00A - R1040 - Staff Study						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R1042 - External Movement						
Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	8582/B00A/R0008/In-fill-panel/S3					
B00A - R1043 - Movement						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R1044 - Stairs						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R1045 - Stairs						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R1046 - Stairs						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R1047 - Staff Study						
No Asbestos						
B00A - R1048 - Tea Room						
No Asbestos						
B00A - R1049 - Staff Study						
No Asbestos						
B00A - R1050 - Tea Room						
No Asbestos						
B00A - R1051 - Commonroom						
No Asbestos						
B00A - R1052 - Tea Room						
No Asbestos						
B00A - R1053 - Commonroom						
No Asbestos						
B00A - R1054 - Staff Study						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - R1055 - Tea Room

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Science Learning - 1988 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior**B00B - R0001 - Main Switchroom**

Ceiling Structures/Linings Flat AC Sheeting
8582/B00A/R0008/In-fill-panel/S3 **No Asbestos Detected**

B00B - R0002 - Toilets-Girls

Wall Linings Internal Flat AC Sheeting
8582/B00A/R0008/In-fill-panel/S3 **No Asbestos Detected**

Ceiling Structures/Linings Flat AC Sheeting
8582/B00A/R0008/In-fill-panel/S3 **No Asbestos Detected**

B00B - R0003 - External Movement

Ceiling Structures/Linings Flat AC Sheeting
8582/B00A/R0008/In-fill-panel/S3 **No Asbestos Detected**

B00B - R0004 - Toilets-Boys

Wall Linings Internal Flat AC Sheeting
8582/B00A/R0008/In-fill-panel/S3 **No Asbestos Detected**

Ceiling Structures/Linings Flat AC Sheeting
8582/B00A/R0008/In-fill-panel/S3 **No Asbestos Detected**

B00B - R0005 - Laboratory L.S.

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0006 - Computer Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0007 - Laboratory L.S.

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0009 - External Movement

Ceiling Structures/Linings Flat AC Sheeting
8582/B00A/R0008/In-fill-panel/S3 **No Asbestos Detected**

B00B - R0010 - Laboratory L.S.

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0011 - Resources Store

No Asbestos

B00B - R0012 - Laboratory L.S.

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0013 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

In-fill-panel Flat AC Sheeting
8582/B00A/R1036/In-fill-panel/S4 **No Asbestos Detected**

B00B - R0014 - Cleaning Store - Distributed

No Asbestos

B00B - R0015 - Chemical Store

Shelving Unit Compressed AC Sheet
8582/B00B/R0015/Shelves for acid/S5 **No Asbestos Detected**

B00B - R0016 - Apparatus Storage

No Asbestos

B00B - R0017 - Laboratory L.S.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0018 - Preparation - Science

No Asbestos

B00B - R0019 - Laboratory L.S.

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0020 - Movement

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0021 - Staff Study

No Asbestos

B00B - R0022 - Tea Room

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Agricultural Science - 1988 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior**B00C - R0001 - General Storeroom**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0002 - Growing/Breeding

No Asbestos

B00C - R0003 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

Wall Linings Internal Flat AC Sheeting
8582/B00C/R0003/Wall Linings Internal/S1 **No Asbestos Detected**

Ceiling Structures/Linings Flat AC Sheeting
8582/B00C/R0003/Wall Linings Internal/S1 **No Asbestos Detected**

B00C - R0005 - Machine Storage

No Asbestos

B00C - R0006 - Animal Space

No Asbestos

B00C - R0007 - External Movement

No Asbestos

B00C - R0008 - Class Tools Storage

No Asbestos

B00C - R0009 - Movement

No Asbestos

B00C - R0010 - Covered Outdoor Space

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Technological & Applied Studies/Art - 1988 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00D - R0001 - Art Learning Space

No Asbestos

B00D - R0002 - Art Learning Space

No Asbestos

B00D - R0003 - Art Learning Space

No Asbestos

B00D - R0005 - Art Learning Space

No Asbestos

B00D - R0006 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting 8582/B00A/R0008/In-fill-panel/S3
----------------------------	--

No Asbestos Detected

B00D - R0007 - Resources Store

No Asbestos

B00D - R0008 - Computer Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0009 - Computer Learning Space

No Asbestos

B00D - R0010 - Computer Learning Space

No Asbestos

B00D - R0011 - Materials Workshop - Type 2

No Asbestos

B00D - R0012 - Welding Area

No Asbestos

B00D - R0013 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting 8582/B00A/R0008/In-fill-panel/S3
----------------------------	--

No Asbestos Detected

B00D - R0014 - Secure Storeroom

No Asbestos

B00D - R0015 - Materials Store

No Asbestos

B00D - R0016 - Metal Technology L.S.

No Asbestos

B00D - R0017 - Metal Technology Bay

No Asbestos

B00D - R0019 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting 8582/B00A/R0008/In-fill-panel/S3
----------------------------	--

No Asbestos Detected

B00D - R0020 - Materials Store

No Asbestos

B00D - R0021 - Wood Technology L.S.

No Asbestos

B00D - R0022 - Wood Technology Bay

No Asbestos

B00D - R0023 - Wood Technology L.S.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos						
B00D - R0024 - Dust Extraction Space						
No Asbestos						
B00D - R0026 - General Storeroom						
No Asbestos						
B00D - R0027 - Resources Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R0028 - Cleaning Store - Distributed						
No Asbestos						
B00D - R0029 - Staff - Toilet						
No Asbestos						
B00D - R0030 - Independent Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R0031 - Resources Store						
No Asbestos						
B00D - R0032 - Project Store - Type 1						
No Asbestos						
B00D - R0034 - External Movement						
Ceiling Structures/Linings	Flat AC Sheeting					
	8582/B00A/R0008/In-fill-panel/S3					No Asbestos Detected
B00D - R0036 - Workshop						
No Asbestos						
B00D - R0037 - Kiln Space						
No Asbestos						
B00D - R0038 - Staff Study						
No Asbestos						
B00D - R0039 - Tea Room						
No Asbestos						
B00D - R0040 - Staff Study						
No Asbestos						
B00D - R0041 - Tea Room						
No Asbestos						
B00D - R0042 - Metal Technology L.S.						
No Asbestos						
B00D - R0043 - Metal Technology Bay						
No Asbestos						
B00D - R0044 - Handwashing Facilities						
No Asbestos						
B00D - R0045 - External Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Administration - 1988 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00E - R0002 - Staff - Toilet

Ceiling Structures/Linings	Flat AC Sheeting 8582/B00A/R0008/In-fill-panel/S3	No Asbestos Detected
----------------------------	--	----------------------

B00E - R0003 - Uniform Shop

No Asbestos

B00E - R0004 - Administration - Clerical

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0005 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting 8582/B00A/R0008/In-fill-panel/S3	No Asbestos Detected
----------------------------	--	----------------------

B00E - R0006 - Deputy Principal Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0007 - Interview/Office - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0008 - Clinic

No Asbestos

B00E - R0009 - Toilets-Girls

No Asbestos

B00E - R0010 - Toilets-Boys

No Asbestos

B00E - R0011 - System Administrators Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0012 - Printing/Photocopying

No Asbestos

B00E - R0013 - Administration - Clerical

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0014 - Principal Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0015 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0016 - Public Reception

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0017 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0018 - Deputy Principal Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0020 - Cleaning Store - Distributed

Non Accessible

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00E - R0022 - External Movement						
Ceiling Structures/Linings	Flat AC Sheeting					
	8582/B00A/R0008/In-fill-panel/S3					No Asbestos Detected
B00E - R0023 - Pupil Entry						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00E - R0024 - Ancillary Staff						
No Asbestos						
B00E - R0025 - Tea Room						
No Asbestos						
B00E - R0026 - Administration - Clerical						
No Asbestos						
B00E - R0027 - Tea Room						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Multi Purpose Facilities - 1988 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior**B00F - R0001 - Shower**

Wall Linings Internal Flat AC Sheeting
8582/B00F/R0026/Wall Linings Internal/S6 No Asbestos Detected

Ceiling Structures/Linings Flat AC Sheeting
8582/B00F/R0026/Wall Linings Internal/S6 No Asbestos Detected

B00F - R0002 - Change

Wall Linings Internal Flat AC Sheeting
8582/B00F/R0026/Wall Linings Internal/S6 No Asbestos Detected

Ceiling Structures/Linings Flat AC Sheeting
8582/B00F/R0026/Wall Linings Internal/S6 No Asbestos Detected

B00F - R0003 - Change

Wall Linings Internal Flat AC Sheeting
8582/B00F/R0026/Wall Linings Internal/S6 No Asbestos Detected

Ceiling Structures/Linings Flat AC Sheeting
8582/B00F/R0026/Wall Linings Internal/S6 No Asbestos Detected

B00F - R0004 - Movement

No Asbestos

B00F - R0005 - Change

Wall Linings Internal Flat AC Sheeting
8582/B00F/R0026/Wall Linings Internal/S6 No Asbestos Detected

Ceiling Structures/Linings Flat AC Sheeting
8582/B00F/R0026/Wall Linings Internal/S6 No Asbestos Detected

B00F - R0006 - Shower

Wall Linings Internal Flat AC Sheeting
8582/B00F/R0026/Wall Linings Internal/S6 No Asbestos Detected

Ceiling Structures/Linings Flat AC Sheeting
8582/B00F/R0026/Wall Linings Internal/S6 No Asbestos Detected

B00F - R0007 - Change

Wall Linings Internal Flat AC Sheeting
8582/B00F/R0026/Wall Linings Internal/S6 No Asbestos Detected

Ceiling Structures/Linings Flat AC Sheeting
8582/B00F/R0026/Wall Linings Internal/S6 No Asbestos Detected

B00F - R0008 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

Ceiling Structures/Linings Flat AC Sheeting
8582/B00F/R0026/Wall Linings Internal/S6 No Asbestos Detected

B00F - R0010 - Multi-Purpose Space

No Asbestos

B00F - R0011 - Toilets-Boys

Wall Linings Internal Flat AC Sheeting
8582/B00F/R0026/Wall Linings Internal/S6 No Asbestos Detected

Ceiling Structures/Linings Flat AC Sheeting
8582/B00F/R0026/Wall Linings Internal/S6 No Asbestos Detected

B00F - R0012 - Toilets-Girls

Wall Linings Internal Flat AC Sheeting
8582/B00F/R0026/Wall Linings Internal/S6 No Asbestos Detected

Ceiling Structures/Linings Flat AC Sheeting
8582/B00F/R0026/Wall Linings Internal/S6 No Asbestos Detected

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00F - R0013 - Movement						
No Asbestos						
B00F - R0014 - Bulk Store						
No Asbestos						
B00F - R0017 - General Storeroom						
No Asbestos						
B00F - R0020 - Toilets-Disabled						
Wall Linings Internal	Flat AC Sheeting					
	8582/B00F/R0026/Wall Linings Internal/S6					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting					
	8582/B00F/R0026/Wall Linings Internal/S6					No Asbestos Detected
B00F - R0021 - Cleaning Store - Distributed						
No Asbestos						
B00F - R0022 - Chair Store						
No Asbestos						
B00F - R0023 - Sport Equipment Store						
No Asbestos						
B00F - R0024 - External Movement						
Ceiling Structures/Linings	Flat AC Sheeting					
	8582/B00F/R0026/Wall Linings Internal/S6					No Asbestos Detected
B00F - R0025 - External Movement						
Ceiling Structures/Linings	Flat AC Sheeting					
	8582/B00F/R0026/Wall Linings Internal/S6					No Asbestos Detected
B00F - R0026 - Student Canteen						
Wall Linings Internal	Flat AC Sheeting					
	8582/B00F/R0026/Wall Linings Internal/S6					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting					
	8582/B00F/R0026/Wall Linings Internal/S6					No Asbestos Detected
B00F - R0027 - General Storeroom						
Wall Linings Internal	Flat AC Sheeting					
	8582/B00F/R0026/Wall Linings Internal/S6					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting					
	8582/B00F/R0026/Wall Linings Internal/S6					No Asbestos Detected
B00F - R0028 - General Assistants						
Wall Linings Internal	Flat AC Sheeting					
	8582/B00F/R0026/Wall Linings Internal/S6					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting					
	8582/B00F/R0026/Wall Linings Internal/S6					No Asbestos Detected
B00F - R0029 - Garden Store Room						
Wall Linings Internal	Flat AC Sheeting					
	8582/B00F/R0026/Wall Linings Internal/S6					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting					
	8582/B00F/R0026/Wall Linings Internal/S6					No Asbestos Detected
B00F - R0031 - External Movement						
No Asbestos						
B00F - R0032 - Plant						
Wall Linings Internal	Flat AC Sheeting					
	8582/B00F/R0026/Wall Linings Internal/S6					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting					
	8582/B00F/R0026/Wall Linings Internal/S6					No Asbestos Detected
B00F - R0033 - Plant						
Wall Linings Internal	Flat AC Sheeting					
	8582/B00F/R0026/Wall Linings Internal/S6					No Asbestos Detected

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

Ceiling Structures/Linings	Flat AC Sheeting 8582/B00F/R0026/Wall Linings Internal/S6					No Asbestos Detected
----------------------------	--	--	--	--	--	-----------------------------

B00F - R0034 - Lift	No Asbestos
B00F - R0035 - Stage	No Asbestos
B00F - R0036 - General Storeroom	No Asbestos
B00F - R0037 - Interview/Meeting	No Asbestos
B00F - R0038 - Tea Room	No Asbestos
B00F - R0039 - General Storeroom	No Asbestos
B00F - R0040 - Staff Shower	No Asbestos
B00F - R0041 - Plant	No Asbestos
B00F - R0042 - Movement	No Asbestos
B00F - R0043 - External Movement	No Asbestos
B00F - R0044 - Covered Area	No Asbestos
B00F - R0045 - Movement	No Asbestos
B00F - R0046 - External Movement	No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Technological & Applied Studies/Music - 1988 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior**B00G - R0001 - Music Learning Space**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0002 - Music Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0003 - Practice/Seminar

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0004 - External Movement

Ceiling Structures/Linings Flat AC Sheeting
8582/B00A/R0008/In-fill-panel/S3

No Asbestos Detected**B00G - R0007 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

Ceiling Structures/Linings Flat AC Sheeting
8582/B00A/R0008/In-fill-panel/S3

No Asbestos Detected**B00G - R0008 - Music Learning Space**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0010 - Textiles Technology L.S.

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0011 - Textiles Technology L.S.

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0012 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

Ceiling Structures/Linings Flat AC Sheeting
8582/B00A/R0008/In-fill-panel/S3

No Asbestos Detected**B00G - R0013 - Cleaning Store - Distributed**

No Asbestos

B00G - R0014 - Laundry

No Asbestos

B00G - R0016 - Office/Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0017 - Food Technology L.S.

No Asbestos

B00G - R0018 - Office/Store

No Asbestos

B00G - R0019 - Preparation - Materials

No Asbestos

B00G - R0020 - Food Technology L.S.

No Asbestos

B00G - R0021 - Movement

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0022 - Toilets-Boys

Wall Linings Internal Flat AC Sheeting
8582/B00A/R0008/In-fill-panel/S3

No Asbestos Detected

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	8582/B00A/R0008/In-fill-panel/S3					
B00G - R0023 - Staff - Toilet						
Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	8582/B00A/R0008/In-fill-panel/S3					
B00G - R0024 - External Movement						
Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	8582/B00A/R0008/In-fill-panel/S3					
B00G - R0025 - Toilets-Girls						
Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	8582/B00A/R0008/In-fill-panel/S3					
Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	8582/B00A/R0008/In-fill-panel/S3					
B00G - R0026 - Staff Study						
No Asbestos						
B00G - R0027 - Tea Room						
No Asbestos						
B00G - R0028 - Plant						
No Asbestos						
B00G - R0029 - Music Store						
No Asbestos						
B00G - R0030 - Movement						
No Asbestos						
B00G - R0031 - Handwashing Facilities						
No Asbestos						
B00G - R0032 - Plant						
No Asbestos						
B00G - R0033 - Staff Study						
No Asbestos						
B00G - R0034 - Tea Room						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Support Unit/Performance Learning - 2004 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior**B00H - R0001 - External Movement**

No Asbestos

B00H - R0002 - Staff - Toilet

No Asbestos

B00H - R0003 - Toilets-Disabled

No Asbestos

B00H - R0004 - Special Education Support Centre

No Asbestos

B00H - R0005 - Special Education Support Centre

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00H - R0006 - Special Education Support Centre

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00H - R0007 - Special Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00H - R0008 - Performance Workshop

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00H - R0009 - Resources Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00H - R0010 - General Storeroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00H - R0011 - Cleaning Store - Distributed

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - Storage - 2004 - Metal Shed (Metal Shed)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior

B00I - R0001 - Machine Storage

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - Storage - 2004 - Metal Shed (Metal Shed)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior

B00J - R0001 - Bulk Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Physical Education - 2010 - Steel (Steel)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00K - R0001 - Fitness Laboratory

No Asbestos

B00K - R0002 - Sport Equipment Store

No Asbestos

B00K - R0003 - Sport Equipment Store

No Asbestos

B00K - R0004 - Machine Storage

No Asbestos

B00K - R0005 - External Movement

No Asbestos

B00K - R0006 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Physical Education/General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00L - R0001 - General Learning Space

No Asbestos

B00L - R0002 - Staff Study

No Asbestos

B00L - R0003 - Tea Room

No Asbestos

B00L - R0004 - Resources Store

No Asbestos

B00L - R0005 - Toilets-Disabled

No Asbestos

B00L - R0006 - Cleaning Store - Distributed

No Asbestos

B00L - R0007 - Staff - Toilet

No Asbestos

B00L - R0008 - Staff Shower

No Asbestos

B00L - R0009 - Movement Studio

No Asbestos

B00L - R0010 - Office/Store

No Asbestos

B00L - R0011 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 600 - D10502 - Learning Unit - Small : Placement Date - 30/06/1995

Exterior

Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	8.64 m2

Interior

R1 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	50 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

OS 710 - D10791 - Home Science/Pantry/Laundry : Placement Date - 30/06/1995

Exterior

Eave Lining	Flat AC Sheet	Assumed Asbestos	14.4 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2

R2 - Food Technology L.S.

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	73 m2

R3 - Laundry

Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2
---------	---------------	------------------	------

OS 600 - D10827 - Learning Unit - Small : Placement Date - 6/06/2001

Exterior

Eave Lining	Flat AC Sheet	Assumed Asbestos	8.64 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2

Interior

R1 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	50 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

OS 600 - D11167 - Learning Unit - Small : Placement Date - 30/06/1995

Exterior

Eave Lining	Flat AC Sheet	Assumed Asbestos	8.64 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2

Interior

R1 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	50 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

OS 601 - D11291 - Learning Unit - Standard/Withdrawal : Placement Date - 30/06/1995

Exterior

Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Interior						
R1 - Entry						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
R2 - General Learning Space						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
R3 - Store						
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2
OS 601 - D11468 - Learning Unit - Standard/Withdrawal : Placement Date - 6/06/2001						
Exterior						
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Interior						
R1 - Entry						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
R2 - General Learning Space						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
R3 - Store						
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2
OS 601 - D11476 - Learning Unit - Standard/Withdrawal : Placement Date - 30/06/1995						
Exterior						
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Interior						
R1 - Entry						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
R2 - General Learning Space						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
R3 - Store						
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2
OS 600 - D11551 - Learning Unit - Small : Placement Date - 30/06/1995						
Exterior						
Eave Lining	Flat AC Sheet	Assumed Asbestos				8.64 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Interior						
R1 - General Learning Space						
End wall panel	Flat AC Sheet	Assumed Asbestos				50 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
OS 601 - D11570 - Learning Unit - Standard/Withdrawal : Placement Date - 30/06/1995						
Exterior						
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Interior						
R1 - Entry						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
R2 - General Learning Space						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
R3 - Store						
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2
OS 600 - D11604 - Learning Unit - Small : Placement Date - 30/06/1995						
Exterior						
Eave Lining	Flat AC Sheet	Assumed Asbestos				8.64 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Interior						
R1 - General Learning Space						
End wall panel	Flat AC Sheet	Assumed Asbestos				50 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
OS 720 - D11810 - Science Laboratory/Prep Room : Placement Date - 30/06/1995						
Exterior						
Eave Lining	Flat AC Sheet	Assumed Asbestos				17.28 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Interior						
R1 - Laboratory L.S.						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				90 m2
R2 - Preparation						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				19 m2
OS 600 - D11821 - Learning Unit - Small : Placement Date - 6/06/2001						
Exterior						
Eave Lining	Flat AC Sheet	Assumed Asbestos				8.64 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Interior						
R1 - General Learning Space						
End wall panel	Flat AC Sheet	Assumed Asbestos				50 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
NS 200 - D12138 - Art Learning Space/Workshop/Bulk Store : Placement Date - 30/06/1995						
Exterior						
No Asbestos Found.						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Interior

R1 - Art Learning Space

No Asbestos Found.

R2 - Workshop

No Asbestos Found.

R3 - Bulk Store

No Asbestos Found.

OS 600 - D12146 - Learning Unit - Small : Placement Date - 30/06/1995

Exterior

Eave Lining	Flat AC Sheet	Assumed Asbestos	8.64 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2

Interior

R1 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	50 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

OS 601 - D12699 - Learning Unit - Standard/Withdrawal : Placement Date - 20/09/2004

Exterior

Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2
---------	---------------	------------------	-------

NS 111 - D15201 - Learning Unit - Double Secondary/Secure : Placement Date - 30/06/1995

Exterior

No Asbestos Found.

Interior

R1 - General Learning Space

No Asbestos Found.

R2 - General Learning Space

No Asbestos Found.

R3 - Entry

No Asbestos Found.

R4 - Secure Storeroom

No Asbestos Found.

R5 - Secure Storeroom

No Asbestos Found.

R6 - Entry

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
NS 110 - D15241 - Learning Unit - Single Secondary/Secure : Placement Date - 17/12/1998						
Exterior						
No Asbestos Found.						
Interior						
R1 - General Learning Space						
No Asbestos Found.						
R2 - Entry						
No Asbestos Found.						
R3 - Secure Storeroom						
No Asbestos Found.						
OS 600 - D15970 - Learning Unit - Small : Placement Date - 30/06/1995						
Exterior						
Eave Lining	Flat AC Sheet	Assumed Asbestos				8.64 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Interior						
R1 - General Learning Space						
End wall panel	Flat AC Sheet	Assumed Asbestos				50 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
OS 720 - D15971 - Science Laboratory/Prep Room : Placement Date - 30/06/1995						
Exterior						
Eave Lining	Flat AC Sheet	Assumed Asbestos				17.28 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Interior						
R1 - Laboratory L.S.						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				90 m2
R2 - Preparation						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				19 m2
OS 838 - D16071 - Hcap Shower/Change/Toilet/Laundry : Placement Date - 4/12/2013						
Exterior						
Eave Lining	Flat AC Sheet	Assumed Asbestos				5.76 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Interior						
R1 - Disabled Shower/Toilet/Laundry						
Toilet partitions	Compressed AC Sheet	Assumed Asbestos				2 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				
OS 971 - D80044 - Shed - Container (Garden/Sports/Bulk) : Placement Date - 30/06/1995						
Exterior						
No Asbestos Found.						
Interior						
R1 - Garden Store						
No Asbestos Found.						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017