

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Birrong Girls High School (8854)
Region : South Western Sydney
State Electorate : Bankstown
Local Government Area : Bankstown

Initial Survey : Noel Arnold & Associates : 11 - Mar - 2008
Reviewed By : Parsons Brinckerhoff : 13 - Oct - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Multi Purpose Facilities - 1957 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting 8854/B00A/Eaves Linings/S20					No Asbestos Detected
Rope gasket to pipework	Encapsulated Insulation material within unit 8854/B00A/Rope gasket to pipework/S21					No Asbestos Detected
Underfloor Voids	Packing 8854/B00A/Underfloor Voids/S22					No Asbestos Detected
Underfloor Voids	AC Fragments/Debris 8854/B00A/Underfloor Voids/S23	NA	Throughout	Poor Condition - Extensive Damage (4) Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	Low (1)	Medium Priority (4-5)

Interior

B00A - R0001 - Chair Store

No Asbestos

B00A - R0002 - Plant

No Asbestos

B00A - R0003 - Stairs

No Asbestos

B00A - R1001 - Multi-Purpose Space

No Asbestos

B00A - R1002 - Stage

No Asbestos

B00A - R1003 - Movement

No Asbestos

B00A - R1004 - External Movement

No Asbestos

B00A - R1005 - Sport Equipment Store

No Asbestos

B00A - R1006 - Resources Store

No Asbestos

B00A - R1007 - Staff Study

No Asbestos

B00A - R1008 - Staff Kitchen

No Asbestos

B00A - R1009 - General Storeroom

No Asbestos

B00A - R1010 - Staff - Toilet

No Asbestos

B00A - R1011 - Cleaning Store - Distributed

No Asbestos

B00A - R1012 - Stairs

No Asbestos

B00A - R1013 - Movement

No Asbestos

B00A - R1014 - Stairs

No Asbestos

B00A - R1015 - External Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Administration/General Learning/Art - 1957 - Brick/Block (Brick/Block)**Exterior**

Roof	Resinous Membrane 8854/B00B/Roof/S27					No Asbestos Detected
Eaves Linings	Flat AC Sheeting 8854/B00B/Eaves Linings/S26	200m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	Access hatch 8854/B00B/Ceiling Voids/S24					No Asbestos Detected
Ceiling Voids	Moulded FCS tank, lid and base 8854/B00B/Ceiling Voids/S25	4m2	Variable positions	Minimal Damage (2)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Underfloor Voids	AC Fragments/Debris 8854/B00B/Underfloor Voids/S28	NA	Throughout	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5) Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Underfloor Voids	Packing 8854/B00B/Underfloor Voids/S29					No Asbestos Detected
Underfloor Voids	Insulation to redundant boiler 8854/B00B/Underfloor Voids/S30					No Asbestos Detected
Underfloor Voids	Bituminous membrane to concrete slab 8854/B00B/Underfloor Voids/S31					No Asbestos Detected

Interior**B00B - R0001 - Workshop**

No Asbestos

B00B - R0002 - Workshop

No Asbestos

B00B - R0003 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 8854/B00B/R0005/Ceiling Structures/Linings/S15	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	--	------	--------------	--------------------	---------	--

B00B - R0006 - General Storeroom

Joist packing	Flat AC Sheeting 8854/B00B/R0006/Joist packing/S18	5m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
---------------	---	-----	--------------------	--------------------	---------	---

B00B - R0007 - Project Store - Type 1

No Asbestos

B00B - R0008 - Project Store - Type 1

No Asbestos

B00B - R1002 - Staff - Toilet

No Asbestos

B00B - R1003 - Principal Office

No Asbestos

B00B - R1004 - Staff - Toilet

No Asbestos

B00B - R1005 - Administration - Clerical

No Asbestos

B00B - R1006 - Leading Teacher

No Asbestos

B00B - R1007 - Control Room

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No						Test Result
No Asbestos						
B00B - R1008 - External Movement						
No Asbestos						
B00B - R1009 - Sport Equipment Store						
No Asbestos						
B00B - R1010 - Toilets-Girls						
No Asbestos						
B00B - R1015 - Printing/Photocopying						
No Asbestos						
B00B - R1016 - Staff - Toilet						
No Asbestos						
B00B - R1017 - General Storeroom						
No Asbestos						
B00B - R1018 - General Storeroom						
No Asbestos						
B00B - R1019 - Cleaning Store - Distributed						
No Asbestos						
B00B - R1020 - Movement						
No Asbestos						
B00B - R1021 - External Movement						
No Asbestos						
B00B - R1022 - Administration - Clerical						
No Asbestos						
B00B - R1023 - General Learning Space						
No Asbestos						
B00B - R1024 - General Learning Space						
No Asbestos						
B00B - R1025 - General Learning Space						
No Asbestos						
B00B - R1026 - General Learning Space						
No Asbestos						
B00B - R1027 - General Learning Space						
No Asbestos						
B00B - R1028 - Resources Store						
No Asbestos						
B00B - R1029 - Main Switch Board Cupboard						
Ceiling Structures/Linings	Flat AC Sheeting	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8854/B00B/R1029/Ceiling Structures/Linings/S17				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00B - R1031 - Staff Study						
No Asbestos						
B00B - R1033 - Staff - Toilet						
No Asbestos						
B00B - R1034 - Cleaning Store - Distributed						
No Asbestos						
B00B - R1035 - Movement						
No Asbestos						
B00B - R1036 - External Movement						
No Asbestos						
B00B - R1041 - Staff Study						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
	No Asbestos					
	B00B - R1042 - Tea Room					
	No Asbestos					
	B00B - R1043 - Staff Study					
	No Asbestos					
	B00B - R1044 - Tea Room					
	No Asbestos					
	B00B - R1045 - General Storeroom					
	No Asbestos					
	B00B - R1046 - Stairs					
	No Asbestos					
	B00B - R1047 - Deputy Principal Office					
	No Asbestos					
	B00B - R1048 - Deputy Principal Office					
	No Asbestos					
	B00B - R1049 - Public Reception					
	No Asbestos					
	B00B - R2001 - Commonroom					
	No Asbestos					
	B00B - R2002 - Interview/Meeting					
	No Asbestos					
	B00B - R2003 - Staff Kitchen					
	No Asbestos					
	B00B - R2004 - Interview/Office - Type 1					
	No Asbestos					
	B00B - R2005 - Movement					
	No Asbestos					
	B00B - R2006 - Movement					
	No Asbestos					
	B00B - R2007 - Uniform Shop					
	No Asbestos					
	B00B - R2008 - Cleaning Store - Distributed					
	No Asbestos					
	B00B - R2009 - Computer Learning Space					
	No Asbestos					
	B00B - R2010 - General Learning Space					
	No Asbestos					
	B00B - R2011 - General Learning Space					
	No Asbestos					
	B00B - R2012 - General Learning Space					
	No Asbestos					
	B00B - R2013 - General Learning Space					
	No Asbestos					
	B00B - R2014 - General Learning Space					
	No Asbestos					
	B00B - R2015 - Resources Store					
	No Asbestos					
	B00B - R2017 - Staff Study					
	No Asbestos					
	B00B - R2018 - Interview/Meeting					
	No Asbestos					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00B - R2019 - Staff - Toilet						
No Asbestos						
B00B - R2020 - Cleaning Store - Distributed						
No Asbestos						
B00B - R2021 - Movement						
No Asbestos						
B00B - R2022 - Stairs						
No Asbestos						
B00B - R2023 - Staff Study						
No Asbestos						
B00B - R2024 - Tea Room						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Pupil Facilities/General Learning - 1957 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting 8854/B00C/Eaves Linings/S32	150m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
Roof	Resinous Membrane 8854/B00C/Roof/S33	25m2	South west, Over single storey Section	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Corrugated sheet (debris) 8854/B00C/Underfloor Voids/S36	NA	Throughout	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		
Underfloor Voids	Packing 8854/B00C/Underfloor Voids/S34	NA	Throughout	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		
Underfloor Voids	AC Fragments/Debris 8854/B00C/Underfloor Voids/S35	NA	Throughout	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		

Interior**B00C - M1001 - Movement**

No Asbestos

B00C - M1002 - External Movement

No Asbestos

B00C - M1003 - Movement

No Asbestos

B00C - M1004 - Covered Area

No Asbestos

B00C - M1005 - External Movement

No Asbestos

B00C - R0003 - Cleaning Supplies Store

Wall Linings Internal Flat AC Sheeting
8854/B00C/R0003/Wall Linings Internal/S12

No Asbestos Detected**B00C - R0004 - Movement**

No Asbestos

B00C - R0006 - Staff - Toilet

No Asbestos

B00C - R0007 - Movement

No Asbestos

B00C - R0008 - Student Canteen

No Asbestos

B00C - R0009 - Pantry

No Asbestos

B00C - R0010 - Movement

No Asbestos

B00C - R0011 - Movement

No Asbestos

B00C - R0012 - External Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
	No Asbestos					
	B00C - R0013 - Movement					
	No Asbestos					
	B00C - R0014 - General Assistants					
	No Asbestos					
	B00C - R0015 - External Movement					
	No Asbestos					
	B00C - R0016 - Stairs					
	No Asbestos					
	B00C - R0017 - General Storeroom					
	No Asbestos					
	B00C - R0018 - Covered Area					
	No Asbestos					
	B00C - R0019 - Stairs					
	No Asbestos					
	B00C - R0020 - Lift					
	No Asbestos					
	B00C - R0021 - Movement					
	No Asbestos					
	B00C - R0022 - External Movement					
	No Asbestos					
	B00C - R0023 - External Movement					
	No Asbestos					
	B00C - R0024 - Plant					
	No Asbestos					
	B00C - R1001 - Resources Store					
	No Asbestos					
	B00C - R1002 - General Storeroom					
	No Asbestos					
	B00C - R1005 - General Learning Space					
	No Asbestos					
	B00C - R1006 - Computer Learning Space					
	No Asbestos					
	B00C - R1007 - Seminar					
	No Asbestos					
	B00C - R1008 - Resources Store					
	No Asbestos					
	B00C - R1009 - Archive Store					
	No Asbestos					
	B00C - R1010 - General Learning Space					
	No Asbestos					
	B00C - R1011 - General Learning Space					
	No Asbestos					
	B00C - R1012 - General Learning Space					
	No Asbestos					
	B00C - R1014 - Stairs					
	No Asbestos					
	B00C - R1017 - Movement					
	No Asbestos					
	B00C - R1018 - Stairs					
	No Asbestos					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00C - R2001 - Resources Store						
No Asbestos						
B00C - R2002 - Resources Store						
No Asbestos						
B00C - R2003 - Design/Technology L.S.						
No Asbestos						
B00C - R2004 - General Learning Space						
No Asbestos						
B00C - R2005 - Resources Store						
No Asbestos						
B00C - R2006 - Movement						
No Asbestos						
B00C - R2007 - Stairs						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00D - Technological & Applied Studies/Music - 1957 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting 8854/B00D/Eaves Linings/S40	150m2	East facing, West facing	Good Condition (1) Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	Low (1)	Low Priority (2-3)
Ceiling Voids	Packing below water tank 8854/B00D/Ceiling Voids/S39	1m2	Throughout	Minimal Damage (2) Chrysotile (white asbestos) , Amosite (brown asbestos)	Low (1)	Low Priority (2-3)
Ceiling Voids	Fibre Cement Pipe 8854/B00D/Ceiling Voids/S38	3m	Throughout	Minimal Damage (2) Chrysotile (white asbestos) , Amosite (brown asbestos)	Low (1)	Low Priority (2-3)
Ceiling Voids	AC Fragments/Debris 8854/B00D/Ceiling Voids/S37	NA	Throughout	Poor Condition - Extensive Damage (4) Chrysotile (white asbestos) , Amosite (brown asbestos)	Low (1)	Medium Priority (4-5)
Underfloor Voids	Packing 8854/B00D/Underfloor Voids/S42	NA	Throughout	Poor Condition - Extensive Damage (4) Chrysotile (white asbestos) , Amosite (brown asbestos)	Low (1)	Medium Priority (4-5)
Underfloor Voids	AC Fragments/Debris 8854/B00D/Underfloor Voids/S41	NA	Throughout	Poor Condition - Extensive Damage (4) Chrysotile (white asbestos) , Amosite (brown asbestos)	Low (1)	Medium Priority (4-5)

Interior**B00D - R0001 - Movement**

No Asbestos

B00D - R0003 - Multi Media Workshop

Floor Coverings Res/Textile Vinyl Sheet
8854/B00D/R0003/Floor Coverings Res/Textile/S10

No Asbestos Detected**B00D - R0004 - Interview/Office - Type 1**

No Asbestos

B00D - R0005 - Movement

No Asbestos

B00D - R0006 - Computer Learning Space

No Asbestos

B00D - R0007 - Resources Store

No Asbestos

B00D - R0008 - Food Technology L.S.

No Asbestos

B00D - R0009 - Preparation - Materials

No Asbestos

B00D - R0010 - Food Technology L.S.

No Asbestos

B00D - R0011 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

Ceiling Structures/Linings Flat AC Sheeting
8854/B00D/R0011/Ceiling Structures/Linings/S11

No Asbestos Detected**B00D - R0012 - General Storeroom**

No Asbestos

B00D - R0013 - Pantry

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00D - R0014 - Food Technology L.S.						
No Asbestos						
B00D - R0015 - Pantry						
No Asbestos						
B00D - R0016 - Staff Kitchen						
No Asbestos						
B00D - R0017 - Staff Study						
No Asbestos						
B00D - R0018 - Laundry						
No Asbestos						
B00D - R0019 - Resources Store						
No Asbestos						
B00D - R0020 - Change						
No Asbestos						
B00D - R0021 - External Movement						
No Asbestos						
B00D - R0022 - Movement						
No Asbestos						
B00D - R0023 - Movement						
No Asbestos						
B00D - R0026 - Stairs						
No Asbestos						
B00D - R0028 - External Movement						
No Asbestos						
B00D - R0029 - External Movement						
No Asbestos						
B00D - R0030 - Interview/Office - Type 1						
No Asbestos						
B00D - R0031 - Tea Room						
No Asbestos						
B00D - R0032 - External Movement						
No Asbestos						
B00D - R1001 - Other-Vacant						
No Asbestos						
B00D - R1002 - Staff Study						
No Asbestos						
B00D - R1004 - General Learning Space						
No Asbestos						
B00D - R1005 - Movement						
No Asbestos						
B00D - R1006 - Music Learning Space						
No Asbestos						
B00D - R1007 - Resources Store						
No Asbestos						
B00D - R1008 - Music Store						
No Asbestos						
B00D - R1009 - Music Learning Space						
No Asbestos						
B00D - R1010 - Practice/Seminar						
No Asbestos						
B00D - R1011 - Cleaning Store - Distributed						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00D - R1012 - Resources Store

Ceiling Structures/Linings Flat AC Sheeting 2m2 All surfaces Good Condition (1) Low (1) Low Priority (2-3)

8854/B00D/R1012/Ceiling Structures/Linings/S8

Chrysotile (white asbestos) , Amosite (brown asbestos)**B00D - R1013 - Practice/Seminar**

No Asbestos

B00D - R1015 - Resources Store

No Asbestos

B00D - R1017 - Workroom

No Asbestos

B00D - R1018 - Movement

Ceiling Structures/Linings Flat AC Sheeting 1m2 Electrical Cupboard, South end East facing Some Damage / Unsealed (3) Low (1) Low Priority (2-3)

8854/B00D/R1012/Ceiling Structures/Linings/S8

Chrysotile (white asbestos) , Amosite (brown asbestos)**B00D - R1019 - Movement**

No Asbestos

B00D - R1021 - Stairs

Putty to windows

Mastic

8854/B00D/R1021/Putty to windows/S46

No Asbestos Detected**B00D - R1022 - Design/Technology L.S.**

No Asbestos

B00D - R1023 - Handwashing Facilities

No Asbestos

B00D - R1024 - Design/Technology L.S.

No Asbestos

B00D - R1025 - Handwashing Facilities

No Asbestos

B00D - R1026 - Staff Study

No Asbestos

B00D - R1027 - Tea Room

No Asbestos

B00D - R1028 - Movement

No Asbestos

B00D - R1029 - Cleaning Store - Distributed

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Science Learning/Computer Learning - 1966 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	100m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	8854/B00E/Eaves Linings/S43					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)

Interior**B00E - M0001 - Movement**

No Asbestos

B00E - M0002 - External Movement

No Asbestos

B00E - M0003 - External Movement

No Asbestos

B00E - R0001 - Computer Learning Space

Floor Coverings Res/Textile	Vinyl Tiles	52m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8854/B00E/R0005/Floor Coverings Res/Textile/S4					Chrysotile (white asbestos)

Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	8854/B00E/R0006/Wall Linings Internal/S6					

B00E - R0002 - Preparation - Science

Fume Cupboard	Flat AC Sheeting	1Unit	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	8854/B00E/R0003/Fume Cupboard/S5					Chrysotile (white asbestos) , Amosite (brown asbestos)

Floor Coverings Res/Textile	Vinyl Tiles	26m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8854/B00E/R0005/Floor Coverings Res/Textile/S4					Chrysotile (white asbestos)

B00E - R0003 - Laboratory L.S.

Fume Cupboard	Flat AC Sheeting	1Unit	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	8854/B00E/R0003/Fume Cupboard/S5					Chrysotile (white asbestos) , Amosite (brown asbestos)

Floor Coverings Res/Textile	Vinyl Tiles	89m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8854/B00E/R0005/Floor Coverings Res/Textile/S4					Chrysotile (white asbestos)

B00E - R0004 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

Wall Linings Internal	Flat AC Sheeting	3m2	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	8854/B00E/R0004/Wall Linings Internal/S3					Chrysotile (white asbestos) , Amosite (brown asbestos)

Debris	Flat AC Sheeting	0.1m	On floor in corner	Some Damage / Unsealed (3)	Medium (2)	Low Priority (2-3)
	8854/B00E/R0004/Wall Linings Internal/S3					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00E - R0005 - Movement

Floor Coverings Res/Textile	Vinyl Tiles	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8854/B00E/R0005/Floor Coverings Res/Textile/S4					Chrysotile (white asbestos)

B00E - R0010 - Movement

No Asbestos

B00E - R0011 - Stairs

No Asbestos

B00E - R0012 - Handwashing Facilities

No Asbestos

B00E - R1001 - Laboratory L.S.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Fume Cupboard	Flat AC Sheeting	1Unit	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
8854/B00E/R0003/Fume Cupboard/S5				Chrysotile (white asbestos) , Amosite (brown asbestos)		
Floor Coverings Res/Textile	Vinyl Tiles	92m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8854/B00E/R0005/Floor Coverings Res/Textile/S4				Chrysotile (white asbestos)		
B00E - R1004 - Laboratory L.S.						
Fume Cupboard	Flat AC Sheeting	1Unit	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
8854/B00E/R0003/Fume Cupboard/S5				Chrysotile (white asbestos) , Amosite (brown asbestos)		
Floor Coverings Res/Textile	Vinyl Tiles	92m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8854/B00E/R0005/Floor Coverings Res/Textile/S4				Chrysotile (white asbestos)		
B00E - R1005 - Cleaning Store - Distributed						
Floor Coverings Res/Textile	Vinyl Tiles	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8854/B00E/R0005/Floor Coverings Res/Textile/S4				Chrysotile (white asbestos)		
B00E - R1006 - Movement						
Floor Coverings Res/Textile	Vinyl Tiles	49m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8854/B00E/R0005/Floor Coverings Res/Textile/S4				Chrysotile (white asbestos)		
B00E - R1007 - Preparation - Science						
No Asbestos						
B00E - R1008 - Chemical Store						
No Asbestos						
B00E - R1009 - Stairs						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Performance Learning - 1957 - Timber (Timber)

Exterior

Ceiling Voids	No Asbestos Found					
Underfloor Voids	Flat AC Sheeting	NA	Throughout	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5)
	8854/B00G/Underfloor Voids/S45				Chrysotile (white asbestos)	

Interior

B00G - R0001 - Performance Workshop

No Asbestos

B00G - R0002 - Performance Workshop

No Asbestos

B00G - R0003 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00H - Art/Library - 2000 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior**B00H - R0001 - Movement**

No Asbestos

B00H - R0002 - Kiln Space

No Asbestos

B00H - R0003 - Project Store - Type 1

No Asbestos

B00H - R0004 - Resources Store

No Asbestos

B00H - R0005 - Stairs

No Asbestos

B00H - R0006 - Workshop

No Asbestos

B00H - R0007 - Movement

No Asbestos

B00H - R0008 - Art Learning Space

No Asbestos

B00H - R0009 - Art Learning Space

No Asbestos

B00H - R0010 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00H - R0011 - Staff Study

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00H - R0012 - Art Learning Space

No Asbestos

B00H - R0013 - Darkroom Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00H - R0014 - Dark Room

No Asbestos

B00H - R0015 - Staff Study

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00H - R0016 - Communications Cupboard

No Asbestos

B00H - R0017 - Stairs

No Asbestos

B00H - R0018 - Plant

No Asbestos

B00H - R0019 - Plant

No Asbestos

B00H - R0020 - Movement

No Asbestos

B00H - R0021 - Movement

No Asbestos

B00H - R0022 - Stairs

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
B00H - R1001 - Access Student Shower/Toilet/Change						
No Asbestos						
B00H - R1002 - Movement						
No Asbestos						
B00H - R1003 - Plant						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00H - R1004 - Library Administration						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00H - R1005 - Senior Study						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00H - R1006 - System Administrators Office						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00H - R1007 - Senior Study						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00H - R1008 - Senior Study						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00H - R1009 - Communication Space						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00H - R1010 - Stairs						
No Asbestos						
B00H - R1011 - Staff - Toilet						
No Asbestos						
B00H - R1012 - Careers Advisers Office						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00H - R1013 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B00H - R1014 - Main Area						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00H - R1015 - Plant						
No Asbestos						
B00H - R1016 - Movement						
No Asbestos						
B00H - R1017 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B00H - R1018 - Stairs						
No Asbestos						
B00H - R1019 - Interview/Office - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00H - R9001 - Stairs						
No Asbestos						
B00H - R9002 - Movement						
No Asbestos						
B00H - R9003 - Movement						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00H - R9004 - Stairs

No Asbestos

B00H - R9005 - Movement

No Asbestos

B00H - R9006 - Stairs

No Asbestos

B00H - R9007 - General Storeroom

No Asbestos

B00H - R9008 - Plant

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - Pupil Facilities - 2015 - Brick/Block (Brick/Block)**Exterior**

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior**B00I - R0001 - External Movement**

No Asbestos

B00I - R0002 - Toilets-Girls

No Asbestos

B00I - R0003 - Cleaning Store - Distributed

No Asbestos

B00I - R0004 - Toilets-Unisex

No Asbestos

B00I - R0005 - Toilets-Disabled

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00Z - Building Services - 2000 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00Z - R0001 - Plant

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 720 - D10513 - Science Laboratory/Prep Room : Placement Date - 16/04/2010

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Laboratory L.S.

No Asbestos Found.

R2 - Preparation

No Asbestos Found.

OS 601 - D11047 - Learning Unit - Standard/Withdrawal : Placement Date - 5/01/2010

Exterior

No Asbestos Found.

Interior

R1 - Entry

No Asbestos Found.

R2 - General Learning Space

No Asbestos Found.

R3 - Store

No Asbestos Found.

OS 601 - D11082 - Learning Unit - Standard/Withdrawal : Placement Date - 4/03/2008

Exterior

No Asbestos Found.

Interior

R1 - Entry

No Asbestos Found.

R2 - General Learning Space

No Asbestos Found.

R3 - Store

No Asbestos Found.

OS 600 - D11556 - Learning Unit - Small : Placement Date - 30/06/1995

Exterior

Eave Lining	Flat AC Sheet	Assumed Asbestos	8.64 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2

Interior

R1 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	50 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

OS 601 - D11557 - Learning Unit - Standard/Withdrawal : Placement Date - 30/06/1995

Exterior

Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Interior						
R1 - Entry						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
R2 - General Learning Space						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
R3 - Store						
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2
OS 601 - D11558 - Learning Unit - Standard/Withdrawal : Placement Date - 30/06/1995						
Exterior						
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Interior						
R1 - Entry						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
R2 - General Learning Space						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
R3 - Store						
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2
NS 200 - D11563 - Art Learning Space/Workshop/Bulk Store : Placement Date - 30/06/1995						
Exterior						
No Asbestos Found.						
Interior						
R1 - Art Learning Space						
No Asbestos Found.						
R2 - Workshop						
No Asbestos Found.						
R3 - Bulk Store						
No Asbestos Found.						
OS 601 - D11646 - Learning Unit - Standard/Withdrawal : Placement Date - 30/06/1995						
Exterior						
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Interior						
R1 - Entry						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
R2 - General Learning Space						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
R3 - Store						
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2
OS 601 - D11778 - Learning Unit - Standard/Withdrawal : Placement Date - 30/06/1995						
Exterior						
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Interior						
R1 - Entry						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
R2 - General Learning Space						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
R3 - Store						
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2
OS 601 - D11780 - Learning Unit - Standard/Withdrawal : Placement Date - 30/06/1995						
Exterior						
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Interior						
R1 - Entry						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
R2 - General Learning Space						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
R3 - Store						
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2
OS 720 - D12355 - Science Laboratory/Prep Room : Placement Date - 17/04/2010						
Exterior						
No Asbestos Found.						
Interior						
R1 - Laboratory L.S.						
No Asbestos Found.						
R2 - Preparation						
No Asbestos Found.						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

Available Asbestos Related Electronic Files

8854_ASB_050813_AMP.pdf

* Note : Refer to AMS for details of the attachment(s).

2017