

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Gerringong Public School (1971)


Region : Illawarra and South East

State Electorate : Kiama

Local Government Area : Kiama

Initial Survey : Noel Arnold & Associates : 04 - May - 2008

Register Issue Date : 22 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00A - Administration/Staff Facilities - 1994 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00A - R0001 - Entry Vestibule**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
-------------------------------------------	-------------------

B00A - R0002 - Clerical Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
-------------------------------------------	-------------------

B00A - R0003 - Sick Bay

No Asbestos

B00A - R0004 - Sick Bay - Shower/Toilet

No Asbestos

B00A - R0005 - Special Programs Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
-------------------------------------------	-------------------

B00A - R0006 - Staff Room Annexe

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
-------------------------------------------	-------------------

B00A - R0007 - Staff Room Annexe

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
-------------------------------------------	-------------------

B00A - R0008 - Cleaning Distributed Store

No Asbestos

B00A - R0009 - Staff Room Annexe

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
-------------------------------------------	-------------------

B00A - R0010 - Staff Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
-------------------------------------------	-------------------

B00A - R0011 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
-------------------------------------------	-------------------

B00A - R0012 - Staff Toilet

No Asbestos

B00A - R0013 - Staff Toilet

No Asbestos

B00A - R0014 - Staff Toilet

No Asbestos

B00A - R0015 - General Storeroom

No Asbestos

B00A - R0016 - Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
-------------------------------------------	-------------------

B00A - R0017 - Duplicating Workroom

No Asbestos

B00A - R0018 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0019 - Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00B - Communal Facilities/Pupil Facilities - 1994 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00B - R0001 - Canteen**

No Asbestos

B00B - R0002 - Canteen Office/Store

No Asbestos

B00B - R0003 - General Storeroom

No Asbestos

B00B - R0004 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00B - R0005 - General Storeroom

No Asbestos

B00B - R0006 - General Assistant/Bulk Store

No Asbestos

B00B - R0007 - Raised Platform

No Asbestos

B00B - R0008 - Communal Space

No Asbestos

B00B - R0009 - Toilets - Girls

No Asbestos

B00B - R0010 - P.E. Store

No Asbestos

B00B - R0011 - Plant

No Asbestos

B00B - R0012 - Hall Chair Store

No Asbestos

B00B - R0013 - Shower/Change

No Asbestos

B00B - R0014 - Toilets - Boys

No Asbestos

B00B - R0015 - Movement

No Asbestos

B00B - R0016 - Plant

No Asbestos

B00B - R0017 - Disabled Toilet

No Asbestos

B00B - R0018 - Special Programs Room

No Asbestos

B00B - R0019 - Cleaning Supplies

No Asbestos

B00B - R0020 - Toilets - Girls

No Asbestos

B00B - R0021 - Cleaning Distributed Store

No Asbestos

B00B - R0022 - Toilets - Boys

No Asbestos

B00B - R0023 - Sports Store

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00B - R0024 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning - 1994 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00C - R0001 - Practical Activities - 1hb

No Asbestos

B00C - R0002 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0003 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0005 - Practical Activities - 1hb

No Asbestos

B00C - R0006 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0007 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0008 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0009 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning - 1994 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00D - R0001 - Practical Activities - 1hb

No Asbestos

B00D - R0002 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0003 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0005 - Practical Activities - 1hb

No Asbestos

B00D - R0006 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0007 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0008 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0009 - Movement

No Asbestos

B00D - R0010 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning - 1994 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00E - R0001 - Distribution Board Note: No inspection of live electrical installation.

No Asbestos

B00E - R0002 - Practical Activities - 1hb

No Asbestos

B00E - R0003 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0004 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0005 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0006 - Practical Activities - 1hb

No Asbestos

B00E - R0007 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0008 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0009 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0010 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning - 1994 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00F - R0001 - Practical Activities - 1hb

No Asbestos

B00F - R0002 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0003 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0005 - Practical Activities - 1hb

No Asbestos

B00F - R0006 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0007 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0008 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0009 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning/Pupil Facilities - 1994 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00G - R0001 - Practical Activities - 1hb

No Asbestos

B00G - R0002 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0003 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0005 - Practical Activities - 1hb

No Asbestos

B00G - R0006 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0007 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0008 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0009 - Drinking Facilities

No Asbestos

B00G - R0010 - Toilets - Boys

No Asbestos

B00G - R0011 - Kiln Room

No Asbestos

B00G - R0012 - Toilets - Girls

No Asbestos

B00G - R0013 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Library/Tiered Learning - 1994 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00H - R0001 - Cleaning Distributed Store

No Asbestos

B00H - R0002 - General Storeroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00H - R0003 - Plant

No Asbestos

B00H - R0004 - Main Switch Board

No Asbestos

B00H - R0005 - Special Programs Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00H - R0006 - Reading Area

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00H - R0007 - K.L.A. Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00H - R0008 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00H - R0009 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00I - R0001 - External Movement

No Asbestos

B00I - R0002 - Practical Activities/Movement - 1hb

No Asbestos

B00I - R0003 - Home Base Store

No Asbestos

B00I - R0004 - Home Base

No Asbestos

B00I - R0005 - Withdrawal Space - 2hb

No Asbestos

B00I - R0006 - Home Base

No Asbestos

B00I - R0007 - Home Base Store

No Asbestos

B00I - R0008 - Practical Activities/Movement - 1hb

No Asbestos

B00I - R0009 - Movement

No Asbestos

B00I - R0010 - Security Store

No Asbestos

B00I - R0011 - Security Store

No Asbestos

B00I - R0012 - Special Programs Room

No Asbestos

B00I - R0013 - Practical Activities/Movement - 1hb

No Asbestos

B00I - R0014 - Home Base Store

No Asbestos

B00I - R0015 - Home Base

No Asbestos

B00I - R0016 - Withdrawal Space - 2hb

No Asbestos

B00I - R0017 - Home Base

No Asbestos

B00I - R0018 - Home Base Store

No Asbestos

B00I - R0019 - Practical Activities/Movement - 1hb

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D11789 - Learning Unit - Standard With P.A.A. : Placement Date - 30/03/2007

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Learning space/withdrawal/entry

Ceiling	Flat AC Sheet	Assumed Asbestos	70 m2
---------	---------------	------------------	-------

R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	3 m2

OS 602 - D12702 - Learning Unit - Standard With P.A.A. : Placement Date - 12/03/2013

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D13541 - Learning Unit - Standard With P.A.A. : Placement Date - 30/06/1995

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Learning space/withdrawal/entry

Ceiling	Flat AC Sheet	Assumed Asbestos	70 m2
---------	---------------	------------------	-------

R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	3 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017