

# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Gilgai Public School (1978)  
**Region :** New England  
**State Electorate :** Northern Tablelands  
**Local Government Area :** Inverell

**Initial Survey :** Noel Arnold & Associates : 21 - May - 2008  
**Reviewed By :** AECOM : 29 - Apr - 2016



2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00A - General Learning/Administration - 1920 - Timber (Timber)****Exterior**

|                                   |   |      |              |                    |         |   |
|-----------------------------------|---|------|--------------|--------------------|---------|---|
| Ceiling Voids - Raked Ceiling     | Non Accessible Area<br>- Height Restriction AR0003. 3.5m.     |      |              |                    |         |   |
| Underfloor Voids - Slab on Ground | Non Accessible Area<br>- Area inaccessible, no access points. |      |              |                    |         |   |
| Eaves Linings                     | Flat AC Sheeting  | 10m2 | North, South | Good Condition (1) | Low (1) | Low Priority (2-3)  |
|                                   | 1978/B00A/R0001/Ceiling Structures/Linings/S1                 |      |              |                    |         | <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b> |

**Interior****B00A - R0001 - Duplicating Workroom**

|                            |   |     |            |                    |         |   |
|----------------------------|---|-----|------------|--------------------|---------|---|
| Ceiling Structures/Linings | Flat AC Sheeting                              | 6m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3)  |
|                            | 1978/B00A/R0001/Ceiling Structures/Linings/S1 |     |            |                    |         | <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b> |

**B00A - R0002 - Clerical Office**

No Asbestos

**B00A - R0003 - Principal**

No Asbestos

**B00A - R0004 - Home Base**

No Asbestos

**B00A - R0005 - Withdrawal Space - 1hb**

|                            |   |      |            |                    |         |   |
|----------------------------|---|------|------------|--------------------|---------|---|
| Ceiling Structures/Linings | Flat AC Sheeting                              | 17m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3)  |
|                            | 1978/B00A/R0001/Ceiling Structures/Linings/S1 |      |            |                    |         | <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b> |

**B00A - R0006 - External Movement**

No Asbestos

**B00A - R0007 - External Movement**

No Asbestos

**B00A - R0008 - External Movement**

No Asbestos

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00B - General Learning/Staff Facilities - 1884 - Brick/Block (Brick/Block)**

**Exterior**

|                                   |   |      |            |                    |                                    |                    |
|-----------------------------------|---|------|------------|--------------------|------------------------------------|--------------------|
| Ceiling Voids - Raked Ceiling     | No Asbestos Found   |      |            |                    |                                    |                    |
| Underfloor Voids - Slab on Ground | Non Accessible Area<br>- Area inaccessible, no access points. |      |            |                    |                                    |                    |
| Eaves Linings                     | Flat AC Sheeting  | 20m2 | Throughout | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
|                                   | 1978/B00B/Eaves Linings/S5                                    |      |            |                    | <b>Chrysotile (white asbestos)</b> |                    |
| Electrical Backing Board          | Resinous Board  | 1m2  | East       | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
|                                   | 1978/B00C/Electrical Backing Board/S4                         |      |            |                    | <b>Chrysotile (white asbestos)</b> |                    |

**Interior**

**B00B - R0001 - Personal Effects Storage**

|                             |  |  |  |  |                             |  |
|-----------------------------|--|--|--|--|-----------------------------|--|
| Floor Coverings Res/Textile | Vinyl Tiles                                    |  |  |  |                             |  |
|                             | 1978/B00B/R0001/Floor Coverings Res/Textile/S7 |  |  |  | <b>No Asbestos Detected</b> |  |

**B00B - R0002 - Staff Room**

No Asbestos

**B00B - R0003 - Personal Effects Storage**

No Asbestos

**B00B - R0004 - Home Base**

No Asbestos

**B00B - R0005 - Withdrawal Space - 1hb**

No Asbestos

**B00B - R0006 - Staff Room**

No Asbestos

**B00B - R0007 - Withdrawal Space - 1hb**

No Asbestos

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00C - Pupil Facilities - 1955 - Timber (Timber)****Exterior**

|  |   |     |       |                    |         |                                    |
|--|---|-----|-------|--------------------|---------|------------------------------------|
| Ceiling Voids - Raked Ceiling              | Non Accessible Area<br>- Area inaccessible no access points               |     |       |                    |         |                                    |
| Underfloor Voids - Packing to Floor Joists | Non Accessible Area<br>- Area inaccessible low height, restricted access. |     |       |                    |         |                                    |
| Electrical Backing Board                   | Resinous Board  | 1m2 | South | Good Condition (1) | Low (1) | Low Priority (2-3)                 |
|  | 1978/B00C/Electrical Backing Board/S4                                     |     |       |                    |         | <b>Chrysotile (white asbestos)</b> |

**Interior****B00C - R0001 - Canteen**

|   |  |     |      |                    |         |                                    |
|---|--|-----|------|--------------------|---------|------------------------------------|
| Upper wall lining surrounding roller door | Flat AC Sheeting   | 6m2 | East | Good Condition (1) | Low (1) | Low Priority (2-3)                 |
|   | 1978/B00C/R0001/Upper wall lining surrounding roller door/S9 |     |      |                    |         | <b>Chrysotile (white asbestos)</b> |

**B00C - R0002 - External Movement**

No Asbestos

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00D - Pupil Facilities/Staff Facilities - 1975 - Brick/Block (Brick/Block)****Exterior**

|                                   |   |      |   |                    |         |  |
|-----------------------------------|---|------|---|--------------------|---------|--|
| Ceiling Voids - Flat Roof         | Non Accessible Area<br>- Area inaccessible no access points.                  |      |   |                    |         |  |
| Underfloor Voids - Slab on Ground | Non Accessible Area<br>- Area inaccessible, slab to ground, no access points. |      |   |                    |         |  |
| Wall Cladding                     | Flat AC Sheeting<br>1978/B00D/Wall Cladding/S2                                |      |   |                    |         | <b>No Asbestos Detected</b>                              |
| Eaves Linings                     | Flat AC Sheeting<br>1978/B00D/R0001/Ceiling Structures/Linings/S3             | 20m2 | Western building (surrounding rooms DR0001, 0002, 0004, 0005) | Good Condition (1) | Low (1) | Low Priority (2-3)<br><b>Chrysotile (white asbestos)</b> |
| Eaves Linings                     | Flat AC Sheeting<br>1978/B00D/Eaves Linings/S8                                |      |   |                    |         | <b>No Asbestos Detected</b>                              |

**Interior****B00D - R0001 - Toilets - Boys**

|                            |   |      |            |                    |         |  |
|----------------------------|---|------|------------|--------------------|---------|--|
| Ceiling Structures/Linings | Flat AC Sheeting<br>1978/B00D/R0001/Ceiling Structures/Linings/S3 | 19m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3)<br><b>Chrysotile (white asbestos)</b> |
|----------------------------|---|------|------------|--------------------|---------|--|

**B00D - R0002 - Staff Toilet**

|                            |   |     |            |                    |         |  |
|----------------------------|---|-----|------------|--------------------|---------|--|
| Ceiling Structures/Linings | Flat AC Sheeting<br>1978/B00D/R0001/Ceiling Structures/Linings/S3 | 3m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3)<br><b>Chrysotile (white asbestos)</b> |
|----------------------------|---|-----|------------|--------------------|---------|--|

**B00D - R0004 - Staff Toilet**

|                            |   |     |            |                    |         |  |
|----------------------------|---|-----|------------|--------------------|---------|--|
| Ceiling Structures/Linings | Flat AC Sheeting<br>1978/B00D/R0001/Ceiling Structures/Linings/S3 | 4m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3)<br><b>Chrysotile (white asbestos)</b> |
|----------------------------|---|-----|------------|--------------------|---------|--|

**B00D - R0005 - Toilets - Girls**

|                            |   |      |            |                    |         |  |
|----------------------------|---|------|------------|--------------------|---------|--|
| Ceiling Structures/Linings | Flat AC Sheeting<br>1978/B00D/R0001/Ceiling Structures/Linings/S3 | 17m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3)<br><b>Chrysotile (white asbestos)</b> |
|----------------------------|---|------|------------|--------------------|---------|--|

**B00D - R0006 - Access Shower/Toilet**

No Asbestos

**B00D - R0007 - Staff Toilet**

No Asbestos

**B00D - R0008 - External Movement**

|                            |  |  |  |  |  |                             |
|----------------------------|--|--|--|--|--|-----------------------------|
| Ceiling Structures/Linings | Flat AC Sheeting<br>1978/B00D/Eaves Linings/S8 |  |  |  |  | <b>No Asbestos Detected</b> |
|----------------------------|--|--|--|--|--|-----------------------------|

**B00D - R0009 - External Movement**

|                            |   |     |       |                    |         |  |
|----------------------------|---|-----|-------|--------------------|---------|--|
| Ceiling Structures/Linings | Flat AC Sheeting<br>1978/B00D/R0001/Ceiling Structures/Linings/S3 | 8m2 | North | Good Condition (1) | Low (1) | Low Priority (2-3)<br><b>Chrysotile (white asbestos)</b> |
|----------------------------|---|-----|-------|--------------------|---------|--|

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00F - Administration - 1955 - Timber (Timber)**

**Exterior**

Underfloor Voids - Slab on Ground      Non Accessible Area  
 - Area inaccessible, slab on ground.

Ceiling Voids - Flat Roof      No Asbestos Found

**Interior**

**B00F - R0001 - General Storeroom**

No Asbestos

**B00F - R0002 - General Storeroom**

No Asbestos

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00G - Shed - 1999 - Steel (Steel)**

**Exterior**

Underfloor Voids - Slab on Ground      Non Accessible Area  
 - Area inaccessible, slab to ground, no access points.

Ceiling Voids      No Asbestos Found

**Interior**

**B00G - R0001 - Communal Space**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00G - R0002 - General Storeroom**

No Asbestos

**B00G - R0003 - External Movement**

No Asbestos

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00H - Administration - 1884 - Brick/Block (Brick/Block)**

**Exterior**

|                                   |   |
|-----------------------------------|---|
| Ceiling Voids - Raked Ceiling     | Non Accessible Area<br>- Height Restriction |
| Underfloor Voids - Slab on Ground | Non Accessible Area<br>- Area inaccessible  |

**Interior**

**B00H - R0001 - External Movement**

No Asbestos

**B00H - R0002 - Movement**

No Asbestos

**B00H - R0003 - Clerical/Printing**

No Asbestos

**B00H - R0004 - General Storeroom**

No Asbestos

**B00H - R0005 - Entry Vestibule**

No Asbestos

**B00H - R0006 - Clerical Office**

No Asbestos

**B00H - R0007 - Principal**

No Asbestos

**B00H - R0008 - Movement**

No Asbestos

**B00H - R0009 - Staff Toilet**

No Asbestos

**B00H - R0010 - Staff Change**

No Asbestos

**B00H - R0011 - Clerical Office**

No Asbestos

**B00H - R0012 - Staff Kitchen**

No Asbestos

**B00H - R0013 - Staff Room**

|   |   |         |            |                    |                                    |                    |
|---|---|---------|------------|--------------------|------------------------------------|--------------------|
| Floor Coverings Res/Textile                     | Vinyl Tiles (Under Floor Covering/Carpet) | 21.11m2 | Throughout | Minimal Damage (2) | Low (1)                            | Low Priority (2-3) |
| 1978/B00H/R0014/Floor Coverings Res/Textile/S10 |   |         |            |                    | <b>Chrysotile (white asbestos)</b> |                    |

**B00H - R0014 - General Storeroom**

|   |             |      |            |                    |                                    |                    |
|---|-------------|------|------------|--------------------|------------------------------------|--------------------|
| Floor Coverings Res/Textile                     | Vinyl Tiles | 12m2 | Throughout | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 1978/B00H/R0014/Floor Coverings Res/Textile/S10 |             |      |            |                    | <b>Chrysotile (white asbestos)</b> |                    |



| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00I - Library - 2010 - Fibre Cement Clad (Fibre Cement Clad)**

**Exterior**

Underfloor Voids - Slab on Ground      Non Accessible Area  
 - Area inaccessible, slab to ground, no access points.

Ceiling Voids      No Asbestos Found

**Interior**

**B00I - R0001 - External Movement**

No Asbestos

**B00I - R0002 - Reading Area**

No Asbestos

**B00I - R0003 - Handwashing Facilities**

No Asbestos

**B00I - R0004 - K.L.A. Store**

No Asbestos

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00J - Storage - 1975 - Metal Shed (Metal Shed)**

**Exterior**

Underfloor Voids - Slab on Ground      Non Accessible Area  
 - Area inaccessible, slab to ground, no access points.

Ceiling Voids - Raked Ceiling      No Asbestos Found

**Interior**

**B00J - R0001 - General Storeroom**

No Asbestos

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

### Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 531 - D10677 - Library : Placement Date - 30/06/1995

#### Exterior

|             |                     |                  |  |          |
|-------------|---------------------|------------------|--|----------|
| Step Treads | Compressed AC Sheet | Assumed Asbestos |  | 1.08 m2  |
| Landing     | Compressed AC Sheet | Assumed Asbestos |  | 1.2 m2   |
| Eave Lining | Flat AC Sheet       | Assumed Asbestos |  | 11.52 m2 |

#### Interior

##### R1 - Entry/classroom

|                |               |                  |  |       |
|----------------|---------------|------------------|--|-------|
| End wall panel | Flat AC Sheet | Assumed Asbestos |  | 18 m2 |
| Ceiling        | Flat AC Sheet | Assumed Asbestos |  | 63 m2 |

##### R2 - Reading Area/workroom

|                |               |                  |  |       |
|----------------|---------------|------------------|--|-------|
| End wall panel | Flat AC Sheet | Assumed Asbestos |  | 18 m2 |
| Ceiling        | Flat AC Sheet | Assumed Asbestos |  | 10 m2 |

# 2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017