


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Girilambone Public School (1986)  
**Region :** Western NSW  
**State Electorate :** Barwon  
**Local Government Area :** Bogan

**Initial Survey :** Noel Arnold & Associates : 22 - Apr - 2008  
**Reviewed By :** Grencap-NAA : 02 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - General Learning/Library - 1913 - Timber (Timber)**

**Exterior**

In-fill-panel	Flat AC Sheeting 1986/B00A/In-fill-panel/S2					<b>No Asbestos Detected</b>
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

**Interior**

**B00A - R0001 - Craft Store**

Wall Linings Internal	Flat AC Sheeting 1986/B00A/R0001/Wall Linings Internal/S1	12m2	North, South, East	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Compressed AC Sheet 1986/B00A/R0006/Floor Coverings Res/Textile/S3	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>

**B00A - R0002 - Home Base**

No Asbestos

**B00A - R0005 - Reading Area**

No Asbestos

**B00A - R0006 - External Movement**

Floor Coverings Res/Textile	Compressed AC Sheet 1986/B00A/R0006/Floor Coverings Res/Textile/S3	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>

**B00A - R0008 - Entry Vestibule**

Recently Modified Space Requires Inspection

**B00A - R0009 - Movement**

Recently Modified Space Requires Inspection

**B00A - R0010 - Staff Kitchen**

Recently Modified Space Requires Inspection

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - Communal Facilities - 1977 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Eaves Linings	Flat AC Sheeting 1986/B00B/Eaves Linings/S4					<b>No Asbestos Detected</b>
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

**Interior**

**B00B - R0001 - Communal Space**

No Asbestos

**B00B - R0002 - Shelter**

No Asbestos

**B00B - R0003 - Covered Outdoor Learning Area**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - General Learning - 1974 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

**Interior**

**B00C - R0001 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00C - R0002 - External Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - Administration - 1999 - Fibre Cement Clad (Fibre Cement Clad)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00D - R0004 - General Storeroom**

No Asbestos

**B00D - R0005 - Clerical Office/Workroom**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00D - R0006 - Principal**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00D - R0007 - Staff Toilet**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - Physical Education - 2007 - Metal Shed (Metal Shed)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00E - R0001 - Sports Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - Building Services - 1970 - Metal Shed (Metal Shed)**

**Exterior**

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

**Interior**

**B00F - R0001 - General Assistant/Bulk Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - Staff Facilities - 1970 - Timber (Timber)**

**Exterior**

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

**Interior**

**B00G - R0001 - Garage/Carport**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

### Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 844 - D13831 - Country Toilet - Reltc - Boys/Girls : Placement Date - 30/06/1995

#### Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	2.88 m2

#### Interior

##### R1 - Staff Toilet

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	9 m2

##### R2 - Staff Toilet

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	9 m2

# 2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Listing of Electronic Attachments as of 22/03/2017***

**There are no asbestos related file attachment(s) for this school.**

2017