

# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Gladstone Public School (1991)  
**Region :** North Coast  
**State Electorate :** Oxley  
**Local Government Area :** Kempsey

**Initial Survey :** Noel Arnold & Associates : 01 - May - 2008  
**Reviewed By :** Parsons Brinckerhoff : 01 - Nov - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - Administration/Staff Facilities - 1977 - Timber (Timber)**

**Exterior**

Eaves Linings	Flat AC Sheeting	25m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1991/B00A/Eaves Linings/S6				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
Underfloor Void	No Asbestos Found					
Ceiling Void	No Asbestos Found					

**Interior**

**B00A - R0001 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1991/B00A/R0001/Ceiling Structures/Linings/S7				<b>Chrysotile (white asbestos)</b>	

**B00A - R0002 - Clerical Office**

No Asbestos

**B00A - R0003 - Principal**

No Asbestos

**B00A - R0004 - Entry Vestibule**

No Asbestos

**B00A - R0005 - Staff Room**

No Asbestos

**B00A - R0006 - Staff Kitchen**

No Asbestos

**B00A - R0007 - Duplicating Workroom**

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1991/B00A/R0001/Ceiling Structures/Linings/S7				<b>Chrysotile (white asbestos)</b>	
Floor Coverings Res/Textile	Vinyl Tiles					
	1991/B00A/R0007/Floor Coverings Res/Textile/S8				<b>No Asbestos Detected</b>	

**B00A - R0008 - Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - General Learning - 1877 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Void	No Asbestos Found
Ceiling Void	No Asbestos Found

**Interior**

**B00B - R0001 - Practical Activities - 1hb**

Floor Coverings Res/Textile	Vinyl Tiles	1991/B00B/R0001/Floor Coverings Res/Textile/S4	<b>No Asbestos Detected</b>
Wall Linings Internal	Flat AC Sheeting	1991/B00B/R0001/Wall Linings Internal/S5	<b>No Asbestos Detected</b>

**B00B - R0002 - Home Base**

No Asbestos

**B00B - R0003 - Home Base**

No Asbestos

**B00B - R0004 - Home Base Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - Pupil Facilities - 1977 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	20m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1991/B00C/Eaves Linings/S1			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Ceiling Void	No Asbestos Found					

**Interior**

**B00C - R0002 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting					<b>No Asbestos Detected</b>
	1991/B00C/R0003/Ceiling Structures/Linings/S2					

**B00C - R0003 - Toilets - Boys**

Partition Walls (Cubicles)	Compressed AC Sheet	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1991/B00C/R0003/Partition Walls (Cubicles)/S3			<b>Chrysotile (white asbestos)</b>		

**B00C - R0004 - Movement**

No Asbestos

**B00C - R0005 - Toilets - Girls**

No Asbestos

**B00C - R0006 - Staff Toilet**

No Asbestos

**B00C - R0007 - Staff Toilet**

No Asbestos

**B00C - R0008 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting					<b>No Asbestos Detected</b>
	1991/B00C/R0003/Ceiling Structures/Linings/S2					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - Pupil Facilities - 1977 - Metal Shed (Metal Shed)**

**Exterior**

Ceiling Voids - Flat Roof	No Asbestos Found
Underfloor Void	No Asbestos Found

**Interior**

**B00D - R0001 - Movement**

No Asbestos

**B00D - R0002 - Canteen**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - Pupil Facilities - 1900 - Timber (Timber)**

**Exterior**

Underfloor Voids	AC Fragments/Debris	1m2	Throughout	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5)
	1991/B00E/Underfloor Voids/S9			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Ceiling Void	No Asbestos Found					

**Interior**

**B00E - R0001 - Canteen Covered Area**

No Asbestos

**B00E - R0002 - General Assistant/Bulk Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - Shed - 1977 - Metal Shed (Metal Shed)**

**Exterior**

Underfloor Voids - Slab on Ground      No Asbestos Found

Ceiling Void      No Asbestos Found

**Interior**

**B00F - R0001 - Sports Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - Library - 2010 - Fibre Cement Clad (Fibre Cement Clad)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Void	No Asbestos Found

**Interior**

**B00G - R0001 - Reading Area**

No Asbestos

**B00G - R0002 - K.L.A. Store**

No Asbestos

**B00G - R0003 - Practical Activities**

No Asbestos

**B00G - R0004 - External Movement**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - Storage - 2015 - Metal Shed (Metal Shed)**

**Exterior**

Ceiling Void	No Asbestos Found
Ceiling Void	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Void	No Asbestos Found
Ceiling Void	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Void	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Void	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Void	No Asbestos Found
Ceiling Void	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

**Interior**

**B00H - R0001 - External Movement**

No Asbestos
No Asbestos
No Asbestos
No Asbestos
No Asbestos
No Asbestos
No Asbestos
No Asbestos
No Asbestos

**B00H - R0002 - Sports Store**

No Asbestos
No Asbestos
No Asbestos
No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Demountables**

**Demountable details as per the AMS records as of 15 Feb 2017.**

**OS 837 - D17088 - Hcap Shower/Change/Toilet : Placement Date - 15/07/2016**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Disabled Shower/Toilet**

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017