


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Glenmore Road Public School (2009)
Region : Sydney
State Electorate : Sydney
Local Government Area : Woollahra

Initial Survey : Noel Arnold & Associates : 11 - Feb - 2008
Reviewed By : AECOM : 26 - May - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/Staff Facilities - 1882 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found					
Underfloor Voids	Non Accessible Area - Area inaccessible - due to storage.					

Interior

B00A - R0002 - Toilets-Disabled

No Asbestos						
-------------	--	--	--	--	--	--

B00A - R0003 - Security Store

Ceiling Structures/Linings	Flat AC Sheeting	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2009/B00A/R0007/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)	

B00A - R0006 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	16m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2009/B00A/R0007/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)	

B00A - R0007 - Movement

Floor Coverings Res/Textile	Vinyl Tiles					
2009/B00A/R0007/Floor Coverings Res/Textile/S1					No Asbestos Detected	

Ceiling Structures/Linings	Flat AC Sheeting	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2009/B00A/R0007/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)	

B00A - R0008 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2009/B00A/R0007/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)	

B00A - R0009 - Music Store

Floor Coverings Res/Textile	Vinyl Tiles					
2009/B00A/R0007/Floor Coverings Res/Textile/S1					No Asbestos Detected	

Ceiling Structures/Linings	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2009/B00A/R0007/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)	

B00A - R0010 - Sports Store

Floor Coverings Res/Textile	Vinyl Tiles					
2009/B00A/R0010/Floor Coverings Res/Textile/S4					No Asbestos Detected	

B00A - R0011 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2009/B00A/R0007/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)	

B00A - R0015 - Home Base

No Asbestos						
-------------	--	--	--	--	--	--

B00A - R0016 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2009/B00A/R0007/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)	

B00A - R0017 - Clerical Office

Ceiling Structures/Linings	Flat AC Sheeting	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2009/B00A/R0007/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)	

B00A - R0018 - Staff Toilet

No Asbestos						
-------------	--	--	--	--	--	--

B00A - R0019 - Communal Space

No Asbestos						
-------------	--	--	--	--	--	--

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R0020 - Home Base						
No Asbestos						
B00A - R0021 - Raised Platform						
No Asbestos						
B00A - R9001 - Main Switch Board						
No Asbestos						
B00A - R9002 - Hall Chair Store						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning/Pupil Facilities - 1972 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	15m2	North facing, South facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	2009/B00B/R1010/Ceiling Structures/Linings/S6					Chrysotile (white asbestos)
Ceiling Voids	Non Accessible Area - Area inaccessible - due to height.					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior

B00B - R0001 - Cleaning Distributed Store

No Asbestos

B00B - R0002 - Movement

No Asbestos

B00B - R0003 - Home Base

No Asbestos

B00B - R0004 - Movement

No Asbestos

B00B - R0005 - Home Base

No Asbestos

B00B - R0006 - Home Base

No Asbestos

B00B - R0007 - Movement

No Asbestos

B00B - R0008 - Cleaning Distributed Store

No Asbestos

B00B - R0009 - Garden Store

No Asbestos

B00B - R0010 - Garden Store

No Asbestos

B00B - R0011 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet	24m2	North facing, South facing, East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	2009/B00B/R0011/Partition Walls (Cubicles)/S7					Chrysotile (white asbestos)

B00B - R0012 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet	32m2	North facing, South facing, East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	2009/B00B/R0011/Partition Walls (Cubicles)/S7					Chrysotile (white asbestos)

B00B - R0013 - Stairs

No Asbestos

B00B - R0014 - Stairs

Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	2009/B00B/R0014/Ceiling Structures/Linings/S2					

B00B - R0015 - Covered Outdoor Learning Area

No Asbestos

B00B - R1001 - Movement

No Asbestos

B00B - R1002 - Movement

No Asbestos

B00B - R1003 - Home Base

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00B - R1004 - Home Base

No Asbestos

B00B - R1005 - Home Base

No Asbestos

B00B - R1010 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	16m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2009/B00B/R1010/Ceiling Structures/Linings/S6					Chrysotile (white asbestos)	

B00B - R1011 - Stairs

Ceiling Structures/Linings	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
2009/B00B/R1010/Ceiling Structures/Linings/S6					Chrysotile (white asbestos)	

B00B - R1012 - Stairs

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning/Library - 1910 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	Non Accessible Area - Height Restriction

Interior

B00C - R0001 - Movement

Ceiling Structures/Linings	Flat AC Sheeting					
	2009/B00C/R1001/Ceiling Structures/Linings/S9					No Asbestos Detected

B00C - R0002 - Cleaning Distributed Store

No Asbestos

B00C - R0003 - Home Base

Wall Linings Internal	Flat AC Sheeting					
	2009/B00C/R1001/Ceiling Structures/Linings/S9					No Asbestos Detected

B00C - R0004 - Home Base

Wall Linings Internal	Flat AC Sheeting	16m2	East facing, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Area inaccessible						

B00C - R0005 - Canteen

Ceiling Structures/Linings	Flat AC Sheeting					
	2009/B00C/R1001/Ceiling Structures/Linings/S9					No Asbestos Detected

B00C - R0006 - Movement

Ceiling Structures/Linings	Flat AC Sheeting					
	2009/B00B/R0014/Ceiling Structures/Linings/S2					No Asbestos Detected

B00C - R0007 - Reading Area

No Asbestos

B00C - R0008 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0009 - Communications Room

No Asbestos

B00C - R0010 - K.L.A. Store

No Asbestos

B00C - R0011 - Library Office/Workroom

No Asbestos

B00C - R0012 - Stairs

Ceiling Structures/Linings	Flat AC Sheeting					
	2009/B00C/R1001/Ceiling Structures/Linings/S9					No Asbestos Detected

B00C - R1001 - Movement

Ceiling Structures/Linings	Flat AC Sheeting					
	2009/B00C/R1001/Ceiling Structures/Linings/S9					No Asbestos Detected

B00C - R1002 - Home Base

No Asbestos

B00C - R1003 - Home Base

No Asbestos

B00C - R1004 - Movement

Ceiling Structures/Linings	Flat AC Sheeting					
	2009/B00C/R1004/Ceiling Structures/Linings/S10					No Asbestos Detected

B00C - R1005 - Staff Toilet

No Asbestos

B00C - R1006 - Craft Store

Ceiling Structures/Linings	Flat AC Sheeting					
	2009/B00C/R1001/Ceiling Structures/Linings/S9					No Asbestos Detected

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - R1007 - Withdrawal Space - 1hb

No Asbestos

B00C - R1008 - Stairs

Ceiling Structures/Linings	Flat AC Sheeting					
	2009/B00C/R1001/Ceiling Structures/Linings/S9					No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Other-After School Care - 1893 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00D - R0001 - General Storeroom

No Asbestos

B00D - R0002 - Movement

No Asbestos

B00D - R0003 - Staff Toilet

No Asbestos

B00D - R0004 - Staff Kitchen

No Asbestos

B00D - R0005 - Special Programs Room

No Asbestos

B00D - R0006 - Special Programs Room

No Asbestos

B00D - R0007 - Movement

No Asbestos

B00D - R0008 - Out Of School Hours Care Centre

No Asbestos

B00D - R0009 - Out Of School Hours Care Centre

No Asbestos

B00D - R0010 - Out Of School Hours Care Centre

No Asbestos

B00D - R0011 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Pupil Facilities - 1893 - Brick/Block (Brick/Block)

Exterior

Wall Cladding	Flat AC Sheeting 2009/B00E/Wall Cladding/S3	15m2	North facing, East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos) , Amosite (brown asbestos)
Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids - Raked Ceiling	Non Accessible Area - Area inaccessible					

Interior

B00E - R0001 - Toilets - Boys/Girls

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00F - Administration/General Learning - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

No Asbestos

Interior

B00F - R0001 - Entry Vestibule

No Asbestos

B00F - R0002 - Clerical Office/Workroom

No Asbestos

B00F - R0003 - Sick Bay

No Asbestos

B00F - R0004 - Access Shower/Toilet

No Asbestos

B00F - R0005 - Main Switch Board

No Asbestos

B00F - R0006 - General Storeroom

No Asbestos

B00F - R0007 - Cleaning Distributed Store

No Asbestos

B00F - R0008 - Toilet - Lobby

No Asbestos

B00F - R0009 - Interview

No Asbestos

B00F - R0010 - Principal

No Asbestos

B00F - R0011 - Staff Room

No Asbestos

B00F - R0012 - Staff Kitchen

No Asbestos

B00F - R0013 - External Movement

No Asbestos

B00F - R0014 - External Movement

No Asbestos

B00F - R0015 - Movement

No Asbestos

B00F - R0016 - Staff Toilet

No Asbestos

B00F - R1001 - Home Base

No Asbestos

B00F - R1002 - Home Base Store

No Asbestos

B00F - R1003 - Practical Activities - 1hb

No Asbestos

B00F - R1004 - Withdrawal Space - 2hb

No Asbestos

B00F - R1005 - Home Base

No Asbestos

B00F - R1006 - Home Base Store

No Asbestos

B00F - R1007 - Practical Activities - 1hb

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - R1008 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Building Services - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

No Asbestos

Interior

B00G - R0001 - Other

No Asbestos

B00G - R0002 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D11035 - Learning Unit - Standard With P.A.A. : Placement Date - 16/01/2013

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017