

# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Glenreagh Public School (2016)  
**Region :** North Coast  
**State Electorate :** Clarence  
**Local Government Area :** Clarence Valley

**Initial Survey :** Noel Arnold & Associates : 09 - May - 2008  
**Reviewed By :** Greencap-NAA : 05 - May - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - Administration/Staff Facilities - 1995 - Timber (Timber)**

**Exterior**

Eaves Linings	Flat AC Sheeting 2016/B00A/Eaves Linings/S1					<b>No Asbestos Detected</b>
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior**

**B00A - R0001 - Security Store**

No Asbestos

**B00A - R0008 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting 2016/B00A/R0008/Ceiling Structures/Linings/S10	42m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>

**B00A - R0009 - Special Programs Room**

Ceiling Structures/Linings	Flat AC Sheeting 2016/B00A/R0008/Ceiling Structures/Linings/S10	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>

**B00A - R0010 - Sick Bay**

No Asbestos

**B00A - R0012 - Principal**

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 2016/B00A/R0012/Floor Coverings Res/Textile/S8	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive 2016/B00A/R0012/Floor Coverings Res/Textile/S9					<b>No Asbestos Detected</b>

**B00A - R0014 - Home Base**

Wall Linings Internal	Flat AC Sheeting 2016/B00A/R0018/Wall Linings Internal/S2	10m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive 2016/B00A/R0012/Floor Coverings Res/Textile/S9					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 2016/B00A/R0012/Floor Coverings Res/Textile/S8	45m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>

**B00A - R0015 - Practical Activities - 1hb**

No Asbestos

**B00A - R0018 - Staff Room**

Wall Linings Internal	Flat AC Sheeting 2016/B00A/R0018/Wall Linings Internal/S2	30m2	South, East	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>

**B00A - R0019 - General Assistant/Bulk Store**

No Asbestos

**B00A - R0020 - Disabled Toilet**

Wall Linings Internal	Flat AC Sheeting 2016/B00A/R0020/Wall Linings Internal/S3					<b>No Asbestos Detected</b>
-----------------------	--	--	--	--	--	-----------------------------

**B00A - R0021 - Movement**

No Asbestos

**B00A - R0022 - Clerical Office**

Floor Coverings Res/Textile	Adhesive 2016/B00A/R0012/Floor Coverings Res/Textile/S9					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 2016/B00A/R0012/Floor Coverings Res/Textile/S8	21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00A - R0023 - Entry Vestibule</b>						
Floor Coverings Res/Textile	Adhesive					
	2016/B00A/R0012/Floor Coverings Res/Textile/S9				<b>No Asbestos Detected</b>	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2016/B00A/R0012/Floor Coverings Res/Textile/S8				<b>Chrysotile (white asbestos)</b>	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - General Learning - 1995 - Fibre Cement Clad (Fibre Cement Clad)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00B - R0001 - Movement**

No Asbestos

**B00B - R0002 - Home Base**

No Asbestos

**B00B - R0003 - Practical Activities - 1hb**

No Asbestos

**B00B - R0004 - Home Base Store**

No Asbestos

**B00B - R0005 - Withdrawal Space - 1hb**

No Asbestos

**B00B - R0006 - Home Base**

No Asbestos

**B00B - R0007 - Home Base Store**

No Asbestos

**B00B - R0008 - Practical Activities - 1hb**

No Asbestos

**B00B - R0009 - Movement**

No Asbestos

**B00B - R0010 - Movement**

No Asbestos

**B00B - R0011 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - Library - 1978 - Timber (Timber)**

**Exterior**

Ceiling Voids - Raked Ceiling	Non Accessible Area - Area inaccessible
Underfloor Voids	No Asbestos Found

**Interior**

**B00C - R0001 - Withdrawal Space - 2hb**

No Asbestos

**B00C - R0002 - Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - Pupil Facilities - 1955 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible					
Eaves Linings	Flat AC Sheeting 2016/B00A/Eaves Linings/S1					<b>No Asbestos Detected</b>

**Interior**

**B00D - R0001 - Toilets - Boys**

Partition Walls (Cubicles)	Compressed AC Sheet	5m2	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	2016/B00D/R0002/Partition Walls (Cubicles)/S4					<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2016/B00D/R0001/Ceiling Structures/Linings/S7					<b>Chrysotile (white asbestos)</b>
Flue Pipe	Fibre Cement Pipe	4m	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	2016/B00D/R0001/Flue Pipe/S6					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00D - R0002 - Toilets - Girls**

Partition Walls (Cubicles)	Compressed AC Sheet	10m2	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	2016/B00D/R0002/Partition Walls (Cubicles)/S4					<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2016/B00D/R0001/Ceiling Structures/Linings/S7					<b>Chrysotile (white asbestos)</b>

**B00D - R0003 - Staff Toilet**

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2016/B00D/R0001/Ceiling Structures/Linings/S7					<b>Chrysotile (white asbestos)</b>

**B00D - R0004 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2016/B00D/R0001/Ceiling Structures/Linings/S7					<b>Chrysotile (white asbestos)</b>

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - Building Services - 1999 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids - Slab on Ground      No Asbestos Found

Ceiling Voids      No Asbestos Found

**Interior**

**B00G - R0001 - General Assistant/Bulk Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - General Learning/Library - 2003 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

**Interior**

**B00H - R0001 - Withdrawal Space - 1hb**

No Asbestos

**B00H - R0002 - Home Base**

No Asbestos

**B00H - R0003 - Practical Activities - 1hb**

No Asbestos

**B00H - R0004 - Home Base Store**

No Asbestos

**B00H - R0005 - Withdrawal Space - 1hb**

No Asbestos

**B00H - R0006 - Reading Area**

No Asbestos

**B00H - R0007 - Security Store**

No Asbestos

**B00H - R0008 - Communications Room**

No Asbestos

**B00H - R0009 - Library Office/Workroom**

No Asbestos

**B00H - R0010 - Staff Toilet**

No Asbestos

**B00H - R0011 - Cleaning Distributed Store**

No Asbestos

**B00H - R0012 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00H - R0013 - Movement**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00I - Pupil Facilities/Multi Purpose Facilities - 2010 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

**Interior**

**B00I - R0001 - Special Programs Room**

No Asbestos

**B00I - R0002 - P.E. Store**

No Asbestos

**B00I - R0003 - General Assistant/Bulk Store**

No Asbestos

**B00I - R0004 - General Assistant/Bulk Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00J - Pupil Facilities - 2010 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

**Interior**

**B00J - R0001 - Canteen**

No Asbestos

**B00J - R0002 - Canteen Office/Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Demountables***

**There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017