

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Glossodia Public School (2021)
Region : Western Sydney
State Electorate : Hawkesbury
Local Government Area : Hawkesbury

Initial Survey : Noel Arnold & Associates : 22 - Apr - 2008
Register Issue Date : 22 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Communal Facilities/Administration - 1990 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00A - R0001 - Community Clinic

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0002 - Clinic-Toilets

No Asbestos

B00A - R0003 - Community Clinic

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0004 - Movement

No Asbestos

B00A - R0005 - Uniform Shop

No Asbestos

B00A - R0006 - General Assistant/Bulk Store

No Asbestos

B00A - R0007 - Cleaning Supplies

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0008 - Main Switch Board

No Asbestos

B00A - R0009 - Garden Store

No Asbestos

B00A - R0010 - Craft Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0017 - Hall Chair Store

No Asbestos

B00A - R0018 - Raised Platform

No Asbestos

B00A - R0021 - Communal Space

No Asbestos

B00A - R0022 - Movement

No Asbestos

B00A - R0023 - P.E. Store

No Asbestos

B00A - R0024 - Main Switch Board

No Asbestos

B00A - R0025 - Sound Cupboard

No Asbestos

B00A - R0026 - Access Shower/Toilet/Change

No Asbestos

B00A - R0027 - Toilets - Boys

No Asbestos

B00A - R0028 - Toilets - Girls

No Asbestos

B00A - R0029 - Cleaning Distributed Store

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - R0030 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Pupil Facilities - 1990 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00B - R0001 - Movement

No Asbestos

B00B - R0002 - Movement

No Asbestos

B00B - R0003 - Canteen

No Asbestos

B00B - R0004 - Disabled Toilet

No Asbestos

B00B - R0005 - Canteen Office/Store

No Asbestos

B00B - R0006 - Stairs

No Asbestos

B00B - R0007 - Stairs

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00C - Administration/Staff Facilities - 1990 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00C - R0001 - Staff Room Annexe

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0002 - Staff Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0003 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0004 - Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0005 - Security Store

No Asbestos

B00C - R0006 - Duplicating Workroom

No Asbestos

B00C - R0007 - Entry Vestibule

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0008 - Movement

No Asbestos

B00C - R0009 - Clerical Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0010 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0011 - Sick Bay

No Asbestos

B00C - R0012 - Staff Shower/Change

No Asbestos

B00C - R0013 - Interview

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0014 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0015 - Staff Toilet

No Asbestos

B00C - R0016 - Cleaning Distributed Store

No Asbestos

B00C - R0017 - Staff Toilet

No Asbestos

B00C - R0018 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0019 - Movement

No Asbestos

B00C - R0020 - Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00C - R0021 - Movement

No Asbestos

B00C - R0022 - Ramp

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Library/Tiered Learning - 1990 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00D - R0001 - Reading Area

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0002 - Plant

No Asbestos

B00D - R0003 - Cleaning Supplies

No Asbestos

B00D - R0004 - Special Programs Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0005 - Special Programs Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0006 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0007 - Movement

No Asbestos

B00D - R0008 - Reading Area

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0009 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0010 - Communications Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0011 - Ramp

No Asbestos

B00D - R0012 - General Storeroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0013 - Special Programs Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0014 - Special Programs Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning - 1990 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00E - R0001 - Movement

No Asbestos

B00E - R0002 - Practical Activities - 1hb

No Asbestos

B00E - R0003 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0004 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0005 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0006 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0007 - Cleaning Distributed Store

No Asbestos

B00E - R0008 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00E - R0009 - Practical Activities - 1hb

No Asbestos

B00E - R0010 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0011 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0012 - Practical Activities - 1hb

No Asbestos

B00E - R0013 - Sports Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0014 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0015 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0016 - Movement

No Asbestos

B00E - R0017 - Plant

No Asbestos

B00E - R0018 - Stairs

No Asbestos

B00E - R1002 - Practical Activities - 1hb

No Asbestos

B00E - R1003 - Home Base

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00E - R1004 - Home Base Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00E - R1005 - Withdrawal Space - 1hb						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00E - R1006 - Home Base Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00E - R1007 - Cleaning Distributed Store						
No Asbestos						
B00E - R1008 - Distribution Board					Note: No inspection of live electrical installation.	
No Asbestos						
B00E - R1009 - Practical Activities - 1hb						
No Asbestos						
B00E - R1010 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00E - R1011 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00E - R1012 - Practical Activities - 1hb						
No Asbestos						
B00E - R1013 - Home Base Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00E - R1014 - Kiln Room						
No Asbestos						
B00E - R1015 - Withdrawal Space - 1hb						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00E - R1016 - Special Programs Room						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00E - R1017 - Plant						
No Asbestos						
B00E - R1018 - Stairs						
No Asbestos						
B00E - R1019 - Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00F - General Learning/Pupil Facilities - 1990 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00F - R0001 - Movement

No Asbestos

B00F - R0002 - Toilets - Boys

No Asbestos

B00F - R0003 - Toilets - Girls

No Asbestos

B00F - R0004 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00F - R0005 - Disabled Toilet

No Asbestos

B00F - R0006 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0007 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0008 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0009 - Practical Activities - 1hb

No Asbestos

B00F - R0010 - Practical Activities - 1hb

No Asbestos

B00F - R0011 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0012 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0013 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0014 - Stairs

No Asbestos

B00F - R1001 - Movement

No Asbestos

B00F - R1002 - Toilets - Boys

No Asbestos

B00F - R1003 - Toilets - Girls

No Asbestos

B00F - R1004 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00F - R1005 - General Storeroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R1006 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00F - R1007 - Withdrawal Space - 1hb						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00F - R1008 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00F - R1009 - Practical Activities - 1hb						
No Asbestos						
B00F - R1010 - Practical Activities - 1hb						
No Asbestos						
B00F - R1011 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00F - R1012 - Withdrawal Space - 1hb						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00F - R1013 - Home Base Store						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00F - R1014 - Stairs						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Building Services - 1990 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00G - R0001 - Garden Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017