


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Goodooga Central School (2033)  
**Region :** Western NSW  
**State Electorate :** Barwon  
**Local Government Area :** Brewarrina

**Initial Survey :** Noel Arnold & Associates : 13 - May - 2008  
**Reviewed By :** Parsons Brinckerhoff : 25 - Aug - 2016

2033 - Goodooga Central School  
Site Plan (All Sites)



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - Building Services - 1958 - Timber Shed (Timber Shed)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2033/B00A/Eaves Linings/S6				<b>Chrysotile (white asbestos)</b>	
Ceiling Void	No Asbestos Found					

**Interior**

**B00A - R0001 - General Assistant/Bulk Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - Special Purpose - 1958 - Timber (Timber)**

**Exterior**

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

**Interior**

**B00B - R0001 - General Learning Space**

No Asbestos

**B00B - R0002 - External Movement**

Ceiling Structures/Linings	Flat AC Sheeting 2033/B00B/R0002/Ceiling Structures/Linings/S8	<b>No Asbestos Detected</b>
----------------------------	---	-----------------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - General Learning - 1958 - Timber (Timber)**

**Exterior**

Eaves Linings	Flat AC Sheeting	10m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	2033/B00C/Eaves Linings/S7				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	
Ceiling Void	No Asbestos Found					
Underfloor Void	No Asbestos Found					

**Interior**

**B00C - R0001 - Home Base**

No Asbestos

**B00C - R0002 - General Storeroom**

No Asbestos

**B00C - R0003 - Music Store**

No Asbestos

**B00C - R0004 - External Movement**

Ceiling Structures/Linings	Flat AC Sheeting					
	2033/B00B/R0002/Ceiling Structures/Linings/S8				<b>No Asbestos Detected</b>	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

**B00D - Pupil Facilities - 1968 - Timber (Timber)****Exterior**

Eaves Linings	Flat AC Sheeting 2033/B00D/Eaves Linings/S3	40m2	East, West	Some Damage / Unsealed (3)	Medium (2)	Low Priority (2-3)
				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Ceiling Void	No Asbestos Found					
Underfloor Void	No Asbestos Found					

**Interior****B00D - R0001 - General Storeroom**

Wall Linings Internal	Flat AC Sheeting 2033/B00D/R0004/Wall Linings Internal/S5					<b>No Asbestos Detected</b>
Ceiling Structures/Linings	Flat AC Sheeting 2033/B00D/R0002/Ceiling Structures/Linings/S9	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				<b>Chrysotile (white asbestos) , Crocidolite (blue asbestos)</b>		

**B00D - R0002 - General Storeroom**

Wall Linings Internal	Flat AC Sheeting 2033/B00D/R0004/Wall Linings Internal/S5					<b>No Asbestos Detected</b>
Ceiling Structures/Linings	Flat AC Sheeting 2033/B00D/R0002/Ceiling Structures/Linings/S9	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				<b>Chrysotile (white asbestos) , Crocidolite (blue asbestos)</b>		

**B00D - R0003 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting 2033/B00D/R0002/Ceiling Structures/Linings/S9	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				<b>Chrysotile (white asbestos) , Crocidolite (blue asbestos)</b>		
Wall Linings Internal	Flat AC Sheeting 2033/B00D/R0004/Wall Linings Internal/S5					<b>No Asbestos Detected</b>

**B00D - R0004 - Cleaning Supplies**

Wall Linings Internal	Flat AC Sheeting 2033/B00D/R0004/Wall Linings Internal/S5					<b>No Asbestos Detected</b>
Ceiling Structures/Linings	Flat AC Sheeting 2033/B00D/R0002/Ceiling Structures/Linings/S9	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				<b>Chrysotile (white asbestos) , Crocidolite (blue asbestos)</b>		

**B00D - R0005 - Toilets - Boys**

Ceiling Structures/Linings	Flat AC Sheeting 2033/B00D/R0007/Ceiling Structures/Linings/S4					<b>No Asbestos Detected</b>
----------------------------	---	--	--	--	--	-----------------------------

**B00D - R0006 - External Movement**

Wall Linings Internal	Flat AC Sheeting 2033/B00D/R0004/Wall Linings Internal/S5					<b>No Asbestos Detected</b>
-----------------------	--	--	--	--	--	-----------------------------

**B00D - R0007 - Toilets - Girls**

Ceiling Structures/Linings	Flat AC Sheeting 2033/B00D/R0007/Ceiling Structures/Linings/S4					<b>No Asbestos Detected</b>
----------------------------	---	--	--	--	--	-----------------------------

**B00D - R0008 - General Storeroom**

Ceiling Structures/Linings	Flat AC Sheeting 2033/B00D/R0002/Ceiling Structures/Linings/S9	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				<b>Chrysotile (white asbestos) , Crocidolite (blue asbestos)</b>		
Partition Walls (Cubicles)	Compressed AC Sheet 2033/B00D/R0008/Partition Walls (Cubicles)/S11					<b>No Asbestos Detected</b>

Wall Linings Internal	Flat AC Sheeting 2033/B00D/R0004/Wall Linings Internal/S5					<b>No Asbestos Detected</b>
-----------------------	--	--	--	--	--	-----------------------------

**B00D - R0009 - General Storeroom**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Wall Linings Internal	Flat AC Sheeting 2033/B00D/R0004/Wall Linings Internal/S5					<b>No Asbestos Detected</b>
Ceiling Structures/Linings	Flat AC Sheeting 2033/B00D/R0002/Ceiling Structures/Linings/S9	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				<b>Chrysotile (white asbestos) , Crocidolite (blue asbestos)</b>		
<b>B00D - R0010 - Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting 2033/B00D/R0002/Ceiling Structures/Linings/S9	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				<b>Chrysotile (white asbestos) , Crocidolite (blue asbestos)</b>		
Wall Linings Internal	Flat AC Sheeting 2033/B00D/R0004/Wall Linings Internal/S5					<b>No Asbestos Detected</b>

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - General Learning/Science Learning - 1970 - Brick/Block (Brick/Block)**

**Exterior**

Flue	Fibre Cement Pipe	1m	East	Good Condition (1)	Low (1)	Low Priority (2-3)	
<b>Assumed Asbestos - Unable to sample - On roof</b>							
In-fill-panel	Flat AC Sheeting	29m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)	
2033/B00E/In-fill-panel/S1					<b>Chrysotile (white asbestos)</b>		
In-fill Panel under windows	Putty						
2033/B00E/In-fill Panel under windows/S14					<b>No Asbestos Detected</b>		
Underfloor Void	No Asbestos Found						
Ceiling Void	No Asbestos Found						

**Interior**

**B00E - R0001 - External Movement**

No Asbestos

**B00E - R0002 - Apparatus Store**

No Asbestos

**B00E - R0003 - Kiln Room**

No Asbestos

**B00E - R0005 - Apparatus Store**

No Asbestos

**B00E - R0006 - Chemical Store**

Fume Cupboard	Flat AC Sheeting	1Unit	North	Good Condition (1)	Low (1)	Low Priority (2-3)
2033/B00E/R0006/Fume Cupboard/S10					<b>Chrysotile (white asbestos)</b>	

**B00E - R0007 - Drinking Facilities**

No Asbestos

**B00E - R0008 - General Storeroom**

Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2033/B00E/R0016/Floor Coverings Res/Textile/S2					<b>Chrysotile (white asbestos)</b>	

**B00E - R0009 - General Storeroom**

Floor Coverings Res/Textile	Vinyl Tiles						
2033/B00E/R0009/Floor Coverings Res/Textile/S12					<b>No Asbestos Detected</b>		

**B00E - R0010 - Food Technology L.S.**

Floor Coverings Res/Textile	Vinyl Tiles	66m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2033/B00E/R0016/Floor Coverings Res/Textile/S2					<b>Chrysotile (white asbestos)</b>	

Thermacon Heater	Encapsulated Insulation material within unit	3Unit	East, West	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - Encapsulated material within units</b>						

**B00E - R0011 - Staff Kitchen**

Floor Coverings Res/Textile	Vinyl Tiles	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2033/B00E/R0016/Floor Coverings Res/Textile/S2					<b>Chrysotile (white asbestos)</b>	

**B00E - R0012 - Staff Room Annexe**

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)						
2033/B00E/R0009/Floor Coverings Res/Textile/S12					<b>No Asbestos Detected</b>		

**B00E - R0013 - Movement**

No Asbestos

**B00E - R0014 - Staff Toilet**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00E - R0015 - Staff Toilet</b>						
No Asbestos						
<b>B00E - R0016 - Staff Room Annexe</b>						
Floor Coverings Res/Textile	Vinyl Tiles	26m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2033/B00E/R0016/Floor Coverings Res/Textile/S2					<b>Chrysotile (white asbestos)</b>	
<b>B00E - R0017 - Distribution Board</b>						
Note: No inspection of live electrical installation.						
Electrical Mounting Board	Resinous Board	1Unit	East	Good Condition (1)	Low (1)	Low Priority (2-3)
2033/B00E/R0017/Electrical Mounting Board/S13					<b>Chrysotile (white asbestos)</b>	
<b>B00E - R0018 - Plant</b>						
No Asbestos						
<b>B00E - R0019 - Plant</b>						
No Asbestos						
<b>B00E - R0020 - General Storeroom</b>						
No Asbestos						
<b>B00E - R0021 - Staff Room Annexe</b>						
No Asbestos						
<b>B00E - R0022 - General Learning Space</b>						
No Asbestos						
<b>B00E - R0025 - Plant</b>						
No Asbestos						
<b>B00E - R0026 - Cleaning Distributed Store</b>						
Floor Coverings Res/Textile	Vinyl Tiles	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2033/B00E/R0016/Floor Coverings Res/Textile/S2					<b>Chrysotile (white asbestos)</b>	
<b>B00E - R0027 - Distribution Board</b>						
Note: No inspection of live electrical installation.						
No Asbestos						
<b>B00E - R0028 - General Storeroom</b>						
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2033/B00E/R0016/Floor Coverings Res/Textile/S2					<b>Chrysotile (white asbestos)</b>	
<b>B00E - R0029 - General Learning Space</b>						
Thermacon Heater	Encapsulated Insulation material within unit	2Unit	West	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - Encapsulated material within units</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
2033/B00E/R0009/Floor Coverings Res/Textile/S12					<b>No Asbestos Detected</b>	
<b>B00E - R0030 - Computer Learning Space</b>						
No Asbestos						
<b>B00E - R0031 - General Learning Space</b>						
No Asbestos						
<b>B00E - R0032 - General Learning Space</b>						
No Asbestos						



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00F - General Learning - 1990 - Timber (Timber)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Void	No Asbestos Found

**Interior****B00F - R0001 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00F - R0002 - Practical Activities - 1hb**

No Asbestos

**B00F - R0003 - External Movement**

No Asbestos

**B00F - R0004 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00F - R0005 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00F - R0006 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00F - R0007 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00F - R0008 - Practical Activities - 1hb**

No Asbestos

**B00F - R0009 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00F - R0010 - Practical Activities - 1hb**

No Asbestos

**B00F - R0011 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00F - R0012 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00F - R0013 - Cleaning Distributed Store**

No Asbestos

**B00F - R0014 - Interview**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - Multi Purpose Facilities - 2008 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Void	No Asbestos Found

**Interior**

**B00G - R0001 - Disabled Toilet**

No Asbestos

**B00G - R0002 - Toilets - Boys**

No Asbestos

**B00G - R0003 - Movement**

No Asbestos

**B00G - R0004 - Toilets - Girls**

No Asbestos

**B00G - R0005 - Movement**

No Asbestos

**B00G - R0006 - Store**

No Asbestos

**B00G - R0007 - General Learning Space**

No Asbestos

**B00G - R0008 - Special Programs Room**

No Asbestos

**B00G - R0009 - Kitchen - Pre**

No Asbestos

**B00G - R0010 - Staff Room**

No Asbestos

**B00G - R0011 - Practical Activities**

No Asbestos

**B00G - R0012 - External Movement**

No Asbestos

**B00G - R0013 - External Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - Other-Vacant - 2009 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

**Interior**

**B00H - R0001 - Other-Vacant**

No Asbestos

**B00H - R0002 - Other-Vacant**

No Asbestos

**B00H - R0003 - Other-Vacant**

No Asbestos

**B00H - R0004 - Other-Vacant**

No Asbestos

**B00H - R0005 - Other-Vacant**

No Asbestos

**B00H - R0006 - Toilets-Unisex**

No Asbestos

**B00H - R0007 - Toilets-Unisex**

No Asbestos

**B00H - R0008 - Shower**

No Asbestos

**B00H - R0009 - Staff Kitchen**

No Asbestos

**B00H - R0010 - Other-Vacant**

No Asbestos

**B00H - R0011 - Other-Vacant**

No Asbestos

**B00H - R0012 - Other-Vacant**

No Asbestos

**B00H - R0013 - Stairs**

No Asbestos

**B00H - R1001 - Other-Vacant**

No Asbestos

**B00H - R1002 - Movement**

No Asbestos

**B00H - R1003 - Stairs**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00I - Other-Vacant - 2009 - Metal Shed (Metal Shed)**

**Exterior**

Underfloor Voids - Slab on Ground      No Asbestos Found

Ceiling Voids      No Asbestos Found

**Interior**

**B00I - R0001 - Other-Vacant**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00J - Other-Vacant - 2009 - Metal Shed (Metal Shed)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Void	No Asbestos Found

**Interior**

**B00J - R0001 - Other-Vacant**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00K - Library - 2010 - Fibre Cement Clad (Fibre Cement Clad)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Void	No Asbestos Found

**Interior**

**B00K - R0001 - External Movement**

No Asbestos

**B00K - R0002 - Main Area**

No Asbestos

**B00K - R0003 - Library Office/Workroom**

No Asbestos

**B00K - R0004 - Communications Room**

No Asbestos

**B00K - R0005 - K.L.A. Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00L - Building Services - 2010 - Fibre Cement Clad (Fibre Cement Clad)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Void	No Asbestos Found

**Interior**

**B00L - R0001 - General Assistant/Bulk Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

## Demountables

**Demountable details as per the AMS records as of 15 Feb 2017.**

**OS 780 - D10986 - Woodwork/Metalwork/Heat Area/Store : Placement Date - 30/06/1995**

### Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	17.28 m2

### Interior

#### R1 - Store

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	18 m2

#### R2 - Materials Technology L.S.

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	91 m2

**OS 811 - D10995 - FSU/Shelter/Stores : Placement Date - 30/06/1995**

### Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	31.68 m2

### Interior

#### R1 - Canteen

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	28 m2

#### R2 - Covered Area

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	145 m2

#### R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	4 m2
---------	---------------	------------------	------

#### R4 - Sports Store

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2
---------	---------------	------------------	-------

#### R5 - Garden Store

Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2
---------	---------------	------------------	------

#### R6 - Change Room

Ceiling	Flat AC Sheet	Assumed Asbestos	3 m2
---------	---------------	------------------	------

#### R7 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	2 m2
---------	---------------	------------------	------

**- D13387 - : Placement Date - 23/06/2011**

No Asbestos Found.

**OS 502 - D14352 - Admin Staff/Principal/Clerk/Dup/Clinic : Placement Date - 11/01/2017**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

### Exterior

No Asbestos Found.



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>Interior</b>						
<b>R1 - Clerical Office</b>						
No Asbestos Found.						
<b>R10 - Store</b>						
No Asbestos Found.						
<b>R2 - Security Store</b>						
No Asbestos Found.						
<b>R3 - Duplicating Wookroom</b>						
No Asbestos Found.						
<b>R4 - Clinic-Waiting</b>						
No Asbestos Found.						
<b>R5 - Staff Room</b>						
No Asbestos Found.						
<b>R6 - Principal</b>						
No Asbestos Found.						
<b>R7 - Staff Toilet</b>						
No Asbestos Found.						
<b>R8 - Staff Toilet</b>						
No Asbestos Found.						
<b>R9 - Entry</b>						
No Asbestos Found.						
<b>OS 532 - D15548 - Library : Placement Date - 30/06/1995</b>						
<b>Exterior</b>						
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				17.28 m2
<b>Interior</b>						
<b>R1 - Reading Area</b>						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				90 m2
<b>R2 - Library Office/Workroom</b>						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2
<b>R3 - Communications Room</b>						
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
<b>- D17743 - : Placement Date - 12/07/2011</b>						
No Asbestos Found.						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017