

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Goolmangar Public School (2037)
Region : North Coast
State Electorate : Lismore
Local Government Area : Lismore

Initial Survey : Noel Arnold & Associates : 10 - Jun - 2008
Reviewed By : Parsons Brinckerhoff : 01 - Nov - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning/Administration - 1974 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	24m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2037/B00A/Eaves Linings/S1					Chrysotile (white asbestos)
Ceiling Void	No Asbestos Found					
Underfloor Void	No Asbestos Found					

Interior

B00A - R0001 - Home Base Store

No Asbestos

B00A - R0002 - Home Base

No Asbestos

B00A - R0003 - General Storeroom

No Asbestos

B00A - R0004 - Principal

No Asbestos

B00A - R0005 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Library/Staff Facilities - 1974 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	24m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2037/B00B/Eaves Linings/S2					Chrysotile (white asbestos)
Ceiling Void	No Asbestos Found					
Ceiling Void	No Asbestos Found					

Interior

B00B - R0001 - Reading Area

No Asbestos

B00B - R0002 - Staff Room

No Asbestos

B00B - R0003 - Clerical Office/Workroom

No Asbestos

B00B - R0005 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	32m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2037/B00B/R0005/Ceiling Structures/Linings/S4					Chrysotile (white asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Storage - 1987 - Metal Shed (Metal Shed)

Exterior

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior

B00C - R0002 - Sports Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Pupil Facilities - 1974 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2037/B00D/Eaves Linings/S3				Chrysotile (white asbestos)	
Ceiling Void	No Asbestos Found					

Interior

B00D - R0001 - Toilets - Boys

No Asbestos

B00D - R0002 - Staff Toilet

No Asbestos

B00D - R0003 - Cleaning Distributed Store

No Asbestos

B00D - R0004 - Toilets - Girls

No Asbestos

B00D - R0005 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning - 2010 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior

B00E - R0001 - Home Base

No Asbestos

B00E - R0002 - Home Base Store

No Asbestos

B00E - R0003 - Practical Activities

No Asbestos

B00E - R0004 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017