

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Goonengerry Public School (2042)
Region : North Coast
State Electorate : Ballina
Local Government Area : Byron

Initial Survey : Noel Arnold & Associates : 10 - Jun - 2008
Reviewed By : Parsons Brinckerhoff : 01 - Nov - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning/Staff Facilities - 1901 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	24m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2042/B00A/Eaves Linings/S3				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Void	No Asbestos Found					
Underfloor Void	No Asbestos Found					
Electrical Backing Board	Resinous Board					
	2042/B00A/Electrical Backing Board/S6					No Asbestos Detected

Interior

B00A - R0002 - Security Store

Floor Coverings Res/Textile	Vinyl Tiles					
	2042/B00A/R0005/Floor Coverings Res/Textile/S1					No Asbestos Detected

B00A - R0005 - Practical Activities - 1hb

Floor Coverings Res/Textile	Vinyl Tiles					
	2042/B00A/R0005/Floor Coverings Res/Textile/S1					No Asbestos Detected

B00A - R0006 - Kiln Room

No Asbestos

B00A - R0008 - Covered Outdoor Learning Area

No Asbestos

B00A - R0009 - Home Base

Manhole in Ceiling	Flat AC Sheeting					
	2042/B00A/R0009/Manhole in Ceiling/S5					No Asbestos Detected

B00A - R0010 - Canteen

No Asbestos

B00A - R0011 - Canteen Covered Area

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Building Services/Pupil Facilities - 1959 - Timber (Timber)

Exterior

Wall Cladding	Flat AC Sheeting 2042/B00B/Wall Cladding/S2					No Asbestos Detected
Ceiling Void	No Asbestos Found					
Underfloor Void	No Asbestos Found					

Interior

B00B - R0001 - Canteen Covered Area

Wall Linings Internal	Flat AC Sheeting 2042/B00B/Wall Cladding/S2					No Asbestos Detected
-----------------------	--	--	--	--	--	-----------------------------

B00B - R0002 - Sports Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Building Services - 1976 - Metal Shed (Metal Shed)

Exterior

Underfloor Void	No Asbestos Found
Ceiling Void	No Asbestos Found

Interior

B00C - R0001 - Cleaning Supplies

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Building Services - 1976 - Metal Shed (Metal Shed)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Void No Asbestos Found

Interior

B00D - R0001 - Garden Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Pupil Facilities/Building Services - 2008 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids	No Asbestos Found					
Eaves Linings	Flat AC Sheeting					
	2042/B00E/Eaves Linings/S4					No Asbestos Detected

Interior

B00E - R0001 - Disabled Shower/Toilet

No Asbestos

B00E - R0002 - Cleaning Distributed Store

No Asbestos

B00E - R0003 - Toilet - Lobby

No Asbestos

B00E - R0004 - External Movement

No Asbestos

B00E - R0005 - Toilets - Girls

No Asbestos

B00E - R0006 - Toilet - Lobby

No Asbestos

B00E - R0007 - Toilets - Boys

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning - 2010 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior

B00F - R0001 - External Movement

No Asbestos

B00F - R0002 - Practical Activities - 1hb

No Asbestos

B00F - R0003 - Home Base Store

No Asbestos

B00F - R0004 - Home Base

No Asbestos

B00F - R0005 - Withdrawal Space - 2hb

No Asbestos

B00F - R0006 - Home Base

No Asbestos

B00F - R0007 - Home Base Store

No Asbestos

B00F - R0008 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 500 - D18101 - Admin - Library : Placement Date - 16/05/2002

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				20.16 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				13 m2

R2 - Principal

Ceiling	Flat AC Sheet	Assumed Asbestos				18 m2
---------	---------------	------------------	--	--	--	-------

R3 - Staff Room/Kitchen

Ceiling	Flat AC Sheet	Assumed Asbestos				19 m2
---------	---------------	------------------	--	--	--	-------

R4 - Clerical Office

Ceiling	Flat AC Sheet	Assumed Asbestos				18 m2
---------	---------------	------------------	--	--	--	-------

R5 - Library

Ceiling	Flat AC Sheet	Assumed Asbestos				54 m2
---------	---------------	------------------	--	--	--	-------

R6 - Storeroom

Ceiling	Flat AC Sheet	Assumed Asbestos				0 m2
---------	---------------	------------------	--	--	--	------

R7 - Staff Toilet

Toilet partitions	Compressed AC Sheet	Assumed Asbestos				6 m2
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				4 m2

R8 - Entry to toilet

Ceiling	Flat AC Sheet	Assumed Asbestos				0 m2
---------	---------------	------------------	--	--	--	------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017