


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Gosford Public School (2049)
Region : Hunter/Central Coast
State Electorate : Gosford
Local Government Area : Gosford

Initial Survey : Noel Arnold & Associates : 04 - Apr - 2008
Reviewed By : AECOM : 27 - Jun - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0AS - General Learning - 1978 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
Sunhood (Louvers)	Compressed AC Sheet 2049/B0AS/Sunhood (Louvers)/S16	50m2	east and west	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

Interior

B0AS - R0004 - Adjoining School (0.76 m2)

No Asbestos

B0AS - R0005 - Adjoining School (4.41 m2)

Ceiling Structures/Linings	Vermiculite 2049/B0AS/R0055/Ceiling Structures/Linings/S15					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
----------------------------	---	--	--	--	--	--

B0AS - R0006 - Adjoining School (23.41 m2)

Ceiling Structures/Linings	Vermiculite 2049/B0AS/R0055/Ceiling Structures/Linings/S15					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
----------------------------	---	--	--	--	--	--

B0AS - R0026 - Stairs (10.55 m2)

Ceiling Structures/Linings	Vermiculite 2049/B0AS/R0055/Ceiling Structures/Linings/S15					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
----------------------------	---	--	--	--	--	--

B0AS - R0027 - Stairs (5.4 m2)

Ceiling Structures/Linings	Vermiculite 2049/B0AS/R0055/Ceiling Structures/Linings/S15					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
----------------------------	---	--	--	--	--	--

B0AS - R0028 - Adjoining School (50.62 m2)

Ceiling Structures/Linings	Vermiculite 2049/B0AS/R0055/Ceiling Structures/Linings/S15					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
----------------------------	---	--	--	--	--	--

B0AS - R0029 - Adjoining School (48.35 m2)

Ceiling Structures/Linings	Vermiculite 2049/B0AS/R0055/Ceiling Structures/Linings/S15					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
----------------------------	---	--	--	--	--	--

B0AS - R0030 - Adjoining School (26 m2)

Ceiling Structures/Linings	Vermiculite 2049/B0AS/R0055/Ceiling Structures/Linings/S15					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
----------------------------	---	--	--	--	--	--

B0AS - R0031 - Adjoining School (51.85 m2)

Ceiling Structures/Linings	Vermiculite 2049/B0AS/R0055/Ceiling Structures/Linings/S15					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
----------------------------	---	--	--	--	--	--

B0AS - R0032 - Adjoining School (16.39 m2)

Ceiling Structures/Linings	Vermiculite 2049/B0AS/R0055/Ceiling Structures/Linings/S15					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
----------------------------	---	--	--	--	--	--

B0AS - R0033 - Adjoining School (42.15 m2)

Ceiling Structures/Linings	Vermiculite 2049/B0AS/R0055/Ceiling Structures/Linings/S15					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
----------------------------	---	--	--	--	--	--

B0AS - R0034 - Adjoining School (50.25 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite	2049/B0AS/R0055/Ceiling Structures/Linings/S15			Limited Samples Taken	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B0AS - R0035 - Adjoining School (22.85 m2)						
Ceiling Structures/Linings	Vermiculite	2049/B0AS/R0055/Ceiling Structures/Linings/S15			Limited Samples Taken	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B0AS - R0036 - Adjoining School (2.99 m2)						
Ceiling Structures/Linings	Vermiculite	2049/B0AS/R0055/Ceiling Structures/Linings/S15			Limited Samples Taken	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B0AS - R0037 - Adjoining School (52.59 m2)						
Ceiling Structures/Linings	Vermiculite	2049/B0AS/R0055/Ceiling Structures/Linings/S15			Limited Samples Taken	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B0AS - R0038 - Adjoining School (59 m2)						
Ceiling Structures/Linings	Vermiculite	2049/B0AS/R0055/Ceiling Structures/Linings/S15			Limited Samples Taken	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B0AS - R0039 - Adjoining School (1.89 m2)						
Ceiling Structures/Linings	Vermiculite	2049/B0AS/R0055/Ceiling Structures/Linings/S15			Limited Samples Taken	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B0AS - R0040 - Adjoining School (1.64 m2)						
Ceiling Structures/Linings	Vermiculite	2049/B0AS/R0055/Ceiling Structures/Linings/S15			Limited Samples Taken	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B0AS - R0041 - Adjoining School (3.83 m2)						
Ceiling Structures/Linings	Vermiculite	2049/B0AS/R0055/Ceiling Structures/Linings/S15			Limited Samples Taken	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B0AS - R0042 - Adjoining School (51.94 m2)						
Ceiling Structures/Linings	Vermiculite	2049/B0AS/R0055/Ceiling Structures/Linings/S15			Limited Samples Taken	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B0AS - R0043 - Adjoining School (49.33 m2)						
Ceiling Structures/Linings	Vermiculite	2049/B0AS/R0055/Ceiling Structures/Linings/S15			Limited Samples Taken	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B0AS - R0044 - Adjoining School (7.65 m2)						
Ceiling Structures/Linings	Vermiculite	2049/B0AS/R0055/Ceiling Structures/Linings/S15			Limited Samples Taken	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B0AS - R0045 - Adjoining School (15.14 m2)						
Ceiling Structures/Linings	Vermiculite	2049/B0AS/R0055/Ceiling Structures/Linings/S15			Limited Samples Taken	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B0AS - R0046 - Adjoining School (46.95 m2)						
Ceiling Structures/Linings	Vermiculite	2049/B0AS/R0055/Ceiling Structures/Linings/S15			Limited Samples Taken	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B0AS - R0047 - Adjoining School (2.95 m2)						
Ceiling Structures/Linings	Vermiculite	2049/B0AS/R0055/Ceiling Structures/Linings/S15			Limited Samples Taken	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B0AS - R0048 - Adjoining School (5.22 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2049/B0AS/R0055/Ceiling Structures/Linings/S15					
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B0AS - R0049 - Adjoining School (52.52 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2049/B0AS/R0055/Ceiling Structures/Linings/S15					
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B0AS - R0050 - Adjoining School (43.31 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2049/B0AS/R0055/Ceiling Structures/Linings/S15					
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B0AS - R0051 - Adjoining School (49.38 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2049/B0AS/R0055/Ceiling Structures/Linings/S15					
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B0AS - R0052 - Adjoining School (39.12 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2049/B0AS/R0055/Ceiling Structures/Linings/S15					
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B0AS - R0053 - Adjoining School (44.56 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2049/B0AS/R0055/Ceiling Structures/Linings/S15					
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B0AS - R0054 - Adjoining School (43.02 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2049/B0AS/R0055/Ceiling Structures/Linings/S15					
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B0AS - R0055 - Movement (297.22 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2049/B0AS/R0055/Ceiling Structures/Linings/S15					
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B0AS - R0056 - Stairs (9.17 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2049/B0AS/R0055/Ceiling Structures/Linings/S15					
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B0AS - R0057 - Adjoining School (1.74 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	2049/B0AS/R0055/Ceiling Structures/Linings/S15					
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B0AS - R1001 - Cleaning Distributed Store (2 m2)						
Non Accessible						
B0AS - R1003 - General Storeroom (5.67 m2)						
No Asbestos						
B0AS - R1005 - Distribution Board (0.72 m2)						
No Asbestos					Note: No inspection of live electrical installation.	
B0AS - R1006 - Cleaning Distributed Store (2 m2)						
No Asbestos						
B0AS - R1007 - Special Programs Room (47.73 m2)						
No Asbestos						
B0AS - R1019 - Staff Toilet (3.32 m2)						
No Asbestos						
B0AS - R1036 - Stairs (8.57 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result
	No Asbestos					
	B0AS - R1037 - Stairs (7.46 m2)					
	No Asbestos					
	B0AS - R1038 - Stairs (16.85 m2)					
	No Asbestos					
	B0AS - R1039 - Home Base (64.22 m2)					
	No Asbestos					
	B0AS - R1040 - Distribution Board (0.83 m2)				Note: No inspection of live electrical installation.	
	No Asbestos					
	B0AS - R1041 - Home Base (18.38 m2)					
	No Asbestos					
	B0AS - R1042 - Home Base Store (6.63 m2)					
	No Asbestos					
	B0AS - R1043 - Withdrawal Space - 2hb (11.69 m2)					
	No Asbestos					
	B0AS - R1044 - Home Base Store (6.63 m2)					
	No Asbestos					
	B0AS - R1045 - Practical Activities (17.87 m2)					
	No Asbestos					
	B0AS - R1046 - Home Base (58.27 m2)					
	No Asbestos					
	B0AS - R1047 - Home Base (44.09 m2)					
	No Asbestos					
	B0AS - R1048 - Practical Activities (21.43 m2)					
	No Asbestos					
	B0AS - R1049 - Home Base Store (6.63 m2)					
	No Asbestos					
	B0AS - R1050 - Withdrawal Space - 2hb (11.69 m2)					
	No Asbestos					
	B0AS - R1051 - Home Base Store (6.7 m2)					
	No Asbestos					
	B0AS - R1052 - Practical Activities (21.18 m2)					
	No Asbestos					
	B0AS - R1053 - Home Base (50.34 m2)					
	No Asbestos					
	B0AS - R1054 - Home Base (54.33 m2)					
	No Asbestos					
	B0AS - R1055 - Practical Activities (18.07 m2)					
	No Asbestos					
	B0AS - R1056 - Special Programs Store (4.6 m2)					
	No Asbestos					
	B0AS - R1057 - Withdrawal Space - 1hb (10.9 m2)					
	No Asbestos					
	B0AS - R1058 - Home Base Store (7.67 m2)					
	No Asbestos					
	B0AS - R1059 - Practical Activities (18.5 m2)					
	No Asbestos					
	B0AS - R1060 - Home Base (61.52 m2)					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B0AS - R1061 - Home Base (60.23 m2)

No Asbestos

B0AS - R1062 - Practical Activities (18.69 m2)

No Asbestos

B0AS - R1063 - Home Base Store (6.63 m2)

No Asbestos

B0AS - R1064 - Withdrawal Space - 2hb (11.66 m2)

No Asbestos

B0AS - R1065 - Home Base Store (6.63 m2)

No Asbestos

B0AS - R1066 - Practical Activities (18.5 m2)

No Asbestos

B0AS - R1067 - Home Base (63.68 m2)

No Asbestos

B0AS - R1068 - Distribution Board (0.8 m2)

Note: No inspection of live electrical installation.

No Asbestos

B0AS - R1069 - Access Shower/Toilet (6.91 m2)

No Asbestos

B0AS - R1070 - Cleaning Distributed Store (3.21 m2)

No Asbestos

B0AS - R1071 - Staff Toilet (4.84 m2)

No Asbestos

B0AS - R1072 - Withdrawal Space - 1hb (11.3 m2)

No Asbestos

B0AS - R1073 - Home Base Store (6.82 m2)

No Asbestos

B0AS - R1074 - Practical Activities (18.05 m2)

No Asbestos

B0AS - R1075 - Home Base (56.8 m2)

No Asbestos

B0AS - R1076 - Movement (317.82 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B0BB - General Learning/Library - 2014 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Packing to Floor Joists No Asbestos Found

Ceiling Voids No Asbestos Found

Interior**B0BB - R0001 - Practical Activities - 1hb (19.92 m2)**

No Asbestos

B0BB - R0002 - Home Base (59.22 m2)

No Asbestos

B0BB - R0003 - Home Base Store (7.09 m2)

No Asbestos

B0BB - R0004 - Withdrawal Space - 2hb (11.37 m2)

No Asbestos

B0BB - R0005 - Home Base (59.76 m2)

No Asbestos

B0BB - R0006 - Home Base Store (6.24 m2)

No Asbestos

B0BB - R0007 - Practical Activities - 1hb (19.73 m2)

No Asbestos

B0BB - R0008 - Practical Activities - 1hb (19.11 m2)

No Asbestos

B0BB - R0009 - Home Base (60.22 m2)

No Asbestos

B0BB - R0010 - Home Base Store (5.17 m2)

No Asbestos

B0BB - R0011 - Withdrawal Space - 1hb (7.78 m2)

No Asbestos

B0BB - R0012 - External Movement (76.46 m2)

No Asbestos

B0BB - R0013 - External Stairs (8.59 m2)

No Asbestos

B0BB - R1001 - Reading Area (230.7 m2)

No Asbestos

B0BB - R1002 - Library Office/Workroom (24.91 m2)

No Asbestos

B0BB - R1003 - Communications Room (7.99 m2)

No Asbestos

B0BB - R1004 - K.L.A. Store (23.52 m2)

No Asbestos

B0BB - R1005 - Entry Vestibule (6.97 m2)

No Asbestos

B0BB - R1006 - Staff Kitchen (1.69 m2)

No Asbestos

B0BB - R1007 - External Movement (48.55 m2)

No Asbestos

B0BB - R1008 - External Stairs (8.59 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B0BB - R9001 - Garden Store (21.26 m2)						
No Asbestos						
B0BB - R9002 - General Assistant/Bulk Store (23.23 m2)						
No Asbestos						
B0BB - R9003 - Other (217.23 m2)						
No Asbestos						
B0BB - R9004 - General Assistant/Bulk Store (21.09 m2)						
No Asbestos						
B0BB - R9005 - Other (10.69 m2)						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0CC - General Learning/Other - 2014 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible, no floor space access points.
Ceiling Voids	No Asbestos Found

Interior

B0CC - R0001 - Lift (2.24 m2)

No Asbestos

B0CC - R0003 - Canteen Office/Store (12.34 m2)

No Asbestos

B0CC - R0004 - Canteen (46 m2)

No Asbestos

B0CC - R0005 - Plant (0.58 m2)

No Asbestos

B0CC - R0006 - Stairs (11.99 m2)

No Asbestos

B0CC - R0007 - Movement (2.14 m2)

No Asbestos

B0CC - R0008 - External Movement (16.96 m2)

No Asbestos

B0CC - R0009 - Distribution Board (0.98 m2)

Note: No inspection of live electrical installation.

No Asbestos

B0CC - R1001 - Movement (2.14 m2)

No Asbestos

B0CC - R1002 - Special Programs Store (7.87 m2)

No Asbestos

B0CC - R1003 - Distribution Board (1.93 m2)

Note: No inspection of live electrical installation.

No Asbestos

B0CC - R1004 - Cleaning Distributed Store (4.41 m2)

No Asbestos

B0CC - R1005 - Staff Toilet (5.25 m2)

No Asbestos

B0CC - R1006 - Special Programs Room (53.8 m2)

No Asbestos

B0CC - R1007 - Staff Kitchen (2.84 m2)

No Asbestos

B0CC - R1008 - External Movement (16.96 m2)

No Asbestos

B0CC - R9001 - Movement (1.68 m2)

No Asbestos

B0CC - R9002 - Plant (10.76 m2)

No Asbestos

B0CC - R9003 - Stairs (12.76 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0DD - Communal Facilities - 2014 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible, slab to ground no access points.
Ceiling Voids	No Asbestos Found

Interior

B0DD - R0001 - Communal Space (204.74 m2)

No Asbestos

B0DD - R0002 - Raised Platform (56.47 m2)

No Asbestos

B0DD - R0003 - Ramp (11.53 m2)

No Asbestos

B0DD - R0004 - Movement (7.86 m2)

No Asbestos

B0DD - R0005 - Stairs (16.39 m2)

No Asbestos

B0DD - R0006 - Communal/Performance Store (15.79 m2)

No Asbestos

B0DD - R0007 - Sports Store (15.75 m2)

No Asbestos

B0DD - R0008 - Hall Chair Store (11.26 m2)

No Asbestos

B0DD - R0009 - Sound Cupboard (3.82 m2)

No Asbestos

B0DD - R0010 - P.E. Store (6.89 m2)

No Asbestos

B0DD - R0011 - Distribution Board (2.01 m2)

Note: No inspection of live electrical installation.

No Asbestos

B0DD - R0012 - Stairs (9.84 m2)

No Asbestos

B0DD - R0013 - Other (0.43 m2)

No Asbestos

B0DD - R0014 - External Movement (24.65 m2)

No Asbestos

B0DD - R1001 - External Movement (79.37 m2)

No Asbestos

B0DD - R1003 - External Stairs (13.35 m2)

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0EE - Administration/Other-After School Care - 2014 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible slab to ground. No access points.
Ceiling Voids	No Asbestos Found

Interior

B0EE - R0001 - General Storeroom (15.89 m2)

No Asbestos

B0EE - R0002 - General Storeroom (15.67 m2)

No Asbestos

B0EE - R0003 - Other (85.1 m2)

No Asbestos

B0EE - R0004 - Distribution Board (1.78 m2)

Note: No inspection of live electrical installation.

No Asbestos

B0EE - R0005 - Plant (1.05 m2)

No Asbestos

B0EE - R0006 - Kitchen - Pre (15.03 m2)

No Asbestos

B0EE - R0007 - Out Of School Hours Care Centre (50.73 m2)

No Asbestos

B0EE - R0008 - Out Of School Hours Care Centre (38.96 m2)

No Asbestos

B0EE - R0009 - Other (10.35 m2)

No Asbestos

B0EE - R0010 - Toilets - Boys (21.14 m2)

No Asbestos

B0EE - R0011 - Access Shower/Toilet/Change (6.24 m2)

No Asbestos

B0EE - R0012 - Toilets - Girls (21.3 m2)

No Asbestos

B0EE - R0013 - External Movement (84.69 m2)

No Asbestos

B0EE - R0014 - External Stairs (16.61 m2)

No Asbestos

B0EE - R1001 - Entry Vestibule (29.2 m2)

No Asbestos

B0EE - R1002 - Interview (12.36 m2)

No Asbestos

B0EE - R1003 - Principal (16.2 m2)

No Asbestos

B0EE - R1004 - Deputy Principal - Type 1 (13.21 m2)

No Asbestos

B0EE - R1005 - Deputy Principal - Type 1 (12.69 m2)

No Asbestos

B0EE - R1006 - Cleaning Distributed Store (5.1 m2)

No Asbestos

B0EE - R1007 - Plant (0.46 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
	No Asbestos					
	B0EE - R1008 - Staff Room (59.22 m2)					
	No Asbestos					
	B0EE - R1009 - Staff Kitchen (10.9 m2)					
	No Asbestos					
	B0EE - R1010 - Staff Room Annexe (28.88 m2)					
	No Asbestos					
	B0EE - R1011 - Movement (58.15 m2)					
	No Asbestos					
	B0EE - R1012 - Staff Toilet (4.04 m2)					
	No Asbestos					
	B0EE - R1013 - Staff Toilet (4.25 m2)					
	No Asbestos					
	B0EE - R1014 - Staff Toilet (4.25 m2)					
	No Asbestos					
	B0EE - R1015 - Access Shower/Toilet (8.4 m2)					
	No Asbestos					
	B0EE - R1016 - Sick Bay (9.12 m2)					
	No Asbestos					
	B0EE - R1017 - Security Store (14.92 m2)					
	No Asbestos					
	B0EE - R1018 - Clerical Office (40.29 m2)					
	No Asbestos					
	B0EE - R1019 - Clerical/Printing (41.54 m2)					
	No Asbestos					
	B0EE - R1020 - Interview/Office - Type 3 (18.66 m2)					
	No Asbestos					
	B0EE - R1021 - Distribution Board (0.92 m2)				Note: No inspection of live electrical installation.	
	No Asbestos					
	B0EE - R1022 - Movement (6.53 m2)					
	No Asbestos					
	B0EE - R1024 - External Movement (69.96 m2)					
	No Asbestos					
	B0EE - R1025 - External Movement (136.25 m2)					
	No Asbestos					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0FF - General Learning/Communal Facilities - 2014 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Packing to Floor Joists No Asbestos Found

Ceiling Voids No Asbestos Found

Interior

B0FF - R0001 - Practical Activities - 1hb (19.76 m2)

No Asbestos

B0FF - R0002 - Home Base (59.4 m2)

No Asbestos

B0FF - R0003 - Home Base Store (5.89 m2)

No Asbestos

B0FF - R0004 - Withdrawal Space - 2hb (11.61 m2)

No Asbestos

B0FF - R0005 - Home Base (59.83 m2)

No Asbestos

B0FF - R0006 - Home Base Store (5.79 m2)

No Asbestos

B0FF - R0007 - Practical Activities - 1hb (19.66 m2)

No Asbestos

B0FF - R0008 - Plant (6.65 m2)

No Asbestos

B0FF - R0009 - Distribution Board (1.91 m2)

Note: No inspection of live electrical installation.

No Asbestos

B0FF - R0010 - Toilets - Boys (27.99 m2)

No Asbestos

B0FF - R0011 - Toilets - Girls (26.43 m2)

No Asbestos

B0FF - R0012 - Cleaning Distributed Store (8.02 m2)

No Asbestos

B0FF - R0013 - Practical Activities - 1hb (19.64 m2)

No Asbestos

B0FF - R0014 - Home Base Store (5.94 m2)

No Asbestos

B0FF - R0015 - Home Base (60.57 m2)

No Asbestos

B0FF - R0016 - Withdrawal Space - 2hb (11.61 m2)

No Asbestos

B0FF - R0017 - Home Base (60.56 m2)

No Asbestos

B0FF - R0018 - Home Base Store (5.96 m2)

No Asbestos

B0FF - R0019 - Practical Activities - 1hb (19.58 m2)

No Asbestos

B0FF - R0020 - Home Base Store (6.07 m2)

No Asbestos

B0FF - R0021 - Withdrawal Space - 1hb (8.69 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B0FF - R0022 - Home Base (58.85 m2)						
No Asbestos						
B0FF - R0023 - Practical Activities - 1hb (19.92 m2)						
No Asbestos						
B0FF - R0024 - External Stairs (6.94 m2)						
No Asbestos						
B0FF - R0025 - External Stairs (6.85 m2)						
No Asbestos						
B0FF - R0026 - External Movement (231.28 m2)						
No Asbestos						
B0FF - R1001 - Practical Activities - 1hb (20.59 m2)						
No Asbestos						
B0FF - R1002 - Home Base (60.34 m2)						
No Asbestos						
B0FF - R1003 - Home Base Store (5.92 m2)						
No Asbestos						
B0FF - R1004 - Withdrawal Space - 2hb (10.43 m2)						
No Asbestos						
B0FF - R1005 - Home Base (60.21 m2)						
No Asbestos						
B0FF - R1006 - Home Base Store (5.86 m2)						
No Asbestos						
B0FF - R1007 - Practical Activities - 1hb (19.78 m2)						
No Asbestos						
B0FF - R1008 - Plant (6.54 m2)						
No Asbestos						
B0FF - R1009 - Distribution Board (1.51 m2)						
No Asbestos					Note: No inspection of live electrical installation.	
B0FF - R1010 - Toilets - Boys (27.26 m2)						
No Asbestos						
B0FF - R1011 - Toilets - Girls (26.39 m2)						
No Asbestos						
B0FF - R1012 - Access Shower/Toilet/Change (8.05 m2)						
No Asbestos						
B0FF - R1013 - Practical Activities - 1hb (19.81 m2)						
No Asbestos						
B0FF - R1014 - Home Base Store (5.9 m2)						
No Asbestos						
B0FF - R1015 - Home Base (60.02 m2)						
No Asbestos						
B0FF - R1016 - Withdrawal Space - 2hb (10.36 m2)						
No Asbestos						
B0FF - R1017 - Home Base (60.35 m2)						
No Asbestos						
B0FF - R1018 - Home Base Store (5.99 m2)						
No Asbestos						
B0FF - R1019 - Practical Activities - 1hb (19.83 m2)						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B0FF - R1020 - Home Base Store (5.96 m2)						
No Asbestos						
B0FF - R1021 - Withdrawal Space - 1hb (8.79 m2)						
No Asbestos						
B0FF - R1022 - Home Base (58.62 m2)						
No Asbestos						
B0FF - R1023 - Practical Activities - 1hb (19.98 m2)						
No Asbestos						
B0FF - R1024 - External Stairs (13.6 m2)						
No Asbestos						
B0FF - R1025 - External Stairs (20.37 m2)						
No Asbestos						
B0FF - R1026 - External Movement (237.58 m2)						
No Asbestos						
B0FF - R9001 - Movement (1095.38 m2)						
No Asbestos						
B0FF - R9002 - Plant (47.27 m2)						
No Asbestos						
B0FF - R9003 - General Storeroom (16.62 m2)						
No Asbestos						
B0FF - R9004 - General Assistant/Bulk Store (19.38 m2)						
No Asbestos						
B0FF - R9005 - Plant (16.58 m2)						
No Asbestos						
B0FF - R9006 - Movement (19.71 m2)						
No Asbestos						
B0FF - R9007 - Stairs (23.02 m2)						
No Asbestos						
B0FF - R9008 - Distribution Board (2.81 m2)					Note: No inspection of live electrical installation.	
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017