

# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Goulburn East Public School (2054)  
**Region :** Illawarra and South East  
**State Electorate :** Goulburn  
**Local Government Area :** Goulburn Mulwaree

**Initial Survey :** Noel Arnold & Associates : 13 - May - 2008  
**Register Issue Date :** 22 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - Administration/General Learning - 1887 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

**Interior**

**B00A - R0001 - Principal**

No Asbestos

**B00A - R0006 - External Movement**

No Asbestos

**B00A - R0007 - External Movement**

No Asbestos

**B00A - R0009 - Deputy Principal**

No Asbestos

**B00A - R0010 - Movement**

No Asbestos

**B00A - R0011 - Security Store**

No Asbestos

**B00A - R0013 - Staff Room Annexe**

No Asbestos

**B00A - R0014 - No Access**

No Asbestos

**B00A - R0015 - Movement**

No Asbestos

**B00A - R0016 - Clerical Office**

No Asbestos

**B00A - R0017 - Sick Bay**

No Asbestos

**B00A - R0018 - Staff Toilet**

Wall Linings Internal	Flat AC Sheeting
2054/B00A/R0018/Wall Linings Internal/S1	

No Asbestos Detected

**B00A - R0019 - Staff Kitchen**

No Asbestos

**B00A - R0020 - Staff Room**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - General Learning - 1887 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting	50m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
---------------	------------------	------	------------	--------------------	---------	--------------------

**Assumed Asbestos**

Ceiling Voids	Requires Inspection
---------------	---------------------

Underfloor Voids	Requires Inspection
------------------	---------------------

**Interior****B00B - R0001 - Home Base**

No Asbestos

**B00B - R0002 - Toilets - Boys/Girls**

Wall Linings Internal	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
-----------------------	------------------	------	------------	--------------------	---------	--------------------

2054/B00B/R0002/Wall Linings Internal/S3

**Chrysotile (white asbestos) , Amosite (brown asbestos)**

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	-----	------------	--------------------	---------	--------------------

2054/B00B/R0002/Wall Linings Internal/S3

**Chrysotile (white asbestos) , Amosite (brown asbestos)****B00B - R0003 - Home Base Store**

Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
-----------------------------	-------------	-----	------------	--------------------	---------	--------------------

2054/B00B/R0003/Floor Coverings Res/Textile/S2

**Chrysotile (white asbestos)****B00B - R0004 - Personal Effects Storage**

No Asbestos

**B00B - R0005 - External Movement**

Wall Linings Internal	Flat AC Sheeting	2m2	Behind bag hanging pegs	Good Condition (1)	Low (1)	Low Priority (2-3)
-----------------------	------------------	-----	-------------------------	--------------------	---------	--------------------

2054/B00B/R0002/Wall Linings Internal/S3

**Chrysotile (white asbestos) , Amosite (brown asbestos)**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

**B00C - Pupil Facilities - 1959 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2054/B00C/R0004/Ceiling Structures/Linings/S6			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
In-fill-panel	Flat AC Sheeting	6m2	North, South, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	2054/B00C/R0004/Ceiling Structures/Linings/S6			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

**Interior****B00C - R0002 - Toilets - Girls**

Ceiling Structures/Linings	Flat AC Sheeting	33m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2054/B00C/R0004/Ceiling Structures/Linings/S6			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00C - R0003 - Cleaning Distributed Store**

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2054/B00C/R0004/Ceiling Structures/Linings/S6			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00C - R0004 - Toilets - Boys**

Ceiling Structures/Linings	Flat AC Sheeting	31m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2054/B00C/R0004/Ceiling Structures/Linings/S6			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00C - R0005 - Staff Toilet**

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2054/B00C/R0004/Ceiling Structures/Linings/S6			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - Communal Facilities/Pupil Facilities - 1991 - Steel (Steel)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior****B00D - R0001 - Communal Space**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00D - R0002 - General Storeroom**

No Asbestos

**B00D - R0003 - Raised Platform**

No Asbestos

**B00D - R0004 - Canteen**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00D - R0005 - General Assistant/Bulk Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - Pupil Facilities - 1940 - Timber (Timber)**

**Exterior**

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

**Interior**

**B00E - R0001 - Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - Communal Facilities - 1950 - Timber Shed (Timber Shed)**

**Exterior**

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

**Interior**

**B00F - R0001 - Sports Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - General Learning - 1997 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Eaves Linings	Flat AC Sheeting 2054/B00G/R0001/Ceiling Structures/Linings/S5					No Asbestos Detected
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Requires Inspection					

**Interior**

**B00G - R0001 - External Movement**

Floor Coverings Res/Textile	Compressed AC Sheet 2054/B00G/R0001/Floor Coverings Res/Textile/S4					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting 2054/B00G/R0001/Ceiling Structures/Linings/S5					No Asbestos Detected

**B00G - R0002 - Home Base**

No Asbestos

**B00G - R0003 - Home Base**

No Asbestos

**B00G - R0004 - Home Base Store**

No Asbestos

**B00G - R0005 - Covered Outdoor Learning Area - M**

No Asbestos

**B00G - R0006 - Withdrawal Space - 1hb**

No Asbestos

**B00G - R0007 - Covered Outdoor Learning Area - M**

No Asbestos

**B00G - R0008 - Home Base Store**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - Library - 2010 - Fibre Cement Clad (Fibre Cement Clad)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00H - R0001 - External Movement**

No Asbestos

**B00H - R0002 - Reading Area**

No Asbestos

**B00H - R0003 - Library Office/Workroom**

No Asbestos

**B00H - R0004 - Communications Room**

No Asbestos

**B00H - R0005 - K.L.A. Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B001 - Building Services - 2009 - Metal Shed (Metal Shed)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B001 - R0001 - General Assistant/Bulk Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Demountables**

**Demountable details as per the AMS records as of 15 Feb 2017.**

**OS 602 - D11755 - Learning Unit - Standard With P.A.A. : Placement Date - 4/03/2014**

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 531 - D13569 - Library : Placement Date - 30/06/1995**

**Exterior**

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

**Interior**

**R1 - Entry/classroom**

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	63 m2

**R2 - Reading Area/workroom**

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2

**OS 603 - D16190 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 18/04/2013**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017