


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Granville South Public School (2066)
Region : South Western Sydney
State Electorate : Granville
Local Government Area : Parramatta

Initial Survey : Noel Arnold & Associates : 26 - Mar - 2008
Reviewed By : Parsons Brinckerhoff : 28 - Dec - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/General Learning - 1889 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids	No Asbestos Found
Ceiling Void	Non Accessible Area - No access - Manhole > 5m high

Interior

B00A - R0001 - Home Base

No Asbestos

B00A - R0002 - Home Base

No Asbestos

B00A - R0003 - Security Store

No Asbestos

B00A - R0004 - Staff Toilet

No Asbestos

B00A - R0005 - Principal

No Asbestos

B00A - R0006 - Movement

No Asbestos

B00A - R0007 - Movement

No Asbestos

B00A - R0008 - General Storeroom

No Asbestos

B00A - R0009 - Security Store

No Asbestos

B00A - R0010 - Library Office/Workroom

No Asbestos

B00A - R0011 - Movement

No Asbestos

B00A - R0012 - Clerical Office

No Asbestos

B00A - R0013 - Entry Vestibule

No Asbestos

B00A - R0014 - Reading Area

No Asbestos

B00A - R0015 - Special Programs Room

No Asbestos

B00A - R0016 - Staff Toilet

Floor Coverings Res/Textile	Vinyl Tiles					No Asbestos Detected
	2066/B00A/R0016/Floor Coverings Res/Textile/S6					
Wall Linings Internal	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2066/B00A/R0016/Wall Linings Internal/S7					Chrysotile (white asbestos)

B00A - R0017 - External Movement

No Asbestos

B00A - R0018 - Cleaning Supplies

No Asbestos

B00A - R0019 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	2066/B00A/R0019/Wall Linings Internal/S8					

B00A - R0020 - Handwashing Facilities

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00A - R0021 - Staff Kitchen

No Asbestos

B00A - R0022 - External Movement

No Asbestos

B00A - R0023 - Staff Room

No Asbestos

B00A - R0024 - Home Base

No Asbestos

B00A - R0025 - Home Base

No Asbestos

B00A - R0026 - Movement

No Asbestos

B00A - R0027 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Pupil Facilities - 1955 - Timber (Timber)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Void No Asbestos Found

Interior

B00B - R0001 - Drinking Facilities

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Pupil Facilities - 1955 - Timber (Timber)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Void	No Asbestos Found

Interior

B00C - R0001 - Drinking Facilities

No Asbestos

B00C - R0002 - Drinking Facilities

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Pupil Facilities - 1955 - Timber (Timber)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Void	No Asbestos Found

Interior

B00F - R0001 - Garden Store

No Asbestos

B00F - R0002 - Garden Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Pupil Facilities - 1922 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Flat Roof	Non Accessible Area - No manhole in Building					
Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2066/B00G/Eaves Linings/S9					Chrysotile (white asbestos)

Interior

B00G - R0002 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2066/B00G/R0002/Ceiling Structures/Linings/S14					Chrysotile (white asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Building Services - 1955 - Timber (Timber)

Exterior

Ceiling Voids - Flat Roof	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00H - R0001 - General Storeroom

Wall Linings Internal	Flat AC Sheeting 2066/B00J/R0001/Wall Linings Internal/S5	No Asbestos Detected
-----------------------	--	-----------------------------

B00H - R0002 - General Storeroom

Wall Linings Internal	Flat AC Sheeting 2066/B00J/R0001/Wall Linings Internal/S5	No Asbestos Detected
-----------------------	--	-----------------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - General Learning - 1956 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	2066/B00K/Eaves Linings/S10				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Underfloor Voids	AC Fragments/Debris	1m2	Throughout	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5)
	2066/B00K/Underfloor Voids/S12				Chrysotile (white asbestos)	
Ceiling Void	No Asbestos Found					

Interior

B00K - R0001 - Home Base Store

No Asbestos

B00K - R0002 - Staff Room Annexe

No Asbestos

B00K - R0003 - Home Base

Wall Linings Internal	Flat AC Sheeting	2m2	South, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2066/B00K/R0003/Wall Linings Internal/S2				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00K - R0004 - Home Base

No Asbestos

B00K - R0005 - Cleaning Distributed Store

No Asbestos

B00K - R0006 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	35m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	2066/B00N/R0001/Ceiling Structures/Linings/S4				Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00N - General Learning - 1955 - Timber (Timber)

Exterior

Underfloor Voids	Flat AC Sheeting 2066/B00N/Underfloor Voids/S11					No Asbestos Detected
Ceiling Void	No Asbestos Found					

Interior

B00N - R0001 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	6m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	2066/B00N/R0001/Ceiling Structures/Linings/S4					Chrysotile (white asbestos)

B00N - R0002 - Home Base

No Asbestos

B00N - R0003 - Home Base

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B000 - General Learning - 1955 - Timber (Timber)

Exterior

Underfloor Voids	AC Fragments/Debris 2066/B000/Underfloor Voids/S13					No Asbestos Detected
Ceiling Void	No Asbestos Found					

Interior

B000 - R0001 - Home Base Store

No Asbestos

B000 - R0002 - Home Base

No Asbestos

B000 - R0003 - Home Base

No Asbestos

B000 - R0004 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00P - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00P - R0001 - External Movement

No Asbestos

B00P - R0002 - Practical Activities/Movement - 1hb

No Asbestos

B00P - R0003 - Home Base Store

No Asbestos

B00P - R0004 - Home Base

No Asbestos

B00P - R0005 - Withdrawal Space - 2hb

No Asbestos

B00P - R0006 - Home Base

No Asbestos

B00P - R0007 - Home Base Store

No Asbestos

B00P - R0008 - Practical Activities/Movement - 1hb

No Asbestos

B00P - R0009 - No Access

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00Q - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00Q - R0001 - External Movement

No Asbestos

B00Q - R0002 - Practical Activities/Movement - 1hb

No Asbestos

B00Q - R0003 - Home Base Store

No Asbestos

B00Q - R0004 - Home Base

No Asbestos

B00Q - R0005 - Withdrawal Space - 2hb

No Asbestos

B00Q - R0006 - Home Base

No Asbestos

B00Q - R0007 - Home Base Store

No Asbestos

B00Q - R0008 - Practical Activities/Movement - 1hb

No Asbestos

B00Q - R0009 - No Access

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00R - Pupil Facilities - 2010 - Steel (Steel)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00R - R0001 - External Movement

No Asbestos

B00R - R0002 - Toilets - Boys

No Asbestos

B00R - R0003 - No Access

No Asbestos

B00R - R0004 - Toilets - Girls

No Asbestos

B00R - R0005 - Access Shower/Toilet/Change

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 751 - D11958 - Learning Unit - ESL : Placement Date - 10/12/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Esl

No Asbestos Found.

R2 - Esl

No Asbestos Found.

OS 602 - D12397 - Learning Unit - Standard With P.A.A. : Placement Date - 24/12/2015

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D14198 - Learning Unit - Standard With P.A.A. : Placement Date - 24/12/2015

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 811 - D14259 - FSU/Shelter/Stores : Placement Date - 30/06/1995

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	31.68 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Interior

R1 - Canteen

End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				28 m2

R2 - Covered Area

End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				145 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos				4 m2
---------	---------------	------------------	--	--	--	------

R4 - Sports Store

Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2
---------	---------------	------------------	--	--	--	-------

R5 - Garden Store

Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
---------	---------------	------------------	--	--	--	------

R6 - Change Room

Ceiling	Flat AC Sheet	Assumed Asbestos				3 m2
---------	---------------	------------------	--	--	--	------

R7 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos				2 m2
---------	---------------	------------------	--	--	--	------

OS 602 - D16794 - Learning Unit - Standard With P.A.A. : Placement Date - 10/12/2016

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017